

ASS. REC. BY:

REF: CS/ II 18000 345 / Krd3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Gabriel Weeof IIIDate/Time: 8/1/2018 @ 10:29am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJF 1194SInsured: SHC 1512Yat Workshop m/s Ah Chang MotorTel: 6483 5434of BIK 10, AMK Ind. Prk 2A #03-1691117978Policy No: MCOM00LS

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 31/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time: 11:02am @ 08/01/2017Person Contacted: DianaVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	Estimate
	<u>SJF 1194S -x</u>	
	<u>SHC 1512Y - cc3 / CTI 16019984 / MJ2a3n2</u>	<u>D.O.A: 18/10/2016</u>
<u>14/5</u>	<u>1/1/17 @ 300d email, 5 days</u>	
	<u>Red: 935745, 767.</u>	

ASS. REC. BY:

REF: 111 /Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s In Chingof 03-18

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8/11K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STF 11945 Yr Regn: 04/05, 08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota c.c. 1497Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 214287 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR054149104036216Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 6 mm RearL/Bal. 6 mm R/Bal. 6 mmD.O.A. 3/12/17 L/Bal. 6 mmD.O.I. 8/1/18

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop orO/S Front & etc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/11 File goes to Carhenn, Est not ready

RECEIVED 31 MAY 2010

Date/Time, File Pass to?

1) typist ☐ : Prel. Report☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS, \$

Photos

Others

TOTAL

Report Format: TPLump Sum / L&I: (\$ 3000)35010360



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS/III18000395/Krd3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 08-01-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 1512Y	Veh. Inspected	SJF 1194S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	GABRIEL WEE	Assign Date	08/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/12/2017	Inspection Date	08/01/2018
Survey held at	AH CHANG MOTOR SERVICE CENTRE BLK 10 ANG MO KIO IND PARK 2A AMK AUTOPOINT #03-16 SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 8 January 2018 10:29 AM
To: Cheong Hoh Lee; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sherini Pillai
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJF1194S (Accident involving SJF1194S and SHC1512Y on 31.12.2017)
Attachments: shc1512y_20180108095142.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJF1194S and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Cheong Hoh Lee [mailto:mail@cheonghoh.sg]
Sent: 08 January, 2018 10:22 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJF1194S (Accident involving SJF1194S and SHC1512Y on 31.12.2017)

Dear Sir/ Madam,

We refer to the above matter and your email of 5 January 2018.

Our client hereby nominate surveyor from LKK Auto Consultants Pte Ltd named in paragraph 2 serial no 1 of your said email for the pre-repair survey ("PRS") of the damages to our client's vehicle but not a single joint expert arising out of the above mentioned accident.

Please be informed that our client's vehicle, SJF 1194 S is currently laying at our client's workshop, Ah Chang Motor Service Centre, Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo Kio Point #03-16 Singapore 568047.

Kindly proceed to do the needful.

Regards,
Melody
Cheonghoh Law Corporation

Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

On Jan 8, 2018, at 9:56 AM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

<shc1512y_20180108095142.pdf>

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2018 15:16
Date Of Accident	31/12/2017 23:50
Exact Location Of Accident	T/JUNCTION OF WALLICH ST / MAXWELL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF1194S
Insured/Policyholder	
Name Of Registered Owner	HERMITLU
Co Reg No	53322493D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-92786267

Vehicle Particulars

Manufacturer	TOYOTA
Model	YARIS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	IN TRANSIT

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5086107614
Cover Note Number	14/11/2016 - 19/05/2018

Driver

Name of Driver	LU YIMING
NRIC No	S8242625F
Date Of Birth	12/12/1982
Occupation	OUTDOOR
Date Of Driving Pass	06/06/2006
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92786267
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 410 SAUJANA ROAD #14-106
Postcode	670410
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MICHELE GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MR MICHELE
Phone Number	98310997
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC1512Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 2493D

Vehicle Details

Vehicle No.: SJF11945
Vehicle to be Exported: No
Intended De-registration Date: 09 Jan 2018
Vehicle Make: TOYOTA
Vehicle Model: YARIS E AUTO
Primary Colour: Blue
Manufacturing Year: 2008
Engine No.: 1NZX745258
Chassis No.: MR054HY9104036216
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$14,176.00
Original Registration Date: 20 May 2008
First Registration Date: 20 May 2008
Transfer Count: 2
Actual ARF Paid: \$14,176.00

Intended PARF Rebate Details


PARF Eligibility: Yes
PARF Eligibility Expiry Date: 19 May 2018
PARF Rebate Amount: \$7,088.00

Intended COE Rebate Details

COE Expiry Date: 19 May 2018
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$16,930.00
COE Rebate Amount: \$609.00
Total Rebate Amount: \$7,697.00

The information contained herein is correct as at 09 Jan 2018

OK



AH CHANG MOTOR SERVICE CENTRE

Bik 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJF1194S Toyota Yaris

*Not Authorized
 61 Sm @ 3000h
 Running After Paint 5 days*

No	Qty	Parts Description		Estimated Parts Price	
1	1	Front bumper assy	Bu	\$ 789.60	✓
2	2	Front bumper bracket		\$ 82.30	X
3	2	Front bumper side retainer	011 DIT	\$ 86.20	✓ 43.10
4	1	Front bumper reinforcement	R	\$ 287.90	X
5	1	Front bumper sponge	Sm	\$ 175.10	X
6	1	Front grille assy	Sm	\$ 227.30	X
7	1	Front grille emblem	Sm	\$ 68.50	X
8	1	Front left headlamp	Sm	\$ 823.20	X
9	1	Front right headlamp	my cm	\$ 823.20	✓
10	1	Front right fog lamp	Sm	\$ 280.70	X
11	1	Front right fog lamp garnish	Sm	\$ 56.20	X
12	1	Front bonnet assy	R	\$ 992.10	X
13	1	Front bonnet lock mechanism	R	\$ 225.50	X
14	2	Front bonnet hinges	R	\$ 108.20	X
15	1	Front bonnet insulator	Sm	\$ 197.80	X
16	2	Front bonnet rubber stopper	Sm	\$ 36.80	X
17	1	Front bonnet lock brace panel	R	\$ 127.10	X
18	1	Front support panel	R	\$ 882.70	X
19	4	Front support panel rubber stopper	Sm	\$ 38.80	X
20	1	Front support panel top garnish	Sm	\$ 149.20	X
21	1	Front right fender assy	Bu	\$ 778.10	✓
22	1	Front right fender lamp	Sm	\$ 78.70	X
23	1	Front right fender inner cowl	cm	\$ 118.20	✓
24	1	Front right fender vvti emblem	cm	\$ 68.60	✓
25	1	Front right suspension assy	R	\$ 682.60	✓
26	1	Front right lower arm	0-1	\$ 320.40	✓
27	1	Front right knuckle arm	R	\$ 332.20	✓
28	1	Front right wheel hub with bearing	cm	\$ 279.50	✓
29	1	Front right brake disc	Sm	\$ 151.90	X
30	1	Front right brake disc housing	Sm	\$ 68.60	X
31	1	Front right lower ball joint	Sm	\$ 179.40	X
				\$ 9,516.60	
Less 25%				\$ 2,379.15	
				<u>\$ 7,137.45</u>	



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJF1194S Toyota Yaris

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Front bumper clips	\$ 50.00 ✓
2	4	Front grille clips	\$ 20.00 X
3	1	Front bumper spoiler assy	\$ 780.00 X
4	1	Front bumper spoiler sealant	\$ 80.00 X
5	10	Front bumper spoiler clips	\$ 50.00 X
6	8	Front bonnet insulator clips	\$ 30.00 X
7	1	Front right sport rim	\$ 650.00 280mm
8	1	Front right tyre	\$ 300.00 X
9	1	Front right fender sealant	\$ 80.00 X
10	6	Front right fender inner cowlings clips	\$ 30.00 ✓
11	6	Front support panel top garnish clips	\$ 20.00 X
12	1	Front no plate with garnish	\$ 80.00 X
			<u>\$ 2,170.00</u>
Total parts			\$ 9,307.45


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJF1194S Toyota Yaris

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front right damaged parts.	\$ 1,000.00	400
2	To putty and spray painting front right portion.	\$ 1,000.00	400
3	To remove and install front bonnet lock mechanism.	nn \$ 80.00	X
4	To apply anti rust proofing to front right affected area.	\$ 100.00	30
5	To check and focus front headlamp.	\$ 30.00	20
6	To remove and install front right undercarriage parts.	\$ 280.00	160
7	To conduct chassis alignment.	nn \$ 350.00	X
8	To conduct wheel alignment.	\$ 80.00	60
9	To balance front right wheel.	\$ 30.00	20
10	Towing service.	nn \$ 100.00	X
Total labour :		\$ 3,050.00	

Total parts : \$ 9,307.45

Total labour : \$ 3,050.00

Total repair cost : \$ 12,357.45

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18000395/KRD3N2

Date: 05/06/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SJF1194S	Insured Vehicle No :	SHC1512Y
Date of Loss:	31/12/2017	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF1194S	Engine No:	1NZX745258
Make & Model:	TOYOTA YARIS E AUTO, 1.5 (A)	Chassis No:	MR054HY9104036216
Reg. Date:	20/05/2008 (Man. Year: 2008)	Odometer:	214297 km
Colour:	Metallic Blue		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,307.45	3,536.62	5,770.83	62.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,090.00	1,960.00	64.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,357.45	4,626.62	7,730.83	62.56
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	12,357.45	3,000.00	9,357.45	75.72
+ GST 7.00/7.00% (S\$)	865.02	210.00	655.02	75.72
Nett Amount (S\$)	13,222.47	3,210.00	10,012.47	75.72

INSPECTION

Date of Assignment:	08/01/2018	
Date Inspected:	08/01/2018 Inspected At:	Ah Chang Motor Service Centre (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, ANG MO KIO POINT #03-16 Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2018)
Parts: 144	TOYOTA YARIS E AUTO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJF1194S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER ASSY	Buckled	789.60 FL	*789.60 FL
2	2	*FRONT BUMPER BRACKET	Repair	82.30 FL	*- FL
3	1	*FRONT BUMPER SIDE RETAINER	O/s Distorted	86.20 FL	*43.10 FL
4	1	*FRONT BUMPER REINFORCEMENT	Repair	287.90 FL	*- FL
5	1	*FRONT BUMPER SPONGE	Serviceable	175.10 FL	*- FL
6	1	*FRONT GRILLE ASSY	Serviceable	227.30 FL	*- FL
7	1	*FRONT GRILLE EMBLEM	Serviceable	68.50 FL	*- FL
8	1	*FRONT LEFT HEADLAMP	Serviceable	823.20 FL	*- FL
9	1	*FRONT RIGHT HEADLAMP	Mtg Cracked	823.20 FL	*823.20 FL
10	1	*FRONT RIGHT FOG LAMP	Serviceable	280.70 FL	*- FL
11	1	*FRONT RIGHT FOG LAMP GARNISH	Serviceable	56.20 FL	*- FL
12	1	*FRONT BONNET ASSY	Repair	992.10 FL	*- FL
13	1	*FRONT BONNET LOCK MECHANISM	Repair	225.50 FL	*- FL
14	2	*FRONT BONNET HINGES	Repair	108.20 FL	*- FL
15	1	*FRONT BONNET INSULATOR	Serviceable	197.80 FL	*- FL
16	2	*FRONT BONNET RUBBER STOPPER	Serviceable	36.80 FL	*- FL
17	1	*FRONT BONNET LOCK BRACE PANEL	Repair	127.10 FL	*- FL
18	1	*FRONT SUPPORT PANEL	Repair	882.70 FL	*- FL
19	4	*FRONT SUPPORT PANEL RUBBER STOPPER	Serviceable	38.80 FL	*- FL
20	1	*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	149.20 FL	*- FL
21	1	*FRONT RIGHT FENDER ASSY	Buckled	778.10 FL	*778.10 FL
22	1	*FRONT RIGHT FENDER LAMP	Serviceable	78.70 FL	*- FL
23	1	*FRONT RIGHT FENDER INNER COWLING	Cracked	118.20 FL	*118.20 FL
24	1	*FRONT RIGHT FENDER VVTI EMBLEM	Necessary	68.60 FL	*68.60 FL
25	1	*FRONT RIGHT SUSPENSION ASSY	Bent	682.60 FL	*682.60 FL
26	1	*FRONT RIGHT LOWER ARM	Distorted	320.40 FL	*320.40 FL
27	1	*FRONT RIGHT KNUCKLE ARM	Bent	332.20 FL	*332.20 FL
28	1	*FRONT RIGHT WHEEL HUB WITH BEARING	Necessary	279.50 FL	*279.50 FL
29	1	*FRONT RIGHT BRAKE DISC	Serviceable	151.90 FL	*- FL
30	1	*FRONT RIGHT BRAKE DISC HOUSING	Serviceable	68.60 FL	*- FL
31	1	*FRONT RIGHT LOWER BALL JOINT	Serviceable	179.40 FL	*- FL
32	10	*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
33	4	*FRONT GRILLE CLIPS	Not fitted	20.00 FS	*- FS
34	1	*FRONT BUMPER SPOILER ASSY	Serviceable	780.00 FS	*- FS
35	1	*FRONT BUMPER SPOILER SEALANT	Serviceable	80.00 FS	*- FS
36	10	*FRONT BUMPER SPOILER CLIPS	Not Necessary	50.00 FS	*- FS
37	8	*FRONT BONNET INSULATOR CLIPS	Not Necessary	30.00 FS	*- FS
38	1	*FRONT RIGHT SPORT RIM	Dented	650.00 FS	*280.00 FS
39	1	*FRONT RIGHT TYRE	Serviceable	300.00 FS	*- FS
40	1	*FRONT RIGHT FENDER SEALANT	Not Necessary	80.00 FS	*- FS
41	6	*FRONT RIGHT FENDER INNER COWLING CLIPS	Necessary	30.00 FS	*30.00 FS
42	6	*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
43	1	*FRONT NO PLATE WITH GARNISH	Serviceable	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	11,686.60	4,595.50
				- List Item Discount on L Items 25.00/25.00% (S\$)	2,379.15	1,058.88
				Total Parts (S\$)	9,307.45	3,536.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT DAMAGED PARTS	New	1,000.00	400.00
2	TO PUTTY AND SPRAY PAINTING FRONT RIGHT PORTION	New	1,000.00	400.00
3	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM	New	80.00	-
4	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA	New	100.00	30.00
5	TO CHECK AND FOCUS FRONT HEADLAMP	New	30.00	20.00
6	TO REMOVE AND INSTALL FRONT RIGHT UNDERCARRIAGE PARTS	New	280.00	160.00
7	TO CONDUCT CHASSIS ALIGNMENT	New	350.00	-
8	TO CONDUCT WHEEL ALIGNMENT	New	80.00	60.00
9	TO BALANCE FRONT RIGHT WHEEL	New	30.00	20.00
10	TOWING SERVICE	New	100.00	-
Gross Labour Cost (S\$)			3,050.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >