

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

## **Immediate Advice**

To: AXA Insurance Pte Ltd Date: 16/11/2019

## **Survey Details:**

Date of loss	2-Jan-18
Date of appointment	5-Jan-18
Date of survey	5-Jan-18
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

## **Vehicle Details:**

Claim Type:	Third party
Vehicle number	SHB 9759E
Make and Model	RENAULT LATITUDE 2.0L DCI AUTO
Date of registration	31-Jul-13
Excess	
Market Value (est)	\$0.00
Parf Rebate (est)	\$0.00
Nett Loss (est)	\$0.00

# **Repair details:**

Initial Estimate	\$	38,430.58
------------------	----	-----------

## **Proposed/Revised repair cost:**

Parts	\$ 1,137.11
Check items (estimate)	\$ -
Labour	\$ 1,120.00
Total	\$ 2,257.11
Lump Sum(if applicable)	\$ 1,800.00

Number of days for repair	2.5 DAYS
---------------------------	----------



 $51\; UBI\; AVE\; 1,\, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; FAX: \\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PAYA\; UBI\; P$ 

#### **Remarks:**

We have not authorized repairs. It was reported that Insured Driver was changing lane when TP vehicle was also changin towards the same lane when the collision occurred. However, TP reported that he was within his lane when hit by the Insured vehicle. A letter was sent out to the Insured to notify TP claim and NCD issues. No evidence e.g. Video footage and PIR were available. TP LOD IN.

### **Mandate:**

Liability(TP)	100%	
Proposed Repair Cost	\$ 1,926.00	w/gst
Loss of Use	\$ -	no. of days
Loss of Rental	\$ 397.28	\$99.32 x 4 days
Loss of Income	\$ 200.00	\$50 x 4 days
LTA Search Fees	\$ 5.35	
Others (Medical Bills)	\$ -	
Proposed Total	\$ 2,528.63	
***TBC - To Be Confirmed		