

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9759E**AAD1801-048***Not Authorised
11 Sep @ 1800*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9759E

VF1ABL15AUC273244

RENAULT

LATITUDE

2.1.2018

AXA

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Bu/m</i> 1,108.46 <i>✓</i>
2	1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84 <i>✓</i>
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 <i>✓</i>
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 <i>✓</i>
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 <i>✓</i>
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 <i>✓</i>
7	1	BUMPER BEAM REAR	\$	<i>n</i> 777.52 <i>✓</i>
8	1	BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95 <i>✓</i>
9	1	FENDER PANEL REAR RH	\$	<i>n</i> 3,299.13 <i>✓</i>
10	1	WHEELARCH REAR RH	\$	<i>n</i> 543.47 <i>✓</i>

TOTAL	\$	7,061.42
10%	\$	706.14
	\$	6,355.28

Specical Nett

1	1SET	PARKING AID	\$	<i>Sn</i> 700.00 <i>✓</i>
2	1SET	REAR BUMPER CLIP	\$	<i>n</i> 66.00 <i>✓</i>
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>n</i> 33.00 <i>✓</i>
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>n</i> 10.00 <i>✓</i>
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>n</i> 20.00 <i>✓</i>
6	1SET	BUMPER LOWER REAR RIVET	\$	<i>n</i> 22.00 <i>✓</i>
7	1SET	BUMPER LOWER REAR CLIP	\$	<i>n</i> 66.00 <i>✓</i>
8	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>n</i> 35.00 <i>✓</i>

TOTAL	\$	952.00
--------------	-----------	---------------

TOTAL PARTS	\$	7,307.28
--------------------	-----------	-----------------

Trans-cab Auto Services Pte Ltd

AAD1801-048

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9759E

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>6601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 <i>4001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nr</i> 170.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nr</i> 170.00 <i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nr</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nr</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nr</i> 380.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nr</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00 <i>X</i>

(PARTS BY PARTS)**Repair Days**

TOTAL \$	7,710.00
Over All Total \$	38,430.58

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after repair
- To display damaged part(s) during resurvey
- Resurvey fees are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

10 Days
2 1/2 days