


## SMRT Accident Vehicle Repair Estimates

AXA

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4259J  
 Ref. No : TAX/01/18/2006  
 Reg. Date : 22/11/2013  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : THIYAGARAJAN S/O K MUNIYANDI  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 02/01/2018 11:34:00 AM  
 Accident Reported Date / Time : 02/01/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024093882  
 Special Instruction to ARC, if any :  
 GBG4233H - AXA  
 Prepared Date : 02/01/2018 01:03:01 PM



Sebastian.  
5/1/18.

- Lump Sum Repair.
  - Question Mark Item Photo.
  - Photo After Paint
- 90036121

sebastianyeang@lkkauto.com.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U60-5705359 Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	845.00	0.00
Total Spray Painting Charges :	1,116.00	0.00
Total Material Charges :	1,994.98	2,599.71
Other Charges :	480.00	0.00
<b>TOTAL :</b>	<b>4,435.98</b>	<b>0.00</b>
<b>Lum Sum Total :</b>	<b>4,450.00</b>	<b>0.00</b>
No. of Repair Days :	5.00	0.00
Prepared / Adjusted By :		3 days
Arc / Surveyor Sing Off Date :	02/01/2018 02:32:59 PM	01/01/1900 12:00:00 AM

*S*

Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/01/2018 02:30:52 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

LKK Auto Consultants hence notify  
 the Repairer of the following:  
 • To reserve damaged parts for repair  
 • To display damaged parts for repair  
 • Parts prices are subject to contract  
 • Third party survey is on a "Without Prejudice" basis  
 • No legal, medical or other claims allowed  
 • Supplemental claims must be reserved and  
 is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date:

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	845.00	0.00 400
<b>Total Labour</b>	<b>845.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00 ?	0.00
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00 ?	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,116.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 30
<b>Total Other Costs</b>	<b>480.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace ✓ PNN	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace ?	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace ?	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace ?	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓ CAK	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓ NEE	No
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace X	No
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace X	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace ✓ SCR	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace ?	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace ?	No
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.93	Repair	Replace R	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓ NEE	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace ?	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ?	No
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace ✓ CAK	No
<b>TOTAL MATERIALS</b>							<b>2,493.75</b>	<b>3,249.65</b>		
<b>TOTAL MATERIALS(Discounted)</b>							<b>1,994.98</b>	<b>2,599.71</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									