

INS. CASE OWNER:

Jaya

CC3 / CT118000411

Kh\$302

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KENNETH

DOI:

05/01/18

Date / Time:

05/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 103L

Claim No.:

SNM18D0094C02/3/LKKDS

Name of Insured:

CHE MAY LENG CAROLINE

Policy No.:

DMPCSN1722201700

Insured Tel No.:

HP: 9109 1963

Make / Model:

HONDA JAZZ 1.5L AT ABS D/AB

Excess Sec II :\$S

D.O.A.: 03/01/18

Place of Accident:

HID 2ND SDR
JALAN RULOH PERINDU / EAST COAST
ROAD

Is driver the owner?

(YES ☒ NO)

Nature of Accident:

If NO, Driver Name / Age: LIM YING TSUI

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Driver Tel No.:

8102 2445

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SHF 666C



INSRS:

WSP: Trans-Cab (Mk)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

10/01/18 (vic)

SHF 666C - X; SLK 103L - X
- PICKUPED.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 10/01/18 11:37 Sfrs. Hana

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

10/1/18 1406hrs

- Called OI Adm Chan May Leng Caroline 9109 1963,
called OI, Ms Lim Ying Tsui 8102 2445 both
no respond

10/1/18 1714hrs

A return call from OI, she want to know the amount
might want to settle personally. finalized

12/01/18

- SEND LETTER TO OI.

11/1/18 1230hrs

spoke to OI she agreed to settled on TP claims. Aware
of NCD issue.

25/01/18

- FOR BULK SETTLEMENT. FROM ETC. SETTLED.

03/02/18

- THE REPORT FOR WAIVER TO BE FILING
TP LOD. ORIGINAL TP LOD IN.
- REPORT DONE.

PRELIMINARY ADVICE

Date/Time: 03/01/18

Sent By:

Shirley Hsu

10/03/18

- OI APPROVED WAIVER.

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

49

SS

8,300.00

(3 days)

Reduction:

66 %

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

11/03/18

Confirm with:

SKALINE

Email ☐Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

9

Repair Cost:

Cw/act

SS

8,881.00

Loss of Rental (LOR):

SS

1,217.52

(12 days)

x \$101.46

Loss of Use (LOU):

SS

600.00

x 12 days

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☒

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

10,705.97

Global Sum \$S:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

SS

10,705.97

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

RECEIVED 22 MAY 2018

ASS. REC. BY:

REF:

CTZ /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHF 666C

Yr Regn:

06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perodua Latitude

c.c

1995

Colour

M. White 1st

A/C:

Insured / Std / NI / NA

Sp. Reading

263502

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABL15AUC - 278757

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

NII / S/Rim / STD A/Rim or

Tyre Size:

F: Falken

215/60R16

R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

3/1/18

D.O.I.

5/1/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rec body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

8/11 File pass to Carhena
u 8/11 by 88300

25/1 11 by 88300 Confirm Tarnish (8+4x101.46 + 600)
CRWD: 16, 12A.28 (66%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18000411/Khs3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 08-01-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 103L	Veh. Inspected	SHF 666C	
Policy No.	DMPCSN1722201700	Coverage (\$)	0.00	
Claim No.	SNM18D00094C02/3/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	08/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/01/2018	Inspection Date	05/01/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI18000411/Khs3

Date: 08.01.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHF 666C


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.01.2018 at the premises of M/s Trans-Cab Auto Services Pte Ltd (Ang Mo Kio) and have the following to report:-

Workshop Estimate Amount	: S\$	24,424.28
Revised Estimate Amount	: S\$	10,387.93
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Rear Body Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 8.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHF666C
Vehicle to be Exported:	Yes
Intended De-registration Date:	04 Jan 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001735
Chassis No.:	VF1ABL15AUC278757
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Jun 2014
First Registration Date:	30 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	29 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$32,153.00
Total Rebate Amount:	\$41,526.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Jan 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 666C**AAD1801-062***Not Authorised*
11 Sep @ 8300h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 666C

VF1ABL15AUC278757

RENAULT

LATITUDE

3.1.2018

CHINA TAIPING**PART****LIST**

1 DOOR PANEL FRT LH	\$	R 2,844.66	X
2 DOOR PANEL REAR LH	\$	R 2,844.66	✓
3 DOOR GUIDE REAR LH	\$	L 176.82	}
4 DOOR HINGE UPPER LH	\$	R 274.50	
5 DOOR HINGE LOWER LH	\$	R 300.55	
6 DOOR CHECK REAR LH	\$	L 203.06	
7 DOOR LOCK REAR LH	\$	R 908.75	
8 DOOR GRAB HANDLE REAR LH	\$	L 210.96	}
9 DOOR HANDLE OUTER REAR LH	\$	L 126.49	
10 DOOR HANDLE CAP REAR LH	\$	L 35.52	
11 DOOR HANDLE COVER REAR LH	\$	L 13.22	}
12 DOOR HANDLE MODULE REAR LH	\$	L 133.60	
13 DOOR FINISHER REAR LH	\$	L 423.10	
14 DOOR WHEATHESTRIIP REAR LH	\$	L 410.66	✓
15 DOOR SEAL REAR LH	\$	L 162.02	X
16 DOOR WAIST SEAL OUTER REAR LH	\$	L 334.69	X
17 DOOR MOULDING REAR LH	\$	L 176.82	X
18 FENDER PANEL REAR LH	\$	R 3,299.13	✓
19 FENDER PANEL INNER TRIM REAR	\$	L 671.45	X
20 WHEELARCH REAR LH	\$	L 543.47	X
21 ROCKER PANEL INNER GARNISH LH	\$	L 466.51	X
22 ROCKER PANEL INNER LH	\$	R 1,024.79	✓
23 BUMPER COVER REAR	\$	R 1,108.46	✓
24 BUMPER LOWER REAR	\$	L 768.84	X
25 BUMPER BRACKET CTR REAR	\$	L 113.47	X
26 BUMPR RETAINER RH REAR	\$	L 44.99	X
27 BUMPR BRACKET SIDE LH REAR	\$	L 135.97	X
28 BUMPR RETAINER LH REAR	\$	L 44.99	X
29 BUMPER REFLECTOR LH	\$	L 43.61	X
30 BUMPER BEAM REAR	\$	R 777.52	X

Trans-cab Auto Services Pte Ltd

AAD1801-062

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 666C

31 BUMPER BEAM BRACKET LH REAR \$ 225.95 X

TOTAL	\$	18,849.23
10%	\$	1,884.92
	\$	16,964.30

Special Nett

1SET	DOOR CASING CLIP	\$	12.63 X
1SET	DOOR HINGE BOLT	\$	10.85 X
1SET	DOOR HINGE NUT RH	\$	14.60 X
1SET	DOOR HANDLE SEAL REAR LH	\$	7.89 X
1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00 X
1	Front Door sticker 'Trans-cab'	\$	80.00 X
1	Front Door sticker 'Chassis'	\$	30.00 X
1	Rear Door sticker '6555 3333'	\$	80.00
1SET	REAR BUMPER CLIP	\$	66.00
1SET	BUMPER BRACKET CTR CLIP	\$	33.00
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00 X

TOTAL \$ 379.98**GRAND TOTAL \$ 17,344.28****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	11001
To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To transfer of door fittings, attachments and perform water seepage test.	\$	170.00	601

Trans-cab Auto Services Pte Ltd**AAD1801-062**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 666C

To repair and realign rear exhaust pipe.	\$	170.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 <i>1001</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 <i>1201</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>601</i>

TOTAL \$ 7,080.00**Over All Total \$ 24,424.28****(PARTS BY PARTS)
Repair Days****10 Days***8 days*LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18000411/Khb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 22-05-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 103L	Veh. Inspected	SHF 666C
Policy No.	DMPCSN1722201700	Coverage (\$)	0.00
Claim No.	SNM18D00094C02/3	Excess (\$)	0.00
Assign From		Assign Date	05/01/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278757	Colour	METALLIC WHITE / RED
Odometer	263502	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FALKEN	7 mm
L/H Front Tyre	215/60 R16	FALKEN	7 mm
R/H Rear Tyre	215/60 R16	GOODYEAR	6 mm
L/H Rear Tyre	215/60 R16	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/01/2018	Inspection Date	05/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 666C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR PANEL REAR LH	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR LH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH	SERVICEABLE	203.06	-
1	DOOR LOCK REAR LH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR LH	SERVICEABLE	423.10	-
1	DOOR WEATHERSTRIP REAR LH	CUT	410.66	410.66
1	DOOR SEAL REAR LH	SERVICEABLE	162.02	-
1	DOOR WAIST SEAL OUTER REAR LH	SERVICEABLE	334.69	-
1	DOOR MOULDING REAR LH	SERVICEABLE	176.82	-
1	FENDER PANEL REAR LH	BENT	3,299.13	3,299.13
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	ROCKER PANEL INNER GARNISH LH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER LH	BENT	1,024.79	1,024.79
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-

Report Ref No. CC3/CTI18000411/Khb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
	LESS 10% DISCOUNT		-1,884.92	-868.77
			16,964.31	7,818.93
	SPECIAL NETT ITEMS			
1	SET DOOR CASING CLIP (SN)	NOT NECESSARY	12.63	-
1	SET DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	SET DOOR HINGE NUT RH (SN)	SERVICEABLE	14.60	-
1	SET DOOR HANDLE SEAL REAR LH (SN)	NOT NECESSARY	7.89	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR STICKER "CHASSIS" (SN)	NOT NECESSARY	30.00	-
1	REAR DOOR STICKER "65553333" (SN)	NECESSARY	80.00	60.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
			379.97	159.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	880.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL FRT LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER LH,DOOR LOCK REAR LH,BUMPER BEAM REAR AND BUMPER BEAM BRACKET LH REAR.		2,800.00	1,100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	100.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
			7,080.00	2,410.00
GRAND TOTAL			24,424.28	10,387.93
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,300.00

Report Ref No. CC3/CT118000411/Khb3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.