



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street | Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

12 January 2018

HHTPClaims18-03

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#09-16 AIG Building
Singapore 079120

ACCIDENT INVOLVING YP 6677 C & SKH 8507 E ON 20/09/2017 ALONG SERANGOON AVENUE 2 AT ABOUT 0745 HOURS

Insured : FLY BUILD PTE LTD
Vehicle Registration No : YP 6677 C
Vehicle Make : HINO
Vehicle Model : XZU710R-HKFMS3
Vehicle Chassis No : JHHUCS3H90K019587
Policy No : VCA/P1969630
Date of Accident : 20/9/2017

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper ✓ BT		\$ 600.00
2	2	Rear Bumper Bracket (LH/RH) ✓ BT	\$ 250.00	\$ 500.00
3	1	Rear Bumper Step ✓ BT		\$ 250.00
				<u>\$ 1,350.00</u>

To dismantle & change rear bumper, rear bumper step, knocking & pull straight rear chassis frame and all area affected by accident. \$ ~~800.00~~ 500

To spray rear bumper, rear bumper LH/RH bracket, rear bumper step and rear chassis frame. \$ ~~800.00~~ 500

7% GST

Total

\$	2,950.00
\$	206.50
<u>\$</u>	<u>3,156.50</u>

3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sebastian. 23/1/18.

- Part by part repair.
- Photo Before Paint.

90036121

Sebastian.yeang@lkkauto.com.

Authorised by Claimant
Mrs Tan @ 9639 9195

