

VEHICLE NO:GBF 141X

KIM CHWEE AUTO PTE LTD

Not Allowed
2/5 \$4000
Hday.
8/1/18

1PC	TAILGATE	DD/300	\$1,645.10	—
1PC	TAILGATE DYNA STICKER	neu	\$45.50	—
1PC	TAILGATE LOWER MEMBER	n	\$545.10	x
1PC	TAILGATE LOCK LATCH O/S	n	\$119.30	x
1PC	TAILGATE 1500kg STICKER	neu	\$30.00	—
1PC	TAILLAMP O/S	one	\$285.30	—
1PC	TAILLAMP PANEL O/S	sel	\$119.30	—
1PC	TAILGATE LOWER 'L' PANEL O/S	n	\$68.50	x
1PC	TAILGATE LOWER 'L' PANEL RUBBER O/S	cut	\$62.30	—
2PCS	TAILGATE LOWER MEMBER REFLECTORS	@\$65. SW	\$130.00	—
1PC	REAR EXHAUST PIPE	sel	\$585.20	—
1PC	REAR EXHAUST PIPE MONTING	Tw,	\$112.00	—
1PC	REAR CENTRE CROSS MEMBER	DD/300	\$845.20	—
1PC	REAR SPARE TYRE CHAIN & BRACKET	gm	\$392.50	—
1PC	REAR LICENCE PLATE BRACKET	sel	\$119.50	—
		25%	\$5,104.80	

S.NETT

1PC	TAILGATE 70KM/hr STICKER	neu	\$20.00	105.00
1PC	TAILGATE 13 PAX STICKER	neu	\$20.00	105.00
1SET	REAR REVERSE SENSOR	NF	\$380.00	x
1PC	REAR LICENCE PLATE	one	\$40.00	—
1PC	REAR EXHAUST CHROME	DD	\$100.00	—
1PC	REAR TAILLAMP REFLECTOR O/S	one	\$50.00	—

TO CHECK WIRING
TO DISMANTLE & REPLACING REVERSE SENSOR
TO SPRAY RUST PROOFING
TO DISMANTLE & REPLACING REAR EXHAUST
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$80.00 30
11 \$80.00 x
\$120.00 50
\$100.00 60
\$1,000.00 800
\$1,500.00 600
TOTAL \$8,594.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

43719
327852
502822