

INS. CASE OWNER:

CC 3/CTI1800 0427 / 172 160702

LKK:

IDAC:

Surveyor:

Kalin

DOI:

6/1/18

Date / Time:

6/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBA 18607

Name of Insured:

ROYAL KNIGHT INTERNATIONAL

Insured Tel No.:

HP:

Excess Sec II :\$

D.O.A:

07/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

STAN RUSSEN NEW SEMI TRUCK

Driver Tel No.:

96771571

(V/L: YES / NO)

Claim No.:

SNM18000008608

Policy No.:

PMCSN 1613591701

Make / Model:

FIAT

Place of Accident:

CLP TMS HAWAII

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHD 99745

GBA 18607

SHC 12070



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

16/1/18

TH

19/1/18 @ 1:58

SHC 12070 - 12/1/18
GBA 18607 - X

called OI, no response.

3 vehicle chain collision.
Send letter to OI.

RECEIVED 15 MAR 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

12/3/18

Confirm with

William

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

0

Repair Cost:

SS

1926.00

Loss of Rental (LOR):

SS

442.13

(

4.5 days)

x 98.25

Loss of Use (LOU):

SS

225.00

(\$

50 x 4.5 days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

7.49

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

2600.62

Global Sum SS:

2600.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2600.00

Name 1:

COMFORTDELGRO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18000423/K1ub3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 08-01-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 1860Z	Veh. Inspected	SHC 1207D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	08/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	03/01/2018	Inspection Date	05/01/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18000423/K1ub3

Date: 08.01.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC1207D


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.01.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,318.82
Revised Estimate Amount	: S\$	2,281.62
"Check" Items Amount	: S\$	704.48
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Shu Pei (LKKAUTO)

From: Jowyn Tay <jowyn.tay@sg.cntaiping.com>
Sent: Thursday, 11 January 2018 6:22 PM
To: Shu Pei (LKKAUTO); Thin Thin (LKKAUTO)
Cc: Alfred Toh; Admin A; Jas Khine (LKKAUTO); Jowyn Tay
Subject: RE: Direct Settlement - Accident Involving GBA1860Z (OI : SNM18D00086C02/0) and SHC1207D (TP : LKK REF - CC3/CTI18000423/K1ub3) on 03.01.2018
Attachments: SNM18D00086C02 20180111-TO INSD-APPT LKK AS SETTLEMENT AGENT.pdf; MSM118001850-GBA1860Z.pdf
Importance: High

Dear Thin Thin and/or Shu Pei,

Refer to your email on 08 Jan 18.

We attached our insured's accident report and letter for your immediate attention.

Thank you.

Regards,

Jowyn Tay

Deputy Claims Executive

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6174

Fax: 6224 7175 / 6224 7478

Email: claimsdept@sg.cntaiping.com

jowyn.tay@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]

Sent: Monday, 8 January, 2018 5:52 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Jowyn Tay <jowyn.tay@sg.cntaiping.com>; Joel Goh

<joel.goh@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBA1860Z (OI : SNM18D00086C02/0) and SHC1207D (TP : LKK REF - CC3/CTI18000423/K1ub3) on 03.01.2018

WITHOUT PREJUDICE

Dear Jowyn,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 1207D at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.ctaiping.com
Co. Reg. No: 200208384E

Our Reference: **SNM18D00086/C02/0**

Date: **11 JANUARY 2018**

via Ordinary & Registered Mail

**ROYAL KNIGHT INTERNATIONAL
192 WATERLOO STREET
#05-01
SINGAPORE 187966**

Dear Sir / Madam

**ACCIDENT INVOLVING GBA1860Z AND SHC1207D ON 03 JANUARY 2018
ALONG ECP TOWARDS CHANGI**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC1207D**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : THIN THIN
Ref : CC3/CT118000423/K1UB3
Contact No : 68412360
via Email : thinthin@lkkauto.com

CC : Agent - (AN0324A) - LOY HSIEH-YIH

F01/LKKDS-2013

Date/Time: 04.01.2018 12:42

Page : 1

Job: IN ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305103898

OWNER
IS COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (R) (O)

REGN NO:
SHC1207D

MILEAGE

MAKE:
HYUNDAI

FUEL

E.....1/2.....F

MODEL
SONATA

DATE/TIME IN
04.01.2018 10:40

YR OF MANU
19.04.2012

TARGET DATE

CHASSIS CODE
KMHE141VMCA822982

COMPLETION DATE/TIME:

JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 03.01.2018
NATURE: 3P 03.01.18

/NO LABOR CODE DESCRIPTION

WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Reception Slip

Exit Pass

No.: SHC1207D

LIMITS

Vehicle No.: SHC1207D

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTÉ LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1207D

MAKE :

MODEL : HYUNDAI SONATA

Ching Taiping TS
DATE 5/1/2018 (L/S)

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ - 578.40
	Rear Bumper Reinforcement ?			\$ 2 483.30
	Rear Bumper Clip ✓			\$ - 22.00
	Rear Bumper Sponge ?			\$ 2 137.40
	Rear Bumper Under Cover ?			\$ 2 185.80
	Rear Bumper Protector (LH) ✓			\$ - 38.00
	Tail Lamp (LH) ✓			\$ - 344.00
	Rear Fender (LH) X 14-22			\$ 2 1,935.90
	Rear Fender Inner Lining (LH) ?			\$ 2 74.10
	Rear Windscreen Moulding X			\$ 2 60.00
	SUB TOTAL			\$ 3,858.90
	LESS 20%			\$ 771.78
	DISCOUNTED TOTAL			\$ 3,087.12
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) ✓	\$	100.00	\$ 200.00 Nett
	Rear Fender Comfort Sticker (LH/RH) ✓	\$	30.00	\$ 60.00 Nett
	Rear Windscreen Sealant X			\$ 2 46.00 Nett
				\$ 491.70
	Labour Charge			6.00
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 400.00 360
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 X
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 50
	Remove/Refix Rear Windscreen Glass			\$ 120.00 X
	Remove/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 1,740.00
	ESTIMATE TOTAL			\$ 5,318.82
	<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>			

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to inspection
- Third party survey is on a "no prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO.: SHC 1207D

MAKE :

MODEL : HYUNDAI SONATA

Ching Taiping

DATE 5/1/2018

CL(S) TS

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>Refined</i>			\$ 578.40	
	Rear Bumper Reinforcement <i>Xm</i>			\$ 483.30	
	Rear Bumper Clip <i>ac</i>			\$ 22.00	
	Rear Bumper Sponge <i>Xm</i>			\$ 137.40	
	Rear Bumper Under Cover <i>Xm</i>			\$ 185.80	
	Rear Bumper Protector (LH) <i>ac</i>			\$ 38.00	
	Tail Lamp (LH) <i>ac</i>			\$ 344.00	
	Rear Fender (LH) <i>X repair</i>			\$ 1,935.90	
	Rear Fender Inner Lining (LH) <i>Xm</i>			\$ 74.10	
	Rear Windscreen Moulding <i>X m</i>			\$ 60.00	
	SUB TOTAL			\$ 3,858.90	
	LESS 20%			\$ 771.78	
	DISCOUNTED TOTAL			\$ 3,087.12	
	Rear Bumper Reverse Sensor <i>skt</i>			\$ 135.70	Nett
	Rear Bumper Advertisement Logo <i>ac</i>			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) <i>ac</i>	\$	100.00	\$ 200.00	Nett
	Rear Fender Comfort Sticker (LH/RH) <i>ac</i>	\$	30.00	\$ 60.00	Nett
	Rear Windscreen Sealant <i>X "</i>			\$ 46.00	Nett
				\$ 491.70	
	Labour Charge			6.00	
	Panel Beating			\$ 850.00	
	Spray Painting Charge			\$ 400.00	360
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 50.00	X "
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	50
	Remove/Refix Rear Windscreen Glass			\$ 120.00	X "
	Remove/Refix Reverse Sensor			\$ 120.00	20
				\$ 1,740.00	
	TOTAL LABOUR			\$ 5,318.82	
	ESTIMATE TOTAL				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalin (LKK)

5/1/8 10:00h

4 Rep.

L/S

After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305103898

Date : 09/01/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHC1207D

Date of Accident : 03-Jan-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- GBA1860Z

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$1,800.00

Final Lumpsum Repair cost \$1,800.00

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : KALVIN

Date : 10/1/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18000423/K1ub3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 15-03-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 1860Z	Veh. Inspected	SHC 1207D	
Policy No.	DMCVSN1613591701	Coverage (\$)	0.00	
Claim No.	SNM18D00086C02/0	Excess (\$)	0.00	
Assign From		Assign Date	05/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SONATA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KMHET41VMCA822982	Colour	BLUE	
Odometer	209863	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	WEST LAKE	7 mm	
L/H Front Tyre	215/60 R16	WEST LAKE	7 mm	
R/H Rear Tyre	215/60 R16	WEST LAKE	7 mm	
L/H Rear Tyre	215/60 R16	WEST LAKE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/01/2018	Inspection Date	05/01/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1207D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	578.40	578.40
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	483.30	-
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	SERVICEABLE	137.40	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	185.80	-
1	REAR BUMPER PROTECTOR (LH)	CUT	38.00	38.00
1	TAIL LAMP (LH)	CRACKED	344.00	344.00
1	REAR FENDER (LH)	TO REPAIR SEE LABOUR	1,935.90	-
1	REAR FENDER INNER LINING (LH)	SERVICEABLE	74.10	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	60.00	-
	LESS 20% DISCOUNT		-771.78	-196.48
			3,087.12	785.92
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
2	REAR FENDER COMFORT STICKER (LH/RH) @\$30.00 (SN)	NECESSARY	60.00	60.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			491.70	445.70
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER (LH).		850.00	600.00
	SPRAY PAINTING CHARGE.		400.00	360.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	50.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-

Report Ref No. CC3/CTI18000423/K1ub3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX REVERSE SENSOR.		120.00	20.00
			1,740.00	1,050.00
GRAND TOTAL			5,318.82	2,281.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CC3/CTI18000423/K1ub3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.