COMFORTDELGRO ENGINEERING PTÉ LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 1207D

MAKE :



ODEL	: HYUNDAI SONATA	100	IVIN		
Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ - 578.40	1
	Rear Bumper Reinforcement ?			\$ 7 483.30	
	Rear Bumper Clip —			\$ - 22.00	
	Rear Bumper Sponge ?			\$ 7 137.40	
	Rear Bumper Under Cover ?			\$ 1185.80	
	Rear Bumper Protector (LH)			\$,38.00	
	-			\$ - 344.00	
	Tail Lamp (LH)			\$ 1,935.90	
	Rear Fender (LH) X Fender			\$ 1,733.70	
	Rear Fender Inner Lining (LH)			\$ 2 60.00	
	Rear Windscreen Moulding ×			\$ 1. 60.00	
	SUB TOTAL			\$ 3,858.90	1
	LESS 20%			\$ 771.78	
	DISCOUNTED TOTAL			\$ 3,087.12	1
	DISCOUNTED TOTAL			,,,,,,,,,,	
	. *				
	Rear Bumper Reverse Sensor			\$ 135.70	N
	Rear Bumper Advertisement Logo			\$ 50.00	N
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	N
	Rear Fender Comfort Sticker (LH/RH)		\$ 30.00	\$ 60.00	N
	Rear Windscreen Sealant			\$ 0 46.00	N
	Real Windscreen Scalant			1	
				\$ 491.70	
	Labour Charge			600	
	Panel Beating			\$ 850.00	
	Spray Painting Charge			\$ 400.00	- 3
	LKK Auto	Consultant	hence notify	\$ 50.00	- 2
	uig Nepa	rer of the fo before/after	lowing:	\$ 50.00	- 1
	Pamaya/Pafix Cushion & Unhalstery Rear To display	damaged part	d. Tid resurvey	\$ 150.00	- 1
	• Paris price	es are subject t	minimation.	\$ 120.00	
		y survey is on a	rejudice" basis	\$ 120.00	1 -
	Suppleme	rtan itemis) m	st have support and	1 7 .00	
	TOTAL LABOUR	i inal approva	From Insurance Company	\$ 1,740.00	
	Acknowledg Signature:	ed by Repairer			
	// 5//8 ESTIMATE TOTAL	4		\$ 5,318.82	
	TOTAL LABOUR Acknowledge Signature: Ships ESTIMATEOROTAL 4 Port 4 S After Regard plate				
	45				
	After Renit alob				
		1	1		1