

22/03/2002

ASS. REC. BY:

REF: CS/MSG18000425/T19d3

Special Instruction:

Survivor:
Meinmen

Taufan

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MSG

Date/Time: 08/01/2017 @ 9:44am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLK 6392D

Insured:

SFG 6379K

at Workshop m/s

Ding Auto

Tel:

8131 6518

of

31 Corporation Rd

Policy No:

A27276146QMX

Claim No:

544415

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 05/01/2018

CA / REV / REP. / REV 24 HRS

wp'

09/01/2018 @ 249 jalan Boontay

H.O.D. Endorsement:

Date/Time:

4:30pm @ 08/01/17

Person Contacted:

Lucas

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 6392D - x

SFG 6379K - x

11/11/18 @

4-12pm revised to Muhd Ashik via Meinmen.

Tajm

MS/G

Report Date 09/01/2018 SLK 6392D 2017 Jan.

Estimated Cost

CD 12 WS THRES CD RES EVA INVA

To insure vehicle SLK 6392D
at address Ding Auto
249 jalan Boontay

Insured

Policy No

Claims No

Sum Insured


Excess

Client's Record

Vehicle driven

Policy Condition

Remarks: The van had commenced its repair at the time of inspection.



Ball or Marker Value

DAC Accident Report Consistent? Yes or No

GA - PP Seen Consistent? Yes or No

Est. Repairs 6 days Res. Yes or No

LT Sum 3 val. Yes or No

CA REV PER 24 HRS Wp

Date Person Contacted

Date Time Action Inspector

4542500, 6 days e-mail to Michelle.
(Red to 6474.40, 72%)

Day Time Repass



Preli. Report



Final Report

Days Of Repair

Reserve, No. of This

Add Fee



One day

Two day

Three day

Four day

Five day

Six day

Seven day

Eight day

Rate Fee

Amount

200

10

10

10

10

10

10

10

RECEIVED 2010

MEB-TP

7500

9/3/2018

210

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000425/T1qd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 08-01-2018



Code : MSG

1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SFG 6379K	Veh. Inspected	SLK 6392D
Policy No.	A27276146QMX	Coverage (\$)	0.00
Claim No.	544415	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	08/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/01/2018	Inspection Date
Survey held at	249 JALAN BOON LAY	
Repairer	DING AUTO PTE LTD	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No.: CS/MS518000425/719d3
 Policy Type: OD / TP / TP RES / TL / EVA

SLK 6392D

Case Handler

Typist

Admin (Nirthe): Case handler to make sure all information created by the assignment team are **ACCURATE**:

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	☒			
C Customer Code	☒			
N Assign From	☒			
C Assign Date	☒			
C Veh No (Inspected)	☒			
C Veh No (Insured)	☒			
C D.O.A	☒			
C Policy No	☒			
C Claim No	☒			
C Insurance Authorisation (CA /REV/REP)				
C Report Type	☒			
C Weekend Charges				
N Survey held at/Repairer	☒			
C Excess				

Surveyor (Taufik): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	☒			
C Regn Month/Year	☒			
N Vehicle Type	☒			
N Make & Model	☒			
C Engine Capacity. (C.C)	☒			
N Colour	☒			
C Odometer. (Sp.Reading)	☒			
C Chassis No	☒			
N General Condition	☒			
N Steering	☒			
N Brake	☒			
N Modification (Modi)	☒			
C Tyre Size	☒			
N Tyre Make	☒			
C Tyre Balance	☒			
C Date of Inspection	☒			
N Survey held	☒			
N Des.of Damages	☒			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	☒			
--	-------------------------------------	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition	☒			
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair	☒			
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C Resurvey photo Uploaded	☒			
---------------------------	-------------------------------------	--	--	--

Check By:

[Signature]
Case Handler

09/05/18
Date

*C: Critical *N: Non-Critical

21/05/2014

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Ppt	Adj Submitted	Ins Auth'd	Status
Main	05 Jan 2018		08 Jan 2018 09:44 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHUA POH SAN, ID: S0240810D, Tel: +6596333605, Email: NOEMAIL		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLK6392D	Date of Loss:	05/01/2018 11:00 - :59
Claim Type:	TP / 544415	Policy/Cover Note No.:	A27276146QMX (TP, Fire & Theft) Coverage: 17/03/2017 - 16/03/2018
Vehicle Reg. No. (Insured):	SFG6379K	Policy No. (Claimant):	
		Excess:	
Repairer:	Ding Auto Pte Ltd (corporation Road) (HQ) 31 Corporation Road, 649825 Boon Lay - Tel: 81316518		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/01/2018]		
Driver/Custodian (Insured):	CHUA POH SAN (67 / Male), NRIC: S0240810D, Tel: +6596333605		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Eileen Ang

From: Woon Choo Kwok
Sent: Monday, 8 January, 2018 9:10 AM
To: Muhd Ashik B Madi; Eileen Ang
Cc: Christopher Chionh; Foo Ai Ngoh; Jason Sim
Subject: FW: ACCIDENT INVOLVING SLK6392D & SFG6379K DOA 05/01/2018

Dear ASHIK & EA,

FYA

Best Regards

Kwok Woon Choo
Senior Administrative Officer, Claims Services
Direct line +65 6643 1330 | Direct fax +65 6225 7402 | woonchoo_kwok@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Agnes Lee
Sent: Saturday, January 06, 2018 2:49 PM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>
Subject: FW: ACCIDENT INVOLVING SLK6392D & SFG6379K DOA 05/01/2018

From: yvonne wong [<mailto:yvonne.wong@dingauto.sg>]
Sent: 06 January 2018 09:47
To: Claims <claims@sg.msig-asia.com>
Cc: Kenneth Ding <kenneth.ding@dingauto.sg>; You jingfeng <jingfeng@dingauto.sg>; Accounts Ding Auto <accounts@dingauto.sg>
Subject: Re: ACCIDENT INVOLVING SLK6392D & SFG6379K DOA 05/01/2018

Dear Motor claims dept

Please arrange surveyor to survey the vehicle SLK6392D.

Vehicle lying at 249 Jalan Boon Lay

Thank you

Regards
Yvonne Wong
Ding Auto Pte Ltd

Tel: 92394128

On Fri, Jan 5, 2018 at 6:46 PM, yvonne wong <yvonne.wong@dingauto.sg> wrote:

Dear Motor claims dept

Please arrange surveyor to survey the vehicle SLK6392D.

Vehicle lying at 249 Jalan Boon Lay

Thank you

Yvonne Wong
Ding Auto Pte Ltd

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 11 Jan 2018

Preliminary Advice

Insured Vehicle No	: SFG6379K	Accident Date	: 05/01/2018
TP Vehicle No	: SLK6392D	Assignment Date	: 08/01/2018
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 6.00
Date of Inspection	: 09/01/2018		
Inspection At	: DING AUTO PTE LTD (CORPORATION ROAD) (HQ) 31 CORPORATION ROAD SINGAPORE 649825		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,974.40
Revised Amount	:S\$	3,005.00
Check Items (Estimated)	:S\$	433.40
Total	:S\$	3,438.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

By completing this form, you are making a statement to speed up the claims process.

This form is to be filled out by the Policyholder and/or the Authorised Driver.

Information given must be correct and accurate as possible. Any wilful misrepresentation or withholding of material facts may lead to the report being referred to the Police for investigation.

Information given to the Family Insurance companies is not an admission of policy liability on the part of the insurance companies.

Any accident may be referred to the Police for investigation.

Information given to the insurers of the insurers of the GIA Records Management Centre established by the Government of Singapore will for a fee be made available upon application by interested parties.

By completing this form, you hereby consent to the archiving of this report at the centre and to its use in the way described above.

ACCIDENT STATEMENT

Date of Report 05/01/2018 17:27
Date of Accident 05/01/2018 11:15
Location of Accident BALESTIER ROAD
City of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLK6392D
Insured Policyholder LCRF PTE LTD
Name of Registered Owner 201624597K
Home Address NOEMAIL
Mobile Phone No
Home Phone No OFFICE-31584255
Vehicle Particulars
Make TOYOTA
Model COROLLA ALTIS CLASSIC 1.6 CVT
Purpose for which vehicle was being used at time of accident PRIVATE HIRER
Is your vehicle covered under your own insurance policy? NO
What type of action to be taken THIRD PARTY
Type of Company PRIVATE CAR
Insurance Company
Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD
Type of Coverage COMPREHENSIVE
Is it a new car? NO
Police File Number 999995061
Police Case Number
Driver
Name TAMBIRAJA SELWARAJA DHARMASIRI
Licence S7287865E
Date of Birth 10/02/1972
Location OUTDOOR
Date of Driving Pass 28/03/2013
Driving Experience 4 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-92394128
Home Number
Fax Number
E-mail Address NOEMAIL

Is the Vehicle of the Insured's Company	NO
Is the Vehicle Owned by the Insured	OTHER - HIRER
Is the Transport of Driver's Own	-
	-
Is the Transport of Driver's Own Vehicle	-
	-
	-
Direction of the Accident	
Direction of the	COLLISION - HEAD TO REAR
Direction of the	RAINING
Direction of the	WET

Information

1. Was the vehicle involved in this accident?	NO
2. How many vehicles involved in the accident?	
3. How many injured in the Accident?	NO
4. How many injured conveyed to hospital by ambulance?	NO
5. Was any other material or property damaged?	YES
6. Was anyone approached by unknown person(s) offering accident claims assistance.	NO
7. Number of Passengers (Including Driver)	1

Policy of Police Action

Is the accident reported to the police? NO

Is the driver state which Police Station

Is a charge of intended Prosecution given? NO

Is the driver return?

Characteristics of Accident

STATEMENT

☐ Attachment(s)
☐ Photograph photos available for attachment? YES
☐ Photograph video captured by Car Camera? NO
☐ Photograph audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFG6379K
Vehicle Make/Model/Colour	
Category of Property	
Initial Valuation	PRIVATE CAR
Current Valuer	PAUL CHUA
Vehicle Road Number	
Vehicle Number	96333605
Insurance	
Remarks	
Insurance Company Name	
Amount of Damage	
With Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. I will fill out (and sign) the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material information may allow insurance companies to repudiate policy liability.
4. Issuance and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any dispute may be referred to the Police for investigation.
6. This Form will be forwarded to the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. With the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- The insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Insurance Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - investigating the accident and/or my claims;
 - administering, but not for or dealing with my instructions or responding to any enquiries by me;
 - formulating my claims (including the mailing of correspondence, statements, invoices, reports or notices to me (which may involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages)); and/or
 - complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- Insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- Personal Information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - for complying with requirements under any regulations, laws or court orders.

Insured's Signature
(or Authorised)




Driver's Signature
(If Driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:



LOCATION PLAN



A - SFG 63794
B - SFG 63794
Paul Chan
H/O 963351

Balestier Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

5/01/18 11:15 a.m.
I am travelling Balestier Road
I was stopping for traffic light
suddenly motorcycle SFG 63794
Hit on car Rear position no one
injured

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645
Tel: 6452 1208 Fax: 6452 0014

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

06/01/2018 15:43

JOB-NO: 85008033

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLK6392D

TRANS: AUTO

CHASSIS: MR053REH104562990

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY348280

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 PANEL BEAT AND STRAIGHTEN CHASSIS	1.00	2,000.00	0.00	2,000.00		Y	900
2 CHECK WIRING	1.00	60.00	0.00	60.00		Y	30
3 R & R BOOTLID COMPONENT	1.00	120.00	0.00	120.00		Y	X nn
4 MOUNT WORK BENCH	1.00	250.00	0.00	250.00		Y	X nn
5 SPRAY PAINT ON ACCIDENT AREA	1.00	1,900.00	0.00	1,900.00		Y	1000 1100
6 APPLY MISTPROOFING/TUFF COAT	1.00	100.00	0.00	100.00		Y	40 12070
TOTAL:		4,430.00	0.00	4,430.00			
MATERIALS							
1 REAR BUMPER	1.00	190.00	19.00	209.00		Y	de
2 REAR BUMPER SIDE RETAINER LHS	1.00	25.00	2.50	27.50		Y	ner
3 REAR BUMPER SIDE RETAINER RHS	1.00	25.00	2.50	27.50		Y	ner
4 REAR BUMPER BEAM ARM LHS	1.00	55.00	5.50	60.50		Y	X nn
5 REAR BUMPER BEAM ARM RHS	1.00	55.00	5.50	60.50		Y	X nn
6 REAR BUMPER REINFORCEMENT	1.00	180.00	18.00	198.00		Y	ht
7 REAR BUMPER REFLECTOR LHS	1.00	45.00	4.50	49.50		Y	X nn
8 REAR BUMPER REFLECTOR RHS	1.00	45.00	4.50	49.50		Y	X nn
9 BOOTLID	1.00	350.00	35.00	385.00		Y	Rp
10 BOOTLID TOYOTA EMBLEM	1.00	30.00	0.00	30.00		Y	ner
11 BOOTLID COROLLA BADGE	1.00	28.00	0.00	28.00		Y	ner
12 BOOTLID ALTIS BADGE	1.00	28.00	0.00	28.00		Y	ne
13 BOOTLID HINGE	2.00	0.00	0.00	0.00		Y	Rp
14 BOOTLID INNER BOARD	1.00	0.00	0.00	0.00		Y	X
15 BOOTLID KEY LOCK	1.00	0.00	0.00	0.00		Y	X
16 BOOTLID CABLE	1.00	40.00	4.00	44.00		Y	X
17 BOOTLID OUTER CHROME GARNISH	1.00	140.00	14.00	154.00		Y	X
18 BOOTLID LICENCE PLATE LAMP	1.00	40.00	4.00	44.00		Y	X
19 TAILLAMP OUTER RHS	1.00	190.00	19.00	209.00		Y	X
20 TAILLAMP OUTER LHS	1.00	190.00	19.00	209.00		Y	X
21 TAILLAMP INNER RHS	1.00	180.00	18.00	198.00		Y	X
22 TAILLAMP INNER LHS	1.00	180.00	18.00	198.00		Y	X
23 REAR END PANEL	1.00	220.00	22.00	242.00		Y	ht
24 REAR END PANEL TOP GARNISH	1.00	140.00	14.00	154.00		Y	X
25 REAR END TOP GARNISH CLIP	30.00	54.00	5.40	59.40		Y	X nn
26 REAR SPARE TYRE COMPARTMENT	1.00	230.00	23.00	253.00		Y	Rp
27 REAR SPARE TYRE COMPARTMENT FLOOR BOARD	1.00	190.00	19.00	209.00		Y	X nn

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
23 REAR END PANEL BRACKET LHS	1.00	50.00	5.00	55.00		Y	X
29 REAR END PANEL BRACKET RHS	1.00	50.00	5.00	55.00		Y	X
30 REAR END PANEL WEATHERSTRIP	1.00	90.00	9.00	99.00		Y	X
31 REAR END PANEL INNER CENTER TRIM	1.00	140.00	14.00	154.00		Y	X
32 REAR FENDER RHS	1.00	550.00	55.00	605.00		Y	X
33 REAR BUMPER CLIP	1.00	45.00	0.00	45.00	S	Y	X
34 REAR REVERSE SENSOR	1.00	280.00	0.00	280.00	S	Y	X
35 REAR NUMBER PLATE	1.00	45.00	0.00	45.00	S	Y	X
36 REAR NUMBER PLATE CASING	1.00	30.00	0.00	30.00	S	Y	X
37 BOO TLID INNER BOARD CLIP	1.00	50.00	0.00	50.00	S	Y	X
TOTAL:		4,180.00	364.40	4,544.40			

TOTAL PARTS & LABOUR :

8,610.00 364.40 8,974.40

EXCESS/LOADING:\$\$ 0.00

No. Of Day: 6

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: 9 / 1 / 18

SURVEYED BY: Tanykh

CONTACT NO: 9245741

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

740 726
+18% - 90825 +18% 834.9

2700
3315
1704

50 2050
2 48250

Signature: 2/5/18
1-1/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Shiau Chan (LKKAuto)

From: JingFeng <jingfeng@dingauto.sg>
Sent: Friday, 9 February 2018 9:42 AM
To: SUR; Taufikh (LKKAuto)
Cc: kenneth.ding@dingauto.sg; ACCOUNTS@DINGAUTO.SG; 'Vivian'; Yvonne Wong
Subject: 85008033/SLK6392D - FINALIZE AMOUNT AND AFTER PAINT PHOTO
Attachments: DSC07200.JPG; DSC07195.JPG; DSC07196.JPG; DSC07197.JPG; DSC07198.JPG; DSC07199.JPG

HI ALL

Please see attach file for the finalize according to our conversion to finalize for SLK6392D

Total Repair - 06 Days

Labour - \$1970.00 ~~2020~~
Special Netts - \$246.00 245 331
Parts - \$726.00 ✓
Parts after +15% - \$834.90 ✓ 704
Total (Labour + S.N + Part) :\$3049.90 ~~3049.90~~ 3105

Final Amount After -20% : \$2439.92 2512.500

Thanks You And Please Help To Close The File

Best Regards
Ding Auto Pte Ltd
You Jing Feng
Hp : 9733 5832

This email has been checked for viruses by Avast antivirus software.
<https://www.avast.com/antivirus>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jan 2018		08 Jan 2018 09:44 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHUA POH SAN, ID: S0240810D, Tel: +6596333605, Email: NOEMAIL		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLK6392D	Date of Loss:	05/01/2018 11:00 - :59
Claim Type:	TP / 544415	Policy/Cover Note No.:	A27276146QMX (TP, Fire & Theft) Coverage: 17/03/2017 - 16/03/2018
Vehicle Reg. No. (Insured):	SFG6379K	Policy No. (Claimant):	
		Excess:	
Repairer:	Ding Auto Pte Ltd (corporation Road) (HQ) 31 Corporation Road, 649825 Boon Lay - Tel: 81316518		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 07/02/2018]		
Driver/Custodian (Insured):	CHUA POH SAN (67 / Male), NRIC: S0240810D, Tel: +6596333605		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLK6392D (544415)**
[SFG6379K]
TP
LCRF PTE LTD
Jan 5 2018 11:00AM
[CHUA POH SAN]
Ding Auto Pte Ltd (corporation Road)

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/01/18 09:35	Accident Statement From: SC - Reg. No: SFG6379K, Claimant: CHUA POH SAN	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/01/18 16:12	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/02/18 09:36	General View	Load JPG	☒
2	15/02/18 09:36	General View	Load JPG	☒
3	15/02/18 09:36	General View	Load JPG	☒
4	15/02/18 09:36	General View	Load JPG	☒
5	15/02/18 09:36	General View	Load JPG	☒
6	15/02/18 09:36	General View	Load JPG	☒
7	15/02/18 09:36	General View	Load JPG	☒
8	15/02/18 09:36	General View	Load JPG	☒
9	15/02/18 09:36	General View	Load JPG	☒
10	15/02/18 09:36	General View	Load JPG	☒
11	15/02/18 09:36	General View	Load JPG	☒
12	15/02/18 09:36	General View	Load JPG	☒
13	15/02/18 09:36	General View	Load JPG	☒
14	15/02/18 09:36	General View	Load JPG	☒
15	15/02/18 09:36	General View	Load JPG	☒
16	15/02/18 09:36	General View	Load JPG	☒
17	15/02/18 09:36	General View	Load JPG	☒
18	15/02/18 09:36	General View	Load JPG	☒
19	15/02/18 09:36	General View	Load JPG	☒
20	15/02/18 09:36	General View	Load JPG	☒
21	15/02/18 09:36	General View	Load JPG	☒
22	15/02/18 09:36	General View	Load JPG	☒
23	15/02/18 09:36	General View	Load JPG	☒
24	15/02/18 09:36	General View	Load JPG	☒
25	15/02/18 09:36	General View	Load JPG	☒
26	15/02/18 09:36	General View	Load JPG	☒
27	15/02/18 09:36	General View	Load JPG	☒
28	15/02/18 09:36	General View	Load JPG	☒

29	15/02/18 09:36	Odometer Reading		Load JPG	☒
30	15/02/18 09:36	Chassis Number		Load JPG	☒
31	15/02/18 09:36	General View		Load JPG	☒
32	15/02/18 09:36	General View		Load JPG	☒
33	15/02/18 09:36	General View		Load JPG	☒
34	15/02/18 09:36	General View		Load JPG	☒
35	15/02/18 09:36	General View		Load JPG	☒
36	15/02/18 09:36	General View		Load JPG	☒
37	15/02/18 09:36	Reinspection Photo		Load JPG	☒
38	15/02/18 09:36	Reinspection Photo		Load JPG	☒
39	15/02/18 09:36	Reinspection Photo		Load JPG	☒
Documentation				1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	08/01/18 09:48	SLK6392D E-FILE REPORT		Load PDF	
2	08/01/18 09:48	PRI FROM DING AUTO		Load PDF	
3	08/01/18 09:48	Survey Agree on SJE - LKK		Load PDF	
4	23/02/18 09:15	Loss of Income		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000425/T1QD3E2
Date: 13/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A27276146QMX
Claimant Vehicle No :	SLK6392D	Insured Vehicle No :	SFG6379K
Date of Loss:	05/01/2018	Nature of Claim:	TP
		Claim No:	544415

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK6392D	Engine No:	1ZRY348280
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Chassis No:	MR053REH104562990
Reg. Date:	23/01/2017 (Man. Year: 2016)	Odometer:	82505 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,544.40	1,035.00	3,509.40	77.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	2,070.00	2,360.00	53.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,974.40	3,105.00	5,869.40	65.40
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	8,974.40	2,500.00	6,474.40	72.14
+ GST 7.00/7.00% (S\$)	628.21	175.00	453.21	72.14
Nett Amount (S\$)	9,602.61	2,675.00	6,927.61	72.14

INSPECTION

Date of Assignment:	08/01/2018	
Date Inspected:	09/01/2018	Inspected At: Ding Auto Pte Ltd (corporation Road) (HQ) 31 Corporation Road Singapore 649825
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Mar 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLK6392D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	190.00 F	*190.00 F
2	1		*REAR BUMPER SIDE RETAINER LHS	Necessary	25.00 F	*25.00 F
3	1		*REAR BUMPER SIDE RETAINER RHS	Necessary	25.00 F	*25.00 F
4	1		*REAR BUMPER BEAM ARM LHS	Not Necessary	55.00 F	*- F
5	1		*REAR BUMPER BEAM ARM RHS	Not Necessary	55.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	Bent	180.00 F	*180.00 F
7	1		*REAR BUMPER REFLECTOR LHS	Not Necessary	45.00 F	*- F
8	1		*REAR BUMPER REFLECTOR RHS	Not Necessary	45.00 F	*- F
9	1		*BOOTLID	Repair	350.00 F	*- F
10	1		*BOOTLID TOYOTA EMBLEM	Necessary	30.00 FS	*30.00 FS
11	1		*BOOTLID COROLLA BADGE	Necessary	28.00 FS	*28.00 FS
12	1		*BOOTLID ALTIS BADGE	Necessary	28.00 FS	*28.00 FS
13	2		*BOOTLID HINGE (NPA)	Repair	0.00 F	*- F
14	1		*BOOTLID INNER BOARD (NPA)	Not Necessary	0.00 F	*- F
15	1		*BOOTLID KEY LOCK (NPA)	Not Necessary	0.00 F	*- F
16	1		*BOOTLID CABLE	Not Necessary	40.00 F	*- F
17	1		*BOOTLID OUTER CHROME GARNISH	Not Necessary	140.00 F	*- F
18	1		*BOOTLID LICENCE PLATE LAMP	Not Necessary	40.00 F	*- F
19	1		*TAILLAMP OUTER RHS	Not Necessary	190.00 F	*- F
20	1		*TAILLAMP OUTER LHS	Not Necessary	190.00 F	*- F
21	1		*TAILLAMP INNER RHS	Not Necessary	180.00 F	*- F
22	1		*TAILLAMP INNER LHS	Not Necessary	180.00 F	*- F
23	1		*REAR END PANEL	Bent	220.00 F	*220.00 F
24	1		*REAR END PANEL TOP GARNISH	Not Necessary	140.00 F	*- F
25	1		*REAR END TOP GARNISH CLIP (30 PCS)	Not Necessary	54.00 F	*- F
26	1		*REAR SPARE TYRE COMPARTMENT	Repair	230.00 F	*- F
27	1		*REAR SPARE TYRE COMPARTMENT FLOOR BOARD	Not Necessary	190.00 F	*- F
28	1		*REAR END PANEL BRACKET LHS	Not Necessary	50.00 F	*- F
29	1		*REAR END PANEL BRACKET RHS	Not Necessary	50.00 F	*- F
30	1		*REAR END PANEL WEATHERSTRIP	Not Necessary	90.00 F	*- F
31	1		*REAR END PANEL INNER CENTER TRIM	Not Necessary	140.00 F	*- F
32	1		*REAR FENDER RHS	Repair	550.00 F	*- F
33	1		*REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
34	1		*REAR REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
35	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
36	1		*REAR NUMBER PLATE CASING	Not Necessary	30.00 FS	*- FS
37	1		*BOOTLID INNER BOARD CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,180.00	971.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	364.40	64.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					4,544.40	1,035.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT AND STRAIGHTEN CHASSIS	New	2,000.00	900.00
2	CHECK WIRING	New	60.00	30.00
3	R&R BOOTLID COMPONENT	New	120.00	0.00
4	MOUNT WORK BENCH	New	250.00	0.00
5	SPRAY PAINT ON ACCIDENT AREA	New	1,900.00	1,100.00
6	APPLY MISTPROOFING / TUFF COAT	New	100.00	40.00
Gross Labour Cost (\$\$)			4,430.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >