

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : EQ INSURANCE COMPANY LIMITED
 5 MAXWELL ROAD, #17-00
 TOWER BLOCK MND COMPLEX
 SINGAPORE 069110
 TEL: 62239433 FAX: 62243903
 ATTN: Motor Claim Department

Claim No: EST1503134
Estimate No: EST1503134
Date: 02 Jan 2018
Policy No: VPA/P1470992
Veh Reg No: SKM2959Y
Make/Model: VOLKSWAGEN
 PASSAT 1.8 TSI AT
 3624H7 HID
Chassis No: WVWZZZ3CZEE044849
Engine No: CDA426296
Reg. Date: 17/02/2014

Your Ref No: TP 0118-4892
Claim Type: Third Party
Accident Date: 01/01/2018
TP Veh Reg No: GW5801T

Vic.

Estimate Repair Cost to Vehicle No : SKM2959Y

Description	U/Price	Quantity	Cost SS	Amount SS
Special Net				
1 FRONT NUMBER PLATE WITH CASING <i>ct</i>	35	1 SET	35.00	35.00
Spare Parts				
2 GRILLE ASSY	320.00	1 PC	320.00 <i>+</i>	
3 GRILLE LOGO	50.00	1 PC	50.00 <i>+</i>	
4 HEAD LAMP ASSY - LH	1,150.00	1 PC	1,150.00 <i>+</i>	
5 HEAD LAMP ASSY - RH	1,150.00	1 PC	1,150.00 <i>+</i>	
6 FRONT NUMBER PLATE GARNISH	75.00	1 PC	75.00	
7 FRONT BUMPER	860.00	1 PC	860.00 <i>800</i>	
8 FRONT BUMPER CLIPS	1.50	10 PC	15.00	
9 FRONT BUMPER SIDE HOLDER - LH	18.00	1 PC	18.00 <i>+</i>	
10 FRONT BUMPER SIDE HOLDER - RH	18.00	1 PC	18.00 <i>+</i>	
11 FRONT BUMPER TOWING COVER - RH	28.00	1 PC	28.00 <i>+</i>	
12 FRONT BUMPER REINFORCEMENT	385.00	1 PC	385.00 <i>+</i>	
13 FRONT BUMPER CENTRE LOWER GRILLE	300.00	1 PC	300.00 <i>+</i>	
14 FRONT BUMPER LOWER GRILLE CHROME - CENTRE	75.00	1 PC	75.00 <i>+</i>	
15 FRONT BUMPER LOWER GRILLE CHROME - LH	120.00	1 PC	120.00 <i>+</i>	
16 FRONT BUMPER LOWER GRILLE CHROME - RH	120.00	1 PC	120.00 <i>+</i>	
17 FRONT BUMPER SENSOR	95.00	4 PC	380.00 <i>+</i>	
			5,064.00	
	Add 20%		1,012.80	6,076.80
Labour				
18 TO KNOCK OUT DENTS, FRONT BOTH FENDER, REMOVE, REPLACE ACCIDENT PARTS	700.00	1 JOB	700.00 <i>200</i>	
19 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.00	1 JOB	800.00 <i>200</i>	
20 TO CHECK WIRING	20.00	1 JOB	20.00	
21 TO REMOVE, REPLACE FRONT BUMPER SENSOR	100.00	1 JOB	100.00 <i>60</i>	
22 TO RESET CHECK LIGHT	100.00	1 JOB	100.00 <i>x</i>	
				1,720.00

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD, #17-00
TOWER BLOCK MND COMPLEX
SINGAPORE 069110

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

Your Ref No: TP 0118-4892
Claim Type: Third Party
Accident Date: 01/01/2018
TP Veh Reg No: GW5801T

Claim No: EST1503134

Estimate No: EST1503134

Date: 02 Jan 2018

Policy No: VPA/P1470992

Veh Reg No: **SKM2959Y**

Make/Model: VOLKSWAGEN
PASSAT 1.8 TSI AT
3624H7 HID

Chassis No: WVWZZZ3CZEE044849

Engine No: CDA426296

Reg. Date: 17/02/2014

Estimate Repair Cost to Vehicle No : SKM2959Y

Total	S\$ 7,831.80
Add GST @ 7%	548.23
Total Amount payable	S\$ 8,380.03

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND THREE HUNDRED EIGHTY AND CENTS THREE ONLY

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

Adrian Lj
P/P 08/01/18.
03 days

total: 1583 (P/P)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: