

INS. CASE OWNER: Justin

CC 4/EQ1800 0429, A p394

LKK

IDAC

Surveyor: WWP

DOI: 08/01/18

Date / Time: 8/1/18

Registered in Merimen: -

Pre-assign / CCU / FTE



Insured Vehicle No. GBE 5882F

Name of Insured: FAIVASAM S/O PERIYAN MASARAN

Insured Tel No. HP: -

Excess Sec II : \$5

Is driver the owner? (YES / NO)

Nature of Accident: -

If NO. Driver Name / Age: MUNESESHWARAN S/O KAVASAM

Driver Tel No.:

(V/L: YES / NO)

Claim No. : DM18H000085

Policy No. : DMCP11AA-000289

Make / Model : MASAN

Place of Accident : BRADEN FLYOVER

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

GSD 6866J

GBE 5882F

YP 6798T

GSD 4877R



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS: 01



INSRS:

WSP:

Tel:

Liability:

RMKS: TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

11/1/18

WWT

18/1/18

6veh cc. 5
- Old was 5th vehicle.
- Sent letter to OI.

26/1/18

- PA ✓

26/1/18

- File pass to type mandate.

7/9/18

- DV sent

10/9/18

- File pass to SHU Per to close.

RECEIVED 11 SEP 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List:

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Min/late/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

26/1/18

Sent By:

CH

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

2/9/18

Confirm with:

CH

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

2815cc. 010444

If NO or B 28, Ass. Lia:

0%.

Repair Cost:

\$5

26000.00

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

2880.00

(S

x 24 days)

Loss of Income (LOI):

\$5

(S

x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

Legal Cost:

\$5

(e.g. Tow/ Independent)

Total:

\$5

28880.00

Global Sum \$5:

FINAL PAYMENT

Date/Time:

2/9/18

Confirm with:

CH

Email

Call

Payee 1:

\$5

28880.00

Name 1:

F-1 Autoclinic Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400

* Rental Receipt TP Company Name & TP Name Invoice

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OO RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / FR Seen: _____ Consistent?: Yes or No

Est. Repairs: 24 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YP578T Yr Regn: 2017 MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit ~~Eco~~ Center cc 2998Colour: White A/C: Insured / Std / NI / NASp. Reading: 23093 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEB21EA21215Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: NI / S/Rim / STD A/Rim orTyre Size: F: 195/83R15R: 195/85R15BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. _____ D.O.L: 08/01/18Survey held at: FI Auto ClinicDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP EQ.

US \$ 2600 (Reel \$ 32410.30/59%)MV: 96K
PV: 34.5K
Nett: 61.5K

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photo: _____

Other: _____

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format: _____

Lump Sum / I.B.I: (\$

TOTAL

61382



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|---------------------------|------------|---|
| EQ INSURANCE COMPANY LTD | | Ref : CC4/EQ118000429/Ab3 | | |
| 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110 | | Date : 08-01-2018 | |  |
| | | Code : EQI | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | GBE 5883K | Veh. Inspected | YP 5798T | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 08/01/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 05/01/2018 | Inspection Date | 08/01/2018 | |
| Survey held at | F-1 AUTOCLINIC PTE LTD 25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @ KB SINGAPORE 417800 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800
 HP: 96583371 TEL: (65) 67022915 FAX: 67022916

N GENERATION
 BLOCK 25 KAKI BUKIT ROAD 4
 # 08-26 SYNERGY @KB
 Singapore 417800

10th January 2018

TP EQ

Xiao Tong

Accident date: 05th JANUARY 2018
 Estimated repair cost for vehicle no: YP5798T

| S/n | Qty | Items | U/price | Amount |
|-----|-----|--|----------|------------|
| 1 | 2 | Front Head Lamp <i>Smashed</i> | \$672.70 | \$1,345.40 |
| 2 | 1 | Front windscreen glass <i>Shattered</i> | | \$955.10 |
| 3 | 1 | Front windscreen glass moulding <i>new</i> | | \$500.90 |
| 4 | 2 | Front signal lamp <i>3 could</i> | \$266.40 | \$532.80 |
| 5 | 2 | Front side lamp | \$185.40 | \$370.80 |
| 6 | 1 | Front Grille <i>Smashed</i> | | \$1,043.00 |
| 7 | 1 | Front Grille Clips <i>new</i> | | \$15.00 |
| 8 | 1 | Front Grille Emblem Logo <i>new</i> | | \$77.00 |
| 9 | 1 | Front fuso Logo <i>new</i> | | \$163.00 |
| 10 | 1 | Front Bumper <i>Distorted</i> | | \$1,010.30 |
| 11 | 2 | Front Bumper Bracket <i>Best</i> | \$196.20 | \$392.40 |
| 12 | 2 | Front corner panel <i>LH Delnd</i> | \$466.30 | \$932.60 |
| 13 | 1 | front bumper side cover <i>Cracked</i> | | \$341.70 |
| 14 | 1 | brake booster pump <i>Not in</i> | | \$1,329.00 |
| 15 | 1 | glove box <i>Not in</i> | | \$355.60 |
| 16 | 1 | front panel <i>Distorted</i> | | \$2,436.50 |
| 17 | 1 | Front dashboard <i>Delnd</i> | | \$1,586.30 |
| 18 | 1 | dashboard reinforcement <i>Best</i> | | \$489.10 |
| 19 | 1 | dashboard centre console <i>Delnd</i> | | \$459.40 |
| 20 | 1 | dashboard lower cover <i>Delnd</i> | | \$388.40 |
| 21 | 1 | front wiper garnish <i>Delnd</i> | | \$382.70 |
| 22 | 1 | front wiper garnish clips <i>new</i> | | \$20.00 |
| 23 | 2 | front wiper arm <i>Best</i> | \$137.40 | \$274.80 |
| 24 | 2 | Front wiper blade <i>at</i> | \$42.20 | \$84.40 |
| 25 | 1 | front wiper motor <i>Not in</i> | | \$655.50 |
| 26 | 1 | front wiper linkage <i>Best</i> | | \$249.40 |

Sheet1

| | | | | | |
|----|---|--|------------|------------|---|
| 27 | 1 | FRONT Door INNER TRIM Board clips | | \$60.00 | ✓ |
| 28 | 2 | Front Door <i>Replaced</i> | \$2,001.50 | \$4,003.00 | ✓ |
| 29 | 2 | Front Door lock <i>Replaced</i> | \$485.00 | \$970.00 | ✓ |
| 30 | 2 | Front Door weatherstrip <i>Replaced</i> | \$295.00 | \$590.00 | ✓ |
| 31 | 2 | Front Door Inner Trim Board <i>Replaced</i> | \$498.40 | \$996.80 | ✓ |
| 32 | 1 | torsion bar <i>Best</i> | | \$566.20 | ✓ |
| 33 | 2 | front wing mirror stay <i>Replaced</i> | \$433.00 | \$866.00 | ✓ |
| 34 | 1 | rear view mirror <i>Replaced</i> | | \$142.90 | ✓ |
| 35 | 1 | ABS pump <i>Replaced</i> | | \$4,585.40 | ✓ |
| 36 | 1 | air filter duct <i>Replaced</i> | | \$398.40 | ✓ |
| 37 | 3 | brake pipe <i>Replaced</i> | \$65.10 | \$195.30 | ✓ |
| 38 | 1 | turbo oil cooler <i>Replaced</i> | | \$1,498.90 | ✓ |
| 39 | 1 | front cabin lock frame <i>Replaced</i> | | \$823.40 | ✓ |
| 40 | 1 | front cabin lock hinge <i>Best</i> | | \$296.90 | ✓ |
| 41 | 2 | front mud flap <i>Replaced</i> | \$261.00 | \$522.00 | ✓ |
| 42 | 1 | cabin rear panel <i>Replaced</i> | | \$1,465.50 | ✓ |
| 43 | 1 | radiator <i>Replaced</i> | | \$2,616.10 | ✓ |
| 44 | 1 | radiator spare tank <i>Replaced</i> | \$0.00 | \$0.00 | ✓ |
| 45 | 1 | radiator fan blade <i>Replaced</i> | | \$225.50 | ✓ |
| 46 | 1 | radiator fan cowling <i>Replaced</i> | | \$346.30 | ✓ |
| 47 | 1 | radiator fan clutch <i>Replaced</i> | | \$1,461.70 | ✓ |
| 48 | 1 | air cond condenser <i>Replaced</i> | | \$1,200.50 | ✓ |
| 49 | 1 | air cond fan assy <i>Replaced</i> | | \$1,466.20 | ✓ |
| 50 | 1 | air cond discharge pipe <i>Best</i> | | \$454.20 | ✓ |
| 51 | 1 | air cond section pipe <i>Best</i> | | \$484.10 | ✓ |
| 52 | 1 | air cond liquid pipe <i>Best</i> | | \$345.60 | ✓ |
| 53 | 1 | air cond blower <i>Replaced</i> | | \$1,431.30 | ✓ |
| 54 | 1 | air cond evaporator <i>Replaced</i> | | \$1,261.50 | ✓ |
| 55 | 1 | rear windscreen glass moulding <i>Replaced</i> | | \$118.40 | ✓ |
| 56 | 1 | rear number Plate bracket <i>Best</i> | | \$74.90 | ✓ |

3107620

2330745

Subtotal :- \$45,858.10

| S/n | Qty | Items/S Nett | U/price | Amount | |
|-----|-----|---|------------|------------|-----|
| 1 | 1 | front number plate <i>Best</i> | | \$30.00 | ✓ |
| 2 | 1 | front windscreen sealant <i>Replaced</i> | | \$60.00 | ✓ |
| 3 | 1 | ERP bracket <i>Replaced</i> | | \$20.00 | ✓ |
| 4 | 1 | Rear Number Plate <i>Best</i> | | \$30.00 | ✓ |
| 5 | 1 | rear windscreen glass sealant <i>Replaced</i> | | \$60.00 | ✓ |
| 6 | 1 | rear wooden step plank <i>Replaced</i> | | \$500.00 | 380 |
| 7 | 2 | rear wooden chassis frame <i>LH Replaced</i> | \$1,280.00 | \$2,560.00 | 980 |
| 8 | 1 | tail gate <i>Replaced</i> | | \$1,850.00 | 480 |

Sheet1

| | | | | |
|----|---|---|----------|---------------------|
| 9 | 2 | tail gate lower wooden plank <i>new</i> | \$850.00 | \$1,700.00 <i>X</i> |
| 10 | 1 | 60km logo <i>new</i> | | \$15.00 <i>X</i> |
| 11 | 2 | Tail lamp <i>new</i> | \$243.60 | \$487.20 <i>X</i> |

2940

Subtotal :- \$7,312.20

Labour charges

| | |
|--|------------------------|
| to remove & install front windscreen | \$180.00 <i>120</i> |
| to remove & install rear windscreen | \$180.00 <i>100</i> |
| to Remove & install dashboard | \$380.00 <i>280</i> |
| remove & Refix front LH & RH door fitting | \$300.00 <i>200</i> |
| to remove & install rear <i>deck</i> wooden canopy | \$500.00 <i>350</i> |
| to remove & Refix steering column | \$280.00 <i>180</i> |
| To remove & refix radiator | \$180.00 <i>120</i> |
| To remove & refix brake system | \$280.00 <i>180</i> |
| to tow vehicle | \$150.00 <i>✓</i> |
| to remove & install rear wooden deck | \$1,000.00 <i>800</i> |
| to underseal | \$250.00 <i>120</i> |
| to remove & install air con system & top up gas | \$380.00 <i>120</i> |
| To Check Wiring System | \$180.00 <i>150</i> |
| Panel beating | \$3,500.00 <i>2000</i> |
| Spray painting | \$2,500.00 <i>1800</i> |

6670

total 32517.15
L/S: 261K.
24 Days

Subtotal :- \$10,240.00

Total:- \$63,410.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|--------------------------------|-------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 6438Z |
| Vehicle Details | |
| Vehicle No.: | YP5798T |
| Vehicle to be Exported: | Yes |
| Intended De-registration Date: | 08 Jan 2018 |
| Vehicle Make: | MITSUBISHI |
| Vehicle Model: | CANTER FEB21ER4SDEB |
| Primary Colour: | White |
| Manufacturing Year: | 2016 |
| Engine No.: | 4P10C42765 |
| Chassis No.: | FEB21EA21215 |
| Maximum Power Output: | - |
| Open Market Value: | \$34,937.00 |
| Original Registration Date: | 13 Mar 2017 |
| First Registration Date: | 13 Mar 2017 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$1,747.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 12 Mar 2027 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| PQP Paid: | \$43,174.00 |
| COE Rebate Amount: | \$34,539.00 |
| Total Rebate Amount: | \$34,539.00 |

The information contained herein is correct as at 08 Jan 2018

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips

- Unusual or rare cars
- Harrier 2017
- Mitsubishi Attrage

Post an Advertisement
Sell it yourself. Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2008 Hyundai Avante 1.6A Sunroof At \$33888



Charged In The Past To
Exceed For 5 Years Low Mileage
C/L 100K km
Direct Owner

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997

[VIEW OUR SITES](#)

Browse by Category

Sort by Date Posted

20 results/page

15 vehicles

Canter

Advanced Search

| Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|--|--|------------------|---------------------|--------------------|-----------------|-----------------|--|
| Search Selection | Canter | Any | Any | 2017 | Any | Any | Available |
|  | Mitsubishi Fuso Canter FEB21 Fuel Type: Diesel Free 12 Times Servicing, Warranty 3 Years / 100k Km, Free Logo, Free Accessory, High Loan Available, Low Interest Rate, Call Now To Book. ABWIN Bus Pte Ltd Posted: 08-Jan-2018 Tags: 2017 Mitsubishi Fuso, 2017 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi | \$97,900 | \$10,700 /yr | 03-Mar-2017 | 2,998 cc | - | Truck Available View More Details |
|  | Mitsubishi Fuso Canter FEB21 Fuel Type: Diesel Hot Selling! Warranty And Free Servicing By Agent, Free Road Tax, High Loan With Low Interest Rate, High Trade-In, Call Fast To Book Appointment And Check Location Before Drop By. ABWIN Bus Pte Ltd Posted: 28-Dec-2017 Tags: 2017 Mitsubishi Fuso, 2017 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi | \$97,900 | \$10,670 /yr | 13-Mar-2017 | 2,998 cc | - | Truck Available View More Details |
|  | Mitsubishi Fuso Canter FEB21 Fuel Type: Diesel Newly Registered Mitsubishi FEB21 (CBU) 14 Feet Euro 5 Truck. 12 x Free Servicing. 3 Years Warranty Or 100,000km Whichever Comes First. Posted: 27-Dec-2017 Tags: 2017 Mitsubishi Fuso, 2017 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi | \$96,800 | \$10,480 /yr | 03-Apr-2017 | 2,998 cc | 18 km | Truck Available View More Details |
|  | Mitsubishi Fuso Canter FEB21 Fuel Type: Diesel Almost Brand New Unit. Take Ready Stock. 100% Loan. Bank Or In-House. Class 3. Prime Motor & Leasing Posted: 05-Jan-2018 Tags: 2017 Mitsubishi Fuso, 2017 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi | \$77,500 | \$8,390 /yr | 05-Apr-2017 | 2,998 cc | 3,500 km | Truck Available Details |
| <div><div>Car Buying</div><div>Car Ownership</div></div> <div><div>Car Selling</div><div>On The Move</div></div> <div><div>Car Aftermarket</div><div>Lifestyle</div></div> <div><div>Buying a pre-owned car, but unsure of its condition?</div><div>Get STA Car Evaluation</div></div> | | | | | | | |
|  | Mitsubishi Fuso Canter FEB50 Fuel Type: Diesel Almost Brand New Unit. Take This Opportunity To Own This Brand New Workhorse When The CDE Is Low. Ready Stock. 100% Loan. Bank Or In-House. Immediate Approval. No Income Or Bank Statement Required. No... Posted: 11-Dec-2017 Tags: 2017 Mitsubishi Fuso, 2017 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi | \$86,899 | \$9,400 /yr | 05-Apr-2017 | 2,998 cc | - | Truck Available View More Details |
|  | Mitsubishi Fuso Canter FEB21 Fuel Type: Diesel High Loan Is Possible. High Trade In For Your Old Vehicle. Insurance Quotation We Can Do For You. Hurry While Stock Last. Call Our Sales Executive Now! KSL Automotive Pte Ltd Posted: 08-Jan-2018 Tags: 2017 Mitsubishi Fuso, 2017 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi, Fuso, Fuso, Used Mitsubishi | \$102,800 | \$11,120 /yr | 06-Apr-2017 | 2,998 cc | - | Truck Available Details |
| | Mitsubishi Fuso Canter FEB21 Fuel Type: Diesel Almost New Mitsubishi Canter FEB21, High Loan And Hand Over Faster. Call Us Now! | \$103,988 | \$11,230 /yr | 13-Apr-2017 | 2,998 cc | - | Truck Available View More Details |

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 26 July 2018 8:12 AM
To: 'justin.wong@eqinsurance.com.sg'
Cc: Admin A
Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3
Attachments: TP ESTIMATE_MARKED.pdf; Preliminary Advice-YP 5798T.pdf; PARF_COE REBATE.pdf; LKK Survey Photos.pdf

Your Ref: **TBA**
LKK REF: CC4/EQI18000429/Apb3

Dear Sirs/Madam,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 8 January, 2018 1:57 PM
To: 'Bazlin Ahmad' <bazlin.ahmad@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: YP5798T & GBE5883K DOA 05.01.2018

Dear Bazlin Ahmad,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]
Sent: Monday, 8 January 2018 1:33 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: YP5798T & GBE5883K DOA 05.01.2018

Dear LKK

We refer to the abovementioned new assignment, please find attached our insured GIA report.

Thank You.

Regards,

Lynn Ahmad
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road, #17-00 Tower Block MND Complex Singapore 069110
did not 6496 5881 | tel 65 6223 9433 ext 381 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]
Sent: Monday, January 8, 2018 1:15 PM
To: louis.sim@eqinsurance.com.sg
Cc: Bazlin Ahmad
Subject: Fw: YP5798T & GBE5883K DOA 05.01.2018

Dear Sir / Mdm ,

Enclosed is our police report & accident scene photos.

Please advise OIC & claim no .

If your insured agree liability 100% for our favour , we will arrange your panel survey LKK AUTO CONSULTANT PTE LTD for direct settlement .

Please let us have your reply soon . Thanks

Regards,
Chris Chan Pick Yuen
F-1 AUTOCLINIC PTE LTD
Block 25 Kaki Bukit Road 4
05-26 @ Synergy
Singapore 417800
Fax: 6702 2916
HP: 92712214



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/EQI18000429/Apb3

Date: 26.07.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD
Attn : Justin

Dear Sirs,

PRELIMINARY ADVICE OF VEHICLE NO.

YP 5798T

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08/01/2018 at the premises of M/s F-1 AUTOCLINIC PTE LTD and have the following to report:-

| | | | |
|--------------------------|-------|-----------|-------|
| Workshop Estimate Amount | : S\$ | 63,410.30 | |
| Revised Estimate Amount | : S\$ | 26,000.00 | |
| "Check" Items Amount | : S\$ | | |
| Market Value | : S\$ | 96,000.00 | (est) |
| LTA Reimbursement Value | : S\$ | 34,539.00 | (est) |
| Nett Value | : S\$ | 61,461.00 | (est) |

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 24.0 days

Yours faithfully,

Adrian Ling
Licensed Appraiser

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 30 August 2018 12:18 PM
To: 'justin.wong@eqinsurance.com.sg'
Cc: Admin A
Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3
Attachments: LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey Photos 1.pdf; LKK Resurvey Photos 2.pdf; LKK Resurvey Photos 3.pdf; LKK Resurvey Photos 4.pdf; TP SUPP DOCS.pdf

Your ref : **TBA**
Our ref : CC4/EQI18000429/Apb3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING GBE5883K(OI)/ YP5798T(TP) /OTHERS ON 05/01/2018

We refer to the above matter.

The said chain collision involved 6 vehicles whereby our insured was the 5th vehicle.
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "F-1 AUTOCLINIC PTE LTD" at \$29,600.00(all-in).

The summary is as follows: -

| | Amount Claimed | Amount Revised |
|---------------------------------------|----------------|--------------------------------|
| 1. Cost of Repair | \$ 63,410.30 | \$ 26,000.00 |
| 2. Loss of Rental (24days x \$250.00) | \$ 6,000.00 | \$ 3,600.00 (24days x \$15.00) |
| Total | \$ 69,410.30 | <u>\$ 29,600.00</u> |

***24days recommendation for repair.

| | |
|--------------------------|-----------------------------|
| Market Value | : \$ 96,000.00 (est) |
| LTA Rebate | : \$ 34,539.00 (est) |
| Nett Value/ Repair Limit | : <u>\$ 61,461.00 (est)</u> |

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Justin Wong <justin.wong@eqinsurance.com.sg>
Sent: Friday, 31 August 2018 8:57 AM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Dear Hsiao Tong,

Please proceed to offer Third Party repairer "F-1 AUTOCLINIC PTE LTD" at \$29,600.00(all-in).

Thank you.

Regards,
Justin Wong
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Thursday, August 30, 2018 12:18 PM
To: Justin Wong <justin.wong@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Your ref : **TBA**
Our ref : CC4/EQI18000429/Apb3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING GBE5883K(OI)/ YP5798T(TP) /OTHERS ON 05/01/2018

We refer to the above matter.

The said chain collision involved 6 vehicles whereby our insured was the 5th vehicle.
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "F-1 AUTOCLINIC PTE LTD" at \$29,600.00(all-in).

The summary is as follows: -

| | Amount Claimed | Amount Revised |
|---------------------------------------|----------------|--------------------------------|
| 1. Cost of Repair | \$ 63,410.30 | \$ 26,000.00 |
| 2. Loss of Rental (24days x \$250.00) | \$ 6,000.00 | \$ 3,600.00 (24days x \$15.00) |
| Total | \$ 69,410.30 | \$ 29,600.00 |

***24days recommendation for repair.

| | |
|--------------------------|-----------------------------|
| Market Value | : \$ 96,000.00 (est) |
| LTA Rebate | : \$ 34,539.00 (est) |
| Nett Value/ Repair Limit | : \$ 61,461.00 (est) |

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Thursday, 26 July 2018 8:12 AM

To: 'Justin.wong@eqinsurance.com.sg' <justin.wong@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Your Ref: **TBA**

LKK REF: CC4/EQI18000429/Apb3

Dear Sirs/Madam,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 8 January, 2018 1:57 PM

To: 'Bazlin Ahmad' <bazlin.ahmad@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: YP5798T & GBE5883K DOA 05.01.2018

Dear Bazlin Ahmad,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]

Sent: Monday, 8 January 2018 1:33 PM

To: Admin A <admin-a@lkkauto.com>

Subject: FW: YP5798T & GBE5883K DOA 05.01.2018

Dear LKK

We refer to the abovementioned new assignment, please find attached our insured GIA report.

Thank You.

Regards,

Lynn Ahmad

Executive | Claims

eqinsurance

EQ Insurance Company Limited

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]
Sent: Monday, January 8, 2018 1:15 PM
To: louis.sim@eqinsurance.com.sg
Cc: Bazlin Ahmad
Subject: Fw: YP5798T & GBE5883K DOA 05.01.2018

 Dear Sir / Mdm ,

Enclosed is our police report & accident scene photos.

Please advise OIC & claim no .

If your insured agree liability 100% for our favour , we will arrange your panel survey LKK AUTO
CONSLUTANT PTE LTD for direct settlement .

Please let us have your reply soon . Thanks

 Regards,
Chris Chan Pick Yuen
F-1 AUTOCLINIC PTE LTD
Block 25 Kaki Bukit Road 4
05-26 @ Synergy
Singapore 417800
Fax:6702 2916
HP: 92712214

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 3 September 2018 2:22 PM
To: 'chan pick yuen'
Subject: RE: YP5798T after paint *** LKK REF: CC4/EQ118000429/Apb3

Without Prejudice

Hi Chris,

We refer to your below email.

We have our principal instruction to offer as follows: -

| | |
|------------------------------------|----------------------------|
| 1. Cost of Repair | \$ 26,000.00 |
| 2. Loss of Use (24days x \$120.00) | \$ 2,880.00 |
| TOTAL | <u>\$ 28,880.00</u> |

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Monday, 27 August 2018 10:31 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: YP5798T after paint *** LKK REF: CC4/EQ118000429/Apb3

Dear Hsiao Tong ,

Final Reminder

Hsiao Tong (LKKAUTO)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Wednesday, 5 September 2018 1:01 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: YP5798T after paint *** LKK REF: CC4/EQI18000429/Apb3

Dear Hsiao Tong ,

Accept offer . DV please

Regards,
Chris Chan Pick Yuen

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Monday, September 3, 2018 2:22 PM
To: chan pick yuen
Subject: RE: YP5798T after paint *** LKK REF: CC4/EQI18000429/Apb3

Without Prejudice

Hi Chris,

We refer to your below email.

We have our principal instruction to offer as follows: -

| | |
|------------------------------------|----------------------------|
| 1. Cost of Repair | \$ 26,000.00 |
| 2. Loss of Use (24days x \$120.00) | \$ 2,880.00 |
| TOTAL | <u>\$ 28,880.00</u> |

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Monday, 27 August 2018 10:31 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: YP5798T after paint *** LKK REF: CC4/EQI18000429/Apb3

Dear Hsiao Tong ,

Final Reminder

Please let u shave your offer in next 7 days . Thanks

Regards,
Chris Chan Pick Yuen
F1 AUTOCLINIC PTE LTD
+6567479241
Fax : +6567417276

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Saturday, August 18, 2018 10:52 AM
To: chan pick yuen
Cc: Admin A; Reports (LKKAuto)
Subject: RE: YP5798T after paint *** LKK REF: CC4/EQI18000429/Apb3

Without Prejudice

Hi Chris,

We are preparing report in order to seek mandate from EQ.

Kindly bear with us for time being.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Thursday, 16 August 2018 9:41 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: YP5798T after paint *** LKK REF: CC4/EQI18000429/Apb3

Dear Hsiao Tong ,

2ND REMINDER

Please let us have your offer soon . Thanks

Regards,

Chris Chan Pick Yuen

From: chan pick yuen <chris_chanbebe@hotmail.com>

Sent: Tuesday, July 31, 2018 10:23 PM

To: chewht@lkkauto.com

Subject: Fw: YP5798T after paint *** LKK REF: CC4/EQI18000429/Apb3

Dear Hsiao Tong ,

1t Reminder

Chain collision case , liability is 100% .

Please let us have your offer soon . Thanks

Regards,

Chris Chan Pick Yuen

From: chan pick yuen <chris_chanbebe@hotmail.com>

Sent: Thursday, July 19, 2018 8:46 PM

To: chewht@lkkauto.com

Subject: Re: YP5798T after paint *** LKK REF: CC4/EQI18000429/Apb3

Dear Hsiao Tong ,

Enclosed is our GIA report , invoice , Rental & LOA .

Original document will send via post by today .

As request following :

1. RC \$26000 (AS AGREED)
2. LOR \$6000 (\$ 250 X 24DAYS)

Total \$ 32000/-.

Please let us have your offer soon . Thanks

Regards,
Chris Chan Pick Yuen
F1 AUTOCLINIC PTE LTD
+6567479241
Fax : +6567417276

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, February 5, 2018 10:58 AM
To: chan pick yuen; Adrian Ling (LKKAuto); Hsiao Tong (LKKAuto)
Cc: Admin A; Zaini (LKK Auto)
Subject: RE: YP5798T after paint *** LKK REF: CC4/EQI18000429/Apb3

Dear Chris,

Thank you for your email. Please note that your client's vehicle number should be read as YP5798T.

For your info.

| LKK ref | Officer in charge |
|----------------------|------------------------|
| CC4/EQI18000429/Apb3 | Hsiao Tong - 6742 3197 |

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]
Sent: Sunday, 4 February, 2018 11:02 PM
To: Admin A <admin-a@lkkauto.com>
Subject: YP5798P after paint

Regards,
Chris Chan Pick Yuen
hp: 92712214

Hsiao Tong (LKKAUTO)

From: Justin Wong <justin.wong@eqinsurance.com.sg>
Sent: Friday, 7 September 2018 5:34 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Dear Hsiao Tong,

Please note that our claims ref is DM18HO00085-JW

Regards,
Justin Wong
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Friday, September 7, 2018 10:32 AM
To: Justin Wong <justin.wong@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Hi Justin,

We refer to the above matter.

Case has been settled at **\$28,880.00(all-in)** with Third Party repairer. Breakdown as follows: -

| | |
|----------------------------|---------------------|
| 1. Cost of Repair | \$ 26,000.00 |
| 2. LOR (24days x \$120.00) | \$ 2,880.00 |
| TOTAL | \$ 28,880.00 |

We are pending for signed DV from third party and will proceed to close file once DV received.

Meantime, kindly advise claim no. for this case.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Justin Wong <justin.wong@eqinsurance.com.sg>

Sent: Friday, 31 August 2018 8:57 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Dear Hsiao Tong,

Please proceed to offer Third Party repairer "F-1 AUTOCLINIC PTE LTD" at \$29,600.00(all-in).

Thank you.

Regards,

Justin Wong

Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190

www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Thursday, August 30, 2018 12:18 PM

To: Justin Wong <justin.wong@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Your ref : **TBA**

Our ref : CC4/EQI18000429/Apb3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING GBE5883K(OI)/ YP5798T(TP) /OTHERS ON 05/01/2018

We refer to the above matter.

The said chain collision involved 6 vehicles whereby our insured was the 5th vehicle.
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "F-1 AUTOCLINIC PTE LTD" at **\$29,600.00(all-in)**.

The summary is as follows: -

| | Amount Claimed | Amount Revised |
|---------------------------------------|----------------|--------------------------------|
| 1. Cost of Repair | \$ 63,410.30 | \$ 26,000.00 |
| 2. Loss of Rental (24days x \$250.00) | \$ 6,000.00 | \$ 3,600.00 (24days x \$15.00) |
| Total | \$ 69,410.30 | <u>\$ 29,600.00</u> |

***24days recommendation for repair.

| | |
|--------------------------|------------------------------------|
| Market Value | : \$ 96,000.00 (est) |
| LTA Rebate | : \$ 34,539.00 (est) |
| Nett Value/ Repair Limit | : <u>\$ 61,461.00 (est)</u> |

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Thursday, 26 July 2018 8:12 AM

To: 'justin.wong@eqinsurance.com.sg' <justin.wong@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Your Ref: **TBA**

LKK REF: CC4/EQI18000429/Apb3

Dear Sirs/Madam,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 8 January, 2018 1:57 PM

To: 'Bazlin Ahmad' <bazlin.ahmad@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: YP5798T & GBE5883K DOA 05.01.2018

Dear Bazlin Ahmad,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]

Sent: Monday, 8 January 2018 1:33 PM

To: Admin A <admin-a@lkkauto.com>

Subject: FW: YP5798T & GBE5883K DOA 05.01.2018

Dear LKK

We refer to the abovementioned new assignment, please find attached our insured GIA report.

Thank You.

Regards,

Lynn Ahmad

Executive | Claims



EQ Insurance Company Limited

5th Floor, Room 501-504, Tower Block, MNO Complex, Singapore 068110

did no make 9621 | tel 65 6222 8433 ext 881 | fax 65 6222 4190

www.eqinsurance.com.sg



A Member of Citystate



you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]

Sent: Monday, January 8, 2018 1:15 PM

To: louis.sim@eqinsurance.com.sg

Cc: Bazlin Ahmad

Subject: Fw: YP5798T & GBE5883K DOA 05.01.2018

Dear Sir / Mdm ,

Enclosed is our police report & accident scene photos.

Please advise OIC & claim no .

If your insured agree liability 100% for our favour , we will arrange your panel survey LKK AUTO
CONSULTANT PTE LTD for direct settlement .

Please let us have your reply soon . Thanks

Regards,

Chris Chan Pick Yuen

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4

05-26 @ Synergy

Singapore 417800

Fax:6702 2916

HP: 92712214

Hsiao Tong (LKKAUTO)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Thursday, 19 July 2018 8:47 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: YP5798T after paint *** LKK REF: CC4/EQI18000429/Apb3
Attachments: GIA.pdf; Invoice.pdf; SD.pdf

Dear Hsiao Tong ,

Enclosed is our GIA report , invoice , Rental & LOA .
Original document will send via post by today .
As request following :

1. RC \$26000 (AS AGREED)
2. LOR \$6000 (\$ 250 X 24DAYS)

Total \$ 32000/-.

Please let us have your offer soon . Thanks

Regards,
Chris Chan Pick Yuen
F1 AUTOCLINIC PTE LTD
+6567479241
Fax : +6567417276

From: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Sent: Monday, February 5, 2018 10:58 AM
To: chan pick yuen; Adrian Ling (LKKAUTO); Hsiao Tong (LKKAUTO)
Cc: Admin A; Zaini (LKK Auto)
Subject: RE: YP5798T after paint *** LKK REF: CC4/EQI18000429/Apb3

Dear Chris,

Thank you for your email. Please note that your client's vehicle number should be read as YP5798T.

For your info.

| LKK ref | Officer in charge |
|----------------------|------------------------|
| CC4/EQI18000429/Apb3 | Hsiao Tong - 6742 3197 |

To check availability of the case handler, you may contact the undersigned.

Thank you.
Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]

Sent: Sunday, 4 February, 2018 11:02 PM

To: Admin A <admin-a@lkkauto.com>

Subject: YP5798P after paint

Regards,

Chris Chan Pick Yuen

hp: 92712214



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/EQI18000429/Apb3

19 JANUARY 2018

KAILASAM S/O PERIANAN PUSALAN

BLK 150 ANG MO KIO AVE 5

#06-3070

SINGAPORE 560150

Dear Sir/Madam,

ACCIDENT INVOLVING GBE 5883K/ YP 5798T/ OTHERS ON 05/01/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG

Case Handler

DID: 6742 3197

FAX: 6741 4108

EMAIL: chewht@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

LETTER OF AUTHORISATION

F-1 AUTOCLINIC PTE LTD
BLK 25 KAKI BUKIUT ROAD #
05-26 SYNERGY @KB
Singapore 417800

Dear Sir,

Accident on

5/1/18 @ 13:10 hrs

Involving Vehicle Nos

YP5798T & GBE 5883K

Along

CTE TWDs SLE

I/We, the registered owner /driver of vehicle registration no:

YP5798T

have involved in the above accident.

I/We hereby authorize M/S F-1 AUTOCLINIC PTE LTD to commence repairs of the said vehicle forthwith.

I/We agree to assign the whole proceeds of my/our comprehensive third party claim to you and our solicitors to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.
Thank you.


Yours truly,

N GENERATION

新一代桌椅出租

PTD LTD

6 Yishun Industrial St. 1 #05-19
Northview Bizhub Singapore 768090
Tel: 8366 7460 / 9015 2333 / 9067 0790

Owner's Signature: 
www.facebook.com/ngen888
Email: ngeneration888@gmail.com
(Company's stamp if applicable)

Name: _____

NRIC No: _____

Date: _____

WITHOUT PREJUDICE to:
(a) Insurance Subrogated Claim and/or
(b) Any Personal Injury Claims
[Note: This Notice supersedes any inconsistency found in this Discharge Voucher]

EQ Insurance Company Limited

5 Maxwell Road, #17-00 Tower Block,
MND Complex, Singapore 069110
Tel: (65) 6223 9433 Fax: (65) 6223 4190

DISCHARGE VOUCHER

Claim No: 0m18H000065

In consideration of the offer/payment of the sum of SINGAPORE DOLLARS: TWENTY EIGHT THOUSAND EIGHT HUNDRED EIGHTY Only (S\$28,880.00) by EQ Insurance Company Limited, I/we hereby accept such sum in full and final settlement of all claims (present or future), losses of use/injuries that I/we have or may have against EQ Insurance Co. Ltd and/or Kailasam S/O Perianan Pusalan / Vigneshvaran S/O Kailasam (the insurer, owner and driver of vehicle No. GBE5883K) in connection with or in any way arising from the accident along/at CTE towards SLE on 05/01/2018 involving YP5798T (your client) and GBE5883K (Insured with EQ Insurance Co Ltd).

It is further agreed that this offer is not to be deemed as an admission of liability on the part of EQ Insurance Co. Ltd. and/or Kailasam S/O Perianan Pusalan / Vigneshvaran S/O Kailasam (the insurer, owner and driver of vehicle No. GBE5883K).

Dated this 07 (day) of 09 (month) 2018 (year)

CLAIMANT

Name

Signature

Address

NRIC No.

N GENERATION

新一代車務系統

5 Maxwell Road, #17-00 Tower Block,
MND Complex, Singapore 069110
Tel: (65) 6223 9433 Fax: (65) 6223 4190
Email: enquiry@eq.com.sg

WITNESS

Name

Signature

Address

NRIC No.

F-1 AUTOCLINIC PTE LTD

Block 25 Kaki Bukit Road 4, #05-26 Synergy @ KB Singapore 417800
HP: 96583371 TEL: (65) 67022915 FAX: 67022916

INVOICE

N GENERATION PTE LTD
BLK 25 Kaki Bukit Rd 4
#08-26 Synergy @ KB
Singapore 417800

Date: 18th July 18

Accident date: 05th JANUARY 2018
Final Bill For Vehicle No: YP5798T MITSUBISHI CANTER

| Descriptions | AMOUNT |
|---|-------------|
| Lump Sum repair cost as recommended by LKK AUTO CONSULTANTS PTE LTD Surveyor : Mr Adrian Ling | \$26,000.00 |
| Total | \$26,000.00 |

S/DLRS: TWENTY SIX THOUSAN ONLY

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Friday, 7 September 2018 10:32 AM
To: 'Justin Wong'
Cc: Admin A
Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Hi Justin,

We refer to the above matter.

Case has been settled at **\$28,880.00(all-in)** with Third Party repairer. Breakdown as follows: -

| | |
|----------------------------|----------------------------|
| 1. Cost of Repair | \$ 26,000.00 |
| 2. LOR (24days x \$120.00) | \$ 2,880.00 |
| TOTAL | <u>\$ 28,880.00</u> |

We are pending for signed DV from third party and will proceed to close file once DV received.

Meantime, kindly advise claim no. for this case.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Justin Wong <justin.wong@eqinsurance.com.sg>
Sent: Friday, 31 August 2018 8:57 AM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Dear Hsiao Tong,

Please proceed to offer Third Party repairer "F-1 AUTOCLINIC PTE LTD" at **\$29,600.00(all-in)**.

Thank you.

Regards,

Justin Wong

Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Thursday, August 30, 2018 12:18 PM
To: Justin Wong <justin.wong@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Your ref : **TBA**
Our ref : CC4/EQI18000429/Apb3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING GBE5883K(OI)/ YP5798T(TP) /OTHERS ON 05/01/2018

We refer to the above matter.

The said chain collision involved 6 vehicles whereby our insured was the 5th vehicle.
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "F-1 AUTOCLINIC PTE LTD" at \$29,600.00(all-in).

The summary is as follows: -

| | Amount Claimed | Amount Revised |
|---------------------------------------|----------------|--------------------------------|
| 1. Cost of Repair | \$ 63,410.30 | \$ 26,000.00 |
| 2. Loss of Rental (24days x \$250.00) | \$ 6,000.00 | \$ 3,600.00 (24days x \$15.00) |
| Total | \$ 69,410.30 | <u>\$ 29,600.00</u> |

***24days recommendation for repair.

| | |
|--------------------------|-----------------------------|
| Market Value | : \$ 96,000.00 (est) |
| LTA Rebate | : \$ 34,539.00 (est) |
| Nett Value/ Repair Limit | : <u>\$ 61,461.00 (est)</u> |

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Thursday, 26 July 2018 8:12 AM

To: 'Justin.wong@eqinsurance.com.sg' <justin.wong@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: YP5798T & GBE5883K DOA 05.01.2018 *LKK Ref: CC4/EQI18000429/Apb3

Your Ref: **TBA**

LKK REF: CC4/EQI18000429/Apb3

Dear Sirs/Madam,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 8 January, 2018 1:57 PM

To: 'Bazlin Ahmad' <bazlin.ahmad@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: YP5798T & GBE5883K DOA 05.01.2018

Dear Bazlin Ahmad,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]

Sent: Monday, 8 January 2018 1:33 PM

To: Admin A <admin-a@lkkauto.com>

Subject: FW: YP5798T & GBE5883K DOA 05.01.2018

Dear LKK

We refer to the abovementioned new assignment, please find attached our insured GIA report.

Thank You.

Regards,

Lynn Ahmad

Executive | Claims



EQ Insurance Company Limited

5 Raffles Road, #11-00 Tower Block, MND Complex, Singapore 059110

did : 6456 8881 | tel 65 6223 9488 ext 881 | fax 65 6223 8190

www.eqinsurance.com.sg



A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies.

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]

Sent: Monday, January 8, 2018 1:15 PM

To: louis.sim@eqinsurance.com.sg

Cc: Bazlin Ahmad

Subject: Fw: YP5798T & GBE5883K DOA 05.01.2018

Dear Sir / Mdm ,

Enclosed is our police report & accident scene photos.

Please advise OIC & claim no .

If your insured agree liability 100% for our favour , we will arrange your panel survey LKK AUTO CONSULTANT PTE LTD for direct settlement .

Please let us have your reply soon . Thanks

Regards,
Chris Chan Pick Yuen
F-1 AUTOCLINIC PTE LTD
Block 25 Kaki Bukit Road 4
05-26 @ Synergy
Singapore 417800
Fax:6702 2916
HP: 92712214



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 04/10/2018

THIRD PARTY DIRECT SETTLEMENT

| | | | |
|------------------|-----------|------------|---------------------------------------|
| Vehicle No. | GBE 5883K | (Insd Veh) | Your Ref. No. : DM18HO00085-JW |
| | YP 5798T | (TP Veh) | Our Ref. No. : CC4/EQ118000429/Apb3q2 |
| Date of Accident | 5/1/2018 | | |

| | | |
|----------------------|----------------|----------|
| Liability | 100% | |
| Final Repair Cost | : \$ 26,000.00 | |
| Loss of Use | : \$ 2,880.00 | 24 days |
| Rental (If any) | : \$ | 1.5 days |
| Others: | : \$ | |
| | : \$ | |
| | 28,880.00 | |
| Final Settlement Sum | : \$ 28,880.00 | |
| Remarks | : | |
| | | |

| <u>Payment Instruction: Payee's Breakdown</u> | | |
|---|------------------------|----------------|
| 1) | F-1 AUTOCLINIC PTE LTD | : \$ 28,880.00 |
| | | : \$ |
| | | |

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------|------------------------------|---|
| EQ INSURANCE COMPANY LTD | | | Ref : CC4/EQI18000429/Apb3q2 | |
| 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110 | | | Date : 04-10-2018 |  |
| | | | Code : EQI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | GBE 5883K | Veh. Inspected | YP 5798T | |
| Policy No. | DMCPHQ17-000289 | Coverage (\$) | 0.00 | |
| Claim No. | DM18HO00085-JW | Excess (\$) | 0.00 | |
| Assign From | JUSTIN | Assign Date | 08/01/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | MITSUBISHI CANTER | c.c | 2998 | |
| Engine No. | HIDDEN | Year of Reg. | 2017 | |
| Chassis No. | FEB21EA21215 | Colour | WHITE | |
| Odometer | 23093 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | NIL | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/85 R15 | BRIDGESTONE | 6 mm | |
| L/H Front Tyre | 195/85 R15 | BRIDGESTONE | 6 mm | |
| R/H Rear Tyre | 195/85 R15 | BRIDGESTONE | 6 mm | |
| L/H Rear Tyre | 195/85 R15 | BRIDGESTONE | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 05/01/2018 | Inspection Date | 08/01/2018 | |
| Survey held at | F-1 AUTOCLINIC PTE LTD 25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @ KB SINGAPORE 417800 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 24 Working Days | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 5798T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------|---------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 2 | FRONT HEAD LAMP @\$672.70 | SMASHED | 1,345.40 | 1,345.40 |
| 1 | FRONT WINDSCREEN GLASS | SHATTERED | 955.10 | 955.10 |
| 1 | FRONT WINDSCREEN GLASS MOULDING | NECESSARY | 500.90 | 500.90 |
| 2 | FRONT SIGNAL LAMP @\$266.40 | CRACKED | 532.80 | 532.80 |
| 2 | FRONT SIDE LAMP @\$185.40 | CRACKED | 370.80 | 370.80 |
| 1 | FRONT GRILLE | SMASHED | 1,043.00 | 1,043.00 |
| 1 | FRONT GRILLE CLIPS | NECESSARY | 15.00 | 15.00 |
| 1 | FRONT GRILLE EMBLEM LOGO | NECESSARY | 77.00 | 77.00 |
| 1 | FRONT FUSO LOGO | NECESSARY | 163.00 | 163.00 |
| 1 | FRONT BUMPER | DISTORTED | 1,010.30 | 1,010.30 |
| 2 | FRONT BUMPER BRACKET @\$196.20 | BENT | 392.40 | 392.40 |
| 2 | FRONT CORNER PANEL @\$466.30 | N/S DEFORMED | 932.60 | 466.30 |
| 1 | FRONT BUMPER SIDE COVER | CRACKED | 341.70 | 341.70 |
| 1 | BRAKE BOOSTER PUMP | NOT NECESSARY | 1,329.00 | - |
| 1 | GLOVE BOX | NOT NECESSARY | 355.60 | - |
| 1 | FRONT PANEL | DISTORTED | 2,436.50 | 2,436.50 |
| 1 | FRONT DASHBOARD | DEFORMED | 1,586.30 | 1,586.30 |
| 1 | DASHBORD REINFORCEMENT | BENT | 489.10 | 489.10 |
| 1 | DASHBORD CENTRE CONSOLE | DEFORMED | 459.40 | 459.40 |
| 1 | DASHBORD LOWER COVER | DEFORMED | 388.40 | 388.40 |
| 1 | FRONT WIPER GARNISH | DEFORMED | 382.70 | 382.70 |
| 1 | FRONT WIPER GARNISH CLIPS | NECESSARY | 20.00 | 20.00 |
| 2 | FRONT WIPER ARM @\$137.40 | BENT | 274.80 | 274.80 |
| 2 | FRONT WIPER BLADE @\$42.20 | CUT | 84.40 | 84.40 |
| 1 | FRONT WIPER MOTOR | NOT NECESSARY | 655.50 | - |
| 1 | FRONT WIPER LINKAGE | BENT | 249.40 | 249.40 |
| 1 | FROTN DOOR INNER TRIM BOARD CLIPS | NECESSARY | 60.00 | 60.00 |
| 2 | FRONT DOOR @\$2001.50 | BUCKLED | 4,003.00 | 4,003.00 |
| 2 | FRONT DOOR LOCK @\$485.00 | DAMAGED | 970.00 | 970.00 |
| 2 | FRONT DOOR WEATHERSTRIP @\$295.00 | NOT NECESSARY | 590.00 | - |
| 2 | FRONT DOOR INNER TRIM BOARD @\$498.40 | CRACKED | 996.80 | 996.80 |

Report Ref No. CC4/EQ118000429/Apb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------|----------------------|---------------------------|-------------------|
| 1 | TORSION BAR | BENT | 566.20 | 566.20 |
| 2 | FRONT WING MIRROR STAY @\$433.00 | NOT NECESSARY | 866.00 | - |
| 1 | REAR VIEW MIRROR | CRACKED | 142.90 | 142.90 |
| 1 | ABS PUMP | NOT NECESSARY | 4,585.40 | - |
| 1 | AIR FILTER DUCT | DEFORMED | 398.40 | 398.40 |
| 3 | BRAKE PIPE @\$65.10 | NOT NECESSARY | 195.30 | - |
| 1 | TURBO OIL COOLER | DENTED | 1,498.90 | 1,498.90 |
| 1 | FRONT CABIN LOCK FRAME | NOT NECESSARY | 823.40 | - |
| 1 | FRONT CABIN LOCK HINGE | BENT | 296.90 | 296.90 |
| 2 | FRONT MUD FLAP @\$261.00 | NOT NECESSARY | 522.00 | - |
| 1 | CABIN REAR PANEL | TO REPAIR SEE LABOUR | 1,465.50 | - |
| 1 | RADIATOR | DENTED | 2,616.10 | 2,616.10 |
| 1 | RADIATOR SPARE TANK (NPA) | NOT NECESSARY | - | - |
| 1 | RADIATOR FAN BLADE | CUT | 225.50 | 225.50 |
| 1 | RADIATOR FAN COWLING | CRACKED | 346.30 | 346.30 |
| 1 | RADIATOR FAN CLUTCH | NOT NECESSARY | 1,461.70 | - |
| 1 | AIR COND CONDENSER | DENTED | 1,200.50 | 1,200.50 |
| 1 | AIR COND FAN ASSY | NOT NECESSARY | 1,466.20 | - |
| 1 | AIR COND DISCHARGE PIPE | BENT | 454.20 | 454.20 |
| 1 | AIR COND SECTION PIPE | BENT | 484.10 | 484.10 |
| 1 | AIR COND LIQUID PIPE | BENT | 345.60 | 345.60 |
| 1 | AIR COND BLOWER | CRACKED | 1,431.30 | 1,431.30 |
| 1 | AIR COND EVAPORATOR | CRACKED | 1,261.50 | 1,261.50 |
| 1 | REAR WINDSCREEN GLASS MOULDING | NECESSARY | 118.40 | 118.40 |
| 1 | REAR NUMBER PLATE BRACKET | BENT | 74.90 | 74.90 |
| | LESS 25% DISCOUNT | | - | -7,769.05 |
| | | | 45,858.10 | 23,307.15 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRONT NUMBER PLATE (SN) | BENT | 30.00 | 30.00 |
| 1 | FRONT WINDSCREEN SEALANT (SN) | NECESSARY | 60.00 | 60.00 |
| 1 | ERP BRACKET (SN) | NECESSARY | 20.00 | 20.00 |
| 1 | REAR NUMBER PLATE (SN) | BENT | 30.00 | 30.00 |

Report Ref No. CC4/EQI18000429/Apb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|---------------|---------------------------|-------------------|
| 1 | REAR WINDSCREEN SEALANT (SN) | NECESSARY | 60.00 | 60.00 |
| 1 | REAR WOODEN STEP PLANK (SN) | CRACKED | 500.00 | 380.00 |
| 2 | REAR WOODEN CHASSIS FRAME @\$1280.00 (SN) | N/S CRACKED | 2,560.00 | 980.00 |
| 1 | TAIL GATE (SN) | CRACKED | 1,850.00 | 980.00 |
| 2 | TAIL GATE LOWER WOODEN PLANK @\$850.00 (SN) | NOT NECESSARY | 1,700.00 | - |
| 1 | 60KM LOGO (SN) | NECESSARY | 15.00 | 15.00 |
| 2 | TAIL LAMP @\$243.60 (SN) | NOT NECESSARY | 487.20 | - |
| | | | 7,312.20 | 2,555.00 |
| | LABOUR | | | |
| | TO REMOVE & INSTALL FRONT WINDSCREEN. | | 180.00 | 120.00 |
| | TO REMOVE & INSTALL REAR WINDSCREEN. | | 180.00 | 100.00 |
| | TO REMOVE & INSTALL DASHBOARD. | | 380.00 | 280.00 |
| | REMOVE & REFIX FRONT LH & RH DOOR FITTING. | | 300.00 | 200.00 |
| | TO REMOVE & INSTALL REAR DECK WOODEN CANOPY. | | 500.00 | 350.00 |
| | TO REMOVE & REFIX STEERING COLUMN. | | 280.00 | 180.00 |
| | TO REMOVE & REFIX RADIATOR. | | 180.00 | 120.00 |
| | TO REMOVE & REFIX BRAKE SYSTEM. | | 280.00 | 180.00 |
| | TO TOW VEHICLE. | | 150.00 | 150.00 |
| | TO REMOVE & INSTALL REAR WOODEN DECK. | | 1,000.00 | 800.00 |
| | TO UNDERSEAL. | | 250.00 | 120.00 |
| | TO REMOVE & INSTALL AIR CON SYSTEM & TOP UP GAS. | | 380.00 | 120.00 |
| | TO CHECK WIRING SYSTEM. | | 180.00 | 150.00 |
| | PANEL BEATING.INCLUSIVE OF THE REPAIR OF CABIN REAR PANEL. | | 3,500.00 | 2,000.00 |
| | SPRAY PAINTING. | | 2,500.00 | 1,800.00 |
| | | | - | - |
| | | | - | - |
| | | | - | - |
| | | | 10,240.00 | 6,670.00 |
| GRAND TOTAL | | | 63,410.30 | 32,532.15 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 26,000.00 |

Report Ref No. CC4/EQ18000429/Apb3q2



Report Ref No. CC4/EQI18000429/Apb3q2

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.