

Surveyor: Murphy REF: CS3 / MSC118000434 / Wrd302

Special Instruction:
US: \$4000.00
Third Parties:
Claimant:
Surveyor: WGA Appraisal
Workshop: Edwin Service

From (Person): Irene Tan of MSLH Date/Time: 09-02-2018
Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / Evaluation
To Inspect Vehicle No: SLA 9727E Insured: F&J 10557
at Workshop m/s Edwin Service Tel: _____
of Blk 5132 #01-295 Amk Park 2
Policy No: MSD/VMT/17-988534 Claim No: _____
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A. 06/01/2018
(Client's Record)

Do not finalize
H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT
Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 5 days)
Date/Time: 21/2/18 Submit Final Fig 2450, 4 days (Red \$ 1550 / 39 %; Original 5 days)

Date/Time	Action/Instruction
	<u>SLA 9727E - X</u>
	<u>F&J 10557 - X</u>
	<u>PPS + TP-Reinspection</u>

[Signature]
20/2/2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

REF: CS3 / MSC118000434 / Wrd302

Para(3) : Nett Value

Market Value : _____	Inspected/ Evaluated by:	Fee Charged:	Date:				
Salvage Value : _____		Basic & Add	<table border="1"> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> </table>				
Nett Value : _____	Transport						
	Photos						
	Others						
	Total						

- 1) Date/Time 21/2/18 File Pass to typ 1st
- 2) Date/Time _____ File Return to _____
- 3) Date/Time _____ File Pass to _____
- 4) Date/Time _____ File Return to _____
- 5) Date/Time _____ File Pass to _____
- 6) Date/Time _____ File Return to _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18000434/Wrd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 08-01-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	FBJ 1055J	Veh. Inspected	SLA 9727E
Policy No.	MSD/VMT/17-988534	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	08/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/01/2018	Inspection Date	
Survey held at	EDWIN GARAGE 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-295 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569535		

5a. Remarks

	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Ad. Assigned	Ad. Recd	Ad. Submitted	Ins. Activated	Status
Main	08 Jan 2018		08 Jan 2018 15:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	SURESH A/L M RAMALINGAM , ID: F1516660Q								
Main Claimant:	JOMELIVIA , Co. Reg. No.: 53364571M								
Vehicle Reg. No.:	SLA9727E	Date of Loss:	06/01/2018 14:00 - :59						
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMFT/17-988534 (TP, Fire & Theft) Coverage: 30/12/2017 - 29/12/2018						
Vehicle Reg. No. (Insured):	FBJ1055J	Policy No. (Claimant):							
		Excess:	S\$600.00						
Repairer:	Edwin Garage Automotive Pte Ltd (HQ) 5032 #01-295, Ang Mo Kio Industrial Park 2, 569535 Ang Mo Kio - Tel: 9785 6612								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/01/2018]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4571M
Vehicle Details	
Vehicle No.:	SLA9727E
Vehicle to be Exported:	No
Intended De-registration Date:	21 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15B4033770
Chassis No.:	RU11113764
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,208.00
Original Registration Date:	23 Mar 2016
First Registration Date:	23 Mar 2016
Transfer Count:	1
Actual ARF Paid:	\$10,292.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2026
PARF Rebate Amount:	\$7,719.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$37,722.00
Total Rebate Amount:	\$45,441.00

The information contained herein is correct as at 21 Feb 2018

OK

张景祥大律師樓
(律師兼公証及宣誓官)

Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688

Email: KSTEOCO@singnet.com.sg

(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKSF/E479-ACC-39604.18/sf (mc)
Your Ref : FBJ 1055 J
Date : 8 January 2018

Secretary in charge: Janice

Tel : 6333 4222 (ext 60)
Fax : 6333 5676 / 6333 5688
Email : janice.kee@ksteopt.com

MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581

WITHOUT PREJUDICE
BY PDX # 8173 & FAX 6225 7402

Attn: Motor Claims Dept

Suresh A/L M Ramalingam (Owner)
Blk 38 Cambridge Road
#13-135
Singapore 210038

BY POST ONLY

PDX Intercompany Exchange Pte Ltd



010808306435

FROM **TEO KENG SIANG LLC**
PDX Box No. **8902**

Dear Sirs

RE: ACCIDENT INVOLVING SLA 9727 E / FBJ 1055 J ON 6/1/18 ALONG TPE PIE BESIDE 12.5KM EXIT

We are instructed by Jomelivia to notify you of a road traffic accident on 6/1/18 at about 14:00 hours **ALONG TPE PIE BESIDE 12.5KM EXIT** involving our client's vehicle registration number **SLA 9727 E** and vehicle registration number **FBJ 1055 J** driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **SLA 9727 E** is now at the following workshop:-

Edwin Garage Automotive Pte Ltd
Blk 5032 Ang Mo Kio Industrial Park 2
#01-295
Singapore 569535
Contact: 9785 6612 Edwin

Yours faithfully,


M/s Teo Keng Siang LLC
encs

**Survey was conducted by:-

Name of Surveyor:

Date of Survey:

Time of Survey:

Signature

Teo Keng Siang
LL.M(Singapore),
LL.B (Hons) (Singapore)

Wong Yong Sheng, Kenneth
LL.B (Hons) University of Bristol

Joseph Tan Chin Aik
LL.B (Hons) Singapore
PGDE (NTU/NIE)

Irene Tan

张景祥大律師樓
(律師兼公証及宣誓堂)


Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676/5688
Email: KSTEOCO@singnet.com.sg

(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)



Our Ref : TKSF/E479-ACC-39604.18/sf (mc)
Your Ref : FBJ 1055 J ✓ 18-000062
Date : 1 February 2018

Secretary in charge: Janice
Tel : 6333 4222 (ext 60)
Fax : 6333 5676/6333 5688
Email : janice.kee@ksteoptr.com

To: **MSIG Insurance (Singapore) Pte Ltd**
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
Attn: Motor Claims Dept

WITHOUT PREJUDICE
BY PDX# 8173

cc: **Suresh A/L M Ramalingam**
Blk 38 Cambridge Road
#13-135
Singapore 210038

BY CERTIFICATE OF POSTING
(For your information only)

Dear Sirs,

RE: ACCIDENT INVOLVING SLA 9727 E / FBJ 1055 J ON 6/1/18 ALONG TPE PIE BESIDE 12.5KM EXIT

We are instructed by **Jomelivia** to claim damages against you in connection with a road accident on **6/1/18 ALONG TPE PIE BESIDE 12.5KM EXIT** involving our client's motor vehicle registration number **CLIENT'S SLA 9727 E** and motor vehicle registration number **DEFENDANT'S FBJ 1055 J** driven by you or your authorised driver at the material time.

We are instructed that your negligent driving and/or management of your vehicle caused the accident. As a result of the accident, our client's vehicle was damaged and our client was put to loss and expense, particulars of which are as follows:

• Cost of Repair	\$ 4,000.00
• Pre-repair fees (\$120 x 2 days)	\$ 240.00
• Rental fees (\$120 x 6 days)	\$ 720.00
• LTA / GIA search fee	\$ 51.49
• Survey report fee	\$ 387.00
• Costs incl. GST	\$ 856.00
Total	\$ 6,254.49

PDX Intercompany Exchange Pte Ltd



010808324031

FROM **TEO KENG SIANG LLC**
PDX Box No **8902**

Teo Keng Siang
LL.M(Singapore),
LL.B (Hons) (Singapore)

Wong Yong Sheng, Kenneth
LL.B (Hons) University of Bristol

JHE,
1) ↑ AS to \$6300/-
2) Upload
3) MLI 1 & 2
here
5/2/18
Irene Tan [0348]
Senior Executive
Claims Services

Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688
Email: KSTEOCO@singnet.com.sg
(FAX – NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKSF/E479-ACC-39604.18/sf (mc)
Your Ref : FBJ 1055 J
Date : 1 February 2018

Secretary in charge: Janice
Tel : 6333 4222 (ext 60)
Fax : 6333 5676/6333 5688
Email : janice.kee@ksteoptr.com

A copy each of the following supporting documents is enclosed:


- GIA report on CLIENT'S SLA 9727 E
- LTA / GIA search on DEFENDANT'S FBJ 1055 J
- Rental agreement
- Repairer's bill.
- Surveyor's report.
- Photographs of damage of CLIENT'S SLA 9727 E – 37 copies.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter to your insurer.

Please note that you or your insurer should send to us an acknowledgment of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,



Teo Keng Siang LLC
encs.

Edwin Garage Automotive Pte Ltd

Blk 5032 Ang Mo Kio Industrial Park 2 #01-295 S (569535)

H/p: 9785 6612 Edwin

Date: 19 January 2018

Jomelivia

Blk 269C Punggol Field

#04-211

Singapore 823269

FINAL REPAIR COSTS

SLA 9727 E

HONDA VEZEL

Contract Lump Sum Cost of Repair

\$4,000.00 NETT

DOLLAR FOUR THOUSAND ONLY



專營遠善必甲出租
汽車修理
汽車保險賠償服務
嘉實多授權服務中心

國家汽車服務

NATIONAL AUTOMOBILE SERVICE

Block 5033, Ang Mo Kio Industrial Park 2, #01-279
(off Ang Mo Kio Avenue 3) Singapore 569536
TEL: 6482 5577 (3 Lines) FAX: 6482 5000
TOWING SERVICE: 9182 8211 (After 10.30pm)
Reg. No: 062389/00M



TRUCK RENTAL
MOTOR REPAIR
INSURANCE CLAIMS
AGENCY
AUTHORISED CASTROL
SERVICE CENTRE

車輛出租合同 VEHICLE RENTAL AGREEMENT

SLA9727E.

Date: 8/1/18
Owner: NATIONAL AUTOMOBILE SERVICE ("the owner")
Hirer: Than Kian Boon.
Address: Blk 569c Punggol Field #04-211 S2823269
NRIC / Co. Reg. No: S82123985.
Tel: _____ Fax: _____ H/P: 98516166

14:112232554c

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SJJ852 L		Agreement No.: 56361	
Driver's Particulars		Odometer: _____	
Name: Than Kian Boon		Date & Time Out: 8/1/18 1150h	
Address: _____		Date & Time In: 13/1/18 609	
I/C No: S82123985	Dr/Licence No: S2123985	Hour @\$	
Date of Issue: 25/11/2016	Occupation: Financial consultant	6 Days @\$ 120/	
Date of Birth: 19/4/1982	Tools: 0w Spare Tyre: onset	Wks @\$	
		Mths @\$	

Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive). Hirer unconditionally agrees to pay Owner S\$ 3000/ (with signature) comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

Own Vehicle Damage

Hirer is responsible for the first \$ 3000/ (with signature) excess for collision/damage to first party, (i.e.) NATIONAL AUTOMOBILE SERVICE (including windscreen) plus loss of earnings while damaged vehicle is under repair.

Authorised Driver

Hirer shall pay additional excess of S\$1500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable): _____

Sub-Total: _____

Balance To Pay: 2700/ (with signature)



PETROL/DIESEL AT YOUR OWN EXPENSE
FOR LOCAL USE ONLY

NATIONAL AUTOMOBILE SERVICE

(Signature)

Authorised Signature

(Signature)

Hirer's Signature

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: Winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J


Our Ref: WG/TP/2018-05
Invoice No: TP/EDWIN/2018-05
Vehicle No: SLA9727E
Attn: JOMELIVIA
Company: EDWIN GARAGE AUTOMOTIVE PTE LTD
Address: BLK 5032 ANG MO KIO, INDUSTRIAL PARK 2
#01-295.SINGAPORE 569535

Date 17 January 2018

Invoice

Surveyor Fee:	S\$250
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$37/- (@ \$1 per photo, total 37 photos)
Total:	S\$387

Surveyor: Winsen Goh
Signature: 
Date: 17/1/2018





GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-016281
 Date of Request: 30/01/2018

Your Ref No: E479-ACC-39604.18/SF

TEO KENG SIANG LLC
 111 North Bridge Road
 #29-07/08 Peninsula Plaza
 Singapore 179098

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 06/01/2018
 Location of Accident: TPE PIE BESIDE 12.5KM EXIT
 Client Vehicle No: SLA9727E

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
FBJ1055J	SELETAR EXPRESSWAY	06/01/2018 14:10

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-016281
Date of Request: 30/01/2018

Your Ref No: E479-ACC-39604.18/SF

TEO KENG SIANG LLC
111 North Bridge Road
#29-07/08 Peninsula Plaza
Singapore 179098

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 06/01/2018
Type of Accident: TPE PIE BESIDE 12.5KM EXIT
Client Vehicle No: SLA9727E

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-016285

Date of Request: 30/01/2018

Your Ref No: E479-ACC-39604.18/SF

TEO KENG SIANG LLC
111 North Bridge Road
#29-07/08 Peninsula Plaza
Singapore 179098

Dear Sir/Madam,

Date of Accident: 06/01/2018

Vehicle No: SLA9727E

Location of Accident: TPE PIE beside 12.5KM Exit

Involving Vehicle No: FBJ1055J

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
FBJ1055J	TPE PIE beside 12.5KM Exit	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

p:
 GIRO Cash Cheque



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-008953
Date of Request: 17/01/2018

Your Ref No: E479-ACC-39604.18/SF

TEO KENG SIANG LLC
111 North Bridge Road
#29-07/08 Peninsula Plaza
Singapore 179098

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 06/01/2018
Place of Accident: TPE PIE BESIDE 12.5KM EXIT
Client Vehicle No: SLA9727E

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
FBJ1055J	<i>No match found.</i>	

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-008953
Date of Request: 17/01/2018

Your Ref No: E479-ACC-39604.18/SF

TEO KENG SIANG LLC
111 North Bridge Road
#29-07/08 Peninsula Plaza
Singapore 179098

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 06/01/2018
Place of Accident: TPE PIE BESIDE 12.5KM EXIT
Client Vehicle No: SLA9727E

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53376249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S JOMELIVIA
C/O EDWIN GARAGE AUTOMOTIVE PTE LTD
BLK 5032 ANG MO KIO, INDUSTRIAL PARK 2
#01-295.SINGAPORE 569535

Date : 17 January 2018
Our Ref : WG/TP/2018-05

REFERENCE PARTICULARS

Date of Accident : 06 January 2018
Date of Inspection : 08 January 2018

Type of Inspection : Third Party Claim
Date of Re-Inspn : 09 January 2018

VEHICLE PARTICULARS

Registration No : SLA9727E
Make : HONDA
Model : VEZEL
Year : NA

Engine No : NA
Chassis No : RU1-1113764
Odometer : 60666km
Colour : Blue

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>
Front Near side	: Pirelli	215/55R16
Front Off Side	: Pirelli	215/55R16
Rear Near Side	: Pirelli	215/55R16
Rear off Side	: Pirelli	215/55R16

<u>Thread Balance</u>
5 mm
5 mm
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear right portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$4,000.00** nett at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Five (05) working days.

Enclosed Thirty-seven (37) photographs depicting damage to the vehicle.

Inspection conducted at : EDWIN GARAGE AUTOMOTIVE PTE LTD
BLK 5032 ANG MO KIO, INDUSTRIAL PARK 2.#01-295.SINGAPORE 569535

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a "WITHOUT PREJUDICE BASIS".

VEHICLE NO : SLA9727E
 MODEL : VEZEL

Our Ref : WG/TP/2018-05

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY	ASSESSED	ORIGINAL	REVISED
PCSET	CONDITION	QUOTATION	QUOTATION	
1 REAR BUMPER ✓ WP	1	DEFORMED	\$ 953.30	\$ 953.30 850
2 REAR BUMPER RETAINER RNS ✓ WP	201	NECESSARY	\$ 67.20	\$ 67.20 33.60
3 REAR RH BUMPER REFLECTOR ✓ NN ✓ NEC	1	NOT NECESSARY	\$ 151.00	\$ -
4 REAR RH BUMPER CORNER ✓ SCR / WP	1	GRAZED	\$ 198.50	\$ 198.50 ✓
5 REAR RH MUDFLAP X SVC	1	GRAZED	\$ 171.20	\$ 171.20 X
6 REAR RH KNUCKLE BEARING X SVC	1	JAMMED	\$ 307.20	\$ 307.20 X
7 REAR RH SHOCK ABSORBER X SVC	1	BENT	\$ 541.20	\$ 541.20 X
8 REAR RH FENDER OUTER GARNISH ✓ SCR	1	GRAZED	\$ 212.50	\$ 212.50 ✓
9 REAR RH TAILLAMP ✓ SCR	1	GRAZED	\$ 504.00	\$ 504.00 ✓
10 REAR RH DOOR X R	1	REPAIR	\$ -	\$ - X
			\$ 3,106.10	\$ 2,955.10
		Less 20%	\$ 621.22	\$ 591.02
			\$ 2,484.88	\$ 2,364.08 1798.60

B) S/NETT ITEM

11 REAR BUMPER CLIP ✓ NEC	1 SET	NECESSARY	\$ 60.00	\$ 50.00 ✓
12 REAR FENDER OUTER GARNISH CLIP ✓ NEC	1 SET	NECESSARY	\$ 40.00	\$ 30.00 ✓
13 RIM (16") ✓ SCR / chip off	1	GRAZED	\$ 800.00	\$ 700.00 380
14 BRAKE FULD X NN	1	NECESSARY	\$ 50.00	\$ 40.00 X
			\$ 950.00	\$ 820.00
		Parts Total :	\$ 3,434.88	\$ 3,184.08 460

C) LABOUR CHARGES & MISC

15 CHECK REAR WIRING AND LIGHTNING SYSTEM			\$ 60.00	\$ 50.00 30
16 REMOVE AND REFIT REAR REVERSE SENSOR			\$ 100.00	\$ 80.00 40
17 CHECK REAR WHEEL ALIGNMENT			\$ 150.00	\$ 130.00 120
18 REMOVE AND RENEW REAR UNDERCARRIAGE PARTS X NN			\$ 200.00	\$ 180.00 X
19 PANEL BEATING ON AFFECTED AREAS - Repair - RH R Fender / door			\$ 800.00	\$ 600.00 250
20 SPRAY PAINTING ON AFFECTED AREAS			\$ 800.00	\$ 700.00 800
21 APPLY ANTI RUST ON AFFECTED AREAS X N.O			\$ 150.00	\$ 130.00 X
		Labour Total :	\$ 2,260.00	\$ 1,870.00 1140
		Total Parts and Labour :	\$ 5,694.88	\$ 5,054.08 1140

FINAL LUMP SUM ADJUSTMENT

\$ 4,000.00

Parts (List)	\$ 1798.60	5695.04
Discount 20%	- \$ 359.72	
	<u>\$ 1438.88</u>	
Parts (S/NETT)	+ \$ 460.00	
	<u>\$ 1898.88</u>	
Labour	+ \$ 1140.06	
	<u>\$ 3038.88</u>	
Discount 20% (4sum)	- \$ 607.78	
	<u>\$ 2431.10</u>	

* Lump Sum → \$ 2450

4 Repair Days

POINT OF IMPACT

The impact was confined to the rear right portion of the vehicle.
The damages appeared to be consistent as per the accident report statement.
Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$4,000.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
WG APPRAISAL SERVICES



Winson Gon
Automotive Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jan 2018		08 Jan 2018 15:05 Edit Adj Rpt	S\$2,450.00 Edit Estimates	S\$2,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	SURESH A/L M RAMALINGAM, ID: F1516660Q			
Main Claimant:	JOMELIVIA, Co. Reg. No.: 53364571M			
Vehicle Reg. No.:	SLA9727E	Date of Loss:	06/01/2018 14:00 - :59	
Claim Type:	TP / MSC/V/18-000062	Policy/Cover Note No.:	MSD/VMFT/17-988534 (TP, Fire & Theft) Coverage: 30/12/2017 - 29/12/2018	
Vehicle Reg. No. (Insured):	FBJ1055J	Policy No. (Claimant):		
		Excess:	S\$600.00	
Repairer:	Edwin Garage Automotive Pte Ltd (HQ) 5032 #01-295, Ang Mo Kio Industrial Park 2, 569535 Ang Mo Kio - Tel: 9785 6612			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 09/01/2018]			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SLA9727E (MSC/V/18-000062)**
[FBJ1055J]
TP
JOMELIVIA
Jan 6 2018 2:00PM
[SURESH A/L M RAMALINGAM]
Edwin Garage Automotive Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser ▾

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	18/01/18 08:41	Accident Statement From:SC - Reg. No: FBJ1055J, Claimant: SURESH A/L M RAMALINGAM	1	Load HTM	
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	21/02/18 10:33	General View	1	Load JPG	<input checked="" type="checkbox"/>

31	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
32	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
33	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
34	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
35	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
36	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
37	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
38	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
39	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
40	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
41	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
42	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
43	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
44	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
45	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
46	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
47	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
48	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
49	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
50	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
51	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
52	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
53	21/02/18 10:33	General View		Load JPG	<input checked="" type="checkbox"/>
54	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
55	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
56	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
57	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
58	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
59	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
60	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
61	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
62	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
63	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
64	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
65	21/02/18 10:33	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	08/01/18 15:04	PRI		Load PDF	
2	08/01/18 15:04	EMAIL to TP reject their list of surveyor		Load PDF	
3	08/02/18 15:29	LOD		Load PDF	
4	08/02/18 15:29	Final Repair Bill, Rental Invoice, Survey Fee, GIA Search		Load PDF	
5	08/02/18 15:29	Survey Report		Load PDF	
6	09/02/18 14:27	instruction to LKK auto to prepare paper survey report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

//

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18000434/WRD3E2
Date: 21/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. **Policy No:** MSD/VMFT/17-988534
Claimant Vehicle No : SLA9727E **Insured Vehicle No :** FBJ1055J
Date of Loss: 06/01/2018 **Nature of Claim:** TP **Claim No:** MSC/V/18-000062

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA9727E
Make & Model: HONDA VEZEL, 1.5 X CVT (A) **Engine No:** L15B4033770
Reg. Date: 23/03/2016 (Man. Year: 2015) **Chassis No:** RU11113764
Colour: Dark Blue **Odometer:** 60668 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 **Rear Tyre Size:** 215/60 R16
Front Left Side: Pirelli 4 mm **Rear Left Side:** Pirelli 4 mm
Front Right Side: Pirelli 4 mm **Rear Right Side:** Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,435.04	1,898.88	1,536.16	44.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,140.00	1,120.00	49.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,695.04	3,038.88	2,656.16	46.64
Approved Total (Overridden) (S\$)		2,450.00		
Nett Amount (S\$)	5,695.04	2,450.00	3,245.04	56.98

INSPECTION

Date of Assignment: 08/01/2018
Date Inspected: 09/01/2018 **Inspected At:** Edwin Garage Automotive Pte Ltd (HQ)
5032 #01-295, Ang Mo Kio Industrial Park 2
Singapore 569535
Estimated Period of Repair: 4.0 days

Adjuster: Teo Cheng Ming Wilson**Manager:** Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Feb 2018)
Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLA9727E)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Warped	953.50 FL	*850.00 FL
2	1		*REAR BUMPER RETAINER	O/S Necessary	67.20 FL	*33.60 FL
3	1		*REAR RH BUMPER REFLECTOR	Not Necessary	151.00 FL	*- FL
4	1		*REAR RH BUMPER CORNER	Scratched / Warped	198.50 FL	*198.50 FL
5	1		*REAR RH MUDFLAP	Serviceable	171.20 FL	*- FL
6	1		*REAR RH KNUCKLE BEARING	Serviceable	307.20 FL	*- FL
7	1		*REAR RH SHOCK ABSORBER	Serviceable	541.20 FL	*- FL
8	1		*REAR RH FENDER OUTER GARNISH	Scratched	212.50 FL	*212.50 FL
9	1		*REAR RH TAILLAMP	Scratched	504.00 FL	*504.00 FL
10	1		*REAR RH DOOR (NPA)	Repair	0.00 FL	*- FL
11	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
12	1		*SET REAR FENDER OUTER GARNISH CLIP	Necessary	40.00 FS	*30.00 FS
13	1		*RIM (16)	Scratched / Chip Off	800.00 FS	*380.00 FS
14	1		*BRAKE FLUID	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,056.30	2,258.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	621.26	359.72
Total Parts (\$\$)	3,435.04	1,898.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	New	60.00	30.00
2	REMOVE AND REFIT REAR REVERSE SENSOR	New	100.00	40.00
3	CHECK REAR WHEEL ALIGNMENT	New	150.00	120.00
4	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS	New	200.00	0.00
5	PANEL BEATING ON AFFECTED AREAS	New	800.00	350.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	600.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (S\$)			2,260.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >