

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : GBC9931P Case Owner : TP

Make & Model : TOYOTA HIACE Year Manufacture : 2014

Chassis No : JTFHT02PX00136485 Engine No : 1KD2376446

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : 0

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition Surveyor
31	SPARY TYER BRACKET X	1					
32	EXHAUST MUFFLER X	1					
33	FRONT NUMBER PLATE ✓ Bent	1				\$ 45.00	(A)
34	BONNET ✓	1	\$ 240.00				
35	FRONT TOP PANEL WITH GRILLE X	1					
36	FRT LOWER PANEL WITH GRILLE ✓	1	\$ 130.00				
37	FRT BUMPER LOWER GRILLE ✓	1	\$ 55.00				
38	FRONT BUMPER ✓	1	\$ 190.00				
39	FRONT EMBLEM LOGO ✓	1	\$ 26.00				
40	FRT BUMPER SIDE RETAINER RH ✓	1	\$ 55.00				
41	FRT BUMPER SIDE RETAINER LH ✓	1	\$ 55.00				
42	FRT BUMPER BRACKET RH X	1					
43	FRT BUMPER BRACKET LH X	1					
44	FRT HEADLAMP ASSY RH ✓	1	\$ 240.00				
45	FRT HEADLAMP ASSY LH X	1	\$ -				
46	FRT SIGNAL LAMP RH X	1					
47	FRT SIGNAL LAMP LH X	1					
48	FRT BUMPER FOG LAMP COVER RH ✓	1	\$ 25.00	48			
49	FRT BUMPER FOG LAMP COVER LH X	1					
50	FRT BUMPER TOW COVER RH X	1					
51	FRT BUMPER REINFORCEMENT ✓	1	\$ 95.00				
52	FRT BUMPER SPONGE X	1					
53	RADIATOR X	1					
54	A/C CONDENSOR X	1					
55	REAR NUMBER PLATE LAMP GARNISH	1					
56	TAILGATE TRIM BOARD	1	\$ 120.00				
57	REAR RH PANEL ✓	1	\$ 50.00	5001-			
58	STICKER 'WARBURG' (RHR) (A) ✓	1				\$ 80.00	✓
59	STICKER 'TEL: 65657895' (RHR) (A) ✓	1				\$ 80.00	✓
60		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

1281

25/05/2018

6:22 PM

(12)

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : GBC9931P Case Owner : TP

Make & Model : TOYOTA HIACE Year Manufacture : 2014

Chassis No : JTFHT02PX00136485 Engine No : 1KD2376446

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : 0

S/N	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition Surveyor
61	STICKER 'TOYOTA' <i>new 7</i>	1				\$ 22.00	✓
62	STICKER 'HIACE' <i>new 7(A)</i>	1					
63	STICKER 70 km <i>new</i>	1				\$ 10.00	✓
64	www.warburgvending.com.sg STICKER <i>new 7</i>	1				\$ 80.00	✓
65	FRT BONNET HINGE RH <i>3 all 7(A)</i>	1					x
66	FRT BONNET HINGE LH <i>3 all</i>	1					x
67	0	0					
68	0	0					
69	0	0					
70	0	0					
71	0	0					
72	0	0					
73	0	0					
74	0	0					
75	0	0					
76	0	0					
77	S	0					
78	0	0					
79	0	0					
80	0	0					
81	0	0					
82	0	0					
83	0	0					
84	0	0					
85	0	0					
86	0	0					
87	0	0					
88	0	0					
89	0	0					
90	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649

Tel: 68438723/68438736 Fax:67436072

Supplementary 1

Vehicle No : GBC9931P Case Owner : 0

Make & Model : TOYOTA HIACE Year Manufacture : 2014

Chassis No : JTFHT02PX00136485 Engine No : 1KD2376446

Sales Order : 0 Supplier : 0

Order By : _____ Type of Claim : TP-MSIG

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	AIR-CLEANER ASSY <i>cracked</i>	1	\$ 240.00	✓			
2	FRT BUMPER BEAM <i>Not Rec</i>	1		X			
3	REAR BUMPER LOWER BRACKET <i>Bent</i>	2	\$ 40.00				
4	END PANEL CLIPS <i>Rec</i>	7	\$ 17.50	✓			
5	REAR PANEL SIDE RETAINER LH <i>damaged</i>	1	\$ 20.00				
6	REAR PANEL SIDE RETAINER RH	1	\$ 20.00				
7	RH AIR GUARD <i>cracked</i>	1	\$ 18.00	✓			
8	RH PANEL INNER TRIM BOARD <i>damaged</i>	1	\$ 55.00	✓			
9	RH TAILLAMP INNER PANEL <i>distorted</i>	1	\$ 175.00	✓			
10	RH TAILLAMP OUTER PANEL	1	\$ 220.00	✓			
11	FRONT TOWER COVER <i>damaged</i>	1	\$ 15.00	✓			
12	FRT R/ LAMP LOWER COVER <i>ident #10</i>	1	\$ 48.00	✓			
13	REAR END PANEL OUTER <i>distorted</i>	1	\$ 140.00	✓			
14	REAR END PANEL INNER	1	\$ 300.00	✓			
15	GRILLE BASE <i>damaged</i>	1	\$ 210.00	✓			
16							
17							
18			1518.50				
19							
20			1246.25				
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

1518.50

Spark Car Care

ComfortDelGro Engineering Pte Ltd

Tel: 68438723/68438736 FAX : 67436072

Vehicle No. :	<u>GBC9931P</u>	Case Owner :	<u>0</u>
Make & Model :	<u>TOYOTA HIACE</u>	Year of Manufacture :	<u>2014</u>

[illegible]

3620.