

**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, 408610 SINGAPORE

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

LIM TENG CHEONG

C/O AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

068811 SINGAPORE

Customer No. : WA006

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Invoice No.	:	SINV-BS18000107
Invoice Date	:	18/01/18
Order No.	:	SVO18001520
Reference	:	
Job Card No.	:	69682
Date/Time Received	:	09/01/18 / 7:45:51 PM
Licence No.	:	SGV8618S
Model	:	HRV LX CVT YM 2015
Car Chassis No.	:	MRHRU1830FP000172
Car Engine No.	:	L15Z71000174
Mileage	:	52296
Service Advisor	:	ARY CHUA WAI NGEE 1490A
Served By	:	ARYCHUA
Page	:	1

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	GST Amt	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: 69682							
	POLICY/CLAIMS NO: GA104498/1							
	OWNER: LIM TENG CHEONG							
	ACC DATE: 27/12/2017@16:15PM							
	SURVEYED BY: guoqiang@lkkauto.com							
	AUTHORIZED ON: 10-01-2018@12:12PM							
	REF NO:							
	TP INSURER: NTUC INCOME INSURANCE CO-OPERATION LTD							
	TP VEH: AQ9A(BMW/R1200/BLACK)							
BOSUN	0672 SUNDRIES	1	Hours	10.00		10.00	0.70	10.70
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS.	1	Hours	80.00	20	64.00	4.48	68.48
	PERFORM WATER TEST.(N)							
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4	1	Hours	160.00	20	128.00	8.96	136.96
	PCS (N)							
BOMISC1	EXT-YJ REMOVE & INSTALL REVERSE CAMERA &	1	Hours	240.00	20	192.00	13.44	205.44
	CALIBRATION							
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN.(N)	1	Hours	280.00	20	224.00	15.68	239.68
BOMISC1	0672 RESET VEHICLE SMART KEY ACCESS/ENTRY	1	Hours	280.00	20	224.00	15.68	239.68
	SYSTEM							
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT	1	Hours	350.00	20	280.00	19.60	299.60
	LININGS							
	GARNISHES.(N)							
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW	1	Hours	400.00	20	320.00	22.40	342.40
	TAILGATE. ADJUST &							
	ALIGN TAILGATE.(N)							
BP06R	EXT-YBH SPRAY PAINTING ON REPAIRED OR	1	Hours	1,050.00	20	840.00	58.80	898.80
	REPLACED AREAS. (6P)							
BKRP02S	EXT-YJ STRAIGHTEN ALIGN RR PANEL & RENEW	1	Hours	1,350.00	20	1,080.00	75.60	1,155.60
	DAMAGE PARTS.							
68100-T8P-U10ZZ	TAILGATE COMP	1	Each	838.90	35	545.28	38.17	583.45
74440-T7A-003	WEATHERSTRIPTAILGATE	1	Each	96.80	35	62.92	4.40	67.32
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	Each	19.30	35	12.54	0.88	13.42
73226-SZW-000	DAMPERSTD 5X5	1	Each	8.30	35	5.39	0.38	5.77
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	Each	19.30	35	12.54	0.88	13.42
91501-S70-003	FASTENER BW/SHIELD	4	Each	3.20	35	8.32	0.58	8.90
91502-S70-003	FASTENER B	2	Each	4.90	35	6.37	0.45	6.82
91536-SS0-J01	FASTENER AW/SHIELD	2	Each	3.50	35	4.55	0.32	4.87
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	Each	60.00		120.00	8.40	128.40
74800-T7A-J02	LOCK ASSYTAILGATE	1	Each	76.60	35	49.79	3.49	53.28
75722-T7W-A01	EMBLEMRR.	1	Each	12.90	35	8.38	0.59	8.97
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	Each	14.10	35	9.16	0.64	9.80

Printed by ARYCHUA on 18 Jan 2018 at 5:09:27 PM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

GST Amount is calculated from individual line(s)

Please give us your
feedback by scanning
the QR Code using
mobile device.





Service Tax Invoice

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, 408610 SINGAPORE

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

LIM TENG CHEONG

C/O AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

068811 SINGAPORE

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Invoice No. : SINV-BS18000107
Invoice Date : 18/01/18
Order No. : SVO18001520
Reference :
Job Card No. : 69682
Date/Time Received : 09/01/18 / 7:45:51 PM
Licence No. : SGV8618S
Model : HRV LX CVT YM 2015
Car Chassis No. : MRHRU1830FP000172
Car Engine No. : L15Z71000174
Mileage : 52296
Service Advisor : ARY CHUA WAI NGEE 1490A
Served By : ARYCHUA
Page : 2

Customer No. : WA006

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	GST Amt	Amount incld GST
71501-T8N-T50	FACERR.BUMPER	1	Each	463.70	35	301.40	21.10	322.50
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER	1	Each	81.00	35	52.65	3.69	56.34
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER	1	Each	81.00	35	52.65	3.69	56.34
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	Each	11.50	35	7.47	0.52	7.99
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	Each	11.50	35	7.47	0.52	7.99
91505-TM8-003	CLIPBUMPER	8	Each	2.00	35	10.40	0.73	11.13

Sum Labor 3,362.00 235.34 3,597.34

Sum Item 1,277.28 89.43 1,366.71

Total SGD 4,639.28 324.77 4,964.05

Total Payable (SGD) 4,964.05

Printed by ARYCHUA on 18 Jan 2018 at 5:09:27 PM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

GST Amount is calculated from individual line(s)

Please give us your feedback by scanning the QR Code using mobile device.





KAH MOTOR CO. SDN. BHD.

(A Member of Oriental Holdings Berhad)

Tel : +65 6841 3838

www.honda.com.sg

15 Ubi Road 4
Singapore 408610
Fax : +65 6748 0770

6A Mandai Estate
Singapore 729903
Fax : +65 6362 5015

SATISFACTION NOTE

I / We

LIM TENG CHEONG

Hereby certified that repairs to Car **SGV8618S** have been carried out to my/our entire satisfaction

and I / we agree that the discharge of the repair account from **KAH MOTOR CO. SDN. BHD.**

for S\$ 4,964.05 by **AXA INSURANCE S'PORE PTE LTD** shall be in full

discharge of all claims under Policy No. GA104498/1 in respect of damage to this car resulting

from an accident which occurred on or about the 27 day of Dec 2017

Date: 16 JAN 2018

Signature: 



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WA006 / AXA INSURANCE
Chassis No: MRHRU1830FP000172
License No: SGV8618S
Mileage: 50936
Engine No: L15Z71000174

Document No: SVO18001520
Printed By: ARYCHUA
Order Date: 9. January 2018
Order Time: 7:45:51 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: 69682 POLICY/CLAIMS NO: GA104498/1 OWNER: LIM TENG CHEONG ACC DATE: 27/12/2017@16:15PM SURVEYED BY: guoqiang@lkkauto.com AUTHORIZED ON: 10-01-2018@12:12PM REF NO:						
68100-T8P-U10ZZ	TAILGATE COMP	1	838.90	35	545.28	38.17	583.45
74440-T7A-003	WEATHERSTRIPTAILGATE	1	96.80	35	62.92	4.40	67.32
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	35	12.54	0.88	13.42
73226-SZW-000	DAMPERSTD 5X5	1	8.30	35	5.39	0.38	5.77
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	35	12.54	0.88	13.42
91501-S70-003	FASTENER BW/SHIELD	4	3.20	35	8.32	0.58	8.90
91502-S70-003	FASTENER B	2	4.90	35	6.37	0.45	6.82
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	35	4.55	0.32	4.87
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
74800-T7A-J02	LOCK ASSYTAILGATE	1	76.60	35	49.79	3.49	53.28
75722-T7W-A01	EMBLEMRR.	1	12.90	35	8.38	0.59	8.97
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	35	9.16	0.64	9.80
71501-T8N-T50	FACERR.BUMPER	1	463.70	35	301.40	21.10	322.50
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER	1	81.00	35	52.65	3.69	56.34
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER	1	81.00	35	52.65	3.69	56.34
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50	35	7.47	0.52	7.99
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	35	7.47	0.52	7.99
91505-TM8-003	CLIPBUMPER	8	2.00	35	10.40	0.73	11.13
	SUM PARTS:				1,277.28	89.43	1,366.71
BOSUN	0672 SUNDRIES	1	10.00		10.00	0.70	10.70
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	80.00	20	64.00	4.48	68.48
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00	20	128.00	8.96	136.96
BOMISC1	EXT-YJ REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	240.00	20	192.00	13.44	205.44
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	280.00	20	224.00	15.68	239.68
BOMISC1	0672 RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	280.00	20	224.00	15.68	239.68
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	350.00	20	280.00	19.60	299.60
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	400.00	20	320.00	22.40	342.40



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WA006 / AXA INSURANCE
Chassis No: MRHRU1830FP000172
License No: SGV8618S
Mileage: 50936
Engine No: L15Z71000174

Document No: SVO18001520
Printed By: ARYCHUA
Order Date: 9. January 2018
Order Time: 7:45:51 PM
Service Advisor: ARY CHUA WAI NGEE

BP06R	EXT-YBH	1	1,050.00	20	840.00	58.80	898.80
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)						
BKRP02S	EXT-YJ	1	1,350.00	20	1,080.00	75.60	1,155.60
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.						
		SUM LABOUR:	3,362.00		235.34		3,597.34
		TOTAL SGD	4,639.28		324.77		4,964.05
		Total Payable (SGD)					4,964.05

GST Amount is calculated from individual line(s)