



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WA006 / AXA INSURANCE

Chassis No: MRHRU1830FP000172

License No: SGV8618S

Mileage: 50936

Engine No: L15Z71000174

Document No: SVO18001520

Printed By: ARYCHUA

Order Date: 9. January 2018

Order Time: 7:45:51 PM

Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: 69682 POLICY/CLAIMS NO: GA104498/1 OWNER: LIM TENG CHEONG ACC DATE: 27/12/2017@16:15PM SURVEYED BY: guoqiang@lkkauto.com AUTHORIZED ON: 10-01-2018@12:12PM REF NO:						
68100-T8P-U10ZZ	TAILGATE COMP	1	838.90	35	545.28	38.17	583.45
74440-T7A-003	WEATHERSTRIPTAILGATE	1	96.80	35	62.92	4.40	67.32
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	35	12.54	0.88	13.42
73226-SZW-000	DAMPERSTD 5X5	1	8.30	35	5.39	0.38	5.77
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	35	12.54	0.88	13.42
91501-S70-003	FASTENER BW/SHIELD	4	3.20	35	8.32	0.58	8.90
91502-S70-003	FASTENER B	2	4.90	35	6.37	0.45	6.82
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	35	4.55	0.32	4.87
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
74800-T7A-J02	LOCK ASSYTAILGATE	1	76.60	35	49.79	3.49	53.28
75722-T7W-A01	EMBLEMRR.	1	12.90	35	8.38	0.59	8.97
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	35	9.16	0.64	9.80
71501-T8N-T50	FACERR.BUMPER	1	463.70	35	301.40	21.10	322.50
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER	1	81.00	35	52.65	3.69	56.34
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER	1	81.00	35	52.65	3.69	56.34
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50	35	7.47	0.52	7.99
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	35	7.47	0.52	7.99
91505-TM8-003	CLIPBUMPER	8	2.00	35	10.40	0.73	11.13
	SUM PARTS:				1,277.28	89.43	1,366.71
BOSUN	0672 SUNDRIES	1	10.00		10.00	0.70	10.70
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	80.00	20	64.00	4.48	68.48
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00	20	128.00	8.96	136.96
BOMISC1	EXT-YJ REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	240.00	20	192.00	13.44	205.44
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	280.00	20	224.00	15.68	239.68
BOMISC1	0672 RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	280.00	20	224.00	15.68	239.68
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	350.00	20	280.00	19.60	299.60
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	400.00	20	320.00	22.40	342.40



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WA006 / AXA INSURANCE
Chassis No: MRHRU1830FP000172
License No: SGV8618S
Mileage: 50936
Engine No: L15Z71000174

Document No: SVO18001520
Printed By: ARYCHUA
Order Date: 9. January 2018
Order Time: 7:45:51 PM
Service Advisor: ARY CHUA WAI NGEE

BP06R	EXT-YBH	1	1,050.00	20	840.00	58.80	898.80
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)						
BKRP02S	EXT-YJ	1	1,350.00	20	1,080.00	75.60	1,155.60
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.						
SUM LABOUR:					3,362.00	235.34	3,597.34
TOTAL SGD					4,639.28	324.77	4,964.05
Total Payable (SGD)							4,964.05

GST Amount is calculated from individual line(s)