

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J**AAD1801-024***Not Authorised**Resurvey B4 painting*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5935J
VF1ABL15AUC281660
RENAULT
LATITUDE
26.12.2017
CHINA TAIPING

		PART		LIST	
1	1	BUMPER COVER FRT	\$	<i>M1</i> 1,259.42	—
2	1	BUMPER SPOILER FRT	\$	<i>M1</i> 181.75	—
3	1	BUMPER ABSORBER FRT	\$	<i>M1</i> 394.68	—
4	1	BUMPER RETAINER FRT LH	\$	<i>CM</i> 151.41	—
5	1	BUMPER SUPPORT FRT	\$	<i>M1</i> 123.88	—
6	1	BUMPER RETAINER FRT RH	\$	<i>CM</i> 150.77	—
7	1	BUMPER SUPPORT FRT	\$	<i>M1</i> 123.88	—
8	1	BUMPER UNDERTRAY FRT	\$	<i>M1</i> 472.83	—
9	1	BUMPER GRILLE LOWER FRT	\$	<i>M1</i> 266.80	—
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>M1</i> 207.21	—
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>M1</i> 207.21	—
12	1	BUMPER BEAM FRT	\$	<i>B</i> 914.08	—
13	1	TOW COVER FRT	\$	<i>M1</i> 28.61	—
14	1	RADIATOR GRILLE	\$	<i>CM</i> 1,707.78	—
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>M</i> 225.36	—
16	1	RADIATOR GRILLE FRAME	\$	<i>B</i> 1,353.75	—
17	1	FRAME FULL SUPPORT PANEL	\$	<i>B</i> 615.90	—
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>B</i> 89.79	—
19	1	FRONT BRACE PANEL	\$	<i>B</i> 177.22	—
20	1	HORN	\$	<i>D</i> 314.17	—
21	1	HORN BRACKET	\$	<i>B</i> 40.45	—
22	1	HEADLAMP RH	\$	<i>B</i> 1,184.43	—
23	1	HEADLAMP PANEL FRT RH	\$	<i>D</i> 152.15	—
24	1	HEADLAMP HARNESS	\$	928.29	?
25	1	BONNET	\$	<i>B</i> 1,941.63	—
26	1	BONNET INSULATOR	\$	<i>S</i> 405.73	✗
27	1	BONNET STRUT LH	\$	<i>R</i> 88.61	—
28	1	BONNET STRUT RH	\$	<i>R</i> 88.61	—
29	1	BONNET HINGE LH	\$	<i>R</i> 348.31	—

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

30	1	BONNET HINGE RH	\$	B ₁	348.31	✓
31	1	BONNET LOCK	\$	B ₁	305.48	✓
32	1	BONNET CABLE	\$		119.19	?
33	1	BONNET CABLE COVER	\$	M ₁	161.03	✓
34	1	BONNET SEAL OUTER	\$	M ₁	92.36	—
35	1	BONNET SEAL INNER	\$	M ₁	157.28	—
36	1	FENDER PANEL FRT RH	\$	B ₁	783.83	—
37	1	WHEELARCH FRT RH	\$	Z ₁	278.84	—
38	1	FENDER BRACKET LOWER RH	\$	B ₁	15.79	✓
39	1	FENDER INSULATOR RH	\$	S ₁	130.84	X
40	1	FENDER PANEL FRT LH	\$	B ₁	783.83	✓
41	1	WHEELARCH FRT LH	\$	C _M	278.84	—
42	1	FENDER BRACKET LOWER LH	\$	N	15.79	X
43	1	FENDER INSULATOR LH	\$	S ₁	130.84	X
44	1	WIPER RESERVOIR	\$	N ₁	348.25	✓
45	1	WIPER RESERVOIR NECK	\$	N ₁	136.11	—
46	1	WIPER RESERVOIR MOTOR	\$	S ₁	270.06	X
47	1	AIR CLEANER LOWER	\$	C _M	271.26	—
48	1	AIR CLEANER HOSE	\$	C _M	76.14	—
49	1	AUTO COMPUTER	\$		5,032.17	?
50	1	STEERING PUMP ELECTRIC	\$	N ₁	2,306.90	✓
51	1	STEERING PINION RACK	\$		4,413.11	?
52	1	ENGINE HARNESS	\$		4,084.54	?
53	1	SUBFRAME OUTER FRT	\$		2,652.45	?
54	1	SUBFRAME BRACKET OUTER RH	\$		92.36	?
55	1	ENGINE MOUNTING H	\$		552.55	?
56	1	FUSE BOX	\$		987.39	?
57	1	ENGINE MOUNTING RH	\$		552.55	?
58	1	ENGINE MOUNTING LOWER	\$		562.42	?
59	1	ENGINE MOUNTING UPPER	\$		592.02	?
60	1	VEHICLE HARNESS PASS ROOM	\$		10,003.86	?
61	1	AIR CLEANER BOX	\$		464.20	?
62	1	TURBO DUCT	\$		1,027.80	?
63	1	OIL PAN ASSEMBLY	\$		2,283.91	?
64	1	A/C CONDENSER	\$	B ₁	2,020.37	✓
65	1	A/C CONDENSER GARNISH RH UPPER	\$	C _M	39.67	—
66	1	A/C CONDENSER GARNISH RH	\$	C _M	59.60	—
67	1	A/C PIPE CONDENSER TO COMPRESSOR	\$		208.39	?
68	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$		658.72	?

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

69	1	A/C PIPE COMPRESSOR	\$	Sn 334.29 X
70	1	A/C PIPE	\$	Sn 658.72 X
71	1	A/C COMPRESSOR	\$	Sn 2,684.61 X
72	1	AIR COOLER	\$	Pu 792.60
73	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13 7
74	1	AIR INTERCOOLER HOSE (Short)	\$	375.14 7
75	1	TRANSMISSION COOLER	\$	1,219.30 7
76	1	TRANSMISSION COOLER PAD	\$	17.96 7
77	1	RADIATOR	\$	Pu 1,202.20
78	2	RADIATOR STUD UPPER	\$	Sn 14.41 X
79	2	RADIATOR BUSH UPPER	\$	Sn 50.12 X
80	2	RADIATOR MTG LOWER	\$	Sn 55.85 X
81	1	RADIATOR FAN COWLING	\$	820.54 7
82	1	RADIATOR FAN MOTOR LH	\$	967.36 7
83	1	RADIATOR FAN MOTOR RH	\$	1,479.46 7
84	1	RADIATOR TANK	\$	324.62 7
85	1	RADIATOR HOSE UPPER	\$	240.56 7
86	1	RADIATOR HOSE LOWER	\$	491.18 7
87	1	RADIATOR TANK HOSE	\$	61.18 7
88	1	WINDSCREEN FRT	\$	CM Sn 1,364.06 X
89	1	SEATBELT LH	\$	Sn 2,937.80 X
90	1	SEATBELT RH	\$	Sn 2,925.37 X
91	1	SEATBELT BUCKLE LH	\$	Sn 984.13 X
92	1	SEATBELT BUCKLE RH	\$	Sn 949.80 X
93	1	PASSENGER AIRBAG	\$	Sn 3,412.40 X
94	1	STEERING AIRBAG	\$	Sn 2,525.75 X
95	1	AIRBAG COMPUTER	\$	Sn 1,259.82 X
96	1	AIRBAG SENSOR	\$	Sn 724.63 X
97	1	ROTARY SWITCH	\$	Sn 1,253.11 X
98	1	DASHBOARD	\$	Sn 4,900.54 X
99	1	BUMPER COVER REAR	\$	Bu 1,108.46
100	1	BUMPER LOWER REAR	\$	Bu 768.84
101	1	BUMPER BRACKET CTR REAR	\$	Sn 113.47 X
102	1	BUMPER BRACKET SIDE LH REAR	\$	Sn 135.97 X
103	1	BUMPER BRACKET CTR LH REAR	\$	Sn 44.99 X
104	1	BUMPER BRACKET SIDE RH REAR	\$	D, 135.97
105	1	BUMPER BRACKET CTR RH REAR	\$	D, 44.99
106	1	BUMPER BEAM REAR	\$	R 777.52 X
107	1	BUMPER BEAM BRACKET LH REAR	\$	R 225.95 X

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

108	1	BUMPER BEAM BRACKET RH REAR	\$	R 225.95 X
109	1	FENDER PANEL REAR RH	\$	B 3,299.13 ✓
110	1	WHEELARCH REAR RH	\$	B 543.47 ✓
111	1	FENDER PANEL INNER TRIM REAR RH	\$	Return 671.45 ✓
112	1	FENDER PANEL REAR LH	\$	B 3,299.13 ✓
113	1	WHEELARCH REAR LH	\$	S 543.47 X
114	1	FENDER PANEL INNER TRIM REAR LH	\$	S 671.45 X
115	1	LOWER ARM REAR RH	\$	B 905.99 ✓
116	1	KUCKLE ARM REAR RH	\$	B 736.67 ✓
117	1	ABSORBER REAR RH	\$	389.75 ?
118	1	ABSORBER BOLT REAR RH	\$	52.10 ?
119	1	ABSORBER DUST COVER REAR RH	\$	92.16 ?
120	1	DOOR PANEL REAR RH	\$	B 2,844.66 ✓
121	1	DOOR SEAL REAR RH	\$	S 187.08 X
122	1	DOOR PANEL FRT RH	\$	B 2,844.66 ✓
123	1	DOOR HINGE UPPER RH	\$	R 261.28 X
124	1	DOOR HINGE LOWER RH	\$	R 300.55 X
125	1	DOOR CHECK FRT RH	\$	S 194.77 X
126	1	DOOR CHECK BOLT	\$	S 22.69 X
127	1	DOOR LOCK FRT RH	\$	R 908.75 X
128	1	DOOR CATCH FRT RH	\$	R 131.23 X
129	1	DOOR HANDLE OUTER FRT RH	\$	T 477.76 ✓
130	1	DOOR HANDLE COVER FRT RH	\$	S 13.22 X
131	1	DOOR HANDLE MODULE FRT RH	\$	S 133.60 X
132	1	DOOR REGULATOR FRT RH	\$	505.19 ?
133	1	DOOR REGULATOR MOTOR FRT RH	\$	796.46 ?
134	1	DOOR REGULATOR GUIDE FRT RH	\$	120.97 ?
135	1	DOOR GLASS FRT RH	\$	Shatter 625.96 ✓
136	1	DOOR FINISHER FRT RH	\$	515.06 ?
137	1	DOOR MOULDING FRT RH	\$	S 176.82 X
138	1	DOOR FINISHER CLIP KIT FRT RH	\$	S 90.97 X
139	1	DOOR CASING FRT RH	\$	S 1,509.06 X
140	1	DOOR CASING LIGHT	\$	S 82.49 X
141	1	DOOR GRAB HANDLE FRT RH	\$	S 210.96 X
142	1	DOOR MIRROR RH	\$	S 1,725.73 X
143	1	DOOR WEATHERSTRIP FRT RH	\$	S 410.27 X
144	1	DOOR SEAL LOWER FRT RH	\$	S 91.17 X
145	1	DOOR GLASS RUNNER SEAL FRT RH	\$	S 626.36 X
146	1	DOOR WAIST SEAL OUTER FRT RH	\$	S 291.27 X

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

147	1	DOOR WAIST SEAL INNER FRT RH	\$	SL	122.15	X
148	1	DOOR PANEL REAR RH	\$	Repair By	2,844.66	X
149	1	DOOR GUIDE REAR RH	\$	SL	176.82	X
150	1	DOOR HINGE UPPER RH	\$	N	274.50	X
151	1	DOOR HINGE LOWER RH	\$	N	300.55	X
152	1	DOOR CHECK REAR RH	\$	SL	203.06	X
153	1	DOOR LOCK REAR RH	\$	TN	908.75	✓
154	1	DOOR GRAB HANDLE REAR RH	\$	SL	210.96	X
155	1	DOOR HANDLE OUTER REAR RH	\$	SL	126.49	X
156	1	DOOR HANDLE CAP REAR RH	\$	SL	35.52	X
157	1	DOOR HANDLE COVER REAR RH	\$	SL	13.22	X
158	1	DOOR HANDLE MODULE REAR RH	\$	SL	133.60	X
159	1	DOOR FINISHER REAR RH	\$	SL	423.10	X
160	1	DOOR WHEATHESTRIIP REAR RH	\$	CS	410.66	✓
161	1	DOOR SEAL REAR RH	\$		162.02	7
162	1	DOOR WAIST SEAL OUTER REAR RH	\$	N	334.69	✓
163	1	DOOR MOULDING REAR RH	\$	RES	176.82	✓
164	1	FENDER PANEL REAR RH	\$	Repair	3,299.13	X
165	1	FENDER PANEL INNER TRIM REAR	\$	N	671.45	X
166	1	WHEELARCH REAR RH	\$	N	543.47	X
167	1	LOWER ARM RH L70Y	\$	N	685.76	X
168	1	KUNCKLE ARM RH L70Y	\$	N	846.98	X
169	1	KUNCKLE HUB+BEARING RH	\$	N	497.69	X
170	1	KUNCKLE ARM SHIELD RH	\$		131.43	7
171	1	KUNCKLE ARM PLATE RH	\$		174.05	7
172	1	ABSORBER FRT RH	\$		360.54	7
173	1	ABSORBER MOUNTING KIT RH	\$		440.66	7
174	1	ABSORBER DUST COVER	\$		228.72	7
175	1	STABILIZER BAR FRT L70Y	\$		604.65	7
176	1	STABILIZER LINK FRT L70Y	\$		117.22	7
177	1	BRAKE CALIPER FRT RH L70Y	\$	SL	656.94	X
178	1	BRAKE CALIPER BRACKET FRT RH L70Y	\$	SL	555.12	X
179	1	ABS SENSOR FRT RH L70Y	\$	SL	255.75	X
180	1	DRIVESHAFT RH	\$		1,747.45	7
181	1	ROCKER PANEL INNER GARNISH RH	\$	NSP	466.51	X
182	1	ROCKER PANEL INNER LH	\$	N	1,024.79	X
183	1	DOOR PANEL FRT RH	\$	Repair	2,844.66	X
184	1	DOOR HINGE UPPER RH	\$	N	261.28	X
185	1	DOOR HINGE LOWER RH	\$	N	300.55	X

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

186	1	DOOR CHECK FRT RH	\$	194.77	}
187	1	DOOR CHECK BOLT	\$	22.69	
188	1	DOOR LOCK FRT RH	\$	908.75	
189	1	DOOR CATCH FRT RH	\$	131.23	
190	1	DOOR HANDLE OUTER FRT RH	\$	477.76	
191	1	DOOR HANDLE COVER FRT RH	\$	13.22	
192	1	DOOR HANDLE MODULE FRT RH	\$	133.60	
193	1	DOOR REGULATOR FRT RH	\$	505.19	
194	1	DOOR REGULATOR MOTOR FRT RH	\$	796.46	
195	1	DOOR REGULATOR GUIDE FRT RH	\$	120.97	
196	1	DOOR GLASS FRT RH	\$	625.96	
197	1	DOOR FINISHER FRT RH	\$	515.06	
198	1	DOOR MOULDING FRT RH	\$	176.82	
199	1	DOOR FINISHER CLIP KIT FRT RH	\$	90.97	
200	1	DOOR CASING FRT RH	\$	1,509.06	
201	1	DOOR CASING LIGHT	\$	82.49	
202	1	DOOR GRAB HANDLE FRT RH	\$	210.96	
203	1	DOOR MIRROR RH	\$	1,725.73	
204	1	DOOR WEATHERSTRIP FRT RH	\$	410.27	
205	1	DOOR SEAL LOWER FRT RH	\$	91.17	
206	1	DOOR GLASS RUNNER SEAL FRT RH	\$	626.36	
207	1	DOOR WAIST SEAL OUTER FRT RH	\$	291.27	

TOTAL	\$	157,604.43
10%	\$	15,760.44
	\$	141,843.98

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00	×
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	×
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00	✓
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	×
7	1	TOW COVER FRT	\$	14.50	✓
8	1SET	RADIATOR GRILLE SCREW	\$	16.00	✓
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	×
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	✓

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
13	1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	—
14	1SET	WHEELARCH CLIP FRT RH	\$	na	29.40	—
15	1	CAP HUB RH FRT	\$	na	35.00	✓
16	1	CAP HUB RH REAR	\$	na	35.00	—
17	1	RIM RH REAR	\$	na	385.00	✓
18	1	TYRE RH REAR	\$	na	330.00	308 na
19	1SET	BUMPER RR CLIP	\$	na	66.00	—
20	1SET	BUMPER BEAM BOLT	\$	na	22.22	—
21	1SET	PARKING AID	\$	na	600.00	X
22	1	BUMPER BRACKET CLIP CTR REAR	\$	na	15.00	X
23	1	BUMEP R BRACKET SIDE CLIP LH REAR	\$	na	12.00	X
24	1	BUMEP R RETAINER CLIP LH REAR	\$	na	10.40	X
25	1	BUMEP R BRACKET SIDE CLIP RH REAR	\$	na	12.00	X
26	1	BUMEP R RETAINER CLIP RH REAR	\$	na	10.40	X
27	1SET	BOOT FINISHER CLIP	\$	na	25.10	X
28	1	Rear boots sticker "Trans-cab"	\$	na	30.00	X
29	1	Rear boots sticker "6555-3333"	\$	na	30.00	X
30	1	FENDER PANEL INNER TRIM CLIP REAR RH	\$	na	22.00	X
31	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	na	22.00	X
32	1SET	WHEELARCH CLIP LH RR	\$	na	32.34	—
33	1SET	WHEELARCH CLIP RH RR	\$	na	32.34	—
34	2	REAR WINDSCREEN SEALANT	\$	na	80.00	Gain
35	1	WINDSCREEN MOULDING	\$	na	100.00	—
36	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	Gain
37	1	EXHAUST MOUNTING REAR	\$	na	65.50	X
38	1	EXHAUST BRACKET REAR	\$	na	22.22	X
39	1SET	FRONT LICENCE PLATE WITH HOLDER	\$	na	80.00	X
40	1	DOOR STICKER "6555-3333" RH	\$	na	80.00	X
41	1	DOOR STICKER 'Trans-cab' RH	\$	na	80.00	X
42	1	DOOR STICKER 'Chassis' RH	\$	na	30.00	X
43	1	LOWER ARM BOLT	\$	na	34.14	X
44	1	LOWER ARM NUT	\$	na	19.93	X
45	1	ABSORBER BOLT	\$	na	44.01	X
46	1	ABSORBER NUT	\$	na	17.56	X
47	1	BRAKE DISC SCREW FRT	\$	na	15.20	X
48	1	KUNCKLE ARM BOLT LH	\$	na	14.21	X
49	1	BRAKE CALIPER BRACKET BOLT FRT RH	\$	na	19.93	X

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J**TOTAL \$ 2,971.90****TOTAL PARTS \$ 144,815.88****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2600 7,500.00
Towing Fees.	\$	120.00 500
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
Putty and spray painting of the affected portion.	\$	1880 6,000.00
To rust-proofing of the affected areas.	\$	170.00 1500
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 1200
To check steering geometry and computer wheel alignment	\$	220.00 600
To transfer of tire, rim and on wheel balancing.	\$	170.00 200
To Check Electrical Lighting Concerned.	\$	170.00 400
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 2500
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	~ 170.00	X
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00	1201
To reinstall rear bumper parking sensor.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00	} 801
To repair and realign rear exhaust pipe.	\$	170.00	
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X
To lift-up engine with gear box and refit.	\$	440.00	?
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	?
To remove and refit air bag system and reset.	\$	480.00	?
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	601

Trans-cab Auto Services Pte Ltd**AAD1801-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5935J

To vacuum, replace, refix and recharge air condenser	\$	380.00 1001
To replace, refix and top up coolant for radiator	\$	170.00 501
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 X
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 1201

TOTAL \$ 21,110.00**Over All Total \$ 165,925.88****LUMP SUM (REPAIR)****30-DAYS***28 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: