

Surveyor: _____ REF: CS/FCL17005871/T1v²-1
ASSIGNMENT (Office)
 From (Person): Karen Tan of FCL Date/Time: 01-12-2017
 Estimated Cost: _____ Bill to: _____

Special Instruction:
4s: \$ 27436.00
 Third Parties:
 Claimant:
 Surveyor: Formteam Consultancy
 Workshop: Cyber Cars Service

OD/TP Re-inspection / Evaluation
 To Inspect Vehicle No: SU 999H Insured: SHA 3476R
 at Workshop m/s Cyber Cars Service Tel: 6836 1238
 of 548 Havelock Road
 Policy No: _____ Claim No: D17/3110/TPD&TPE/KT
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 2003 2017
 (Client's Record)
09-01-2018 @ Tuesday) @ 1pm H.O.D. Enforcement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT
 Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red S _____ / _____ %; Original 24 days)
 Date/Time: 20/2 Submit Final Fig 423,655, 20 days (Red S 3781 / 14 %; Original 24 days)

Date/Time	Action/Instruction
	<u>14 Cornwall Gardens, Singapore 269642</u>
	<u>SU 999H - CS/FCL17005871 / Sub32</u>
	<u>SHA 3476R - NS/INC17015796 / Klrbr2</u>
	<u>According to lawfirm & Karen Tan, no independent photo</u>
	<u>Tan Kah, Are you aware of the repair limit?</u>

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 20 FEB 2018

Para(3) : Nett Value

Market Value : _____	Inspected/ Evaluated by:	Fee Charged:	Date:
Salvage Value : _____		Basic & Add	<u>170 + 255</u>
Nett Value : _____		Transport	<u>50</u>
		Photos	<u>115</u>
		Others	
		Total	<u>300</u> <u>589</u>

- | | |
|---------------------------------------|---|
| 1) Date/Time _____ File Pass to _____ | 2) Date/Time _____ File Return to _____ |
| 3) Date/Time _____ File Pass to _____ | 4) Date/Time _____ File Return to _____ |
| 5) Date/Time _____ File Pass to _____ | 6) Date/Time _____ File Return to _____ |

Survey Department Check List (Case Handler)

Reference No. : ce/FC117005871/Tlvb-1
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are ACCURATE.

		Y-Date	N-Date	Y-Date	N-Date
(1) Office Assign Form					
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Taufik): Case handler to make sure the surveyor completed all required information.

		Y-Date	N-Date	Y-Date	N-Date
(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)					
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form					
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)					
C	Resurvey photo Uploaded				

Check By: Catherine 20/5/18
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17005871/vb-1

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 08-01-2018



Code : FC12

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3476R	Veh. Inspected	SU 999H
Policy No.		Coverage (\$)	0.00
Claim No.	D17/3110/TPD&TPI/KT	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	01/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/03/2017	Inspection Date	09/01/2018
Survey held at	14 CORNWALL GARDENS		
Repairer	CYBER CARS SERVICE CENTRE PTE LTD (HQ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Your ref: D17003110MFSH
Our ref: CS/FCI17005871/Svb

Date: 6/4/2017

The Motor Claims Department
M/s First Capital Insurance Limited

Without Prejudice

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO.


SU 999H

We thank for your instruction on 24/3/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 3/4/2017 at the premises of M/s PERFORMANCE MOTORS LTD and have the following to report:-

Workshop Estimate Amount	: S\$76,927.00
Revised Estimate Amount	: S\$61,924.90
"Check" Items Amount	: S\$9,925.50
Market Value	: S\$57,000.00
LTA Reimbursement Value	: S\$46,433.00
Nett Value	: S\$10,567.00

Description of Damage:
The vehicle sustained damages at the n/s body.



Comments/Present Status:
Damages Consistent

Yours faithfully,

YEANG WAI KEEN
Automotive Assessor

Catherine Chong (LKK Auto)

From: Beatrice Chiang <chiang.beatrice@nlclaw.com.sg>
Sent: Thursday, 4 January, 2018 11:04 PM
To: 'Catherine Chong (LKK Auto)'
Cc: 'Ng Lip Chih'; KARENTAN@FIRST-INSURANCE.COM.SG; 'assignments';
yu.rachel@nlclaw.com.sg
Subject: RE: CLAIMANT: QUEK SUAN KIAT & CHUA BIN HWEE - ACCIDENT INVOLVING
SU999H AND SHA3476R ON 20.03.2017 - FCI REF: D17/3110/TPD&TPI/KT YR REF:
NLC/LLC/17.0163

Importance: High

SKK 9769A

WITHOUT PREJUDICE SAVE AS TO COSTS

Dear Catherine,

As our client will be out-stationed on 9 January 2018 at 9.00 am, please let us know if your surveyors could conduct the re-inspection of SU999H tomorrow afternoon (5 January 2018) at 2.00 pm at 14 Cornwall Gardens, Singapore 269642.

Alternatively, and in the interest of expediting the matter, your surveyors may proceed to re-inspect SU999H on 9 January 2018 at 1.00 pm (without our client being present for the re-inspection). Our client's helper will be present at 14 Cornwall Gardens, Singapore 269642 to supervise the re-inspection of SU999H.

All our client's rights are expressly reserved.

Best Regards

Beatrice Chiang Sing Hui 郑忻慧
Associate

NLC
LAW
ASIA

ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS
NOTARY PUBLIC

chiang.beatrice@nlclaw.com.sg

30 Cecil Street #11-04 Prudential Tower Singapore 049712
Tel +65 6236 5759 (DID) Fax +65 6538 8580

www.nlclaw.com.sg

NLC Law Asia LLC (Registration/UEN No. 201334024D) is a limited liability company registered in Singapore. A list of the Directors and their professional qualifications may be inspected at the address specified above.

CONFIDENTIALITY CAUTION : This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by return email and delete the original message. Thank you.

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, January 4, 2018 5:40 PM
To: yu.rachel@nlclaw.com.sg
Cc: 'Ng Lip Chih'; 'Beatrice Chiang'; KARENTAN@FIRST-INSURANCE.COM.SG; 'assignments'
Subject: RE: CLAIMANT: QUEK SUAN KIAT & CHUA BIN HWEE - ACCIDENT INVOLVING SU999H AND SHA3476R ON 20.03.2017 - FCI REF: D17/3110/TPD&TPI/KT YR REF: NLC/LLC/17.0163

Dear Rachel,

As spoken, can we arrange RI on 09.01.2018 @ 1pm at 14 Cornwall Gardens?

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Karen Tan [mailto:karentan@first-insurance.com.sg]
Sent: Thursday, 4 January, 2018 5:16 PM
To: 'LKK Auto Consultants Pte Ltd' <sur@lkkauto.com>; Admin-D (LKK Auto) (admin-d@lkkauto.com) <admin-d@lkkauto.com>
Cc: 'Ng Lip Chih' <ng.lipchih@fnqlaw.com>; yu.rachel@nlclaw.com.sg; Beatrice Chiang <chiang.beatrice@nlclaw.com.sg>
Subject: CLAIMANT: QUEK SUAN KIAT & CHUA BIN HWEE - ACCIDENT INVOLVING SU999H AND SHA3476R ON 20.03.2017 - FCI REF: D17/3110/TPD&TPI/KT YR REF: NLC/LLC/17.0163

Dear LKK,

Kindly arrange for a Re-inspection soonest possible.

Best Regards,

Karen Tan

Motor Claims Dept.

First Capital Insurance Ltd | **A FAIRFAX Company** 36 Robinson Road #16-01 Singapore 068877 | DID : 6507 3582

| Fax No. : 6507 3849 | Company Regn. No. 195000106C

W: www.first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Beatrice Chiang [mailto:chiang.beatrice@nlclaw.com.sg]
Sent: Thursday, 4 January, 2018 4:38 PM
To: Karen Tan <karentan@first-insurance.com.sg>

Cc: 'LKK Auto Consultants Pte Ltd' <sur@lkkauto.com>; 'Ng Lip Chih' <ng.lipchih@fnqlaw.com>; yu.rachel@nlclaw.com.sg

Subject: RE: [Spam] Re: CLAIMANT: QUEK SUAN KIAT & CHUA BIN HWEE - ACCIDENT INVOLVING SU999H AND SHA3476R ON 20.03.2017 - FCI REF: D17/3110/TPD&TPI/KT YR REF: NLC/LLC/17.0163

WITHOUT PREJUDICE SAVE AS TO COSTS

Dear Sirs,

We refer to our email below.

To date, we have not heard from you and/or your surveyors as regards the re-inspection of SU999H and your position as regards our client's demand for the repayment of the sum of S\$46,218.75 set out in our email of 6 December 2017.

Please be informed that if we do not hear from you **within 3 days hereof** in relation to any possible re-inspection of SU999H and your position as regards our client's demand for the sum of S\$46,218.75 set out in our email of 6 December 2017, we have our client's firm instructions to commence legal proceedings against your insured.

All our client's rights are reserved.

Best Regards

Beatrice Chiang Sing Hui 郑忻慧
Associate

NLC
LAW
ASIA

ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS
NOTARY PUBLIC

chiang.beatrice@nlclaw.com.sg

30 Cecil Street #11-04 Prudential Tower Singapore 049712
Tel +65 6236 5759 (DID) Fax +65 6538 8580

www.nlclaw.com.sg

NLC Law Asia LLC (Registration/UEN No. 201334024D) is a limited liability company registered in Singapore. A list of the Directors and their professional qualifications may be inspected at the address specified above.

CONFIDENTIALITY CAUTION : This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by return email and delete the original message. Thank you.

From: Beatrice Chiang [<mailto:chiang.beatrice@nlclaw.com.sg>]

Sent: Wednesday, December 27, 2017 9:15 AM

To: Karen Tan

Cc: LKK Auto Consultants Pte Ltd (sur@lkkauto.com); Ng Lip Chih; yu.rachel@nlclaw.com.sg

Subject: [Spam] Re: CLAIMANT: QUEK SUAN KIAT & CHUA BIN HWEE - ACCIDENT INVOLVING SU999H AND SHA3476R ON 20.03.2017 - FCI REF: D17/3110/TPD&TPI/KT YR REF: NLC/LLC/17.0163

WITHOUT PREJUDICE SAVE AS TO COSTS

Dear Sirs,

We refer to your email below.

To date, we have not heard from you and/or your surveyors as regards the re-inspection of SU999H and your position as regards our client's demand for the repayment of the sum of S\$46,218.75 set out in our email of 6 December 2017.

Please let us know if you wish to conduct a re-inspection of SU999H and your position as regards our client's demand for the sum of S\$46,218.75 set out in our email of 6 December 2017 within **3 days hereof**.

All our client's rights are reserved.

Best Regards

Beatrice Chiang Sing Hui 郑忻慧

Associate



chiang.beatrice@nlclaw.com.sg

30 Cecil Street #11-04 Prudential Tower Singapore 049712

Tel +65 6236 5918 (DID) Fax +65 6538 8580

www.nlclaw.com.sg

NLC Law Asia LLC (Registration/UEN No. 201334024D) is a limited liability company registered in Singapore. A list of the Directors and their professional qualifications may be inspected at the address specified above.

CONFIDENTIALITY CAUTION : This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by return email and delete the original message. Thank you.

On 6 Dec 2017, at 2:10 PM, Karen Tan <karentan@first-insurance.com.sg> wrote:

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

Dear Sirs,

We refer to the captioned matter.

Kindly arrange for a Re-inspection of SU999H with the third party solicitors, M/s NLC Law Asia soonest.

Best Regards,

Karen Tan

Motor Claims Dept.

First Capital Insurance Ltd | A FAIRFAX Company

36 Robinson Road #16-01 City House | Singapore 068877 | Reg. No. 195000106C

D: 6507 3582 | M: 6507 3848 | F: 6507 3849

W: www.first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Beatrice Chiang [<mailto:chiang.beatrice@nlclaw.com.sg>]

Sent: Wednesday, 6 December, 2017 2:48 PM

To: Karen Tan <karentan@first-insurance.com.sg>

Cc: 'Ng Lip Chih' <ng.lipchih@fnqlaw.com>

Subject: RE: CLAIMANT: QUEK SUAN KIAT & CHUA BIN HWEE - ACCIDENT INVOLVING SU999H AND SHA3476R ON 20.03.2017 - FCI REF: D17/3110/TPD&TPI/KT YR REF: NLC/LLC/17.0163

WITHOUT PREJUDICE SAVE AS TO COSTS

Dear Sirs,

We refer to your email below.

Apart from a bald statement that the "*costs of repair and general damages are too high*", you have not furnished any particulars to support the assertion that our client's "*costs of repair and general damages are too high*". We note that your position that our client's "*costs of repair and general damages are too high*" is in fact contradicted by your surveyor's own survey report, stating that if our client's car (SU 999H) (the "Car") was to be repaired, the fair and reasonable repair costs of the Car is in the sum of S\$61,924.90.

As you would no doubt be aware, it is our client's choice on whether to proceed with the repair of the Car in order to retain the Car beyond its first Certificate of Entitlement ("**COE**") period (i.e 10 years). Our client's intention to retain the Car for a period of more than 10 years is evidenced by the fact that he proceeded to renew the COE on 26 October 2017. A copy of the receipt for the renewal of the COE for the Car issued by the Land Transport Authority dated 26 October 2017 was attached in our email dated 28 November 2017 at 10.16 pm.

By virtue of the above, there is simply no basis for you to assert that the Car's "*costs of repair and general damages are too high*". We also do not see any reason for a re-inspection of the Car as it does not help to evaluate the present matter. You would no doubt be also aware that our client's repair costs is supported by a survey report of a qualified surveyor. A copy of our client's surveyor report has been forwarded to you earlier. We note that you have to date not raise any issues with

our client's surveyor report. Be that as it may, if you insist on inspecting the Car, please let us know your proposed date and time for the re-inspection of the Car so that we may proceed to liaise with our client as regards his availability on the proposed date and time for the re-inspection of the Car.

Please note that it is our client's every intention to claim back the full amount of S\$ 46,218.75, being the various costs incurred by our client as a result of the wrongful tortious acts of your insured. We have firm instructions from our client that he will not accept any amount lesser than the sum of S\$46,218.75 and will proceed with legal proceedings against your insured if full settlement is not received.

Please let us hear from you within five (5) days hereof.

Best Regards

Beatrice Chiang Sing Hui 郑忻慧
Associate

<image001.jpg>

chiang.beatrice@nlclaw.com.sg

30 Cecil Street #11-04 Prudential Tower Singapore 049712
Tel +65 6236 5759 (DID) Fax +65 6538 8580

www.nlclaw.com.sg

NLC Law Asia LLC (Registration/UEN No. 201334024D) is a limited liability company registered in Singapore. A list of the Directors and their professional qualifications may be inspected at the address specified above.

CONFIDENTIALITY CAUTION : This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by return email and delete the original message. Thank you.

From: Karen Tan [<mailto:karentan@first-insurance.com.sg>]

Sent: Friday, 1 December 2017 12:26 PM

To: chiang.beatrice@nlclaw.com.sg

Cc: 'Ng Lip Chih' <ng.lipchih@fnqlaw.com>

Subject: CLAIMANT: QUEK SUAN KIAT & CHUA BIN HWEE - ACCIDENT INVOLVING SU999H AND SHA3476R ON 20.03.2017 - FCI REF: D17/3110/TPD&TPI/KT YR REF: NLC/LLC/17.0163

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sirs,

We refer to your email dated 28.11.2017.

Your client's claim for the costs of repair and general damages are too high.

Strictly for the purpose to settle this amicably, we are prepared to revise our offer to a global sum of **\$17,000.00** all-in.

Kindly revert with your client's acceptance within 7 days. If your client still reject our offer, we would like to carry out a re-inspection. Please advise the date, time, venue and person to contact at least 7 working days in advance of the appointment.

Best Regards,

Karen Tan

Motor Claims Dept.

First Capital Insurance Ltd | A FAIRFAX Company

36 Robinson Road #16-01 City House | Singapore 068877 | Reg. No. 195000106C

D: 6507 3582 | M: 6507 3848 | F: 6507 3849

W: www.first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: chiang.beatrice@nlclaw.com.sg [mailto:chiang.beatrice@nlclaw.com.sg]

Sent: Tuesday, 28 November, 2017 10:16 PM

To: Karen Tan <karentan@first-insurance.com.sg>

Cc: 'Ng Lip Chih' <ng.lipchih@fnqlaw.com>

Subject: RE: CLAIMANT: QUEK SUAN KIAT & CHUA BIN HWEE - ACCIDENT INVOLVING SU999H AND SHA3476R ON 20.03.2017 - FCI REF: D17/3110/TPD&TPI/KT YR REF: NLC/LLC/17.0163

WITHOUT PREJUDICE SAVE AS TO COSTS

Dear Sirs,

We refer to your email to us dated 20 November 2017 (the "Email").

Our client instructs that he rejects your offer to settle in the sum of S\$14,994.60 set out in the Email and expects to be reimbursed in full (i.e in the sum of S\$46,218.75).

We wish to inform you that if our client had opted to repair vehicle number SU999H (the "Car") at Performance Motors Limited, he would have incurred a repair costs in the sum of S\$82,311.89. In mitigation, our client has instead opted to repair the Car at an alternative workshop at a substantially lower cost of S\$27,436.00. Further to the above, you will note that the car is severely underused with an odometer reading of 72291 km. Our client had every intention of renewing the Car's Certificate Of Entitlement (the "COE"). In this regard, please be informed that our client has renewed the COE for the Car on 26 October 2017. A copy of the receipt for the renewal of the COE for the Car issued by the Land Transport Authority dated 26 October 2017 is attached for your reference.

In view of the above, your offer of S\$14,994.60 is clearly unreasonable as our client has taken all possible and/or necessary steps to minimise his repair costs to your insured. We are surprised that

you have even seen it fit to propose a sum of S\$14,994.60 in full and final settlement of our client's claim.

TAKE NOTICE that we have firm instructions from our client to claim the full amount of S\$46,218.75, failing which we have instructions to proceed with legal proceedings against your insured.

Please let us hear from you within three (3) days hereof.

Best Regards

Beatrice Chiang Sing Hui 郑忻慧
Associate

<image001.jpg>

chiang.beatrice@nlclaw.com.sg

30 Cecil Street #11-04 Prudential Tower Singapore 049712
Tel +65 6236 5759 (DID) Fax +65 6538 8580

www.nlclaw.com.sg

NLC Law Asia LLC (Registration/UEN No. 201334024D) is a limited liability company registered in Singapore. A list of the Directors and their professional qualifications may be inspected at the address specified above.

CONFIDENTIALITY CAUTION : This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by return email and delete the original message. Thank you.

From: Karen Tan [<mailto:karentan@first-insurance.com.sg>]
Sent: Monday, 20 November 2017 11:01 AM
To: 'chiang.beatrice@nlclaw.com.sg' <chiang.beatrice@nlclaw.com.sg>
Subject: CLAIMANT: QUEK SUAN KIAT & CHUA BIN HWEE - ACCIDENT INVOLVING SU999H AND SHA3476R ON 20.03.2017 - FCI REF: D17/3110/TPD&TPI/KT YR REF: NLC/LLC/17.0163

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sirs,

We refer to your letter dated 27.10.2017.

Without prejudice and admission of liability, we are prepared to settle this claim as follows:

General damages	1,000.00
-----------------	----------

Cost of repairs (Not economical to repair - attached our surveyor's report)	10,567.00
Loss of use (10days x \$120/day)	1,200.00
Survey report fee	727.60
LTA/GIA/PR fees	Subject to proof
Costs incl Disbs	1,500.00
Total:	14,994.60

Kindly confirm acceptance to enable us to proceed further.

Best Regards,

Karen Tan

Motor Claims Dept.

First Capital Insurance Ltd | A FAIRFAX Company

36 Robinson Road #16-01 City House | Singapore 068877 | Reg. No. 195000106C

D: 6507 3582 | M: 6507 3848 | F: 6507 3849

W: www.first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.



Virus-free. www.avast.com

FormTeam Consultancy Pte Ltd

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference : TP17-060025/FP/bb

Your Reference: -

Date: **30-Aug-17**

TO : Quek Suan Kiat
14 Cornwall Gardens
Singapore 269642

Assessment of Vehicle No : SU 999H
Date of Accident : 20-March-2017
Date of Inspection : 22-June-2017

We have carried out a physical assessment of SU 999H at M/S Cyber Cars Service Centre Pte Ltd according to your instructions on 22-June-2017 and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No. : SU 999H
Make & Model : BMW 335i
Year of Registration : 2007
Engine Capacity (cc) : 2979
Chassis No. : WBAWL72000JZ95622
Engine No. : 09486684N54B30A
Colour : Beige
Mileage (km) : 72291

2. VEHICLE CONDITION

Body Paint : Good
Steering : Affected
Foot Brake : Serviceable
Parking Brake : Serviceable

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size : Michelin 255/40 R18 - 70%
LH Make/Size : Michelin 255/40 R18 - 70%

Rear

RH Make/Size : Michelin 255/35 R18 - 70%
LH Make/Size : Michelin 255/35 R18 - 70%

Note : % denotes the remaining percentage of the tyre


FormTeam Consultancy Pte Ltd

Our Reference : TP17-060025/FP/bb
Your Reference : -
Vehicle Number : SU 999H

Page No. 2

4. DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **N/S Front & N/S Rear portion**. Please see attached scheduled for details.



5. REMARKS

Market Value : Na
Salvage Value : Na
Repair Limit : Na

Estimated Amount : \$37,316.00
Adjusted Amount : \$27,436.00
Estimated Repair Days : 24 days

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by

FormTeam Consultancy Pte Ltd for any reliance on this report by any third party, unless with the permission of the addressee.

FormTeam Consultancy Pte Ltd

Our Reference : TP17-060025/FP/bb
 Your Reference : -
 Vehicle Number : SU 999H

reuse
↓
not changed

Page No. 3

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
<u>PARTS (LIST ITEMS)</u>				
1	Front Left Xenon Headlamp Part No. 63117182585 ✓	Broken	2,188.00	2,188.00
1	Front Left Control Unit Xenon Light ✓	Broken	847.00	847.00
1	Front Left Xenon Bulb ✓	Broken	373.00	373.00
2	Front Bonnet Twist Protection @ \$8.00 ✓	Necessary	16.00	16.00
1	Front Bonnet Hood Catch	Reuse	38.00	-
1	Front Catch Bracket	Repair	24.00	-
1	Lock F Hood	Repair	115.00	-
1	Bowden Cable, Hood Mechanism	Reuse	33.00	-
1	Rear Bowden Cable	Reuse	33.00	-
1	Front Bonnet Part No. 41617168514 ✓	Buckled/Badly Dented	1,400.00	1,400.00
1	Ball Pin	Reuse	37.00	-
1	Gas Pressurized Spring	Reuse	102.00	-
1	Rear Engine Hood Sealing	Reuse	22.00	-
1	Front Left Engine Bonnet Upper Part Of Seal	Reuse	13.00	-
1	Front Left Lower Section Seal Of Engine Hood	Reuse	13.00	-
1	Rear Sealing, Engine Compartment Laternal	Reuse	9.00	-
1	Front Sealing, Engine Compartment Laternal	Reuse	9.00	-
1	Front Left Stopper	Reuse	10.00	-
1	Front Left Wheel Housing Cover	Torn	111.00	111.00
1	Expanding Rivet	Necessary	3.00	3.00
1	Front Left Cover For Reinforcement	Torn	76.00	76.00
1	Front Left Bottom Cover, Wheel Housing	Torn	111.00	111.00
1	N/S Under Cover	Torn	13.00	13.00
1	Front Left Track Arm With Hydraulic Mount	Bent	206.00	206.00
1	Front Left Lower Arm	Bent	203.00	203.00
1	Heat Resistant Plate	Repair	61.00	-

FormTeam Consultancy Pte Ltd

Our Reference : TP17-060025/FP/bb
 Your Reference : -
 Vehicle Number : SU 999H

Page No. 4

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
1	Repair Kit For Anti-Roll Bar Links	Bent	149.00	149.00
1	Repair Kit For Stabilizer Rubber Bushing	Reuse	58.00	-
1	Level Sensor	Reuse	177.00	-
1	Front Left Ride Height Sensor Bracket	Reuse	18.00	-
1	Regulating Rod	Reuse	19.00	-
1	Front Left Side Bracket, Regulating Rod	Reuse	19.00	-
1	Driver's Side Airbag Module	Activated	1,388.00	1,388.00
1	Control Unit, Active Steering	Necessary	1,706.00	1,706.00
1	Front Left Side Panel	Torn	665.00	665.00
1	Front Left Absorber	Bent	459.00	459.00
1	Front Left Carrier	Bent	394.00	394.00
1	Front Wheel Hub With Bearing	Warped	466.00	466.00
1	Front Left Tie Rod	Bent	275.00	275.00
1	Hydro Steering Rack & Pinion	Reuse	4,830.00	-
1	Front Left Guide Support	Cracked	195.00	195.00
1	Front Left Upper Spring Pad	Necessary	7.00	7.00
1	Front Left Protection Tube	Necessary	9.00	9.00
1	Front Left Lower Spring Pad	Necessary	7.00	7.00
2	4 Front PDC Sensor @ \$363.00	Torn	1,452.00	1,452.00
1	Fan Housing With Fan	Reuse	1,162.00	-
1	Fan Shroud	Reuse	255.00	-
1	Bracket Frame	Reuse	13.00	-
1	Radiator Assembly Part No. 17117558480	Bent	655.00	655.00
1	Module Carrier Part No. 17107524912	Necessary	53.00	53.00
1	Module Carrier Part No. 17107524914	Necessary	53.00	53.00
1	Front Cover, Bumper	Torn	988.00	988.00
1	Front Left Partially Open Grid Chrome	Cracked	49.00	49.00
1	Front Left Partially Open Grid	Cracked	55.00	55.00
1	Front Left Covering	Cracked	34.00	34.00
1	Front Right Covering	Necessary	34.00	34.00
1	Licence Plate Base	Reuse	63.00	-
1	Front Flap O/S Towing Eye, Part No. 51110034	Reuse	31.00	-

FormTeam Consultancy Pte Ltd

Our Reference : TP17-060025/FP/bb
 Your Reference : -
 Vehicle Number : SU 999H

Page No. 5

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
1	Front Left Side Bumper Guide	Necessary	15.00	15.00
1	Front Left Bumper Chrome Centre Grille	Broken	108.00	108.00
1	Front Right Bumper Chrome Centre Grille	Reuse	108.00	-
1	Front Left Headlamp Washer Cover	Torn	35.00	35.00
1	Front Left Headlamp Washer Cover	Torn	35.00	35.00
1	Front Left Headlamp Nozzle	Torn	142.00	142.00
1	Front Left Headlamp Nozzle Pipe	Torn	49.00	49.00
1	Front Bumper Reinforcement	Bent	537.00	537.00
1	Front Left Side Skirt	Deformed	298.00	298.00
1	Rear Left Side Fender	Buckled	1,614.00	1,614.00
1	Michelin Front Left RSC Tyre 225/40 R18	Cut/Torn	390.00	312.00
1	LH Front Wheel Rim	Bent/Distorted	650.00	650.00
1	LH Rear Wheel Rim	Repair	650.00	200.00
1	Front Support Panel	Buckled	645.00	645.00
1	Front Support Panel Air Guide	Cracked	189.00	189.00
1	Front Left Headlight Lower Panel	Distorted	98.00	98.00
1	Headlamp Lock Plate	Bent	60.00	60.00
1	Underhood Shield	Reuse	450.00	-
1	Front Left headlight Support Cover	Cracked	24.00	24.00
1	Right Safety Belt Tensioner	Jammed	290.00	290.00
1	Positive Safety Cable	Failed	480.00	480.00
2	Boot Bump Stop @ \$45.00	Not Consistent	90.00	-
1	Top Hose	Deformed	150.00	150.00
1	Heater Hose	Deformed	90.00	90.00
1	Coolant One Bottle	Necessary	18.00	18.00
1	Front Right Headlamp Washer Nozzle	Cracked	142.00	142.00
1	Aircon Blower And Resistor	Not Consistent	580.00	-
1	Steering Wheel	Bent/Warped	1,300.00	X 1,300.00
1	Front Left Headlight Active Control Unit	Missing	435.00	435.00
			31,476.00	22,556.00
		Less Discount :	0% -	0% -
		Parts Total :	31,476.00	22,556.00

19875

FormTeam Consultancy Pte Ltd

Our Reference : TP17-060025/FP/bb
 Your Reference : -
 Vehicle Number : SU 999H

Page No. 6

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
LABOUR			
1	Knock and spray paint and labour to replace all the accident damaged portion.	4,800.00	3000 4,000.00
2	Performed wheels alignment.	120.00	100.00
3	Tow car fee.	120.00	100.00
4	To remove, refix aircon condenser, and recharged gas.	150.00	120.00
5	To reprogramme and diagnose.	450.00	300 400.00
6	To rewire front portion and refocus headlamp beam.	50.00	40.00
7	To apply underseal.	150.00	120.00
Labour Total :		5,840.00	3780 4,880.00
TOTAL (PARTS & LABOUR) :		37,316.00	27,436.00


Note : (For Part By Part Repair)

The workshop has agreed to undertake the repair at our adjusted amount of

\$27,436.00

(SINGAPORE DOLLARS TWENTY SEVEN THOUSAND FOUR HUNDRED AND THIRTY SIX ONLY)

23,655
20 days



Frankie Pang
 AMSAE (AUST), AMIRTE, AMSOE
 MASPACI, MSAAA
 Licensed Appraiser

**CYBER CARS SERVICE CENTRE PTE LTD**

548 Havelock Road Singapore 169637
Tel : +65 6836 1238 Fax : + 65 6836 9657
Company Registration No: 200703545K
GST Registration No: 200703545K
ISO 9001:2008 Cert No. 2012-2-2118

TAX INVOICE No. 114389Date **30-06-2017**Registration No **SU999H**Model **BMW 335 i**

M/S Mr Quek Ph:96180600

No	Description	Unit Price (S\$)	Qty	Total (S\$)
1	Front left xenon headlamp part no. 63117182585	2188.00	1.0	2188.00
2	Front left control unit xenon light	847.00	1.0	847.00
3	Front left xenon bulb	373.00	1.0	373.00
4	Front left headlight active control unit	435.00	1.0	435.00
5	Front bonnet part no. 4161716854	1400.00	1.0	1400.00
6	Front left wheel housing cover	111.00	1.0	111.00
7	Expanding rivet	3.00	1.0	3.00
8	Front left cover for reinforcement	76.00	1.0	76.00
9	Front left bottom cover,wheel housing	111.00	1.0	111.00
10	N/S under cover	13.00	1.0	13.00
11	Front left track arm with hydraulic	206.00	1.0	206.00
12	Front left lower arm	203.00	1.0	203.00
13	Repair kit for anti roll bar links	149.00	1.0	149.00
14	Driver's side airbag module	1388.00	1.0	1388.00
15	Control unit,active steering	1706.00	1.0	1706.00
Total Amount (Without GST) (S\$)				9209.00
GST 7% (S\$)				644.63
Total Amount (S\$)				9853.63

Remarks: Page 1

Received by:

This is system generated invoice.
No signature is required.

**CYBER CARS SERVICE CENTRE PTE LTD**

548 Havelock Road Singapore 169637
Tel : +65 6836 1238 Fax : + 65 6836 9657
Company Registration No: 200703545K
GST Registration No: 200703545K
ISO 9001:2008 Cert No. 2012-2-2118

TAX INVOICE No. 114594

Date 30-06-2017

Registration No SU999H

Model BMW 335 i


MIS Mr Quek Ph:96180600

No	Description	Unit Price (S\$)	Qty	Total (S\$)
1	Front left side panel	665.00	1.0	665.00
2	Front left absorber	459.00	1.0	459.00
3	Front left carriage	394.00	1.0	394.00
4	Front wheel hub with bearing	466.00	1.0	466.00
5	Front left tie rod	275.00	1.0	275.00
6	Front left guide support	195.00	1.0	195.00
7	front left upper spring pad	7.00	1.0	7.00
8	Front left protection tube	9.00	1.0	9.00
9	Front left lower spring pad	7.00	1.0	7.00
10	Front PDC sensor	363.00	4.0	1452.00
11	Radiator assembly	655.00	1.0	655.00
12	Module carrier Part No.17107524912	53.00	1.0	53.00
13	Module carrier Part No.17107524914	53.00	1.0	53.00
14	Front rim cover, bumper	988.00	1.0	988.00
15	Front left partially open grid	49.00	1.0	49.00
Total Amount (Without GST) (S\$)				5727.00
GST 7% (S\$)				400.89
Total Amount (S\$)				6127.89

Remarks: Page 2
Mechanic: CCP-M

Received by:

This is system generated invoice.
No signature is required.

**CYBER CARS SERVICE CENTRE PTE LTD**

548 Havelock Road Singapore 169637
Tel : +65 6836 1238 Fax : + 65 6836 9657
Company Registration No: 200703545K
GST Registration No: 200703545K
ISO 9001:2008 Cert No. 2012-2-2118

TAX INVOICE No. 114617

Date 30-06-2017

Registration No SU999H

Model BMW 335 i

MIS Mr Quek Ph:96180600

No	Description	Unit Price (S\$)	Qty	Total (S\$)
1	Front left partially open grid	55.00	1.0	55.00
2	Front left covering	34.00	1.0	34.00
3	Front right covering	34.00	1.0	34.00
4	Front left side bumper guide	15.00	1.0	15.00
5	Front left bumper chrome centre grille	108.00	1.0	108.00
6	Front left headlamp washer cover	35.00	1.0	35.00
7	Front left headlamp washer cover	35.00	1.0	35.00
8	Front left headlamp nozzle	142.00	1.0	142.00
9	Front left headlamp nozzle pipe	49.00	1.0	49.00
10	Front bumper reinforcement	537.00	1.0	537.00
11	Front left side skirt	298.00	1.0	298.00
12	Rear left side fender	1614.00	1.0	1614.00
13	Michelin front left RSC tyre 225/40R18 1pcs	312.00	1.0	312.00
14	Front left wheel rim	650.00	1.0	650.00
15	Steering wheel	1300.00	1.0	1300.00
Total Amount (Without GST) (S\$)				5218.00
GST 7% (S\$)				365.26
Total Amount (S\$)				5583.26

Remarks: Page 3

Received by:

This is system generated invoice.
No signature is required.

**CYBER CARS SERVICE CENTRE PTE LTD**

548 Havelock Road Singapore 169637
Tel : +65 6836 1238 Fax : + 65 6836 9657
Company Registration No: 200703545K
GST Registration No: 200703545K
ISO 9001:2008 Cert No. 2012-2-2118

TAX INVOICE No. 115001

Date 30-06-2017

Registration No SU999H

Model BMW 335i

M/S Mr Quek Ph:96180600

No	Description	Unit Price (S\$)	Qty	Total (S\$)
1	Rear left wheel rim	200.00	1.0	200.00
2	Support panel	645.00	1.0	645.00
3	Support panel air guide	189.00	1.0	189.00
4	Front left headlight lower panel	98.00	1.0	98.00
5	Lock plate	60.00	1.0	60.00
6	Front left headlight support cover	24.00	1.0	24.00
7	Right safety belt tensioner	290.00	1.0	290.00
8	Positive safety cable	480.00	1.0	480.00
9	Top hose	150.00	1.0	150.00
10	Heater hose	90.00	1.0	90.00
11	Coolant one bottle	18.00	1.0	18.00
12	Front right headlamp washer nozzle	142.00	1.0	142.00
13	Front bonnet twist protection - 2 pcs	8.00	2.0	16.00
14	Knock and spray paint and labour to replace all the accident damaged portion.	4000.00	1.0	4000.00
15	Perform wheels alignment	100.00	1.0	100.00
Total Amount (Without GST) (S\$)				6502.00
GST 7% (S\$)				455.14
Total Amount (S\$)				6957.14

Remarks: Page 4

Received by:

This is system generated invoice.
No signature is required.

**CYBER CARS SERVICE CENTRE PTE LTD**

548 Havelock Road Singapore 169637
Tel : +65 6836 1238 Fax : + 65 6836 9657
Company Registration No: 200703545K
GST Registration No: 200703545K
ISO 9001:2008 Cert No. 2012-2-2118

TAX INVOICE No. 115002
Date 30-06-2017
Registration No SU999H
Model BMW 335 i

MIS Mr Quek Ph:96180600

No	Description	Unit Price (S\$)	Qty	Total (S\$)
1	To reprogramme and diagnose	400.00	1.0	400.00
2	To rewire front portion and refocus headlamp beam	40.00	1.0	40.00
3	To apply underseal	120.00	1.0	120.00
4	To remove, refix aircon condenser, and recharged gas	120.00	1.0	120.00
5	Tow car fee	100.00	1.0	100.00
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
Total Amount (Without GST) (S\$)				780.00
GST 7% (S\$)				54.60
Total Amount (S\$)				834.60

Remarks: Page 5

Received by:

This is system generated invoice.
No signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17005871/T1vbn2-1		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-02-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3476R	Veh. Inspected	SU 999H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17/3110/TPD&TPI/KT	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	01/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	BMW 335I	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	WBAWL72000JZ95622	Colour	BEIGE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/40 R18	MICHELIN	6 mm	
L/H Front Tyre	255/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	255/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	255/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	20/03/2017	Inspection Date	09/01/2018	
Survey held at	14 CORNWALL GARDENS			
Repairer	CYBER CARS SERVICE CENTRE PTE LTD (HQ)			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		20 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SU 999H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT LEFT XENON HEADLAMP PART NO 63117182585	REPLACED	2,188.00	2,188.00
1	FRONT LEFT CONTROL UNIT XENON LIGHT	REPLACED	847.00	847.00
1	FRONT LEFT XENON BULB	REPLACED	373.00	373.00
2	FRONT BONNET TWIST PROTECTION @\$8.00	REPLACED	16.00	16.00
1	FRONT BONNET HOOD CATCH	NOT CHANGED	38.00	-
1	FRONT CATCH BRACKET	REPAIRED SEE LABOUR	24.00	-
1	LOCK F HOOD	REPAIRED SEE LABOUR	115.00	-
1	BOWDEN CABLE,HOOD MECHANISM	NOT CHANGED	33.00	-
1	REAR BOWDEN CABLE	NOT CHANGED	33.00	-
1	FRONT BONNET PART NO 41617168514	REPLACED	1,400.00	1,400.00
1	BALL PIN	NOT CHANGED	37.00	-
1	GAS PRESSURIZED SPRING	NOT CHANGED	102.00	-
1	REAR ENGINE HOOD SEALING	NOT CHANGED	22.00	-
1	FRONT LEFT ENGINE BONNET UPPER PART OF SEAL	NOT CHANGED	13.00	-
1	FRONT LEFT LOWER SECTION SEAL OF ENGINE HOOD	NOT CHANGED	13.00	-
1	REAR SEALING,ENGINE COMPARTMENT LATERAL	NOT CHANGED	9.00	-
1	FRONT SEALING,ENGINE COMPARTMENT LATERAL	NOT CHANGED	9.00	-
1	FRONT LEFT STOPPER	NOT CHANGED	10.00	-
1	FRONT LEFT WHEEL HOUSING COVER	REPLACED	111.00	111.00
1	EXPANDING RIVET	REPLACED	3.00	3.00
1	FRONT LEFT COVER FOR REINFORCEMENT	REPLACED	76.00	76.00
1	FRONT LEFT BOTTOM COVER,WHEEL HOUSING	REPLACED	111.00	111.00
1	N/S UNDER COVER	REPLACED	13.00	13.00
1	FRONT LEFT TRACK ARM WITH HYDRAULIC MOUNT	REPLACED	206.00	206.00
1	FRONTL LEFT LOWER ARM	REPLACED	203.00	203.00
1	HEAT RESISTANT PLATE	REPAIRED SEE LABOUR	61.00	-
1	REPAIR KIT FOR ANTI-ROLL BAR LINKS	REPLACED	149.00	149.00
1	REPAIR KIT FOR STABILIZER RUBBER BUSHING	NOT CHANGED	58.00	-
1	LEVEL SENSOR	NOT CHANGED	177.00	-

Report Ref No. CS/FC117005871/T1vbn2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LEFT RIDE HEIGHT SENSOR BRACKET	NOT CHANGED	18.00	-
1	REGULATING ROD	NOT CHANGED	19.00	-
1	FRONT LEFT SIDE BRACKET,REGULATING ROD	NOT CHANGED	19.00	-
1	CONTROL UNIT,ACTIVE STEERING	REPLACED	1,706.00	1,706.00
1	FRONT LEFT SIDE PANEL	REPLACED	665.00	665.00
1	FRONT LEFT ABSORBER	REPLACED	459.00	459.00
1	FRONT LEFT CARRIER	REPLACED	394.00	394.00
1	FRONT WHEEL HUB WITH BEARING	REPLACED	466.00	466.00
1	FRONT LEFT TIE ROD	REPLACED	275.00	275.00
1	HYDRO STEERING RACK & PINION	NOT CHANGED	4,830.00	-
1	FRONT LEFT GUIDE SUPPORT	REPLACED	195.00	195.00
1	FRONT LEFT UPPER SPRING PAD	REPLACED	7.00	7.00
1	FRONT LEFT PROTECTION TUBE	REPLACED	9.00	9.00
1	FRONT LEFT LOWER SPRING PAD	REPLACED	7.00	7.00
4	FRONT PDC SENSOR @\$363.00	REPLACED (2 PCS ONLY)	1,452.00	726.00
1	FAN HOUSING WITH FAN	NOT CHANGED	1,162.00	-
1	FAN SHROUD	NOT CHANGED	255.00	-
1	BRACKET FRAME	NOT CHANGED	13.00	-
1	RADIATOR ASSEMBLY PART NO 17117558480	NOT NECESSARY	655.00	-
1	MODULE CARRIER PART NO 17107524912	REPLACED	53.00	53.00
1	MODULE CARRIER PART NO 17107524914	REPLACED	53.00	53.00
1	FRONT COVER,BUMPER	REPLACED	988.00	988.00
1	FRONT LEFT PARTIALLY OPEN GRID CHROME	REPLACED	49.00	49.00
1	FRONT LEFT PARTIALLY OPEN GRID	REPLACED	55.00	55.00
1	FRONT LEFT COVERING	REPLACED	34.00	34.00
1	FRONT RIGHT COVERING	REPLACED	34.00	34.00
1	LICENCE PLATE BASE	NOT CHANGED	63.00	-
1	FRONT FLAP O/S TOWING EYE,PART NO 51110034	NOT CHANGED	31.00	-
1	FRONT LEFT SIDE BUMPER GUIDE	REPLACED	15.00	15.00
1	FRONT LEFT BUMPER CHROME CENTRE GRILLE	REPLACED	108.00	108.00
1	FRONT RIGHT BUMPER CHROME CENTRE GRILLE	NOT CHANGED	108.00	-
1	FRONT LEFT HEADLAMP WASHER COVER	REPLACED	35.00	35.00

Report Ref No. CS/FC117005871/T1vbn2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LEFT HEADLAMP WASHER COVER	REPLACED	35.00	35.00
1	FRONT LEFT HEADLAMP NOZZLE	REPLACED	142.00	142.00
1	FRONT LEFT HEADLAMP NOZZLE PIPE	REPLACED	49.00	49.00
1	FRONT BUMPER REINFORCEMENT	REPLACED	537.00	537.00
1	FRONT LEFT SIDE SKIRT	REPLACED	298.00	298.00
1	REAR LEFT SIDE FENDER	REPLACED	1,614.00	1,614.00
1	MICHELIN FRONT LEFT RSC TYRE 225/40 R18	REPLACED	390.00	312.00
1	LH FRONT WHEEL RIM	REPLACED	650.00	650.00
1	LH REAR WHEEL RIM	REPLACED	650.00	200.00
1	FRONT SUPPORT PANEL	REPLACED	645.00	645.00
1	FRONT SUPPORT PANEL AIR GUIDE	REPLACED	189.00	189.00
1	FRONT LEFT HEADLIGHT LOWER PANEL	REPLACED	98.00	98.00
1	HEADLAMP LOCK PLATE	REPLACED	60.00	60.00
1	UNDERHOOD SHIELD	NOT CHANGED	450.00	-
1	FRONT LEFT HEADLIGHT SUPPORT COVER	REPLACED	24.00	24.00
1	RIGHT SAFETY BELT TENSIONER	REPLACED	290.00	290.00
1	POSITIVE SAFETY CABLE	REPLACED	480.00	480.00
2	BOOT BUMO STOP @\$45.00	NOT CONSISTENT WITH THE IMPACT	90.00	-
1	TOP HOSE	REPLACED	150.00	150.00
1	HEATER HOSE	REPLACED	90.00	90.00
1	COOLANT ONE BOTTLE	REPLACED	18.00	18.00
1	FRONT RIGHT HEADLAMP WASHER NOZZLE	REPLACED	142.00	142.00
1	AIRCON BLOWER AND RESISTOR	NOT CONSISTENT WITH THE IMPACT	580.00	-
1	STEERING WHEEL	SERVICEABLE	1,300.00	-
1	FRONT LEFT HEADLIGHT ACTIVE CONTROL UNIT	REPLACED	435.00	435.00
1	DRIVER'S SIDE AIRBAG MODULE	REPLACED	1,388.00	1,388.00
			31,476.00	19,875.00
	LABOUR			
	KNOCK AND SPRAY PAINT AND LABOUR TO REPLACE ALL THE ACCIDENT DAMAGED PORTION.INCLUSIVE OF THE REPAIR OF FRONT CATCH BRACKET,LOCK F HOOD AND HEAT RESISTANT PLATE.		4,800.00	3,000.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PERFORMED WHEELS ALIGNMENT.		120.00	100.00
	TOW CAR FEE.		120.00	100.00
	TO REMOVE,REFIX AIRCON CONDENSER,AND RECHARGED GAS.		150.00	120.00
	TO REPROGRAMME AND DIAGNOSE.		450.00	300.00
	TO REWIRE FRONT PORTION AND REFOCUS HEADLAMP BEAM.		50.00	40.00
	TO APPLY UNDERSEAL.		150.00	120.00
			5,840.00	3,780.00
	GRAND TOTAL		37,316.00	23,655.00
RECOMMENDED COST OF REPAIRS				23,655.00

Report Ref No. CS/FCI17005871/T1vbn2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.