

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / W5 / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: \$1000
 (Client's Record)
 Make of Veh: _____

Veh No: SLN141K Yr Regn: 2017 April
 Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi A4 Sedan cc: 1395
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 12387 T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: WAUZZZF43HA121927
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: 205/60R16

/	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 148K
 IDAC Accident Rpt. Consistent?: Yes or No
 GIA / PR Seen: Consistent?: Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A.	D.O.I. <u>08/01/18</u>

 Survey held at Premium
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front N/S
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
OD AIG.
SLN 141K - X
all - alert via menmen
11/1 - 10:53am authorize repair by victor
11/1 - 11:02am email premium authorize \$1000

RECEIVED 29 MAY 2018

Part by part \$23,048.60 (Red- 33830.40; 59%)

Date/Time, File Pass to? : Prel. Report
29/5/18 : Final Report
 Case/Time, File Return to?
 Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 12
 Resurvey No. of Trip: 1
 Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech Insp (\$ _____)
 Weekend (\$ _____)
 Survey Fee: 200
 Transporter: _____
 F+R: \$ _____
 Procs: _____
 Other: 10
 Total: 210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18000459/Atb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 08-01-2018



Code : AIG

Policy Particulars :- OWN DAMAGE

1.	Insured Veh.	Veh. Inspected	SLN 141K
	Policy No. 2100507399	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	08/01/2018

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer	Steering	
	Brakes	Modification	
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.		
----	--	--

General Information

5.	Accident Date	05/01/2018	Inspection Date	08/01/2018
	Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699		

Remarks

5a.	A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)	
	B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.	

View Received Message

This mail is associated with :

***SLN141K (77138655755G)**

OO

Jan 5 2018 7:00AM

[WONG GEOK CHUN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 02/11/2018 15:13 PM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SLN141K - Claim Handler: Chan, Kian Meng

Maintained:Supplementary labour - To R & R front lock carrier not approval to take out.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Thursday, 10 January 2019 9:09 AM
To: Fong, Andy-SY
Cc: SUR
Subject: SLN141K / OD / 7713865575SG - Supplementary labour approval

Hi Andy,

Supplementary labour \$1250.00 to R & R front support to replace LH reinforcement bracket was initially rejected. Reason being it is deemed as unnecessary to perform and was counter check against the Audatex procedure. Now the repairer has insisted that the labour is necessary to perform without providing any documentation proof except for a few reinspection photos that they have R&R front support. Issue here is whether it is necessary to perform and if so whether the labour given was in excess? My opinion is that the procedure is not necessary and the bracket could be easily taken out by unbolting the four bolts that tighten the bracket, support panel and chassis member together.

For your review and approval.

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Repairer suggested that representatives from AIG to be present if there is a similar incident in the future, so that they can demonstrate and indicate the necessity of removing the lock carrier in order to replace the reinforcement bracket.

View Received Message

This mail is associated with :

***SLN141K (7713865575SG)**
OD
Jan 5 2018 7:00AM
[WONG GEOK CHUN]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 13/08/2018 17:28 PM.
To LKK_HQ
CC AIG_SG; Andy-SY.Fong@AIG.com
Subject Supplementary parts and labour.

Hi
Damage photos of LH sill panel for the supplementary labour? *112-116.*
Why does the Support panel need to to R & R for replacement of Reinforcement bracket? As check this operation is not necessary. *) See Photo*
Regards *107-108*
Victor Koh

DOCUMENTS SUMMARY
There are no documents.

Sill Panel 112-116.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 11 January 2018 11:02 AM
To: 'Claims Dept'; SUR
Subject: RE: SLN 141 K Own Damage Claims

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLN 141K (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Wednesday, 10 January 2018 9:49 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SLN 141 K Own Damage Claims

Dear Denise,

Kindly follow up with AIG for the approval urgently as the vehicle is awaiting approval before repairs.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 159902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 09 Jan 2018

Preliminary Advice

Vehicle No	: SLN141K	Accident Date	: 05/01/2018
Make	: AUDI A4	Policy No.	: 2100507399
Assignment Date	: 08/01/2018	Excess	: S\$0.00
Date of Inspection	: 08/01/2018	Est. Duration of Repair	: 8.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	52,510.00
Revised Amount	:S\$	20,908.00
Check Items (Estimated)	:S\$	20,627.00
Total	:S\$	41,535.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	148,000.00
COE / PARF Rebate	:S\$	70,650.00
Salvage Value	:S\$	
Margin for Repair	:S\$	77,350.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1381A
Vehicle Details	
Vehicle No.:	SLN141K
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CVN032231
Chassis No.:	WAUZZZF43HA121927
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,086.00
Original Registration Date:	19 Apr 2017
First Registration Date:	19 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$26,921.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Apr 2027
PARF Rebate Amount:	\$20,190.00
Intended COE Rebate Details	
COE Expiry Date:	18 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,405.00
COE Rebate Amount:	\$50,460.00
Total Rebate Amount:	\$70,650.00

The information contained herein is correct as at 09 Jan 2018

OK

View Received Message

This mail is associated with :

***SLN141K (77138655755G)**
OO
Jan 5 2018 7:00AM
[WONG GEOK CHUN]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 11/01/2018 10:53 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$20908.00) - SLN141K - Claim Handler: Chan, Kian Meng

Approved:20908.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/01/2018 10:02
Date Of Accident	05/01/2018 07:50
Exact Location Of Accident	JURONG WEST CENTRAL 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN141K
Insured/Policyholder	
Name Of Registered Owner	WONG GEOK CHUN
NRIC No	S1531381A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97285342
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	AUDI
Model	A4 1.4 TFSI S TRONIC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHNG JIANYAO, NICHOLAS
NRIC No	S9325472D
Date Of Birth	14/07/1993
Occupation	INDOOR
Date Of Driving Pass	12/08/2013
Driving Experience	4 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96378339
Fax Number	
Contact Number	
EMail Address	NCJY1993@GMAIL.COM

Address	BLK 71 JURONG WEST CENTRAL 3 #10-14
Postcode	648335
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

-

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	ROADSIDE FENCE
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: <u>SLN141K</u>	ACCIDENT DATE & TIME: <u>7:50 AM, 5 January 2018</u>
CONTACT NUMBER: <u>96378339 97295342 (Mom)</u>	E-MAIL ADDRESS: <u>ncjy1993@gmail.com</u>
LOCATION: <u>Jurong West Centre 3 #8 5 (649332)</u>	
<p><u>Car was turning out from carpark exit, and the car was not straightened.</u> <u>The car went over the curb and hit the fence on the side.</u></p>	
<p>NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION</p>	
Please state:	
<input checked="" type="checkbox"/> Claim Own Policy <input type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/PIN No.:



HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

COVER NOTE

Cover Note No. 2100507399		Date 17 Apr 2017	
The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder.			
SCHEDULE			
Policyholder	WONG GEOK CHUN		
Age Condition	All Age Condition	Registration No.	SLN 141 K
Policy	AUDI AUTO PROTECTOR <small>(INSURED NOT DRIVING POLICY)</small>	Make/Model	AUDI A4 1.4 TFSI S tronic
Effective Date	19 Apr 2017	CC/Contract	1,395.00
Expiry Date	18 Apr 2018	Engine No	GVN032231
Excess	S\$600.00	Chassis No	WAUZZZF43HA121927
		Year of Registration	2017
		Hire Purchase Company	United Overseas Bank Limited
<p>Any person other than the Insured who is named as a named driver under the policy.</p> <p>In addition to the Policy Excess, a Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00 (before GST) will apply to You or Your Authorised Driver who is below the age of 23 (in case of All Age Condition policies) and/or has less than 2 years' driving experience. The YIDR Excess is not applicable to Named Driver policies.</p> <p>Usage of vehicle only for the following purposes:</p> <ol style="list-style-type: none"> Use only for social, domestic and pleasure purposes and for the Policyholder's business. Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes. <p>Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.</p> <p>The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.</p>			
<p>MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)</p>			
CERTIFICATE OF INSURANCE			
I/We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)			

Issued in SINGAPORE

AIG Asia Pacific Insurance Pte. Ltd.

IMPORTANT NOTICE

THIS COVER NOTE IS VALID FOR 60 DAYS FROM THE FIRST DAY OF THE POLICY PERIOD. APPLICABLE TO CORPORATE POLICIES ONLY.

AUTHORISED REPRESENTATIVE

ORIGINAL

PHLLYY.


Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Driving License

REPUBLIC OF SINGAPORE

Identity Card No. S9325472D

CHING BAN YAN, NICHOLAS

18 Jul 1993

18 Aug 2003



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9325472D



CHING BAN YAN, NICHOLAS

姓名 陈 彬 彦

Sex

Chinese

Date of Birth

4-07-93

Country of Birth

SINGAPORE



REPUBLIC OF SINGAPORE

Identity Card No. S9325472D

CHING BAN YAN, NICHOLAS

18 Jul 1993

18 Aug 2003



REPUBLIC OF SINGAPORE

Identity Card No. S9325472D

CHING BAN YAN, NICHOLAS

18 Jul 1993

18 Aug 2003




Addendum Sheet Pg. 1

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MMAV18023UR Vehicle Registration No : S LN141K
Name(as shown in NRIC) : Wong Geok Chun
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : 91531381A
Address : _____
Contact (Tel) : 97285342 (H/P) : _____
(Email) : _____
Date of Accident : 05/01/18 Time of Accident : 07:50pm
Place of Accident : Jurong West Central
Insurance Company : A16

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

- typo error change date of accident to 05/01/18 instead of
05/01/17



Signature of Vehicle Owner / Driver
Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0024/2018/GW
Date : 6-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Wong Geok Chun
Address : Blk 71 Jurong West Central 3
#10-14
Singapore 648335
Telephone : HP +65 97285342
Type of Claim : Own Damage Claims
Policy No. : 2100507399
Vehicle No : **SLN 141 K**
Model Code : Audi A4 Sedan 1.4 TFSI S-tronic
Model / Year : Apr-17
Engine No : CVN 032231
Chassis No : WAUZZZF43HA121927
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Jan-18
Place of Accident : JURONG WEST CENTRAL 3

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 141 K.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlight, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To remove and transfer aircon condensor, radiator, additional radiator, electrical fans and control unit. Renew damaged aircon piping. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,400.00 ?	✓
3	To remove and transfer lhs front door's multi - lock system and power window devices.	S/N \$ 280.00 ✗	
4	To dismantle front bumper, lhs front fender, bonnet and lhs front door. Renew front lock carrier and align to position. Renew front bumper, lhs front fender, headlight and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 5,100.00	1750 ✓
5	To remove rhs front doont panel trim, renew rhs front door chrome molding	S/N \$ 300.00 ✗	
6	To respray front bumper, lhs front fender, bonnet, hinges and lhs front door.	\$ 3,500.00	2200 ✓
7	To suspend engine, dismantle front suspension assy. Inspect for damages and renew accordingly.	S/N \$ 2,800.00 ?	✗
8	To renew lhs front rim and tyre. Carry out wheel alignment	S/N \$ 280.00 ✓	✓
9	To carry out diagnostic check	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 14,212.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted.</i>	S 1,703.00	✓ 1362.40
2	FRONT BUMPER SECURING STRIP <i>Not New</i>	S 57.00	? X
3	FRONT BUMPER GRILLE - CENTER <i>could</i>	S 163.00	✓ 130
4	FRONT BUMPER CLOSING ELEMENT <i>could</i>	S 171.00	✓ 136.40
5	FRONT BUMPER AIR GUIDE - LH <i>missing</i>	S 67.00	✓ 52.96
6	RADIATOR GRILLE <i>could</i>	S 941.00	✓ 752.40
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Missing</i>	S 112.00	✓ 89.20
8	FRONT BUMPER GUIDE SECTION - LH <i>Repd</i>	S 29.00	✓ 26.08
9	FOAM FILLER PIECE <i>could</i>	S 101.00	✓ 80.80
10	FRONT BUMPER CARRIER <i>Best</i>	S 674.00	✓ 539.20
11	FRONT BUMPER SUPPORT - LH/RH <i>Repd could</i>	S 46.00	? 38.24
12	FRONT BUMPER LOCK CARRIER BRACKET <i>could</i>	S 112.00	? 94
13	FRONT BUMPER TOP COVER <i>could</i>	S 104.00	✓ 82.80
14	SIGN "CAUTION" <i>new</i>	S 12.00	✓ 9.04
15	STICKER FOR AIR CONDITIONER <i>new</i>	S 6.00	✓ 4.64
16	FRONT FENDER - LH <i>Distorted</i>	S 643.00	✓ 514.40
17	FRONT FENDER ATTACHEMENT PARTS - LH <i>Repd</i>	S 44.00	✓ 34.96
18	FRONT FENDER CLOSING ELEMENT - LH <i>Repd</i>	S 42.00	✓ 33.44
19	FRONT FENDER BRACKET - LH	S 29.00	✓ 23.20
20	FRONT FENDER BRACKET DEFORMATION - LH <i>Repd</i>	S 42.00	✓ 33.04
21	FRONT FENDER RETAINING BRACKET - LH <i>Repd</i>	S 27.00	✓ 20.96
22	FRONT FENDER BRACE - LH <i>Repd</i>	S 100.00	✓ 79.44
SUB - TOTAL SPARE PARTS CHARGES		S 5,225.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
23	FRONT STONE CHIP GUARD - LH <i>New B</i>	S	43.00	- 33 68
24	FRONT WHEEL SPOILER - LH <i>3 damaged</i>	S	61.00	? 50 16
25	FRONT BUMPER SPOILER - LH	S	29.00	? 23 92
26	FRONT WHEEL HOUSING LINER - LH <i>tone</i>	S	208.00	- 166
27	WHEEL HOUSING LINER ATTACHMENT PARTS <i>the</i>	S	76.00	? X
28	FRONT FENDER LINER LOWER COVER - LH <i>new</i>	S	12.00	? X
29	LED HEADLIGHT - LH <i>missing could</i>	S	7,861.00	✓ 6288.80
30	POWER MODULE FOR MAIN LIGHT ELECTRONIC? <i>new</i>	S	685.00	? X
31	CONTROL UNIT FOR LIGHT CONTROL SYSTEM <i>new</i>	S	634.00	? 525.60
32	DRAIN HOSE <i>new</i>	S	29.00	? X
33	HEADLIGHT COMPENSATING <i>3 damaged</i>	3 S	105.00	? 55 36
34	HEADLIGHT LIFT CYLINDER - LH <i>one</i>	S	180.00	? 147.20
35	HEADLIGHT LIFT CYLINDER BRACKET - LH <i>new</i>		TBC	? X
36	CORRUGATED PIPE - LH/RH <i>new 1H ut</i>	2 S	106.00	+ 6256 *
37	BONNET <i>new</i>	S	2,001.00	✓ 1600.80
38	BONNET ATTACHMENT PARTS <i>new</i>	S	103.00	? X
39	BONNET LID HINGE - LH/RH <i>new</i>	2 S	514.00	+ X
40	BONNET IMPACT PROTECTION <i>new</i>	3 S	69.00	✓ 54.48
41	FRONT FENDER LEDGE - LH <i>new</i>	2 S	43.00	? X
42	BONNET STRIKER - LH/RH <i>new</i>	2 S	86.00	X
TOTAL SPARE PARTS CHARGES			\$ 12,845.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
43	BONNET LID LOCK <i>Not nec</i>	2 S	360.00 + X
44	BONNET LOCK CARRIER WITH MOUNTING <i>Not nec</i>	S	878.00 * ? 5X
45	COOLANT REGULATOR SUPPORT <i>Repd</i>	S	64.00 ? 52.48
46	RADIATOR AIR GUIDE -LH <i>Not nec</i>	2 S	32.00 ? X
47	ADDITIONAL COOLER FOR COOLANT <i>Not nec</i>	S	444.00 ee 364
48	A/C CONDENSOR WITH FLUID RESERVOIR <i>Not nec</i>	S	525.00 ? >
49	RADIATOR <i>Not nec</i>	S	572.00 ? X
50	RUBBER BUSH <i>Not nec</i>	4 S	38.00 ? X
51	COOLANT CONCENTRATE - 1.5 LTR <i>Not nec</i>	S	132.00 ? X
52	RADIATOR FAN RING <i>Not nec</i>	S	222.00 ? Y
53	RADIATOR FAN WITH CONTROL UNIT <i>nec</i>	S	1,949.00 +.
54	COOLANT PIPE <i>Not nec</i>	2 S	346.00 ? X
55	HIGH NOTE HORN <i>nec</i>	S	35.00 +
56	HIGH NOTE HORN MOUNT BRACKET <i>nec</i>	S	24.00 +.
57	FRONT DOOR - LH <i>Byg</i>	S	1,855.00 +
58	FRONT OUTER DOOR SEAL - LH <i>nec</i>	S	167.00 +
59	BONDING AGENT <i>3 nec</i>	S	42.00 +
60	FRONT DOOR CATCH - LH	S	89.00 +
61	WINDOW SLOT SEAL WITH TRIM STRIP <i>nec</i>	2 S	518.00 +.
TOTAL SPARE PARTS CHARGES			\$ 8,292.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
62	FRONT NO. PLATE <i>see</i>	S/N	\$ 25.00	✓ 25
63	ALUMINIUM RIM - LHS <i>cut</i>		\$ 465.00	✓ 572
64	FRONT WISHBONE - LHS <i>Not nec</i>		\$ 462.00	? X
65	SUSPENSION GUIDE - LHS <i>Not nec</i>		\$ 812.00	? X
66	FRONT WHEEL BEARING HOUSING - LHS <i>Not nec</i>		\$ 822.00	? X
67	BALL JOINT - LHS <i>Not nec</i>		\$ 157.00	? X
68	FRONT WHEEL HUB - LHS <i>Not nec</i>		\$ 630.00	? X
69	FRONT UPPER INNER GUIDE - LHS <i>Not nec</i>		\$ 434.00	? X
70	FRONT UPPER OUTER GUIDE - LHS <i>Not nec</i>		\$ 434.00	? X
71	FRONT NOISE INSULATION PAN <i>Not nec</i>		\$ 489.00	? X
72	UNDERBODY TRIM - FRONT LHS <i>Not nec</i>		\$ 34.00	? X
73	UNDERBODY TRIM - LHS <i>Not nec</i>		\$ 264.00	? X
74	STEERING RACK <i>Not nec</i>		\$ 5,745.00	? X
75	TIE ROD - LHS <i>Not nec</i>		\$ 163.00	? X
76	FRONT TIRE - LHS <i>see</i>		TBC	X
77	SUNDRIES <i>see</i>		\$ 1,000.00	? 54.47
TOTAL SPARE PARTS CHARGES			\$ 38,298.00	
TOTAL LABOUR CHARGES			\$ 14,212.00	
GRAND TOTAL			\$ 52,510.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

56662.48

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian 
Surveyed Date : 08/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 08 Days. 12 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg


Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0024/2018/GW 17-Jan-18 CHANG 1 of 1 SLN 141 K Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To remove and reinstall front lock carrier and align to position. Renew front reinforcement bracket.	\$ 2,400.00	? 1250
TOTAL LABOURS :		\$ 2,400.00	
Parts			
1	FRONT REINFORCEMENT BRACKET - LH	\$ 195.00	Pl - 156
2	HEADLIGHT TRIM - UPPER LH	\$ 13.00	MIS - 9.68
3	FRT FENDER TRIM - LH OUTER	\$ 20.00	cut - 19.36
4	FRT FENDER TRIM - LH INNER	\$ 27.00	cut - 21.04
5	A/C PIPE	\$ 453.00	Pl - 362.40
6	A/C PIPE	\$ 216.00	Pl - 172.40
7	A/C PIPE	\$ 145.00	Pl - 115.60
TOTAL PARTS :		\$ 1,069.00	
GRAND TOTAL :		\$ 3,469.00	

Rasul
 Pl
 18/01/18

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183


Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0024/2018/GW 30-Jan-18 CHANG 1 of 1 SLN 141 K Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To repair and respray lhs sill panel.	\$ 900.00	\$ 900.00 750 ✓
TOTAL LABOURS		\$ 900.00	\$ 900.00
GRAND TOTAL		\$ 900.00	

For Premium Automobiles Pte Ltd

Adrian Ling


 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted.</i>	\$	1,703.00 ✓
2	FRONT BUMPER SECURING STRIP ?	\$	57.00 ?
3	FRONT BUMPER GRILLE - CENTER <i>could</i>	\$	163.00 ✓
4	FRONT BUMPER CLOSING ELEMENT <i>could</i>	\$	171.00 ✓
5	FRONT BUMPER AIR GUIDE - LH <i>missing</i>	\$	67.00 ✓
6	RADIATOR GRILLE <i>could</i>	\$	941.00 ✓
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Missing</i>	\$	112.00 ✓
8	FRONT BUMPER GUIDE SECTION - LH <i>found</i>	\$	29.00 ✓
9	FOAM FILLER PIECE <i>could</i>	\$	101.00 ✓
10	FRONT BUMPER CARRIER <i>Best</i>	\$	674.00 ✓
11	FRONT BUMPER SUPPORT - LH/RH ?	2 \$	46.00 ? <i>new</i>
12	FRONT BUMPER LOCK CARRIER BRACKET ?	\$	112.00 ? <i>check</i>
13	FRONT BUMPER TOP COVER <i>could</i>	\$	104.00 ✓
14	SIGN "CAUTION" <i>new</i>	\$	12.00 ✓
15	STICKER FOR AIR CONDITIONER <i>new</i>	\$	6.00 ✓
16	FRONT FENDER - LH <i>Distorted</i>	\$	643.00 ✓
17	FRONT FENDER ATTACHEMENT PARTS - LH } <i>found</i>	\$	44.00 ✓
18	FRONT FENDER CLOSING ELEMENT - LH }	\$	42.00 ✓
19	FRONT FENDER BRACKET - LH	\$	29.00 ✓
20	FRONT FENDER BRACKET DEFORMATION - LH <i>could</i>	\$	42.00 ✓
21	FRONT FENDER RETAINING BRACKET - LH } <i>found</i>	\$	27.00 ✓
22	FRONT FENDER BRACE - LH	\$	100.00 ✓
SUB - TOTAL SPARE PARTS CHARGES		\$	5,225.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
23	FRONT STONE CHIP GUARD - LH <i>new</i>	S	43.00	✓
24	FRONT WHEEL SPOILER - LH ?	S	61.00	? CRA ✓
25	FRONT BUMPER SPOILER - LH ?	S	29.00	? CRA ✓
26	FRONT WHEEL HOUSING LINER - LH <i>tone</i>	S	208.00	✓
27	WHEEL HOUSING LINER ATTACHMENT PARTS ?	S	76.00	?
28	FRONT FENDER LINER LOWER COVER - LH ?	S	12.00	?
29	LED HEADLIGHT - LH <i>missing control</i>	S	7,861.00	✓
30	POWER MODULE FOR MAIN LIGHT ELECTRONIC ?	S ?	685.00	do ?
31	CONTROL UNIT FOR LIGHT CONTROL SYSTEM <i>factory ?</i>	S ?	634.00	new ✓
32	DRAIN HOSE ?	S	29.00	?
33	HEADLIGHT COMPENSATING ? <i>x 1</i>	3 S	105.00	?
34	HEADLIGHT LIFT CYLINDER - LH ?	S	180.00	? CRA ✓
35	HEADLIGHT LIFT CYLINDER BRACKET - LH ?		TBC	?
36	CORRUGATED PIPE - LH/RH <i>new</i>	2 S	106.00	x new / 1 pc
37	BONNET <i>Sealed</i>	S	2,001.00	✓
38	BONNET ATTACHMENT PARTS ?	S	103.00	?
39	BONNET LID HINGE - LH/RH <i>new</i>	2 S	514.00	x
40	BONNET IMPACT PROTECTION <i>new</i>	3 S	69.00	✓
41	FRONT FENDER LEDGE - LH ?	2 S	43.00	?
42	BONNET STRIKER - LH/RH <i>new</i>	2 S	86.00	x
TOTAL SPARE PARTS CHARGES			\$ 12,845.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
43	BONNET LID LOCK <i>Not in</i>	2 S	360.00 <i>f</i>
44	BONNET LOCK CARRIER WITH MOUNTING <i>200?</i>	S	878.00 <i>* ?</i>
45	COOLANT REGULATOR SUPPORT <i>?</i>	S	64.00 <i>? BPO</i>
46	RADIATOR AIR GUIDE -LH <i>?</i>	2 S	32.00 <i>?</i>
47	ADDITIONAL COOLER FOR COOLANT <i>the -> Dents</i>	S	444.00 <i>e.</i>
48	A/C CONDENSOR WITH FLUID RESERVOIR <i>?</i>	S	525.00 <i>?</i>
49	RADIATOR <i>?</i>	S	572.00 <i>?</i>
50	RUBBER BUSH <i>?</i>	4 S	38.00 <i>?</i>
51	COOLANT CONCENTRATE - 1.5 LTR <i>?</i>	S	132.00 <i>?</i>
52	RADIATOR FAN RING <i>?</i>	S	222.00 <i>?</i>
53	RADIATOR FAN WITH CONTROL UNIT <i>Not in</i>	S	1,949.00 <i>*.</i>
54	COOLANT PIPE <i>? -> A/C pipe.</i>	2 S	346.00 <i>?</i>
55	HIGH NOTE HORN <i>Not in</i>	S	35.00 <i>*.</i>
56	HIGH NOTE HORN MOUNT BRACKET <i>Not in</i>	S	24.00 <i>*.</i>
57	FRONT DOOR - LH <i>Byg</i>	S	1,855.00 <i>*.</i>
58	FRONT OUTER DOOR SEAL - LH <i>Not in</i>	S	167.00 <i>*.</i>
59	BONDING AGENT <i>? Not in</i>	S	42.00 <i>*.</i>
60	FRONT DOOR CATCH - LH	S	89.00 <i>*.</i>
61	WINDOW SLOT SEAL WITH TRIM STRIP <i>Not in</i>	2 S	518.00 <i>*.</i>
TOTAL SPARE PARTS CHARGES			\$ 8,292.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0024/2018/GW
Date : 6-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

*Hi Adrian
You recommended 8 days
We took 23 days exclude 4 Sundays
Parts order - Pls refer Miss Nora
Jb 31 May 18*

Owner's Name : Ms. Wong Geok Chun
Address : Blk 71 Jurong West Central 3
#10-14
Singapore 648335
Telephone : HP +65 97285342
Type of Claim : Own Damage Claims
Policy No. : 2100507399
Vehicle No : **SLN 141 K**
Model Code : Audi A4 Sedan 1.4 TFSI S-tronic
Model / Year : Apr-17
Engine No : CVN 032231
Chassis No : WAUZZZF43HA121927
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Jan-18
Place of Accident : JURONG WEST CENTRAL 3

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 141 K.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlight, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To remove and transfer aircon condensor, radiator, additional radiator, electrical fans and control unit. Renew damaged aircon piping. To carry out vacuum/regas and to pressurise cooling system.	S/N	\$ 1,400.00	\$ 1,400.00
3	To remove and transfer lhs front door's multi - lock system and power window devices.	S/N	\$ 280.00	nil
4	To dismantle front bumper, lhs front fender, bonnet and lhs front door. Renew front lock carrier and align to position. Renew front bumper, lhs front fender, headlight and bonnet. Re-organise front crash management components. Reinstall all parts removed.		\$ 5,100.00	\$ 1,750.00
5	To remove rhs front doont panel trim, renew rhs front door chrome molding	S/N	\$ 300.00	
6	To respray front bumper, lhs front fender, bonnet, hinges and lhs front door.		\$ 3,500.00	\$ 2,200.00
7	To suspend engine, dismantle front suspension assy. Inspect for damages and renew accordingly.	S/N	\$ 2,800.00	nil
8	To renew lhs front rim and tyre. Carry out wheel alignment	S/N	\$ 280.00	\$ 280.00
9	Added labour - see attached		\$ 2,400.00	\$ 1,500.00
10	Added labour - see attached		\$ 900.00	\$ 750.00
9	To carry out diagnostic check	S/N	\$ 192.00	\$ 192.00
	TOTAL LABOUR CHARGES	:	\$ 17,512.00	\$ 8,432.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,703.00	\$ 1,362.40
2	FRONT BUMPER SECURING STRIP	\$ 57.00	
3	FRONT BUMPER GRILLE - CENTER	\$ 163.00	\$ 130.00
4	FRONT BUMPER CLOSING ELEMENT	\$ 171.00	\$ 136.40
5	FRONT BUMPER AIR GUIDE - LH	\$ 67.00	\$ 52.96
6	RADIATOR GRILLE	\$ 941.00	\$ 752.40
7	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 112.00	\$ 89.20
8	FRONT BUMPER GUIDE SECTION - LH	\$ 29.00	\$ 26.08
9	FOAM FILLER PIECE	\$ 101.00	\$ 80.80
10	FRONT BUMPER CARRIER	\$ 674.00	\$ 539.20
11	FRONT BUMPER SUPPORT - LH/RH	2 \$ 46.00	\$ 38.24
12	FRONT BUMPER LOCK CARRIER BRACKET	\$ 112.00	\$ 94.00
13	FRONT BUMPER TOP COVER	\$ 104.00	\$ 82.80
14	SIGN "CAUTION"	\$ 12.00	\$ 9.04
15	STICKER FOR AIR CONDITIONER	\$ 6.00	\$ 4.64
16	FRONT FENDER - LH	\$ 643.00	\$ 514.40
17	FRONT FENDER ATTACHEMENT PARTS - LH	\$ 44.00	\$ 34.96
18	FRONT FENDER CLOSING ELEMENT - LH	\$ 42.00	\$ 33.44
19	FRONT FENDER BRACKET - LH	\$ 29.00	\$ 23.20
20	FRONT FENDER BRACKET DEFORMATION -LH	\$ 42.00	\$ 33.04
21	FRONT FENDER RETAINING BRACKET - LH	\$ 27.00	\$ 20.96
22	FRONT FENDER BRACE - LH	\$ 100.00	\$ 79.44
SUB - TOTAL SPARE PARTS CHARGES		\$ 5,225.00	\$ 4,137.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	Damaged Parts & Prices		
		S/Nett	Remark	
			\$	4,137.60
	<i>c/f</i>		\$	
23	FRONT STONE CHIP GUARD - LH	\$ 43.00	\$	33.68
24	FRONT WHEEL SPOILER - LH	\$ 61.00	\$	50.16
25	FRONT BUMPER SPOILER -LH	\$ 29.00	\$	23.92
26	FRONT WHEEL HOUSING LINER - LH	\$ 208.00	\$	166.00
27	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 76.00		
28	FRONT FENDER LINER LOWER COVER - LH	\$ 12.00		
29	LED HEADLIGHT - LH	\$ 7,861.00	\$	6,288.80
30	POWER MODULE FOR MAIN LIGHT ELECTRONIC	\$ 685.00		
31	CONTROL UNIT FOR LIGHT CONTROL SYSTEM	\$ 634.00	\$	525.60
32	DRAIN HOSE	\$ 29.00		
33	HEADLIGHT COMPENSATING	3 \$ 105.00	\$	55.36
34	HEADLIGHT LIFT CYLINDER - LH	\$ 180.00	\$	147.20
35	HEADLIGHT LIFT CYLINDER BRACKET - LH	TBC		
36	CORRUGATED PIPE - LH/RH	2 \$ 106.00	\$	62.56
37	BONNET	\$ 2,001.00	\$	1,600.80
38	BONNET ATTACHMENT PARTS	\$ 103.00		
39	BONNET LID HINGE - LH/RH	2 \$ 514.00		
40	BONNET IMPACT PROTECTION	3 \$ 69.00	\$	54.48
41	FRONT FENDER LEDGE -LH	2 \$ 43.00		
42	BONNET STRIKER - LH/RH	2 \$ 86.00		
TOTAL SPARE PARTS CHARGES		\$ 12,845.00	\$	13,146.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 13,146.16
43	BONNET LID LOCK	2	\$ 360.00	
44	BONNET LOCK CARRIER WITH MOUNTING		\$ 878.00	
45	COOLANT REGULATOR SUPPORT		\$ 64.00	\$ 52.48
46	RADIATOR AIR GUIDE -LH	2	\$ 32.00	
47	ADDITIONAL COOLER FOR COOLANT		\$ 444.00	\$ 364.00
48	A/C CONDENSOR WITH FLUID RESERVOIR		\$ 525.00	
49	RADIATOR		\$ 572.00	
50	RUBBER BUSH	4	\$ 38.00	
51	COOLANT CONCENTRATE - 1.5 LTR		\$ 132.00	
52	RADIATOR FAN RING		\$ 222.00	
53	RADIATOR FAN WITH CONTROL UNIT		\$ 1,949.00	
54	COOLANT PIPE	2	\$ 346.00	
55	HIGH NOTE HORN		\$ 35.00	
56	HIGH NOTE HORN MOUNT BRACKET		\$ 24.00	
57	FRONT DOOR - LH		\$ 1,855.00	
58	FRONT OUTER DOOR SEAL - LH		\$ 167.00	
59	BONDING AGENT		\$ 42.00	
60	FRONT DOOR CATCH - LH		\$ 89.00	
61	WINDOW SLOT SEAL WITH TRIM STRIP	2	\$ 518.00	
TOTAL SPARE PARTS CHARGES			\$ 8,292.00	\$ 13,562.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
		<i>c/f</i>		\$ 13,562.64
62	FRONT NO. PLATE	S/N \$	25.00	\$ 25.00
63	ALUMINIUM RIM - LHS	\$	465.00	\$ 372.00
64	FRONT WISHBONE - LHS	\$	462.00	
65	SUSPENSION GUIDE - LHS	\$	812.00	
66	FRONT WHEEL BEARING HOUSING - LHS	\$	822.00	
67	BALL JOINT - LHS	\$	157.00	
68	FRONT WHEEL HUB - LHS	\$	630.00	
69	FRONT UPPER INNER GUIDE - LHS	\$	434.00	
70	FRONT UPPER OUTER GUIDE - LHS	\$	434.00	
71	FRONT NOISE INSULATION PAN	\$	489.00	
72	UNDERBODY TRIM - FRONT LHS	\$	34.00	
73	UNDERBODY TRIM - LHS	\$	264.00	
74	STEERING RACK	\$	5,745.00	
75	TIE ROD - LHS	\$	163.00	
76	FRONT TIRE - LHS	TBC		
77	SUPPLEMENTARY	\$	1,069.00	\$ 852.48
78	SUNDRIES	\$	1,000.00	\$ 54.48
	TOTAL SPARE PARTS CHARGES	\$	39,367.00	\$ 14,866.60
	TOTAL LABOUR CHARGES	\$	17,512.00	\$ 8,432.00
	GRAND TOTAL	\$	56,879.00	\$ 23,298.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved. Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0024/2018/GW 17-Jan-18 CHANG 1 of 1 SLN 141 K Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To remove and reinstall front lock carrier and align to position. Renew front reinforcement bracket.	\$ 2,400.00	\$ 2,400.00 1250,
TOTAL LABOURS		\$ 2,400.00	\$ 1,500.00
Parts			
1	FRONT REINFORCEMENT BRACKET - LH	\$ 195.00	\$ 156.00
2	HEADLIGHT TRIM - UPPER LH	\$ 13.00	\$ 9.68
3	FRT FENDER TRIM - LH OUTER	\$ 20.00	\$ 15.36
4	FRT FENDER TRIM - LH INNER	\$ 27.00	\$ 21.04
5	A/C PIPE	\$ 453.00	\$ 362.40
6	A/C PIPE	\$ 216.00	\$ 172.40
7	A/C PIPE	\$ 145.00	\$ 115.60
TOTAL PARTS		\$ 1,069.00	\$ 852.48
GRAND TOTAL		\$ 3,469.00	\$ 2,352.48

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLN 141 K

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0024/2018/MAS

23 May 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLN 141 K, Audi A4 Sedan 1.4 TFSI

With reference to the above-mentioned vehicle, no. **SLN 141 K**, claimant, **Ms. Wong Geok Chun**, please find the related document per attached.

1. A copy of the Original invoice no. 85013765 – S\$23,592.00
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLN 141 K

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6384 2223
Main Telefax: 6471 3751

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6384 2223
Telefax: 6471 1021

Ubi Service Centre
55 Ubi Road 1
Singapore 408711
Telephone: 6384 2111

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6366 2323
9628 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 11:03

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013765 Date : 14/05/2019 Order : SLN0141K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLN0141K (V 33253)	Regn Date: 19/04/2017	Mileage: 30438	WIP No.: 51202
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF43HA121927	Engine: CVM 032231	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. RENEW DAMAGED AIRCON PIPING. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR. REALIGN FRONT LOCK CARRIER TO POSITION. RENEW FRONT BUMPER, LHS FRONT	1750.00	1.00	1,750.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Jurong Centre Singapore
281 Alexandra Road
Singapore 159936
Main Telephone: 6396 2222
Main Telefax: 6471 3731

Alexandra Service Centre
281 Alexandra Road
Singapore 159936
Telephone: 6396 2222
Telefax: 6475 1025

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6388 2122

Customer Service
Service Appointment: 6396 2222
6526 1233
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

INSURANCE TAX INVOICE

Company Reg. No: 199902271W
GST Reg. No. 199902271W

Page 2 11:03

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013765 Date : 14/05/2019 Order : SLN0141K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLN0141K (V 33253)	Regn Date: 19/04/2017	Mileage: 30430	WIP No.: 51202
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF43HA121927	Engine: CVM 032231	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	FENDER, HEADLIGHT AND BONNET. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED M:	2200.00	1.00	2,200.00
S	BODYWORK	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR M:	280.00	1.00	280.00
S	BODYWORK	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT M:	192.00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	750.00	1.00	750.00
S	BODYWORK	TO REPAIR AND RESPRAY LHS SILL PANEL M:	1250.00	1.00	1,250.00
X	ASM0816741RL	COOLANT PIP(A) Less 020%	1.00	144.50	115.60
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2222
Main Telefax: 6471 2733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2222
Telefax: 6471 1022

Ubi Service Centre
55 Ubi Road 1
Singapore 4086 3333

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2222
9828 1222

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 3 11:03

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013765 Date : 14/05/2019 Order : SLN0141K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLN0141K (V 33253) Regn Date: 19/04/2017 Mileage: 38430 WIP No.: 51202

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF43HA121927 Engine: CVN 032231 Dept: U

USB No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABW0601025B	RIM 16" C4M	Less 020%	1.00	465.00	372.00
X	ABW0620769C	BRACKET(A)	Less 020%	1.00	6.00	4.80
X	AN 91071702	BOLT(A)	Less 020%	2.00	1.80	2.88
X	ABW0816743L	COOLANTPIP	Less 020%	1.00	215.50	172.40
X	ABW0853651 3F2	GRILLE	Less 020%	1.00	940.50	752.40
X	ABW0941773A	HEADLIGHT	Less 020%	1.00	7861.00	6,288.80
X	ABW0821105A	FENDER	Less 020%	1.00	643.00	514.40
X	ABW0853867A	SPOILER	Less 020%	1.00	62.70	50.16
X	ABW0821171A	WHEEL HOUS(A)	Less 020%	1.00	297.50	166.00
X	ABW0807081	COVER	Less 020%	1.00	183.50	82.80
X	ABW0807611	PLATE	Less 020%	1.00	178.50	136.40
X	ABW0145804A	RADIATOR (A)	Less 020%	1.00	455.00	364.00
X	ABW0807550A	FOAM INSER	Less 020%	1.00	101.00	80.80
X	ABW0807113	BRACKET	Less 020%	1.00	674.00	539.20
X	ABW0823029A	HOOD	Less 020%	1.00	2001.00	1,600.80
X	ABW0807065C GRU	COVER	Less 020%	1.00	1703.00	1,362.40
X	AN 10414402	BOLT	Less 020%	1.00	3.10	2.48
X	ABW0908625	MOUNT KIT	Less 020%	1.00	43.70	34.96
Sub-Total						
7% GST						
Grand Total						



Premium Automobiles Pte Ltd

Audi Centre Singapore
291 Alexandra Road
Singapore 119938
Main Telephone: 6370 2223
Main Telex: 6471 3733

Alexandra Service Centre
291 Alexandra Road
Singapore 119938
Telephone: 6388 2233
Telex: 6475 1022

Ubi Service Centre
55 Ubi Road 1
Singapore 408721
Telephone: 6388 7211
Telex: 6475 1022

Customer Service
Service Appointment: 6366 2223
6828 1235
Your Breakdown Service
customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 4 11:03

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013765 Date : 14/05/2019 Order : SLN0141K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLN0141K (V 33253)	Regn Date: 19/04/2017	Mileage: 30430	WIP No.: 51202
Model: AA SEDAN 1.4 TFSI 5 tronic	Chassis: WAUZZZF43HA121927	Engine: CVN 032231	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

	Details	Qty	Unit Price	Amount
X	ABW0007334 SUPPORT Less 020%	1.00	23.90	19.12
X	ABW0007333 SUPPORT Less 020%	1.00	23.90	19.12
X	ABW0021467 BRACKET Less 020%	1.00	29.00	23.20
X	A4G8806305 SPACER Less 020%	1.00	34.60	27.68
X	ABW0021469 BRACKET Less 020%	1.00	41.30	33.04
X	ABW0021471 BRACKET Less 020%	1.00	26.20	20.96
X	ABW0005201 MOUNTING Less 020%	2.00	32.00	52.48
X	ABW0021135C SUPPORT Less 020%	1.00	99.30	79.44
X	ABW0007283 GUIDE Less 020%	1.00	30.70	24.56
X	ABW0007133 BRACKET Less 020%	1.00	195.00	156.00
X	ABW0121673A AIR DUCT Less 020%	1.00	9.60	7.68
X	ABW0121763 AIR DUCT Less 020%	1.00	66.20	52.96
X	ABW0023745 COVER Less 020%	1.00	19.20	15.36
X	ABW0021091 PLATE Less 020%	1.00	41.00	33.44
X	ABW0021653 COVER Less 020%	1.00	12.10	9.68
X	ABW0020581B COVER Less 020%	1.00	26.30	21.04
X	ABW0023125 PROTECTION Less 020%	1.00	22.70	18.16
X	ABW0023126 PROTECTION Less 020%	1.00	22.70	18.16
Sub-Total				
7% GST				
Grand Total				



Premium Automobiles Pte Ltd

Qudl Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6384 2223
Main Telefax: 6471 2283

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6384 2223
Telefax: 6471 1021

Ubi Service Centre
55 Ubi Road 1
Singapore 4086 2223

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6384 2223
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 5 11:03

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013765 Date : 14/05/2019 Order : SLN0141K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLN0141K (V 33253) Regn Date: 19/04/2017 Mileage: 30430 WIP No.: 51202

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF43HA121927 Engine: CVN 032231 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A3D0260749C	WASHER	Less 020%	1.00	3.80	3.84
X	A4E0260749C	WASHER	Less 020%	1.00	4.00	3.20
X	ABG0006305	SPACER	Less 020%	1.00	34.60	27.68
X	ABW0016738Q	PIPE	Less 020%	1.00	453.00	362.40
X	ABW0007681B 989	GRILL	Less 020%	1.00	111.50	89.20
X	ABW0007683 989	GRILLE	Less 020%	1.00	162.50	130.00
X	ABW0053833	SPOILER	Less 020%	1.00	29.90	23.92
X	ABW0955970A	TUBING (A)	Less 020%	1.00	78.20	62.56
X	ABW0053823A 989	STONEGUARD	Less 020%	1.00	42.10	33.68
X	ABW0955775	BRACKET	Less 020%	1.00	5.10	4.08
X	ABW0955101A	CYLINDER	Less 020%	1.00	184.00	147.20
X	ABW0010515A	STICKER	Less 020%	1.00	5.80	4.64
X	ABW0010520A	PLATE	Less 020%	1.00	11.30	9.04
X	ABW0121283AR	AIR DUCT	Less 020%	1.00	23.00	18.40
X	ABW0007771	BRACKET	Less 020%	1.00	117.50	94.00
X	A4M0907397AD	CTRL UNIT (A)	Less 020%	1.00	657.00	525.60
X	AN 91093901	RIVET	Less 020%	4.00	0.70	2.24
X	AN 0385012	RIVET	Less 020%	4.00	1.50	4.80
Sub-Total						
7% GST						
Grand Total						



Premium Automobiles Pte Ltd

Madri Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6388 2223
Main Telefax: 6471 3751

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6471 1021

Ubi Service Centre
55 Ubi Road 1
Singapore 408749
Telephone: 6388 2223
Telefax: 6471 1021

Customer Service
Service Appointment: 6346 2323
Service Breakdown Service: 9828 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 6 11:03

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-15 SINGAPORE 079120 079120	Invoice: 85013765 Date : 14/05/2019 Order : SLN0141K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-15 SINGAPORE 079120
---	---	--

Regn No.: SLN0141K (V 33253)	Regn Date: 19/04/2017	Mileage: 30430	WIP No.: 51202
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF43HA121927	Engine: CVN 032231	Dept: U
VSB No.:			
You have been assisted by :- (JB-Jiayee) (33)			

		Details		Qty	Unit Price	Amount
X	AN 10347204	BOLT	Less 020%	3.00	1.00	2.40
X	AGM0823124	PROTECTION	Less 020%	1.00	22.70	18.16

Parts 14,041.60
Labour 0.00
Sublet 8,207.00
Menus 0.00
Lubricant 0.00

Sub-Total	22,048.60
7% GST	1,543.40
Grand Total	23,592.00

Received by


For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLN 141 K

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0024/2018/GW
02 February 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi A4 Sedan 1.4 TFSI S- tronic
Vehicle Chassis No. : WAUZZZF43HA121927
Vehicle Regn No. : SLN 141 K
Vehicle Mileage : 12387 KM
Vehicle Owner : Ms. Wong Geok Chun
Certificate No : 2100507399
Policy Excess : S\$1070.00 (inclusive 7% GST)
Accident Date : 05-January-18
Place : Jurong West Central 3
Repair Cost : \$ 23,592.00
WIP No. : 51202
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

5/2/18

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of CHNG JIANYAO, NICHOLAS

Licence Number: **S9325472D**

Name: **CHNG JIANYAO, NICHOLAS**

Birth Date: **14 Jul 1993**

Issue Date: **12 Aug 2013**

Barcode: 002212206F

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S9325472D



Portrait of CHNG JIANYAO, NICHOLAS

Name: **CHNG JIANYAO, NICHOLAS**

莊建耀

Race: **CHINESE**

Date of birth: **14-07-1993**

Sex: **M**

Country of birth: **SINGAPORE**

9325472D

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3 Motor Cars < 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg **12 Aug 2013**

NP 428A

Licence No: S9325472D

4255502

Barcode

NRIC No: **S9325472D**

Portrait of CHNG JIANYAO, NICHOLAS

Date of issue: **28-07-2008**

BLK 71 JURONG WEST CENTRAL 3 #10-14
SINGAPORE 648335

NRIC No: **S9325472D** Date: **20/08/2009** No: **6252389**



COVER NOTE

Cover Note No. 2100507399 Date 17 Apr 2017

The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder.

SCHEDULE

Policyholder	WONG GEOK CHUN		
Age Condition	All Age Condition	Registration No.	SLN141K
Policy	AUDI AUTO PROTECTOR (INSURED NOT DRIVING POLICY)	Make/Model	AUDI A4 1.4 TFSI S tronic
Effective Date	19 Apr 2017	CC/Carriage	1,395.00
Expiry Date	18 Apr 2018	Engine No	CVN032231
Excess	S\$600.00	Chassis No	WAUZZZF43HA121927
		Year of Registration	2017
		Hire Purchase Company	United Overseas Bank Limited

Any person other than the Insured who is named as a named driver under the policy.

In addition to the Policy Excess, a Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00 (before GST) will apply to You or Your Authorised Driver who is below the age of 23 (in case of All Age Condition policies) and/or has less than 2 years' driving experience. The YIDR Excess is not applicable to Named Driver policies.

Usage of vehicle only for the following purposes:

- Use only for social, domestic and pleasure purposes and for the Policyholder's business.
- Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes.

Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.

The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

CERTIFICATE OF INSURANCE

I/We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Issued in SINGAPORE

AIG Asia Pacific Insurance Pte. Ltd.

IMPORTANT NOTICE
THIS COVER NOTE IS VALID FOR
60 DAYS FROM THE FIRST DAY OF
THE POLICY PERIOD. APPLICABLE
TO CORPORATE POLICIES ONLY.

AUTHORISED REPRESENTATIVE

ORIGINAL

PRLLYY

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jan 2018 Edit Reg		08 Jan 2018 00:00 Edit Adj Rpt	S\$23,048.60 Edit Estimates	S\$23,048.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	WONG GEOK CHUN , ID: S1531381A, Tel: +6597285342								
Vehicle Reg. No.:	SLN141K	Date of Loss:	05/01/2018 07:00 - :59 [8 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 7713865575SG	Policy/Cover Note No.:	2100507399 (Comprehensive)						
		Excess:	S\$1,000.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/01/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> AIG_SG_EXPRESS (09/05/2019): Alert - Adj Mandate Approved (S\$23048.60) - SLN141K - Claim Handler: Chan, Kian ... AIG_SG_EXPRESS (02/11/2018): Alert - Adj Mandate Maintained - SLN141K - Claim Handler: Chan, Kian Meng AIG_SG (13/08/2018): Supplementary parts and labour. AIG_SG_EXPRESS (13/08/2018): Alert - Adj Mandate Maintained - SLN141K - Claim Handler: Chan, Kian Meng AIG_SG_EXPRESS (06/02/2018): Alert - Adj Mandate Approved (S\$21977.00) - SLN141K - Claim Handler: Chan, Kian ... AIG_SG_EXPRESS (11/01/2018): Alert - Adj Mandate Approved (S\$20908.00) - SLN141K - Claim Handler: Chan, Kian ... AIG_SG (11/01/2018): SLN141K / OD / 05/01/2018 / Coverage & Excess update 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN141K (7713865575SSG)
 OD
 Jan 5 2018 7:00AM
 [WONG GEOK CHUN]
 Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/01/18 16:38	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
2	31/01/18 16:50	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
3	13/08/18 15:03	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
2	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
3	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
4	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
5	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
6	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
7	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
8	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
9	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
10	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
11	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
12	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
13	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
14	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
15	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
16	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
17	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
18	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
19	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
20	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
21	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
22	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
23	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
24	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
25	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
26	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
27	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
28	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
29	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
30	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
31	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
32	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>
33	09/01/18 16:05	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
35	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
36	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
37	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
38	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
39	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
40	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
41	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
42	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
43	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
44	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
45	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
46	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
47	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
48	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
49	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
50	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
51	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
52	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
53	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
54	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
55	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
56	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
57	09/01/18 16:05	General View		<input checked="" type="checkbox"/>
58	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
59	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
60	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
61	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
62	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
63	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
64	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
65	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
66	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
67	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
68	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
69	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
70	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
71	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
72	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
73	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
74	31/01/18 16:52	Reinspection Photo		<input checked="" type="checkbox"/>
75	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
76	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
77	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
78	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
79	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
80	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
81	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
82	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
83	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
85	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
86	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
87	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
88	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
89	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
90	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
91	31/01/18 16:54	Reinspection Photo		<input checked="" type="checkbox"/>
92	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
93	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
94	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
95	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
96	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
97	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
98	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
99	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
100	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
101	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
102	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
103	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
104	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
105	31/01/18 16:55	Reinspection Photo		<input checked="" type="checkbox"/>
106	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
107	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
108	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
109	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
110	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
111	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
112	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
113	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
114	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
115	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
116	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
117	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
118	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
119	14/08/18 15:11	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/01/18 16:16	Certificate of Insurance		<input type="checkbox"/>
2	09/01/18 16:16	Driver's Driving License		<input type="checkbox"/>
3	09/01/18 16:16	estimate		<input type="checkbox"/>
4	09/01/18 16:16	Singapore Accident Statement		<input type="checkbox"/>
5	13/08/18 14:57	SUPP 1		<input type="checkbox"/>
6	13/08/18 14:57	SUPP 2		<input type="checkbox"/>
7	30/05/19 11:32	Workshop Invoice		<input type="checkbox"/>
8	30/05/19 11:32	Discharge Voucher		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18000459/ATBE2
Date: 30/05/2019

REFERENCE

Insured/Claimant:	WONG GEOK CHUN	Policy No:	2100507399	
Date of Loss:	05/01/2018	Nature of Claim:	OD	Claim No: 7713865575SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN141K		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN032231
Reg. Date:	19/04/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF43HA121927
Colour:	White	Odometer:	12387 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$148,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,150.48	14,866.60	24,283.88	62.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,512.00	8,182.00	9,330.00	53.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	56,662.48	23,048.60	33,613.88	59.32
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	55,662.48	22,048.60	33,613.88	60.39
+ GST 7.00/7.00% (S\$)	3,896.37	1,543.40	2,352.97	60.39
Nett Amount (S\$)	59,558.85	23,592.00	35,966.85	60.39

INSPECTION

Date of Assignment:	08/01/2018		
Date Inspected:	08/01/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	12.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,703.00 FS	*1,362.40 FS
2	1		*FRONT BUMPER SECURING STRIP	Not Necessary	57.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Cracked	163.00 FS	*130.00 FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	171.00 FS	*136.40 FS
5	1		*FRONT BUMPER AIR GUIDE - LH	Missing	67.00 FS	*52.96 FS
6	1		*RADIATOR GRILLE	Cracked	941.00 FS	*752.40 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	112.00 FS	*89.20 FS
8	1		*FRONT BUMPER GUIDE SECTION - LH	Damaged	29.00 FS	*26.08 FS
9	1		*FOAM FILLER PIECE	Cracked	101.00 FS	*80.80 FS
10	1		*FRONT BUMPER CARRIER	Bent	674.00 FS	*539.20 FS
11	2		*FRONT BUMPER SUPPORT - LH/RH	Damaged	46.00 FS	*38.24 FS
12	1		*FRONT BUMPER LOCK CARRIER BRACKET	Cracked	112.00 FS	*94.00 FS
13	1		*FRONT BUMPER TOP COVER	Cracked	104.00 FS	*82.80 FS
14	1		*SIGN CAUTION	Necessary	12.00 FS	*9.04 FS
15	1		*STICKER FOR AIR CONDITIONER	Necessary	6.00 FS	*4.64 FS
16	1		*FRONT FENDER - LH	Distorted	643.00 FS	*514.40 FS
17	1		*FRONT FENDER ATTACHMENT PARTS - LH	Damaged	44.00 FS	*34.96 FS
18	1		*FRONT FENDER CLOSING ELEMENT - LH	Damaged	42.00 FS	*33.44 FS
19	1		*FRONT FENDER BRACKET - LH	Damaged	29.00 FS	*23.20 FS
20	1		*FRONT FENDER BRACKET DEFORMATION - LH	Deformed	42.00 FS	*33.04 FS
21	1		*FRONT FENDER RETAINING BRACKET - LH	Damaged	27.00 FS	*20.96 FS
22	1		*FRONT FENDER BRACE - LH	Damaged	100.00 FS	*79.44 FS
23	1		*FRONT WHEEL SPOILER - LH	Damaged	61.00 FS	*50.16 FS
24	1		*FRONT BUMPER SPOILER - LH	Damaged	29.00 FS	*23.92 FS
25	1		*FRONT WHEEL HOUSING LINER - LH	Torn	208.00 FS	*166.00 FS
26	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	76.00 FS	*- FS
27	1		*FRONT FENDER LINER LOWER COVER - LH	Not Necessary	12.00 FS	*- FS
28	1		*LED HEADLIGHT - LH	Cracked	7,861.00 FS	*6,288.80 FS
29	1		*POWER MODULE FOR MAIN LIGHT ELECTRONIC	Not Necessary	685.00 FS	*- FS
30	1		*CONTROL UNIT FOR LIGHT CONTROL SYSTEM	Damaged	634.00 FS	*525.60 FS
31	1		*DRAIN HOSE	Not Necessary	29.00 FS	*- FS
32	1		*HEADLIGHT COMPENSATING (3PCS)	Damaged	105.00 FS	*55.36 FS
33	1		*HEADLIGHT LIFT CYLINDER - LH	Cracked	180.00 FS	*147.20 FS
34	1		*HEADLIGHT LIFT CYLINDER BRACKET - LH (NPA)	Not Necessary	0.00 FS	*- FS
35	1		*CORRUGATED PIPE - LH/RH	N/S Cut	106.00 FS	*62.56 FS
36	1		*BONNET	Dented	2,001.00 FS	*1,600.80 FS
37	1		*BONNET ATTACHMENT PARTS	Not Necessary	103.00 FS	*- FS
38	2		*BONNET LID HINGE - LH/RH	Not Necessary	514.00 FS	*- FS
39	3		*BONNET IMPACT PROTECTION	Necessary	69.00 FS	*54.48 FS
40	2		*FRONT FENDER LEDGE - LH	Not Necessary	43.00 FS	*- FS
41	2		*BONNET STRIKER - LH/RH	Not Necessary	86.00 FS	*- FS
42	2		*BONNET LID LOCK	Not Necessary	360.00 FS	*- FS
43	1		*BONNET LOCK CARRIER WITH MOUNTING	Not Necessary	878.00 FS	*- FS
44	1		*COOLANT REGULATOR SUPPORT	Damaged	64.00 FS	*52.48 FS
45	2		*RADIATOR AIR GUIDE - LH	Not Necessary	32.00 FS	*- FS
46	1		*ADDITIONAL COOLER FOR COOLANT	Dented	444.00 FS	*364.00 FS
47	1		*A/C CONDENSOR WITH FLUID RESERVOIR	Not Necessary	525.00 FS	*- FS
48	1		*RADIATOR	Not Necessary	572.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	4		*RUBBER BUSH	Not Necessary	38.00 FS	*- FS
50	1		*COOLANT CONCENTRATE - 1.5LTR	Not Necessary	132.00 FS	*- FS
51	1		*RADIATOR FAN RING	Not Necessary	222.00 F	*- F
52	1		*RADIATOR FAN WITH CONTROL UNIT	Not Necessary	1,949.00 FS	*- FS
53	2		*COOLANT PIPE	Not Necessary	346.00 FS	*- FS
54	1		*HIGH NOTE HORN	Not Necessary	35.00 FS	*- FS
55	1		*HIGH NOTE HORN MOUNT BRACKET	Not Necessary	24.00 FS	*- FS
56	1		*FRONT DOOR - LH	Repair	1,855.00 FS	*- FS
57	1		*FRONT OUTER DOOR SEAL - LH	Not Necessary	167.00 FS	*- FS
58	1		*BONDING AGENT	Not Necessary	42.00 FS	*- FS
59	1		*FRONT DOOR CATCH - LH	Not Necessary	89.00 FS	*- FS
60	2		*WINDOW SLOT SEAL WITH TRIM STRIP	Not Necessary	518.00 FS	*- FS
61	1		*FRONT NO. PLATE	Necessary	25.00 FS	*25.00 FS
62	1		*ALUMINIUM RIM - LHS	Cut	465.00 FS	*372.00 FS
63	1		*FRONT WISHBONE - LHS	Not Necessary	462.00 FS	*- FS
64	1		*SUSPENSION GUIDE - LHS	Not Necessary	812.00 FS	*- FS
65	1		*FRONT WHEEL BEARING HOUSING - LHS	Not Necessary	822.00 FS	*- FS
66	1		*BALL JOINT - LHS	Not Necessary	157.00 FS	*- FS
67	1		*FRONT WHEEL HUB - LHS	Not Necessary	630.00 FS	*- FS
68	1		*FRONT UPPER INNER GUIDE - LHS	Not Necessary	434.00 FS	*- FS
69	1		*FRONT UPPER OUTER GUIDE - LHS	Not Necessary	434.00 FS	*- FS
70	1		*FRONT NOISE INSULATION PAN	Not Necessary	489.00 FS	*- FS
71	1		*UNDERBODY TRIM - FRONT LHS	Not Necessary	34.00 FS	*- FS
72	1		*UNDERBODY TRIM - LHS	Not Necessary	264.00 FS	*- FS
73	1		*STEERING RACK	Not Necessary	5,745.00 FS	*- FS
74	1		*TIE ROD - LHS	Not Necessary	163.00 FS	*- FS
75	1		*FRONT TIRE - LHS (NPA)	Not Necessary	0.00 FS	*- FS
76	1		*SUNDRIES	Necessary	1,000.00 FS	*54.48 FS
77	1		*FRONT REINFORCEMENT BRACKET - LH	Bent	156.00 FS	*156.00 FS
78	1		*HEADLIGHT TRIM - UPPER LH	Missing	9.68 FS	*9.68 FS
79	1		*FRT FENDER TRIM - LH OUTER	Cut	15.36 FS	*15.36 FS
80	1		*FRT FENDER TRIM - LH INNER	Cut	21.04 FS	*21.04 FS
81	1		*A/C PIPE	Bent	362.40 FS	*362.40 FS
82	1		*A/C PIPE	Bent	172.40 FS	*172.40 FS
83	1		*A/C PIPE	Bent	115.60 FS	*115.60 FS
84	1		*FRONT STONE CHIP GUARD - LH	Necessary	43.00 FS	*33.68 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **39,150.48** **14,866.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSOR, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. RENEW DAMAGED AIRCON PIPING. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,400.00	1,400.00
3	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI - LOCK SYSTEM AND POWER WINDOW DEVICES	New	280.00	0.00
4	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, LHS FRONT FENDER, HEADLIGHT AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,100.00	1,750.00
5	TO REMOVE RHS FRONT DOOR PANEL TRIM, RENEW RHS FRONT DOOR CHROME MOLDING	New	300.00	0.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, HINGES AND LHS FRONT DOOR	New	3,500.00	2,200.00
7	TO SUSPEND ENGINE, DISMANTLE FRONT SUSPENSION ASSY. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	New	2,800.00	0.00
8	TO RENEW LHS FRONT RIM AND TYRE. CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
10	TO REMOVE AND REINSTALL FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT REINFORCEMENT BRACKET	New	2,400.00	1,250.00
11	TO REPAIR AND RESPRAY LHS SILL PANEL	New	900.00	750.00
Gross Labour Cost (S\$)			17,512.00	8,182.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >