

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-083

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9831D - FWD*Not Authorised
11 Sep 81300h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB9831D - CANDY

VF1ABL15AUC273328

RENAULT

LATITUDE

05.01.2018

FWD**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Buc m</i> 1,259.42	✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sm</i> 394.68	
3	1	BUMPER BEAM FRT	\$	<i>Sm</i> 914.08	
4	1	BUMPER UNDERTRAY FRT	\$	<i>Sm</i> 472.83	
5	1	BUMPER SPOILER FRT	\$	<i>Sm</i> 181.75	
6	1	BUMPER GRILLE LOWER FRT	\$	<i>Sm</i> 266.80	
7	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sm</i> 207.22	
8	1	BUMPER RETAINER FRT RH	\$	<i>Sm</i> 151.41	
9	1	BUMPER BRACKET FRT RH	\$	<i>Sm</i> 181.75	
10	1	HEADLAMP RH	\$	<i>Sm</i> 1,184.43	
11	1	HEADLAMP PANEL FRT RH	\$	<i>Sm</i> 152.15	
12	1	FENDER PANEL FRT RH	\$	<i>Sm</i> 783.83	
13	1	FENDER INSULATOR RH	\$	<i>Sm</i> 130.84	
14	1	FENDER BRACKET FRT RH	\$	<i>Sm</i> 34.14	
15	1	WHEELARCH FRT RH	\$	<i>Sm</i> 278.84	
16	1	WHEEL HOUSING PANEL FRT RH	\$	<i>Sm</i> 4,682.09	
17	1	LOWER ARM FRT RH	\$	<i>Sm</i> 685.76	
18	1	KUNCKLE ARM FRT RH	\$	<i>Sm</i> 846.98	
19	1	ABSORBER FRT RH	\$	<i>Sm</i> 360.54	
20	1	RADAITOR GRILLE	\$	<i>Sm</i> 1,707.78	
21	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>Sm</i> 173.36	
22	1	RADAITOR GRILLE FRAME	\$	<i>Sm</i> 1,353.75	
23	1	FRAME FULL SUPPORT PANEL	\$	<i>Sm</i> 615.90	
24	1	FRAME FULL SUPPORT BRACKET	\$	<i>Sm</i> 89.79	
25	1	BONNET	\$	<i>Sm</i> 1,941.63	
26	1	DOOR PANEL FRT RH	\$	<i>Sm</i> 2,844.66	
27	1	DOOR HINGE UPPER RH	\$	<i>Sm</i> 274.50	
28	1	DOOR HINGE LOWER RH	\$	<i>Sm</i> 300.55	
29	1	DOOR MOULDING FRT RH	\$	<i>Sm</i> 176.82	
30	1	DOOR MIRROR RH	\$	<i>Sm</i> 1,483.40	
31	1	DOOR MIRROR GLASS RH	\$	<i>Sm</i> 148.20	
32	1	DOOR MIRROR BACK COVER RH	\$	<i>Sm</i> 218.46	
33	1	DOOR WHETHERSTRIP FRT RH	\$	<i>Sm</i> 474.21	
34	1	DOOR SEAL FRT RH	\$	<i>Sm</i> 68.67	

X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-083**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9831D - FWD

35	1	ROCKER PANEL OUTER RH	\$	<i>R</i> 987.49 <i>X</i>
----	---	-----------------------	----	--------------------------

TOTAL	\$	26,028.71
10%	\$	2,602.87
	\$	23,425.84

Specical Nett

1	1SET	WHEELARCH CLIP FRT RH	\$	<i>un</i> 66.00 <i>X</i>
2	1SET	FRONT BUMPER CLIP	\$	<i>un</i> 66.00 ✓
3	1	RIM RH FRT	\$	<i>un</i> 385.00 <i>X</i>
4	1	TYRE RH FRT	\$	<i>un</i> 330.00 <i>X</i>
5	1	DOOR STICKER "Trans-cab"	\$	<i>un</i> 80.00 <i>X</i>
6	1	DOOR STICKER "Classic"	\$	<i>un</i> 30.00 <i>X</i>
7	1	DOOR STICKER "6555-3333"	\$	<i>un</i> 80.00 <i>X</i>
8	1SET	Front licence plate with holder	\$	<i>un</i> 80.00 <i>455m</i>

TOTAL	\$	1,117.00
TOTAL PARTS	\$	24,542.84

To Check Electrical Lighting Concerned.	\$	<i>un</i> 170.00 <i>X</i>
---	----	---------------------------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00 <i>200d</i>
---	----	----------------------

Putty and spray painting of the affected portion.	\$	3,000.00 <i>220d</i>
---	----	----------------------

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>un</i> 170.00 <i>X</i>
---	----	---------------------------

To transfer of tire, rim and on wheel balancing.	\$	<i>un</i> 170.00 <i>X</i>
--	----	---------------------------

To check steering geometry and computer wheel alignment	\$	<i>un</i> 220.00 <i>X</i>
---	----	---------------------------

To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>un</i> 170.00 <i>X</i>
---	----	---------------------------

To transfer of door fittings, attachment and perform water seepage test.	\$	<i>un</i> 170.00 <i>X</i>
--	----	---------------------------

Towing fees	\$	<i>un</i> 120.00 <i>X</i>
-------------	----	---------------------------

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-083**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9831D - FWD

To rust-proofing of the affected areas. \$ *nn* 170.00 *X*

To dismantle and refit front end suspension,
undercarriage parts, final checking and testing. \$ *nn* 380.00 *X*

TOTAL	\$	7,540.00
Over All Total	\$	32,082.84

(PARTS BY PARTS) Repair Days**10 Days***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: