

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel: 6389 - 6111
 Fax: 6224 - 7478 / 7175

Asher.

Quotation
 DATE : 08.01.2018
 VEH NO : SLQ5063D
 MODEL : BMW 120i
 D O A : 06.01.2018
 YR REF : GBG8184P

Attn: Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE: ESTIMATE FOR ACCIDENT REPAIR SLQ5063D (BMW 120i)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<u>NO</u>	<u>LIST ITEMS</u>		
1	Rear Number Plate Lamp <i>not in</i>	2	130.00 ✓
2	Rear Bumper <i>Distorted</i>	1	1,245.00 ✓
3	Rear Bumper Clips <i>m</i>	1 set	50.00 ✓ 30
4	Rear Bumper Side Holder <i>and</i>	2	276.00 ✓
5	Rear Bumper Tow Cover <i>missing</i>	1	22.00 ✓
6	Rear Bumper Reinforcement <i>sent</i>	1	435.00 ✓
7	Rear Bumper Inner Frame <i>embed.</i>	1	158.00 ✓
8	Reverse Sensor <i>2nd</i>	4	1,020.00 ✓
9	Tail Lamp <i>embed</i>	2	760.00 ✓
10	Tail Lamp Panel <i>Dented.</i>	2	590.00 ✓
11	Rear End Panel <i>Distorted</i>	1	658.00 ✓
12	Rear End Panel Top Granish <i>embed</i>	1	128.00 ✓
13	Bootlid <i>Distorted</i>	1	1,285.00 ✓
14	Bootlid Lock <i>2nd</i>	1	186.00 ✓
15	Bootlid Weatherstripe <i>cut</i>	1	198.00 ✓
16	Bootlid Hinges <i>Best</i>	2 sets	170.00 ✓
17	Bootlid Damper <i>men</i>	2 sets	310.00 ✓
18	Bootlid Reflector <i>embed</i>	1	276.00 ✓
19	Bootlid Inner Trim Board <i>men</i>	1	295.00 ✓
20	Bootlid Inner Trim Board Clips <i>m</i>	1 set	50.00 ✓ 30
21	BMW Logo <i>3mm</i>	1	65.00 ✓
22	120i Emblem <i>3mm</i>	1	89.00 ✓
23	Battery Terminal <i>Activated</i>	1	220.00 ✓
24	Rear Exhaust Pipe <i>3mm</i>	1	926.00 ✓
25	Rear Exhaust Mounting <i>3mm</i>	1	56.00 ✓
26	Rear Fender Inner Trim <i>Dented</i>	2	716.00 ✓
27	Rear Fender Inner Trim Clips <i>m</i>	1 set	60.00 ✓
28	Seat Belt Buckle <i>Activated.</i>	2	650.00 ✓

9237
 877515

RE: ESTIMATE FOR ACCIDENT REPAIR GBC8184P (BMW 120I)

\$ 11,024.00
 (1,102.40)
 \$ 9,921.60

S/NET ITEMS

1	Rear Number Plate <i>But</i>	1	30.00 ✓
2	Rear Number Plate Holder <i>Red</i>	1	50.00 ✓
3	Rear End Panel Sealant <i>m</i>	1	60.00 ✓
			130
			\$ 140.00
	Total parts		\$ 10,061.60

LABOUR CHARGE

1	To knocking out rear portion & renew above parts	\$ 1,500.00 <i>1200</i>
2	To putty & spray up paint works	\$ 1,200.00 <i>800</i>
3	To check wiring system	\$ 50.00 <i>30</i>
4	To underseal	\$ 150.00 <i>60</i>
5	To remove upholstery	\$ 150.00 <i>100</i>
6	To remove exhaust pipe	\$ 150.00 <i>x</i>
7	To transfer bootlid fittings	\$ 150.00 <i>100</i>
8	To reset air bag configuration	\$ 350.00 <i>250</i>
9	To reset over-roll protection	\$ 550.00 <i>400</i>
10	To perform diagnostic test	\$ 200.00 <i>120</i>
	Total Labour	\$ 4,450.00
	Grand Total	\$ 14,511.60

3060

total: 1183515
 L/S: 9K
 08 pages

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental items to be resurveyed and is subject to final approval from insurance company

NOTE:

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Acknowledged by: _____
 Signature: _____
 Date: _____

GST will be reflected in the final bills