Surveyor = "Marcus	ASSIGNMENT (Office)	93 Special Instructions
From (Person): Grace Teo	of SMO	Date/Time: 10.59am @ 09/01/1
Estimated Cost:	Bill to:	
OD TP WS/TP RES/OD RES	/EVA/INV/MV/CS	
To Inspect Vehicle No:	(1BE 3356 D	Insured: SKE 2611S
at Workshop m/s	Eastech Auto	Tel: 6746 5405
of I leaki Bkf the	6 # 01-46 Autobau	1
Policy No:		CM7D1860158/NSW
Sum Insured:	Excess:	
Make of Veh:		D.O.A. 08/01/2018
(Client's Record)	1)	2,002
CA / REV / REP. / REV 24 HI	is wp	H.O.D. Endorsement.
Date/Time: 11:58am @ 09/01/1	Person Contacted: Narcy	Vehicl (IN)OUT
Date/Time Action/Instruction (
GBF 3356D-	- NA CTI18000461/h4	D-0-A= 08/01/2018
- 1 L SKE 26/15 -	NA CTI 18000461/h4	D.O.A = 08/01/2018
10/01/18@ 5/15/ Info/	ned Shawn Ngo, we a	ve pending estimate from Vepai
24/1/180 12/10M 1001	1sed to Shawn Ngo	by duel

REF:	Su	mo /		8
Swall mercuf		NMENT		
1		61,-27	(160) Yr Regn: (, 16
From: Date:		The state of the s		
Estimated Cost:		Type: M.Car / M.Cycle / Bus /	/ap/ Lorry / Taxi / Prime Mov	er/
OD ITP WS TP RES OD RES EVA INV MV		Truck / Trailer or (M)	/	0.0
To Inspect Vehicle No: (2 3 6	33500	Make Toyota	1146	29/2 Std/NI/NA
at Workshop m/s		2	T	Std / NI / NA
of		001	6	
Insured: 514 E 76(1		Eng/Na: C/No: JTF H	To 2P 400181	278
Policy No.		Gen, Cond/Good / Fair / Poor	18 LF 4 UUIUI	- 14
Claims No.		Steering: Iporder / Jammed / I		
Sum Insured: Excess:		Brake: Igorder / Jammed /		-
(Client's Record)		Modi: (NILTS/Rim / STD A		
Make of Veh:			A STATE OF THE STA	
Г		Tyre Size: F:	195-n15	
(Policy Condition)	N/S O/S	BS DUN / EXNOVA / GY / FS	LITA (MIC OUTS!! DID	SLIMI /
Remark: The veh had commenced its repair at the time of inspection.	103 03	TOYO / YOKO or	STEIZAT MICTORISCIPIKT	OUMIT.
		_	Rear /	/
Bal. or Market Value: Consistent?: Yes or	No	Front 6	DIE:) mm
IDAO COIGAIN INPOIL	1977		1780	
GIA PR Seen: Consistent? : Yes or	200	-110	D.O.I. 9/	1,0
Est. Repairs: days Res.: Yes o		D.O.A. \$/1/18	_ 4//	118
Lum Sum: 20 % 3 Val.: Yes o	702 1742	Survey held at	1 0 0 1 N/0 1 N/0 1 Doot	22.53
	381-0	Des. of Damages : Frt / Rea	r / O/S / N/S / U/C / Rooft	op ur
Date: Person Contacted:	ehicle: IN / OUT	The U/C / Chassis fram	e / Body Structure affected (due to collision.
Date / Time Action / Instruction	L7A296			
hove 614 olouly	× (11010	. 0		
, ,				
17/1/18 confirmed k/5	# 6200	will Alex	1.	
(Red & 11643.30, 6	5%)			
RECEIVED 2 4 JA	2010			
INCOLITED A 1 SP	04.4 NO.			
Date/Time File Pass to? : Prell. Report		Days Of Repair:	5	
24/1 hiller : Final Report		Resurvey No. of Trip:	2 Survey Fee	
Date/Time. File Return to?			Transportation	
2)	Add Fee	and the same of th		
		Interview (\$	Photos	-
Report Format:		Tech, Invs (\$	Shert	
Lump Sum / LBH S 62 N		Weekend (\$	'	
			TOTAL	450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internati	onale Des Experts En Autom	nobile
JRANCE SINGAPORE PL	Ref : CS/SMO18000	482/Uqd3
PLACE LAND TOWERSINGAPORE 048623	Date: 09-01-2018 Code: SMO	
Policy Particulars	:- THIRD PARTY CLAI	M
Veh. SKE 2611S	Veh. Inspected	GBE 3356D
No.	Coverage (\$)	0.00
No. CMTD1800158/NSW	Excess (\$)	0.00
From GRACE TEO	Assign Date	09/01/2018
Vehicle Part	iculars & Condition	
Model	c.c	0
No. HIDDEN	Year of Reg.	
s No.	Colour	
ter -	Steering	
70	Modification	
ıl		
Condi	tions of Tyres	
Size	Make	Balance
ont Tyre		mm
ont Tyre		mm
ar Tyre		mm
ar Tyre		mm
Descript	tion of Damages	
Gener	al Information	
ent Date 08/01/2018	Inspection Date	09/01/2018
held at FASTECH AUTO PTE LTD		
1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
	Remarks	
NSPEC CORD	SINGAPORE 417883 TION WAS CONDUCTED ON A"W	1 17 17 17 17 18 17 18 17 18 17 18 18 18 18 18 18 18 18 18 18 18 18 18

icy Ty	Pe: OD /(TP) TP RES / TL / EVA	Case Handler	Typ	oist
	Nivither): Case handler to make sure all Inform		1,755	
min (Y-Date N-Date	Y-Date	N-Date
	Assign Form	1-Date N-Date	1-Date	N-Date
C	Reference No.	9		
C	Customer Code			
N	Assign From	4	_	
C	Assign Date		-	
C	Veh No (Inspected)	4	-	
C	Veh No (Insured)			
C	D.O.A			
C	Policy No			
C	Claim No			
C	Insurance Authorisation (CA /REV/REP)			
C	Report Type			
C	Weekend Charges	- 1000000000000000000000000000000000000		
N	Survey held at/Repairer			
C	Excess			
	or (Mavum): Case handler to make sure	the surveyor completed :	all required	information.
rveyo		the surveryor completed t	micquirea	mormoni
	nment Form			
C	Vehicle No	4	-	-
C	Regn Month/Year			
Ν.	Vehicle Type	9	-	
N	Make & Model			
C	Engine Capacity. (C.C)			
N	Colour			
C	Odometer. (Sp.Reading)			
C	Chassis No	9		
N	General Condition	9		
N	Steering	9		
N	Brake			
N	Modification (Modi)	2		
C	Tyre Size			
N	Tyre Make			
С	Tyre Balance			
С	Date of Inspection			
N	Survey held	4		
N	Des.of Damages 4			
\ Cuch	em - (Views/Merimen)			
C	Damaged Vehicle Photographs Uploaded			
				-
) Wor	kshop Estimate/Assignment Form		1	
N	ALL Parts condition		-	
C	Market Value for OD cases			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	, /		
C	Days of repair	4		
С	Finalised Amount			
C	Re-inspection Cases to Finalize within 5 Days			
Court	em - (Views/Merimen)			

Case Handler

Nivitha (LKK Auto)

From:

Teo, Grace <grace.teo@sompo.com.sg>

Sent:

Tuesday, 9 January 2018 10:59 AM

To:

admin-d@lkkauto.com; assignments@lkkauto.com

Cc:

Nancy Lam; Ngo, Sau Wei Shawn; Henry, Irene James

Subject:

CMTD1800158/NSW - ACCIDENT INVOLVING SKE2611S & GBE3356D ON

08.01.2018

Our Reference: CMTD1800158/NSW

Dear LKK AUTO,

Please make arrangement to conduct the survey for GBE3356D.

Please be informed that Shawn Ngo the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]

Sent: Tuesday, January 09, 2018 10:58 AM

To: Teo, Grace

Subject: RE: CMTD1800158/NSW - ACCIDENT INVOLVING SKE2611S & GBE3356D ON 08.01.2018

Dear Grace

Please arrange LKK Auto Consultants to survey the car.

Regards, Nancy Lam Fastech Auto Pte Ltd Tel: 6746 5405

Fax: 6745 8520

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Tuesday, January 9, 2018 10:51 AM

To: Nancy Lam <nancy.lam@fastechauto.com.sg>

Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1800158/NSW - ACCIDENT INVOLVING SKE2611S & GBE3356D ON 08.01.2018

Our Reference: CMTD1800158/NSW

Your Reference: GBE3356D

Without Prejudice

Date: 9th January 2018

Attention:

M/S FASTECH AUTO PTE LTD

Dear Nancy,

ACCIDENT INVOLVING SKE2611S & GBE3356D ON 08.01.2018

We refer to your Notice of Accident dated 08/01/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
	8 77	Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click <a href="https://example.com/here/bease-click-here/bease

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sq]

Sent: Monday, January 08, 2018 4:16 PM

To: Claims - Motor Survey

Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBE3356D

Hi Sir

My client claiming your insured SKE 2611S.

Please kindly arrange PRS for GBE 3356D.

Date of accident 08.01.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards, Nancy Lam Fastech Auto Pte Ltd

Tel: 6746 5405 Fax: 6745 8520

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 24 January 2018 12:10 PM

To:

'Teo, Grace'; assignments; Ngo, Sau Wei Shawn

Cc:

'Henry, Irene James'; SUR

Subject:

RE: CMTD1800158/NSW - ACCIDENT INVOLVING SKE2611S & GBE3356D ON

08.01.2018

Attachments:

CSSMO18000482Uqd3.pdf

Dear Shawn,

Enclosed herewith preliminary advice of GBE 3356D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)

Sent: Wednesday, 10 January 2018 5:15 PM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>; Ngo, Sau Wei Shawn

<Shawn.Ngo@sompo.com.sg>

Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: CMTD1800158/NSW - ACCIDENT INVOLVING SKE2611S & GBE3356D ON 08.01.2018

Dear Shawn,

Please be informed that we have inspected the vehicle GBE 3356D on 09/01/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 9 January, 2018 12:00 PM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR

<sur@lkkauto.com>

Subject: RE: CMTD1800158/NSW - ACCIDENT INVOLVING SKE2611S & GBE3356D ON 08.01.2018

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564315

Your Ref: CMTD1800158/NSW

Date: 24th January 2018

Our Ref: CS/SMO18000482/Uqd3

Without Prejudice

The Motor Claims Department Sompo Insurance

Attn: Grace

Nett Value

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. GBE 3356D .

We thank you for the instruction on _09/01/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/01/2018 at the premises of M/s FASTECH AUTO and have the following to report:-

: S\$ Workshop Estimate Amount 6,200.00 (Lump Sum) : S\$ Revised Estimate Amount "Check" Items Amount : S\$: S\$ Market Value LTA Reimbursement Value : S\$: S\$

Description of Damage: The vehicle sustained damages at the rear portion.



Comments/ Present Status: Damages consistent. Days of repair: 5 days. We have NOT authorize repair.

Yours faithfully

Marcus Chua Licensed Appraiser

Shiau Chan (ŁKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 10 January, 2018 5:15 PM

To:

'Teo, Grace'; assignments; 'Ngo, Sau Wei Shawn'

Cc:

'Henry, Irene James'; SUR

Subject:

RE: CMTD1800158/NSW - ACCIDENT INVOLVING SKE2611S & GBE3356D ON

08.01.2018

Dear Shawn,

Please be informed that we have inspected the vehicle GBE 3356D on 09/01/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 9 January, 2018 12:00 PM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR

<sur@lkkauto.com>

Subject: RE: CMTD1800158/NSW - ACCIDENT INVOLVING SKE2611S & GBE3356D ON 08.01.2018

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Tuesday, 9 January 2018 10:59 AM

To: admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Nancy Lam <nancy.lam@fastechauto.com.sg>; Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Henry, Irene

James <irene.henry@sompo.com.sg>

Subject: CMTD1800158/NSW - ACCIDENT INVOLVING SKE2611S & GBE3356D ON 08.01.2018

Our Reference: CMTD1800158/NSW

Dear LKK AUTO,

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	S .
Owner ID Type:	Business
Owner ID:	3385D
Vehicle Details	
Vehicle No.:	GBE3356D
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2564626
Chassis No.:	JTFHT02P400181275
Maximum Power Output:	*
Open Market Value:	\$27,741.00
Original Registration Date:	11 Nov 2015
First Registration Date:	11 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$1,388.00
Intended PARF Rebate D	etails
PARF Eligibility:	No
PARF Eligibility Expiry Date:	*
PARF Rebate Amount:	\$0.00
Intended COE Rebate De	tails
COE Expiry Date:	10 Nov 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,859.00
COE Rebate Amount:	\$29,656.00
Total Rebate Amount:	\$29,656.00

The information contained herein is correct as at 10 Jan 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	08/01/2018 19:19
Date Of Accident	08/01/2018 07:20
Exact Location Of Accident	BT BATOK WEST AVE 6 TWDS BT BATOK WEST AVE 5
Country/State of Loss	SINGAPORE
C	DETAILS OF OWN VEHICLE
Vehicle Registration Number	GBE3356D
Insured/Policyholder	
Name Of Registered Owner	THYE HONG GAOO
Co Reg No	53073385D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98573768
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3103531701
Cover Note Number	9
Driver	
Name of Driver	LIM YONG THYE
NRIC No	S1629065C
Date Of Birth	12/10/1964
Occupation	INDOOR
Date Of Driving Pass	02/08/1982
Driving Experience	35 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98573768

NOEMAIL

Address

BLK 124 PENDING RD #06-08

Postcode

670124

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: KOH MOY ENG

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKE2611S

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforecast.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My instance, my workshop and the General Instance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by my or postersed by my inturer (collectively the "Personal Information") and declose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law Erms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dualing with my instructions or responding to any enquiries by nie;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' leavers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/low firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (c) the information so collected under (d) above may be shared / disclosed
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with inquirements under any regulations, laws or court orders

Policyhydder's Signature

Date & Time:

Driver's 9 greature

(if driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature Name

NRIC/FIN No.:

Accident Sketch Plan

		000	
		: 14	GBE 835 G.D
	6	B	SKE 26115
LIKI ELACK LEM	Α		
chamor dans	8		
But a across	(manual)		
Ger boes -			
SCRIBE CIRCUMSTANCES OF THE ACCIDI	ENT		
on 08/01/2018	CAT C	,D=~4	LO CIM.
lace much to	ents a	any Panit	Burok wixer
the 6 towards Biri Biron West Are !			
I was styrement (du -1 =	we Fr	on trustic.
			1000
cred lights.	Sudden	in behille	B KH
	Sudden	n behill	B KH
try con.			
try con.	NUR P	1 peases	,or
try con.		1 peases	,or
my com.	NUR P	you how	Eny .
my com.	S68118053	you how	er. Eng
my com.	S68118053	you how	Eny .
my com.	S68118053	you how	Eny .
hy con .	S68118053	you how	Eny .
my com.	SERITE B	Loss inc	Eny .
DECLARATION	SERIE B	Loss inc	Eny .

FASTECH AUTO PTE LTD

NSP Alloral Lleh 2/5 & 6200 9/1/18 5 dg.

Su \$480.00 X

Fuc \$20.00 X

VEH NO:GBE3356D

1SET

1PCS

REAR REVERSE CAMERA

REAR LICENCE PLATE

QTY	PARTICULAR	AMOUNTS\$
LIST ITEM		
1PCS	REAR WIND SCREEN	11 \$1,488.10 X
1PCS	REAR WIND SCREEN MOULDING	, ru \$110.00
1PCS	TAILGATE	3.0h 30 \$2,150.70
1PCS	TAILGATE INNER LOCK	1.1.1.1 \$395.60 V
1PCS	TAILGATE LOCK STRICKER	11 \$40.10X
1PCS	TAILGATE INNER TRIM BOARD	word/1910 \$385.20
1SET	TAILGATE INNER TRIM BOARD CLIPS	nu \$50.00 V
1PCS	TAILGATE OUTER HANDLE	11 \$266.50 K
1PCS	TAILGATE REAR LOGO	su \$45.90
1PCS	TAILGATE WEATHERSTRIP	, 1~1 \$395.10
2PCS	TAILLAMPS @\$303.10	Mscne \$606.20 12c
2PCS	TAILLAMP LOWER APRON GARNISHS @\$169.30	MS m \$338.60 12 C
2PCS	TAILLAMP FILTER PANELS @\$245.10	\$490.20 X
1PCS	REAR BUMPER	30/Bel \$599.30
4PCS	REAR BUMPER LOWER BRACKETS@\$45.00	Sel \$180.00 -
1SET	REAR BUMPER CLIPS	per \$50.00
1PCS	REAR END PANEL OUTER	\$499.50
1PCS	REAR ENDPANEL INNER	\$1,012.10
1PCS	REAR END PANEL TOP STEEL PLATE	\$269.10
1PCS	REAR FLOOR PANEL	↑ \$2,410.10
1PCS	REAR SPARE TYRE BRACKET	Bul \$263.50
1PCS	REAR SPARE TYRE BRACKET HOOK	But \$66.50
2PCS	REAR BUMPER SIDE HOLDERS@\$155.00	su \$230.00
1PCS	REAR EXHAUST PIPE	0/-1/ 11 \$971.00X
2PCS	REAR EXHAUST PIPE MOUNTINGS @\$65.00	12 \$130.00 ×
		\$13,443.30
		7(74.70
		67811
		7 281.1
	S.NETT	
1PCS	REAR WINDSCREEN SEALENT	ru \$50.00 40
1PCS	REAR WINDSCREEN INNER SEAL	ne \$50.00 30
1PCS	TAILGATE 70KM/H STICKER	rec \$20.00 10
1PCS	TAILGATE 5 PAX STICKER	rec \$20.00/0
1PCS	REAR END PANEL SEALENT	M \$50.00 ~
1SET	REAR REVERSE SENSOR	show \$280.00200
2010/10/10	120 (2010 120 130 130 130 130 130 130 130 130 130 13	

TO CHECK WIRING	\$80.00 30
TO DISMANTLE &REPLACING REVERSE SENSOR	\$80.00 50
TO DISMANTLE &REFIX REAR WINDSCREEN	\$150.00 /20
TO TRANSFER TAILGATE COMPONENTS	\$100.00 60
TO DISMANTLE &REPLACING REVERSE CAMERA	ري \$100.00 مح
TO SPRAY RUST PROOFING	\$120.00 80
TO DISMANTLE & REFIX REAR EXHAUST	1 \$100.00 X
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN &	\$1,200.00 900
REPLACING PARTS	,
TO PUTTY &SPRAY PAINTING	\$1,500.00 800
	TOTAL \$17,843.30
	7811.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resum ey before, after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis
- No diego modification(s) is allowed
- Supplementary tem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



5a.

5b.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

10		Affiliated to Federation Internati	onale Des Experts En Autom	nobile
SON	MPO INSURANCE	SINGAPORE PL	Ref : CS/SMO18000	482/Uqd3n2
#05-	RAFFLES PLACE -01/06 GAPORE LAND TO	OWERSINGAPORE 048623	Date: 25-01-2018 Code: SMO	
1.		Policy Particulars	:- THIRD PARTY CLAI	M
	Insured Veh.	SKE 2611S	Veh. Inspected	GBE 3356D
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD1800158/NSW	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	09/01/2018
2.	Village Constitution	Vehicle Part	iculars & Condition	
	Make & Model	TOYOTA HIACE (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JTFHT02P400181275	Colour	SILVER
	Odometer	80572	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Condi	tions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
4.			tion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE R	EAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gener	al Information	
	Accident Date	08/01/2018	Inspection Date	09/01/2018
	Survey held at	FASTECH AUTO PTE LTD	- Marie	
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

Remarks

Estimate Days of Repair

5 Working Days

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

ESTIMATED NORMAL PERIOD FOR REPAIR:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 3356D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WIND SCREEN	NOT NECESSARY	1,488.10	
1	REAR WIND SCREEN MOULDING	NECESSARY	110.00	110.00
1	TAILGATE	BADLY DENTED	2,150.70	2,150.70
1	TAILGATE INNER LOCK	JAMMED / TWISTED	395.60	395.60
1	TAILGATE LOCK STRICKER	NOT NECESSARY	40.10	
1	TAILGATE INNER TRIM BOARD	WARPED / TORN	385.20	385.20
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE OUTER HANDLE	NOT NECESSARY	266.50	
1	TAILGATE REAR LOGO	NECESSARY	45.90	45.90
1	TAILGATE WEATHERSTRIP	TWISTED	395.10	395.10
2	TAILLAMPS @\$303.10	N/S CRACKED	606.20	303.10
2	TAILLAMP LOWER APRON GARNISHS @\$169.30	N/S DENTED	338.60	169.30
2	TAILLAMP FILTER PANELS @\$245.10	TO REPAIR SEE LABOUR	490.20	554000000
1	REAR BUMPER	DENTED / BENT	599.30	599.30
4	REAR BUMPER LOWER BRACKETS @\$45.00	BENT	180.00	180.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL OUTER	BADLY DENTED	499.50	499.50
1	REAR END PANEL INNER	BADLY DENTED	1,012.10	1,012.10
1	REAR END PANEL TOP STEEL PLATE	BENT	269.10	269.10
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	2,410.10	
1	REAR SPARE TYRE BRACKET	BENT	263.50	263.50
1	REAR SPARE TYRE BRACKET HOOK	BENT	66.50	66.50
2	REAR BUMPER SIDE HOLDERS @\$155.00	NECESSARY	230.00	230.00
1	REAR EXHAUST PIPE	NOT NECESSARY	971.00	155
2	REAR EXHAUST PIPE MOUNTINGS @\$65.00	NOT NECESSARY	130.00	
	LESS 25% DISCOUNT		57	-1,793.73
			13,443.30	5,381.17
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	30.00
	TAILGATE 70KM/H STICKER (SN)	NECESSARY	20.00	10.00
	TAILGATE 5 PAX STICKER (SN)	NECESSARY	20.00	

Report Ref No. CS/SMO18000482/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR REVERSE CAMERA (SN)	SERVICEABLE	480.00	
1	REAR LICENCE PLATE (SN)	SERVICEABLE	20.00	
	LABOUR		970.00	340.00
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE COMPONENTS.		100.00	60.00
	TO DISMANTLE & REPLACING REVERSE CAMERA.		100.00	50.00
	TO SPRAY RUST PROOFING.		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP FILTER PANELS AND REAR FLOOR PANEL.		1,200.00	900.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	800.00
			3,430.00	2,090.00
- 15	GRAND TOTAL		17,843.30	7,811.17

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	6,200.00
--	----------

Report Ref No. CS/SMO18000482/Uqd3n2

CHUA KANG SENG

Licensed Appraiser