

22/03/2012

ASS. REC. BY:

REF: CS/FCI18000494/Urd3¹²

Special Instruction:

Survivor:

Marcus

ASSIGNMENT (Office)

From (Person):

Teo Swee Keong

of

FCI

Date/Time:

08/01/18 @ 5:35pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 2234 U

Insured:

SHC 3720 A

at Workshop m/s

Cycle & Camiag Fulco Motor

Tel:

6594 9163

of

330 ubi Rd 3, 408650

Policy No:

Claim No:

SHC3720A (01-01-2018)

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 01/01/2018

11/01/2017 @ 10:00-10:30 am owner waiting

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

8:51am @ 01/01/18

Person Contacted:

Marsler

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 2234U - X

SHC 3720A - CS/TMT16024456/H1/bn2

D.O.A: 21/12/2016

Sent preli through email.

FCI

11/01/2018

SLH 22344

10 16

CA/

int. honor
Ref

1590

22896

JMYSRCYIAGU005942

Steering Lock Jammed / Locked / Burnt

Brake Interlock Jammed / Locked / Burnt

Mod Nil / STD A/Rim on

Tyre Size 205/60R16

BS/DUN/EXNOVA/GR/PS/LIZA/MIC/OHTSU/PIR/SUMI

TOYO/OKO

Front

Rear

Left

Right

Surveyed at

Des of Damages: Frt / Rear / OS / NS / U/G / Roof top

The U/G / Chassis frame / Body Structure affected due to collision

Estimated Cost

Q2 / TP RES / CO RES / EVA / INV / MY

SLH 2234
Cycle & Camigga Fulco Motor
No. 330 Ubi Rd 3, 408650

Insured

Policy No

Claim No

Sum Insured

Excess

Claims Record: 10-10-30am @
owner waiting

Policy Condition

Remark: The van had commenced its
repair at the time of inspection.



Ball on / Market Value

75k

QAC Accident Report Consistent? Yes or No

QAC Rep Seen Consistent? Yes or No

Est Repair 3 days Rep: Yes or No

Est Cost 131 Rep: Yes or No

QAC / REV / REP 24 HRS wp

Date

Person Contacted

Vehicle IN / OUT

Date Time Action Instruction

Rep 8k. L7A 55947

28/1/18 confirmed final fig #2851.60 with Chris

Ref: 6251.30, 691.

Est Time Re-Report



Prelim. Report

typist



Final Report

Est Time Re-Report

Days Of Repair 3

Resurvey No. of Trip 1

Line Fee

170

50

30

33

Add Fee:



Steered



Interie



Recon



Tag &

Report Format

TP

Auto Sum

2851.60

303




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000494/Urd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-01-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3720A	Veh. Inspected	SLH 2234U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	TEO SWEE KEONG	Assign Date	09/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/01/2018	Inspection Date	09/01/2018	
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Catherine Chong (LKK Auto)

From: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>
Sent: Monday, 8 January, 2018 5:35 PM
To: 'assignments@lkkauto.com'
Cc: May Chua Hui Chin; mars.ler@ccfulco.com.sg
Subject: NEW SURVEY ASSIGNMENT - TP VEH REF: SLH2234U OUR REF: SHC3720A DOA 01/01/2018
Attachments: FW: Re:Accident On 01/01/2018 Involving Our Insured SLH2234U And Your In... (4.64 MB); MOTOR SURVEY ASSIGNMENT.pdf

Dear Sirs

New survey request for your handling.

Thanks and Regards,

SK Teo
Motor Claims Dept

36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 | Company Regn. No. 195000106C
email: MotorClaims@first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA");

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Mars Ler [<mailto:mars.ler@ccfulco.com.sg>]
Sent: Monday, January 08, 2018 2:33 PM
To: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>
Cc: May Chua Hui Chin <maychua@first-insurance.com.sg>; Chris Bulaclac <chris.bulaclac@ccfulco.com.sg>
Subject: RE: YR REF: SLH2234U OUR REF: SHC3720A DOA 01/01/2018

Dear Teo ,

Please kindly assign 1. LKK Auto Consultants Pte Ltd for survey .

Thank You,

Best regards

Mars Ler
B & P Service Advisor
Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3 Singapore 408650
D/D 65949163 H/P 91792566

From: Teo Swee Keong [<mailto:TeoSweeKeong@first-insurance.com.sg>]
Sent: Monday, 8 January, 2018 1:01 PM
To: Mars Ler

Cc: May Chua Hui Chin

Subject: YR REF: SLH2234U OUR REF: SHC3720A DOA 01/01/2018

Dear Sirs,

We refer to your survey request dated 08/01/2018.

Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.

1. LKK Auto Consultants Pte Ltd
2. Vicom Ltd

Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.

If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.

Thank you.

Thanks and Regards,

SK Teo
Motor Claims Dept

36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 | Company Regn. No. 195000106C
email: MotorClaims@first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Caroline Cabrera
Sent: Monday, January 08, 2018 9:44 AM
To: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>
Subject: FW: Re:Accident On 01/01/2018 Involving Our Insured SLH2234U And Your Insured SHC3720A

Dear SK,

For survey

Thanks & Regards
Caroline Cabrera
Motor Claims Department

First Capital Insurance Ltd | A FAIRFAX Company
36 Robinson Road #16-01 City House| Singapore 068877 | Reg. No. 195000106C
D: 6507 3848 | F: 6507 3849
email: www.first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing of your personal data.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Our Ref: CS/FCI18000494/Urd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 2234U .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/01/2018 at the premises of M/s CYCLE & CARRIAGE.FULCO MOTOR DEALER PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 9,102.90 .
Revised Estimate Amount	: S\$ 2,851.60 .
"Check" Items Amount	: S\$ 700.30 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at rear portion.



Yours faithfully
MARCUS CHUA
Automotive Assessor

AXA FORM



redefining insurance

Date 2/9/17To: Owner of Vehicle Number SH 22346The following has been advised to you via your workshop, _____ through their staff, Sahlan

Please tick the applicable box if you had been advised on the content as seen below

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☒ You had been advised by the workshop on the liability and merits of the case accordingly
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☐ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☒ Others Claim 3rd party @ other workshop

Signed and acknowledge by

[Signature]
Name and signature of policyholder/authorised driver

[Signature]
Name and signature of workshop personnel including company stamp

POL.316



POLIS DIRAJA MALAYSIA
CAWANGAN TRAFIK
IBU PEJABAT POLIS DAERAH JOHOR BAHRU SELATAN,
JALAN TEBRAU, 80250 JOHOR BAHRU
07-2237977

Resit Akuan Penerimaan Repot Polis :

Nama Pengadu : RASHIDAH BIBI BINTE ABDULLAH
 No Kad Pengenalan / Paspot : E6168681K
 No Repot Polis : TRAFIK JOHOR BAHRU(S)/000034/18
 Tarikh @ Masa Repot Polis : 01/01/2018 @ 12:10
 Pengesahan Penerimaan Repot :

.....
 Tandatangan Ketua Pejabat Pertanyaan

Pegawai Penyasat :

Nama Pegawai Penyasat : (R171741) SJN MOHD FAIZ BIN ZAHARI
 Tempat Tugas : JOHOR, J/BAHRU SELATAN
 No Telefon Pejabat : No Telefon Bimbit : 012-2958657
 Tarikh @ masa Perjumpaan : 1/1/18 @ 1240 hrs
 Pengesahan Penerimaan Repot : (MOHD FAIZ BIN ZAHARI) SJN 171741

Pegawai Penyasat
 Balai Polis Trafik
 IPPD Johor Bahru (S)

.....
 Tandatangan Pegawai Penyasat

Juru Gambar :

Nama : No Badan : Pangkat :

Tarikh @ Masa Gambar Diambil :

Pengesahan Gambar Diambil :

.....
 Tandatangan Juru Gambar

Unit Pembekalan Dokumen Siasatan :

No Telefon Unit Pembekalan Dokumen :

Waktu Pejabat :

Isnin - Khamis
 08:00 Pagi - 01:00 Tengah Hari
 02:00 Petang - 04:30 Petang
 Jumaat :
 08:00 Pagi - 12:30 Tengah Hari
 02:45 Petang - 04:30 Petang
 Cuti Umum / Khas : Tutup

Jenis Dokumen Dibekal Kepada Pengadu :

1. Salinan Repot Polis ☐
2. Gambar Kenderaan ☐
3. Rajah Kasar Kemalangan ☐
4. Keputusan Siasatan ☐
5. Lain-lain Dokumen ☐

Tarikh @ Masa Dokumen Diserah :

Waktu Pejabat :

Ahad - Rabu:
 08:00 Pagi - 01:00 Tengah Hari
 02:00 Petang - 04:30 Petang
 Khamis
 08:00 Pagi - 01:00 Tengah Hari
 02:00 Petang - 03:00 Petang
 Jumaat, Sabtu - Tutup
 Cuti Umum / Khas - Tutup

Pengesahan Kaunter Pembekalan Dokumen :

.....
 Tandatangan Pegawai Kaunter Pembekalan Dokumen



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : TRAFIK JOHOR BAHRU(S) **Pegawai Penyiasat** : R171741
Daerah : J/BAHRU SELATAN
Kontinjen : JOHOR
No Repot : TRAFIK JOHOR BAHRU(S)/000034/18
Tarikh : 01/01/2018
Waktu : 1210 PM
Bahasa Diterima : B. Malaysia

Butir-butir Penerima Repot

Nama : HASRIN B ABD RAHMAN **No Personel** : R117756 **Pangkat** : KPL
Butir-butir Jurubahasa (Jika Ada)
Nama : --- **No K/P (Baru)** : --- **No Polis/Tentera** : ---
No Paspot : --- **Bahasa Asal** : ---
Alamat : ---

Butir-butir Pengadu

Nama : RASHIDAH BIBI BINTE ABDULLAH
No K/P (Baru) : --- **No Polis/Tentera** : --- **No Paspot** : E6168681K
No Sijil Beranak : ---
Jantina : Perempuan **Tarikh Lahir** : 19/03/1961 **Umur** : 56 tahun 9 bulan
Keturunan : Pakistan **Warganegara** : Singapore
Pekerjaan : -
Alamat Tempat Tinggal : BLK 774 # 09-392 PASIR RIS ST 71 , SINGAPORE, 510774
Alamat Ibu/Bapa : ---
Alamat Pejabat : ---
No Tel (Rumah) : --- **No Tel (Pejabat)** : --- **No Tel (HP)** : 6591135605
Emel : ---

Pengadu Menyatakan:-

PADA 01/01/2018 JAM LEBIH KURANG 1140HRS SAYA MEMANDU M/KAR NO SLK42234U DARI SINGAPURA HENDAK KE JOHOR BAHRU. SEMASA SAYA SAMPAI DI LORONG 8 HENDAK COP PASSPORT DI DALAM BANGUNAN SULTAN ISKANDAR SEDANG MENUNGU UNTUK COP PASSPORT TIBA-TIBA SEBUAH M/TEKSI NO SHC3720A DARI ARAH BELAKANG MELANGGAR M/KAR SAYA. NAMA PEMANDU M/TEKSI TERSEBUT NG HONG WEE NO IC/ S0111621E. KEROSAKAN M/KAR SAYA DI BAHAGIAN BELAKANG BUMPER, SENSOR BELAKANG, NO PLAT DAN LAIN-LAIN KEROSAKAN SAYA BELUM PASTI LAGI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu: **Tandatangan Jurubahasa (Jika ada):** **Tandatangan Penerima Repot:**

SALINAN YANG DISAHKAN BENAR
(HANYA UNTUK TUNTUTAN SIVIL)

KETUA TRAFIK DAERAH JOHOR BAHRU



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

account number
 12000

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
 -Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	MOHAMED SALIM MOHD SANALLAH	Certificate number	GA280091 / 1
Cover	Comprehensive	Chassis number	JMYSRCY1AGU005942
Plan name	Peace	Engine number	4A92CL7525
NCD applicable	50%		
Vehicle registration number	SLH2234U		
Period of Insurance	from 27/10/2017 to 26/10/2018 (both dates inclusive)		
Finance loan company	HL BANK		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
- (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 300.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1499891H

NAME

RASHIDAH BIBI BINTE
ABDULLAH

رشيده بنتي عبد الله

PLACE

PAKISTANI

Date of birth

18-03-1961

Expiry of IDP

SINGAPORE



FOR C&C USE ONLY

REPUBLIC OF SINGAPORE DRIVING LICENCE



FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

CLASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which exceeds 3000 kg not exceed 1000 kg

Class 3

28 Jun 1984

FOR C&C USE ONLY



NP 4284

2753188



NP 4284

FOR C&C USE ONLY

28 Jun 1984

APT 514 77A PANGLOSS RD SINGAPORE 510774

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4024E
Vehicle Details	
Vehicle No.:	SLH2234U
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jan 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	4A92CL7525
Chassis No.:	JMYSRCY1AGU005942
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$14,229.00
Original Registration Date:	27 Oct 2016
First Registration Date:	27 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$14,229.00 7114
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Oct 2026
PARF Rebate Amount:	\$10,671.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,507.00
COE Rebate Amount:	\$45,276.00
Total Rebate Amount:	\$55,947.00

The information contained herein is correct as at 11 Jan 2018



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr MOHAMED SALIM S/O MOHD SANAULLAH Blk 774 Pasir Ris St 71 #09-392 Singapore 510774	Cust No/Name /Mr Mohamed Salim S/O Mohd Sanau Reg No/Reg Date SLH2234U*1F / 27/10/2016 Date In/Mileage 04/01/2018/ 0 Chassis No JMYSRCY1AGU005942 Engine No 4A92CL7525 Make/Model MIT/16MY LANCER EX 1.6 4AT Colour/Trim P02 / BK
Contact No Mobile: 91135605	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	06/01/2018/ 10:09	DS	218 / MarsLer	50072
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS			60	80.00
S MIPNT88088	TO REMOVE AND RE-INSTALL REAR CAPERTING & TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFETCED AREAS			11X	600.00
S MIPNT88088	TO REPLACE REAR REVERSE CAMERA LENS			✓	300.00
S MIPNT88088	TO REPLACE REAR BUMPER,REINFORCEMENT,ETC -CUT & RE-WELD REAR END PANEL STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS			800	2400.00
S MIPNT88088	TO APPLY SEALANT ON NEW PANEL			11X	200.00
S MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS			840	2520.00
S MIPNT88088	TO SUPPLY AND REPLACE REAR REVERSE SENSOR			11X	280.00
M SUNDRY	C & C LOGO			11X	35.00
M SUNDRY	MIVEC EMBLEM			20	50.00
P JJ6410B832	FACE,RR BUMPER	1.00	852.00	10.00	766.80
P JJMU488006	CLIP,RR BUMPER	10.00	2.00	10.00	18.00
P JJ6430A083	BRACKET,LICENSE PLAT	1.00	13.00	10.00	11.70
M JJ6410C543	LH BRKT,R/BMPR FACE	1.00	16.00	10.00	14.40
M JJ6410C544	RH BRKT,R/BMPR FACE	1.00	16.00	10.00	14.40
M JJ6410B929	REINFORCEMENT,RR BUM	1.00	220.00	10.00	198.00
M JJ6410B028	UPR REINFORCEMENT,RR	1.00	85.00	10.00	76.50
M JJ5281A179	PANEL,RR END	1.00	529.00	10.00	476.10
P JJMR574899	MARK,LANCER	1.00	48.00	10.00	43.20
M JJ7415A111	MARK,THREE-DIA	1.00	49.00	10.00	44.10
M JJ8355A039	REFLECTOR,LH	1.00	23.00	10.00	20.70

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr MOHAMED SALIM S/O MOHD SANAULLAH Blk 774 Pasir Ris St 71 #09-392 Singapore 510774	Cust No/Name /Mr Mohamed Salim S/O Mohd Sanau Reg No/Reg Date SLH2234U*1F / 27/10/2016 Date In/Mileage 04/01/2018/ 0 Chassis No JMYSRCY1AGU005942 Engine No 4A92CL7525 Make/Model MIT/16MY LANCER EX 1.6 4AT Colour/Trim P02 / BK
Contact No Mobile: 91135605	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00001	Cash	06/01/2018/ 10:09	DS	218 / MarsLer	50072		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	JJ8355A040	REFLECTOR,RH	AM	1.00	23.00	10.00	20.70
M	JJ8637A134	BUZZER,KEYLESS OPERA	mm	1.00	162.00	10.00	145.80
P	W8330A001LED	LED TAILLAMP KIT	mm	1.00	855.00	10.00	769.50
P	JJMR200300	CLIP, BUMPER	mm	10.00	2.00	10.00	18.00
Z	NOTES						
ACCIDENT ON 01/01/2018 ALONG JOHORE BAHRU CHECKPOINT							
OWNER CLAIMING THIRD PARTY							
REQUIRED REPLACEMENT CAR							
TP : SHC3720A							

Estimate

not a bill
whpbl before 11/1/18
327.

Auto Consultants hence notify pairer of the following:

- Survey before/after spray painting
- Display damaged part(s) during resurvey
- Prices are subject to confirmation
- Party survey is on a "Without Prejudice" basis
- Modification(s) is allowed
- Expenditure item(s) must be resurveyed and
- Subject to final approval from Insurance Company

Signed by Repairer

Confirm & accepted by

Parts	2,637.90
Labour	0.00
Standard Menu	0.00
Specialist Job	6,380.00
Others(Lub,etc)	0.00
Sundry	85.00
Total(w/o GST)	9,102.90

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877 Contact No	Cust No/Name	/Mr Mohamed Salim S/O Mohd Sanau
	Reg No/Reg Date	SLH2234U*1F / 27/10/2016
	Date In/Mileage	04/01/2018/ 0
	Chassis No	JMYSRCY1AGU005942
	Engine No	4A92CL7525
	Make/Model	MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	25/01/2018/ 09:28	DS	323 / ChrisBulaclac	50072

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				60.00
S MIPNT88088 TO REPLACE REAR REVERSE CAMERA LENS				300.00
S MIPNT88088 TO REPLACE REAR BUMPER, REINFORCEMENT, ETC - CUT & RE-WELD REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				800.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				840.00
M SUNDRY MIVEC EMBLEM				20.00
P JJ6410B832 FACE, RR BUMPER	4.00	852.00	10.00	766.80
P JJMU488006 CLIP, RR BUMPER	10.00	2.00	10.00	18.00
M JJ6410C543 LH BRKT, R/BMPR FACE	1.00	16.00	10.00	14.40
M JJ6410C544 RH BRKT, R/BMPR FACE	1.00	16.00	10.00	14.40
P JJMR200300 CLIP, BUMPER	10.00	2.00	10.00	18.00
Z NOTES ACCIDENT ON 01/01/2018 ALONG JOHORE BAHRU CHECKPOINT OWNER CLAIMING THIRD PARTY LOSS OF USE 03DAYS x S\$80.00 = S\$240.00 TP : SHC3720A TP INS : FIRST CAPITAL				

Confirm & accepted by

Parts	831.60
Labour	0.00
Standard Menu	0.00
Specialist Job	2,000.00
Others (Lub, etc)	0.00
Sundry	20.00
Total (w/o GST)	2,851.60

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18000494/Urd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3720A	Veh. Inspected	SLH 2234U	
Policy No.		Coverage (\$)	0.00	
Claim No.	SHC3720A (01.01.2018)	Excess (\$)	0.00	
Assign From	TEO SWEE KEONG	Assign Date	08/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER (A)	c.c	1590	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JMYSRCY1AGU005942	Colour	RED	
Odometer	22996	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	8 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	8 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	8 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/01/2018	Inspection Date	11/01/2018	
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2234U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FACE,RR BUMPER (SN)	DENTED / DEFORMED	766.80	766.80
10	CLIP,RR BUMPER (SN)	NECESSARY	18.00	18.00
1	BRACKET,LICENSE PLAT (SN)	NOT NECESSARY	11.70	-
1	LH BRKT,R/BMPR FACE (SN)	NECESSARY	14.40	14.40
1	RH BRKT,R/BMPR FACE (SN)	NECESSARY	14.40	14.40
1	REINFORCEMENT,RR BUM (SN)	TO REPAIR SEE LABOUR	198.00	-
1	UPR REINFORCEMENT,RR (SN)	TO REPAIR SEE LABOUR	76.50	-
1	PANEL,RR END (SN)	TO REPAIR SEE LABOUR	476.10	-
1	MARK,LANCER (SN)	NOT NECESSARY	43.20	-
1	MARK,THREE-DIA (SN)	NOT NECESSARY	44.10	-
1	REFLECTOR,LH (SN)	NOT NECESSARY	20.70	-
1	REFLECTOR,RH (SN)	NOT NECESSARY	20.70	-
1	BUZZER,KEYLESS OPERA (SN)	NOT NECESSARY	145.80	-
1	LED TAILLAMP KIT (SN)	NOT NECESSARY	769.50	-
10	CLIP,BUMPER (SN)	NECESSARY	18.00	18.00
1	C&C LOGO (SN)	NOT NECESSARY	35.00	-
1	MIVEC EMBLEM (SN)	NECESSARY	50.00	20.00
			2,722.90	851.60
<u>LABOUR</u>				
TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS.			80.00	60.00
TO REMOVE AND RE-INSTALL REAR CAPERTING & TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS.		NOT NECESSARY	600.00	-
TO REPLACE REAR REVERSE CAMERA LENS.			300.00	300.00
TO REPLACE REAR BUMPER,REINFORCEMENT,ETC-CUT & RE-WELD REAR END PANEL,STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF REINFORCEMENT,RR BUM,UPR			2,400.00	800.00

Report Ref No. CS/FC118000494/Urd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY SEALANT ON NEW PANEL.	NOT NECESSARY	200.00	-
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS.		2,520.00	840.00
	TO SUPPLY AND REPLACE REAR REVERSE SENSOR.	NOT NECESSARY	280.00	-
			6,380.00	2,000.00
GRAND TOTAL			9,102.90	2,851.60
RECOMMENDED COST OF REPAIRS				2,851.60

Report Ref No. CS/FCI18000494/Urd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.