

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7309P

DATE 8/1/2018 10:53

MAKE :

MODEL : HYUNDAI SONATA

AC

DOA: 06.01.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Sonata Plate <i>SW</i>			\$ 43.60	X
	Boot Lid Hyundai Plate <i>SW</i>			\$ 24.20	X
	Boot Lid 'H' Emblem <i>SW</i>			\$ 26.10	X
	Boot Lid CRDI Plate <i>SW Hec</i>			\$ 22.70	✓
	Rear Bumper <i>SW</i>			\$ 578.40	X
	Rear Bumper Reinforcement <i>SW</i>			\$ 483.30	X
	Rear Bumper Clip <i>Hec</i>			\$ 22.00	✓
	Rear Bumper Sponge <i>SW</i>			\$ 137.40	X
	Rear Bumper Under Cover <i>SW</i>			\$ 185.80	X
	SUB TOTAL			\$ 1,523.50	
	LESS 20%			\$ 304.70	
	DISCOUNTED TOTAL			\$ 1,218.80	
	Boot Lid Comfort Logo & Tel No. Sticker <i>SW</i>			\$ 30.00	Nett ✓
	Rear Bumper Rubber Mat <i>NR</i>			\$ 50.00	Nett X
	Rear Fender Advertisement Logo (LH/RH) <i>Hec</i>		\$ 100.00	\$ 200.00	Nett ✓
				\$ 280.00	
	Labour Charge				
	Panel Beating			\$ 350.00	300/-
	Spray Painting Charge			\$ 400.00	300/-
	TOTAL LABOUR			\$ 750.00	
	ESTIMATE TOTAL			\$ 2,248.80	
08/01/2018 e1430m Hut Anwar L/Smm 2/2/18 2/KC 2/KC Larry Ng LKK Auto Consultants hereby notify the Reparer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					