



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC6/III18000515/Ups3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 09-01-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 6014X	Veh. Inspected	SLH 696H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/01/2018	Inspection Date	09/01/2018
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



M/S INDIA INT'L INS PTE LTD
64 CECIL STREET
#05-01 IOB BUILDING
SINGAPORE 049711

Attention: Motor Claim Department

RE : VEHICLE NO. SLH696H BENZ WDD2040312A825997

Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6
Ark@KB Singapore 417892
Email: vfixauto@gmail.com
Tel: 64489268 Fax: 64452368

ESTIMATE

DATE : 05/01/2018
ACC DATE : 03/01/2018
REF NO. : VFIX-TP20180398
POLICY NO. :

DESCRIPTION	AMOUNT S\$
1 1 REAR BUMPER (AMG) <i>one/de 1980</i>	2,665.00
2 1 REAR BUMPER LOWER SPOILER <i>one</i>	550.00
3 1 REAR BUMPER CARRIER BASE RH <i>one</i>	49.00
4 1 REAR BUMPER CARRIER BASE LH <i>one</i>	49.00
5 1 REAR BUMPER GUIDE RH <i>one</i>	35.00
6 1 REAR BUMPER GUIDE LH <i>one</i>	35.00
7 1 REAR BUMPER FRAME <i>one</i>	122.00
8 1 REAR BUMPER REINFORCEMENT <i>one</i>	460.00
9 1 TAIL LAMP LH <i>one</i>	680.00
10 1 EXHUAUST MUFFLER REAR <i>one LR200S.N</i>	1,105.00
	5,750.00
LESS 10%	575.00
	\$ 5,175.00

SPECIAL NETT	AMOUNT S\$
1 2 REVERSE SENSOR <i>one</i> 320.00	640.00
2 8 BUMPER CLIP <i>one</i>	24.00
	\$ 664.00

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged body panels with all necessary components/attachments apply hot-works where necessary straighten rear end panel repair/reshape dented panels in accordance with factory specifications,replace new parts refit align into position refit all necessary components/attachments <i>300</i>	1,200.00
2 To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials <i>400</i>	1,000.00
3 To remove,replace rear exhaust muffler with all necessary components <i>80</i>	120.00
	\$ 2,320.00

GRAND TOTAL : \$ 8,159.00 *4010.3*

SINGAPORE DOLLARS : EIGHT THOUSAND ONE HUNDRED & FIFTY NINE ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hereby
the Repairer of the following:
• To survey before/after spray painting
• To supply materials and labour only
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	60671
Vehicle Details	
Vehicle No.:	SLH696H
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jan 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 BLUEEFFICIENCY
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	27491030037221
Chassis No.:	WDD2040312A825997
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$30,896.00
Original Registration Date:	28 Mar 2013
First Registration Date:	28 Mar 2013
Transfer Count:	2
Actual ARF Paid:	\$25,896.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Mar 2023
PARF Rebate Amount:	\$19,422.00
Intended COE Rebate Details	
COE Expiry Date:	27 Mar 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$78,301.00
COE Rebate Amount:	\$40,813.00
Total Rebate Amount:	\$60,235.00

The information contained herein is correct as at 10 Jan 2018

OK

M/S INDIA INT'L INS PTE LTD
64 CECIL STREET
#05-01 IOB BUILDING
SINGAPORE 049711

Attention: Motor Claim Department

RE : VEHICLE NO. SLH696H BENZ WDD2040312A825997

Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6
Ark@KB Singapore 417892
Email: vfixauto@gmail.com
Tel: 64489268 Fax: 64452368

ESTIMATE

DATE : 05/01/2018
ACC DATE : 03/01/2018
REF NO. : VFIX-TP20180398
POLICY NO. :

not Adherent
Mark
4/55
3dy.
9/1/18
blue pen. After
sign.

DESCRIPTION	AMOUNT S\$
1 1 REAR BUMPER (AMG) <i>one/De</i>	2,665.00 —
2 1 REAR BUMPER LOWER SPOILER <i>ml</i>	550.00 —
3 1 REAR BUMPER CARRIER BASE RH <i>11</i>	49.00 <i>q</i>
4 1 REAR BUMPER CARRIER BASE LH <i>11</i>	49.00 <i>q</i>
5 1 REAR BUMPER GUIDE RH <i>11</i>	35.00 <i>q</i>
6 1 REAR BUMPER GUIDE LH <i>11</i>	35.00 —
7 1 REAR BUMPER FRAME	122.00 ?
8 1 REAR BUMPER REINFORCEMENT	460.00 ?
9 1 TAIL LAMP LH <i>11</i>	680.00 <i>X</i>
10 1 EXHUAUST MUFFLER REAR	1,105.00 ?
	5,750.00
LESS 10%	575.00
	\$ 5,175.00

SPECIAL NETT	AMOUNT S\$
1 2 REVERSE SENSOR <i>221</i>	320.00 <i>shut</i> 640.00 SN <i>q c</i>
2 8 BUMPER CLIP	<i>nu</i> 24.00 SN —
	\$ 664.00

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged body panels with all necessary components/attachments apply hot-works where necessary straighten rear end panel repair/reshape dented panels in accordance with factory specifications, replace new parts refit align into position refit all necessary components/attachments	<i>300</i> 1,200.00
2 To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	<i>400</i> 1,000.00
3 To remove, replace rear exhaust muffler with all necessary components	<i>80</i> 120.00
	\$ 2,320.00

GRAND TOTAL : \$ 8,159.00

SINGAPORE DOLLARS : EIGHT THOUSAND ONE HUNDRED & FIFTY NINE ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants has acknowledged the Repaire of the following:

- To resurvey before/after spray painting
- To display damaged parts for confirmation
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repaire:
Signature:
Date:

Zaini (LKK Auto)

From: Zaini (LKK Auto)
Sent: Thursday, 22 February 2018 5:02 PM
To: 'vfix auto'
Cc: Hsiao Tong (LKKAuto)
Subject: RE: Your Ref: VFIX-TP20180398_ACCIDENT INVOLVING SHA 6014X & SLH 696H ON 03/01/2018
Attachments: RV III SLH696H 03012018.pdf

WITHOUT PREJUDICE

Dear Irene,

We refer to your email below.

We confirmed the above settlement at **\$3,671.45.(all in)**.

Kindly forward your signed DV with all the relevant documents in **ORIGINAL HARDCOPY** via post. (ie: final repair bill, authorisation to act, discharge voucher) for our necessary action.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: vfix auto [mailto:vfixauto@gmail.com]
Sent: Thursday, 22 February 2018 3:57 PM
To: Zaini (LKK Auto) <Zaini@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: Your Ref: VFIX-TP20180398_ACCIDENT INVOLVING SHA 6014X & SLH 696H ON 03/01/2018

Dear Zaini

We unable to accept your offer at \$3,580.00.

We would like to counter proposal at \$3,671.45.

Thanks
Irene

On Thu, Feb 22, 2018 at 3:04 PM, Zaini (LKK Auto) <Zaini@lkkauto.com> wrote:

WITHOUT PREJUDICE

Your Ref: VFIX-TP20180398

Our Ref: CC6/III18000515/Uks3

Dear Sirs,

ACCIDENT INVOLVING SHA 6014X & SLH 696H ON 03/01/2018

We refer to the above matter

For a quick and amicable settlement, we offer to settle global sum at **SS3,580.00(all in)**

Kindly confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

07 FEB 2018

Our Ref. No. : VFIX-TP20180398

**MOTOR CLAIMS DEPT
INDIA INT'L INS PTE LTD**

64 CECIL STREET
#05-01 IOB BUILDING
SINGAPORE 049711

vfix

Vfix Auto Service Pte Ltd

60 Kaki Bukit Ave 6

Ark@KB Singapore 417892

Email: vfixauto@gmail.com

Tel: 64489268 Fax: 64452368

Co Reg. No: 201602964H

GST Reg No: 201602964H

WITHOUT PREJUDICE

Dear Sir / Madam

PROPERTY CLAIM ONLY

**ACCIDENT INVOLVING SLH696H AND SHA6014X ON 03 JAN 2018
ALONG AFTER KPE TUNNEL TOWARDS TPE BEFORE TAMPINES ROAD**

We refer to the above-mentioned accident.

We are writing on behalf of **MR LI SHUNHUI DANIEL** the registered owner of motor vehicle number **SLH696H** which was involved in the above accident.

We are instructed that the above accident was caused by the negligence and management of your insured's vehicle number **SHA6014X**. As a result of the above accident, our client's vehicle was damaged and our client's has been put to loss and expense, particulars of which are as follows :-

1	Cost of Repair	:S\$	3,424.00
2	Loss of Use (3 days X \$ 100.00)	:S\$	300.00
3	LTA Fees	:S\$	7.45

TOTAL AMOUNTS	:S\$	3,731.45
----------------------	-------------	-----------------

We enclosed a list of the supporting documents :-

- (a) Original Final Repair Bill
- (b) LTA Tax Invoice
- (c) GIA / Police Report lodged by Our Client
- (d) Letter of Authority

Kindly acknowledge receipt of the above said documents and your favourable reply is greatly appreciated.

Any settlement reached is strictly without prejudice to and shall not affect any other claims arising from this accident. Settlement is solely for the items claimed only.

Yours Faithfully,
VFIX AUTO SERVICE PTE LTD




Kelvin Poh

To: INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Dear Sir / Madam,

Claimant:

ACCIDENT INVOLVING SLH 696H AND SHAG014X ON 03/01/18 AT
AFTER KFE TUNNEL TOWARDS THE B/F TAMPINES RD

I/We, LI SHUNHUI, DANIEL, am/are the registered owner of
motor car no. SLH 696H.

Please be informed that I have assigned all compensation monies due to me/us in the above
accident to VFIX AUTO SERVICE PTE LTD.

I/We hereby authorized you to release all monies pertaining to the above mentioned accident
to VFIX AUTO SERVICE PTE LTD and forward the settlement cheque to VFIX AUTO SERVICE PTE
LTD whom I/we have authorized to collect the said compensation monies.

Thank you,



Signature of Claimant &
Company Stamp if applicable

IC no.: 88806067 I

Date: 07/02/18



Signature of Witness

IC no.: S1527552 I

Date: 07/02/18

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18010087
Claimant Ref: SLH696H

We/I, Vfix Auto Service Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 3,424.00 (repair cost), S\$ 240.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SLH696H that was damaged pursuant to the accident which occurred on 03/01/2018 (date) at KPE TWDS BUANGKOK EAST DRIVE (location) involving vehicle no. SHA6014X (insured vehicle). This is pursuant to the inspection conducted on 09/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LI SHUNHUI, DANIEL ("the third party claimant") of vehicle no. SLH696H to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLH696H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 3,671.45 to Vfix Auto Service Pte Ltd

Dated this 24 day of Feb 2018

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

Joanne Leng

NRIC:

5778159A

Address:

60 Jalan Bukit Ang
60 Jalan Bukit Ang 417812

Nationality:

Malaysian

Occupation:

Admin.

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

Block 51, Paya Ubi Industrial Park

Address:

Libi Avenue 1, # 02-23
(65) 4089 23

Nationality:

Occupation:





Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6
Ark@KB Singapore 417892
Email: vfixauto@gmail.com
Tel: 64489268 Fax: 64452368
Co Reg. No: 201602964H
GST Reg No: 201602964H

INDIA INT'L INS PTE LTD
64 CECIL STREET
#05-01 IOB BUILDING
SINGAPORE 049711

FINAL REPAIR BILL

DATE : 07/02/2018
VEHICLE NO : SLH696H
MAKE/MODEL : MERCEDES BENZ
ACC DATE : 03/01/2018
CLAIM NO : VFIX-1P20180398
POLICY NO :

AMOUNT S\$

LUMP SUM REPAIR COST

Repair Amount	3,200.00
7% GST	224.00
Total	<u><u>3,424.00</u></u>

SINGAPORE DOLLARS : THREE THOUSAND FOUR
HUNDRED & TWENTY FOUR ONLY

VFIX AUTO SERVICE PTE LTD


Kelvin Poh





Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

SLH 696 H

Print Date/Time : 05 Jan 2018 / 11:23:17

Receipt Date/Time : 05 Jan 2018 / 11:23:07

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180105-000690

Previous Receipt No. :

**S/N Item Description/
Business Transaction Reference
No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
--	---------------------------------	---------------------------------------

Result of Insurance Enquiry - SHA6014X
As at 03 Jan 2018/19:15:00
Insurance Co: INDIA INTL INS PTE LTD
1 Insurance Enquiry - SHA6014X
Enquiry Fee
20180105112207060347

7.00	0.49	7.49
------	------	------

Sub-Total

7.00	0.49	7.49
------	------	------

Total Before Rounding

7.00	0.49	7.49
------	------	------

Rounding Difference

0.04

Total Amount Payable

7.45

Paid By

xxxxxxxxxxxx8539	Credit Card: Visa /MasterCard	7.45
------------------	----------------------------------	------

Total

7.45

Cash Change

0.00

Tendered Amount

7.45

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jan 2018 Edit Reg		09 Jan 2018 00:00 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:		COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R							
Main Claimant:		LI SHUNHUI, DANIEL , ID: S88060671							
Vehicle Reg. No.:		SLH696H	Date of Loss:	03/01/2018 19:00 - :59					
Claim Type:		TP / MCT18010087	Policy/Cover Note No.:	MCOM0015					
Vehicle Reg. No. (Insured):		SHA6014X	Policy No. (Claimant):	MCOM0015					
		Excess:							
Repairer:		Vfix Auto Service Pte Ltd (HQ) 60 Kaki Bukit Ave 6, ARK@KB, 417892 Kaki Bukit - Tel: 96890102							
Handling Insurer:		India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]							
Claimant's Insurer:		India International Insurance Pte Ltd (HQ) - Tel: 63476100							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/01/2018]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (15/02/2018): Alert - Adj Mandate Approved (S\$3671.45) - SLH696H - Claim Handler: NATALIE LEE - III_SG (19/01/2018): Alert - Adj Mandate Approved (S\$0.00) - SLH696H - Claim Handler: NATALIE LEE									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH696H (MCT18010087)
 [SHA6014X]
 TP
 LI SHUNHUI, DANIEL
 Jan 3 2018 7:00PM
 [COMFORT TRANSPORTATION PTE LTD]
 Vfix Auto Service Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	07/02/18 09:27	Chassis Number							 Load JPG	☒	
2	07/02/18 09:27	Odometer Reading							 Load JPG	☒	
3	07/02/18 09:27	General View							 Load JPG	☒	
4	07/02/18 09:27	General View							 Load JPG	☒	
5	07/02/18 09:27	General View							 Load JPG	☒	
6	07/02/18 09:27	General View							 Load JPG	☒	
7	07/02/18 09:27	General View							 Load JPG	☒	
8	07/02/18 09:27	General View							 Load JPG	☒	
9	07/02/18 09:27	General View							 Load JPG	☒	
10	07/02/18 09:27	General View							 Load JPG	☒	
11	07/02/18 09:27	General View							 Load JPG	☒	
12	07/02/18 09:27	General View							 Load JPG	☒	
13	07/02/18 09:27	General View							 Load JPG	☒	
14	07/02/18 09:27	General View							 Load JPG	☒	
15	07/02/18 09:27	General View							 Load JPG	☒	
16	07/02/18 09:27	General View							 Load JPG	☒	
17	07/02/18 09:27	General View							 Load JPG	☒	
18	07/02/18 09:27	General View							 Load JPG	☒	
19	07/02/18 09:27	General View							 Load JPG	☒	
20	07/02/18 09:27	General View							 Load JPG	☒	
21	07/02/18 09:27	General View							 Load JPG	☒	
22	07/02/18 09:27	General View							 Load JPG	☒	
23	07/02/18 09:27	General View							 Load JPG	☒	
24	07/02/18 09:27	General View							 Load JPG	☒	
25	07/02/18 09:27	General View							 Load JPG	☒	
26	07/02/18 09:27	General View							 Load JPG	☒	
27	07/02/18 09:27	General View							 Load JPG	☒	
28	07/02/18 09:27	General View							 Load JPG	☒	
29	07/02/18 09:27	General View							 Load JPG	☒	
30	07/02/18 09:27	Reinspection Photo							 Load JPG	☒	
31	07/02/18 09:27	Reinspection Photo							 Load JPG	☒	
32	07/02/18 09:27	Reinspection Photo							 Load JPG	☒	
33	07/02/18 09:27	Reinspection Photo							 Load JPG	☒	
34	07/02/18 09:27	Reinspection Photo							 Load JPG	☒	
35	07/02/18 09:27	Reinspection Photo							 Load JPG	☒	

36	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
37	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
38	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
39	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
40	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
41	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
42	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
43	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
44	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
45	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
46	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
47	07/02/18 09:27	Reinspection Photo	1	Load JPG	☒
Documentation			1 per page	☒	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/01/18 15:04	NOTIFICATION FROM WORKSHOP	1	Load PDF	
2	11/01/18 11:06	TP GIA REPORT	1	Load PDF	
3	11/01/18 11:06	TP ESTIMATE - MARKED	1	Load PDF	
4	08/02/18 10:35	LOD	1	Load PDF	
5	08/02/18 10:35	FINAL REPAIR BILL	1	Load PDF	
6	08/02/18 10:35	LTA SEARCH	1	Load PDF	
7	23/03/18 16:14	AUTHORISATION TO ACT FORM	1	Load PDF	
8	23/03/18 16:14	DISCHARGE VOUCHER	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	10/01/18 08:54	Singapore Accident Statement	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18000515/UKS3Q2

Date: 23/03/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SLH696H Insured Vehicle No: SHA6014X
 Date of Loss: 03/01/2018 Nature of Claim: TP Claim No: MCT18010087

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH696H
 Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27491030037221
 Reg. Date: 28/03/2013 (Man. Year: 2012) Chassis No: WDD2040312A825997
 Colour: White Odometer: 69321 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/40Z R18 Rear Tyre Size: 255/35Z R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,839.00	3,254.30	2,584.70	44.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	780.00	1,540.00	66.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,159.00	4,034.30	4,124.70	50.55
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	8,159.00	3,200.00	4,959.00	60.78
+ GST 7.00/7.00% (S\$)	571.13	224.00	347.13	60.78
Nett Amount (S\$)	8,730.13	3,424.00	5,306.13	60.78
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,671.45		

INSPECTION

Date of Assignment: 09/01/2018
 Date Inspected: 09/01/2018 Inspected At: Vfix Auto Service Pte Ltd (HQ)
 60 Kaki Bukit Ave 6, ARK@KB
 Singapore 417892

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Zaini Bin Kusaini

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2018)
Parts:	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH696H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (AMG)	Cracked / Deformed	2,665.00 FL	*1,950.00 FL
2	1		*REAR BUMPER LOWER SPOILER	Deformed	550.00 FL	*550.00 FL
3	1		*REAR BUMPER CARRIER BASE RH	Not Necessary	49.00 FL	*- FL
4	1		*REAR BUMPER CARRIER BASE LH	Not Necessary	49.00 FL	*- FL
5	1		*REAR BUMPER GUIDE RH	Not Necessary	35.00 FL	*- FL
6	1		*REAR BUMPER GUIDE LH	Bent	35.00 FL	*35.00 FL
7	1		*REAR BUMPER FRAME	Cracked	122.00 FL	*122.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Dented	460.00 FL	*460.00 FL
9	1		*TAILLAMP LH	Not Necessary	680.00 FL	*- FL
10	1		*EXHAUST MUFFLER REAR (LOCAL REPAIR)	Bent	994.50 FS	*200.00 FS
11	2		*REVERSE SENSOR	Shorted (1 PCS ONLY)	640.00 FS	*225.00 FS
12	8		*BUMPER CLIP	Necessary	24.00 FS	*24.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,303.50	3,566.00
- List Item Discount on L Items 10.00/10.00% (S\$)	464.50	311.70
Total Parts (S\$)	5,839.00	3,254.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED BODY PANELS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN REAR END PANEL REPAIR /RESHAPE DENTED PANEL IN ACCORDANCE WITH FACTORY SPECIFICATIONS ,REPLACE NEW PARTS REFIT ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS /ATTACHMENTS	New	1,200.00	300.00
2	TO SPRAY PAINT REPLACED/ REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,000.00	400.00
3	TO REMOVE,REPLACE REAR EXHAUST MUFFLER WITH ALL NECESSARY COMPONENTS	New	120.00	80.00
Gross Labour Cost (S\$)			2,320.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >