

M/S INDIA INT'L INS PTE LTD
64 CECIL STREET
#05-01 IOB BUILDING
SINGAPORE 049711

not Adherent
Mark
1/55
3rd
9/1/18
blue ph. Atk
myr.

ESTIMATE

DATE : 05/01/2018
ACC DATE : 03/01/2018
REF NO. : VFIX-TP20180398
POLICY NO. :

Attention: Motor Claim Department

RE : VEHICLE NO.SLH696H BENZ WDD2040312A825997

DESCRIPTION	AMOUNT S\$
1 1 REAR BUMPER (AMG) <i>one/De</i>	2,665.00 —
2 1 REAR BUMPER LOWER SPOLIER <i>re</i>	550.00 —
3 1 REAR BUMPER CARRIER BASE RH <i>11</i>	49.00 <i>q</i>
4 1 REAR BUMPER CARRIER BASE LH <i>11</i>	49.00 <i>q</i>
5 1 REAR BUMPER GUIDE RH <i>11</i>	35.00 <i>q</i>
6 1 REAR BUMPER GUIDE LH <i>11</i>	35.00 —
7 1 REAR BUMPER FRAME	122.00 ?
8 1 REAR BUMPER REINFORCEMENT	460.00 ?
9 1 TAIL LAMP LH <i>11</i>	680.00 <i>X</i>
10 1 EXHUAUST MUFFLER REAR	1,105.00 ?
	5,750.00
LESS 10%	575.00
	\$ 5,175.00
SPECIAL NETT	AMOUNT S\$
1 2 REVERSE SENSOR <i>24</i>	320.00 <i>shp</i> 640.00 <i>SN</i>
2 8 BUMPER CLIP	<i>na</i> 24.00 <i>SN</i>
	\$ 664.00
LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged body panels with all necessary components/attach- ments apply hot-works where necessary straighten rear end panel repair/ reshape dented panels in accordance with factory specifications,replace new parts refit align into position refit all necessary components/attachments	<i>300</i> 1,200.00
2 To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	<i>400</i> 1,000.00
3 To remove,replace rear exhaust muffler with all necessary components	<i>80</i> 120.00
	\$ 2,320.00
	GRAND TOTAL : \$ 8,159.00

SINGAPORE DOLLARS : EIGHT THOUSAND ONE HUNDRED & FIFTY NINE ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hereby certify that the Repairer of the following:
To resurvey before/after spray painting
To display damaged parts for resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: