




SMRT Automotive Service Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592  
Estimator Telephone Number : 68662623  
Accident Reporting Number : 68662672

## SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB178G  
Ref. No : BUS/12/17/1040  
Reg. Date : 01/01/1900  
Vehicle Type : BUS -12M  
Make : MB CITARO MERCEDES  
Model : MB CITARO O530  
Name of Driver : Goh Ying Siang  
Type of Accident : OTHERS  
Date / Time of Accident : 29/12/2017 12:30:00 PM  
Accident Reported Date / Time : 04/01/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : AIG  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No :  
Special Instruction to ARC, if any :  
please check the damages on the front right portion  
Prepared Date : 05/01/2018 09:44:34 AM



### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian.  
8/1/18.

- Lamp Sun Repair.
- Photo After Paint.
- Headlamp, Signal Lamp Photo.

Chassis No :  
Work Shop :

Mileage : 0  
Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,590.00	0.00
Total Spray Painting Charges	786.00	0.00
Total Material Charges	2,942.93	2,942.93
Other Charges	0.00	0.00
<b>TOTAL</b>	<b>5,318.93</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>5,300.00</b>	<b>0.00</b>
No. of Repair Days	3.00	<del>0.90</del>
Prepared / Adjusted By		<i>2 days</i>
Arc / Surveyor Sing Off Date	08/01/2018 01:09:20 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :  
Remarks :

Prepared Date : 08/01/2018 08:57:19 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :  
Quotation Date :  
Invoice Amount :

Invoice No :  
Invoice Date :  
Prepared Date :

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,590.00	<del>0.00</del> 1,250 .
<b>Total Labour</b>	<b>1,590.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	786.00	<del>0.00</del> 520
<b>Total Spray Painting &amp; Panel Beating</b>	<b>786.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
62888002	FRONT	6009903	FRONT BUMPER RH	1	1,754.79	10.00	1,579.31	Replace	Replace ✓ CLK	No
	VE	6009508	FRONT HEADLAMP RH	1	1,276.50	10.00	1,148.85	Replace	Replace ✓ CLK R	No
	VE	6009701	FRONT SIGNAL LAMP RH	1	155.30	10.00	139.77	Replace	Replace ✓ CLK	No
	COMMO	4005301	SMRT STICKER (S)	1	75.00	0.00	75.00	Replace	Replace ✓ CLK	No
TOTAL MATERIALS							2,942.93	2,942.93		
TOTAL MATERIALS(Discouted)							2,942.93	2,942.93		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									