

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0043/2018/JT
Date	:	10-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name	:	Audi Singapore Pte Ltd
Address	:	8 Kallang Avenue #08-01 to 09 Aperia Tower 1 Singapore 339509
Telephone	:	HP +65 6718 6000
Type of Claim	:	Own Damage Claims
Policy No.	:	VFX/P1886473
Vehicle No	:	SLP 2199 X
Model Code	:	Audi A5 SB 2.0 TFSI
Model / Year	:	May-17
Engine No	:	CVK 024233
Chassis No	:	WAUZZZF52HA008902
Mileage	:	
Date In	:	9-Jan-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	30-Dec-17
Place of Accident	:	13 Leedon Heights

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 2199 X.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid sensor and rear lid kick sensor. Check function.	S/N \$	360.00 ✓	
2	To renew LHS 1/4 glass and rear windscreen to facilitate fender renewal.	S/N \$	600.00 ✓	
3	To remove and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,600.00 ✓	
4	To dislodge and reinstall rear seat, back rest, hat trays, ABCD pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbags, etc.	S/N \$	1,600.00 ✓	
5	To dismantle rear bumper and rear lid. Cut out and weld LHS rear fender, reinforcement and connecting plates. Re-organize rear crash management components. Reinstall all parts removed.	\$	6,000.00 4200 ✓	
6	To respray rear bumper, LHS rear fender, connecting plate, LHS sill panel, door entrance, drain panel, roof channel and end panelling. To carry out stone chip treatment and joint sealer works.	\$	4,700.00 2400 ✓	
7	To carry out diagnostic checks.	S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		:	\$ 15,052.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 2199 X.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Deformed</i>	\$ 2,190.00	✓
2	REAR BUMPER CHROME TRIM <i>Not New</i>	\$ 878.00	X
3	REAR BUMPER SECURING STRIP <i>Not New</i>	\$ 191.00	X
4	REAR BUMPER LIGHT REFLECTOR - LHS	\$ 35.00	?
5	REAR BUMPER OUTER GUIDE - LHS	\$ 37.00	?
6	REAR BUMPER INNER GUIDE - LHS	\$ 19.00	?
7	REAR PARKING AID SENSOR <i>Not New</i>	2 \$ 421.00	X
8	REAR SECTIONAL PIECE - LHS (FENDER) <i>Distorted</i>	\$ 2,195.00	✓
9	QUARTER GLASS - LHS <i>Not New</i>	\$ 833.00	✓
10	REAR WINDSCREEN	\$ 1,014.00	✓
11	PRIMER <i>Not New</i>	2 \$ 37.00	✓
12	OUTER LED TAIL LIGHT - LHS <i>Not New</i>	\$ 1,027.00	X
13	REAR FENDER REINFORCEMENT - LHS <i>Repairs</i>	\$ 180.00	✓
14	GROMMET	\$ 63.00	?
15	REAR FENDER CONNECTIONG PLATE - LHS	\$ 49.00	?
16	VENT TRIM <i>Not New</i>	\$ 60.00	X
17	DOOR ENTRANCE SILL TRIM - LHS	\$ 164.00	?
18	1/4 GLASS SEALENT	S/N \$ 100.00	✓
19	REAR WINDSCREEN SEALENT	S/N \$ 200.00	✓
20	ACRYLIC SEALER	S/N \$ 180.00	✓
SUB TOTAL SPARE PARTS CHARGES		\$ 9,873.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 2199 X.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
21	CAVITY WAX	S/N \$ 180.00	✓
22	STONE CHIP	S/N \$ 180.00	✓
23	METAL FILLER POWDER	S/N \$ 280.00	✓
24	SUNDRIES	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		\$ 11,013.00	
TOTAL LABOUR CHARGES		\$ 15,052.00	
GRAND TOTAL		\$ 26,065.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ly
Surveyed Date : 09/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 12 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant