

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

05-Jan-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30 REGN NO: SHD 1552 B

1 pc	Front n/s door <i>✓ 1 pc</i>	\$ 1,723.60
1 pc	Rear n/s door <i>✓ 1 pc</i>	\$ 2,017.48
2 pcs	Rear n/s door hinge @\$39.00 ?	\$ 78.00
1 pc	Rear n/s rim <i>X Repair</i>	\$ 246.00
		<hr/>
		\$ 4,065.08
Less 20%		\$ 813.01
		<hr/>
		\$ 3,252.07

S/NETT

1 set	n/s door sticker <i>✓ 1 set</i>	\$ 280.00
1 pc	Rear n/s door sticker <i>✓ 1 pc</i>	\$ 60.00
Sundry		\$ 50.00 X
To dismantle and refit the inner component of the front n/s door into new shell door		\$ 150.00 60
To dismantle and refit the inner component of the front n/s door into new shell door		\$ 150.00 60
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the n/s rocker panel, rear n/s fender		\$ 800.00 600
To putty and spray painting on front n/s door, rear n/s door, n/s rocker panel, rear n/s fender		\$ 800.00 600
To apply rustproofing on the repaired and replaced panels.		\$ 200.00 X
		<hr/>
		\$ 5,742.07

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

5 Days .

Guo Qiang - 82880282

Guo Qiang @ lkk auto. com

08/1/18 before paint photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: