

VEHICLE NO : SLG 2788 T
 MODEL : MIT LANCER EX 1.6A
 WIP : 18127

Material	:	\$	<u>867.00</u>
Labour	:	\$	<u>2,600.00</u>
Sub-Total	:	\$	<u>3,467.00</u>
	:	\$	<u>3,467.00</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>3,467.00</u>
GST 7%	:	\$	<u>242.69</u>
Grand Total	:	\$	<u>3,709.69</u>
Finalise By/Date	:	<u>LOI / 17/05/18</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 11 WORKING DAYS + 4 Days (2) Weekends
 + 0 Days () Public Holiday
 TOTAL DAYS REPAIR TOOK = 15

☒ TP claim SHD4270U

☐ Claim GIA / LTA fee -

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others -

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms TAN HOCK BOON	Cust No/Name /Ms TAN HOCK BOON
BLK 73 TELOK BLANGAH HEIGHTS #03-309 SINGAPORE 100073	Reg No/Reg Date SLG2788T / 27/09/2016
Contact No Mobile: 96973593	Date In/Mileage 09/01/2018/ 30980
09/01/	Chassis/Package JMYSRCY1AGU005925 /DC17R
	Engine No 4A92CL7288
	Make/Model MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim W03 WHITE SOLID / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00040	Cash	17/05/2018/ 12:53	TLE	260 / AiTing	18127		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR DAMAGED PARTS, REPLACE BOOT LID, REPAIR REAR BUMPER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME							✓ 1100.00
E PNT98000 RESPRAY ON REAR BUMPER, BOOT LID, AND ALL OTHER AFFECTED AREAS TO THE SAME							✓ 840.00
E PNT88000 REMOVE & REINSTALL BOOT LID COMPONENTS, TRIMS AND ALL OTHER ATTACHMENTS TO FACILITATE REPAIR							✓ 150.00
E PNT88000 REMOVE & REINSTALL SPARE TIRE BOARD, TRIMS, CAPET TO FACILITATE REPAIR							✓ 100.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM							✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE							✓ 200.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS							✓ 40.00
E PNT88000 REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR							✓ 80.00
M SUNDRY SUNDRIES							✓ 20.00
M SUNDRY SUPPLY C&C BADGE							✓ 40.00
X	PANEL, TRUNK LID			1.00	✓ 724.00	00.00	724.00
X	MARK, THREE-DIA			1.00	✓ 49.00	00.00	49.00
X	MARK, EX			1.00	✓ 40.00	00.00	40.00
X	MARK, LANCER			1.00	✓ 54.00	00.00	54.00
Z TEXT TP CLAIM ERGO YP1946J DOA : 08.12.17 SURVEYOR TAUFIKH LKK 09.01.18							
"Guarantee your warranty, maintain with Cycle & Carriage."							

Parts	867.00	Nett	3,467.00
Labour	2,500.00	7% GST on	242.69
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	3,709.69
Sundry/Others	100.00		
Total(w/o GST)	3,467.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.