

22/03/2002

ASS. REC. BY:

REF: CS/EGT18000535/Tlvbn2

Special Instruction:

Surveyor

Tauflich

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGL

Date/Time:

09/02/08 11:36am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLG 2788J

Insured:

YP 1946J

at Workshop n/s

Cycle & Carriage Automotive

Tel:

6568 4501

of

209 Pandan Garden

Policy No:

Claim No:

DSMEV1702903

Sum Insured:

Excess:

Make of Veh:

D.O.A.

08/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

09/02/08 2:36pm

Person Contacted:

Schwin

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 2788J - x
	YP 1946J - CS/EGT16008788/Anh302
	Dep: 090516
10/1/18	Email preli revised to Pei Li
18/5/18	Final fig \$ 3467 (Red 1620, 327) confirmed by email

Surveys

Tanflin

REF:

EG1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

NIL

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days 12/5/18 Tanflin Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

☒ CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT
Edwin

Veh No:

SLG2788T

Yr Regn: 2016 Sep

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Lancer EX 1590

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

30980

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYSRCYLAG 4005925

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/45R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

9/1/18 C1745

Survey held at

C&C Pudur Gdn

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 18 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 18/5 - typst

Report Format :

TP

Lump Sum / I.B.I: (\$

3467 1/2

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

(\$ + RS. SI

) Photos

) Others

TOTAL

250

Survey Department Check List (Case Handler)

Reference No. : CS/EG1/8000535/Tivo
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: Veron 18/5/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18000535/T1vb		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 09-01-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 1946J	Veh. Inspected	SLG 2788T	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1702903	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	09/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/12/2017	Inspection Date	09/01/2018	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: DSMCV1702903
Our ref: CS/EG118000535/T1vb

Date: 10/1/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLG 2788T


We thank you for your instruction on 9/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 9/1/2018 at the premises of M/s CYCLE & CARRIAGE AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,087.00
Revised Estimate Amount	: S\$3,467.00
"Check" Items Amount	: S\$244.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 18 May 2018 11:16 AM
To: 'Loi Ai Ting'; Taufikh (LKKAUTO)
Cc: Lauro Araos Songcuan Jr; Cheng Jo Jo; Admin A; Admin-D (LKKAUTO); SUR
Subject: RE: SLG2788T, Mit WIP: 18127 (finalisation)

Dear Ms Loi,

WITHOUT PREJUDICE

Confirm finalised amount at \$3,467 before GST @ 4 working days.

Final invoice and all supporting documents sent over to ERGO INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loi Ai Ting [mailto:aiting.loi@cyclecarriage.com.sg]
Sent: Thursday, 17 May 2018 1:10 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Lauro Araos Songcuan Jr <lauro.songcuan@cyclecarriage.com.sg>; Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: SLG2788T, Mit WIP: 18127 (finalisation)

Hi, Taufikh,

Please confirm finalised amount at \$3,709.69.

Thanks.

Regards,
Loi

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 10 January, 2018 3:13 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: YP1946J / TP : SLG2788T/LKK / DOA : 08/12/2017 (DSMCV1702903)
Attachments: SLG 2788T PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SLG 2788T
Date of survey: 9/1/2018
Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 9 January, 2018 2:50 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: YP1946J / TP : SLG2788T/LKK / DOA : 08/12/2017 (DSMCV1702903)

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 9 January, 2018 11:36 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : YP1946J / TP : SLG2788T/LKK / DOA : 08/12/2017 (DSMCV1702903)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CYCLE & CARRIAGE AUTOMOTIVE PTE LTD**.

ADDRESS : 209 PANDAN GARDENS
SINGAPORE 609339

PERSON TO CONTACT : EDWIN @ 6568 4501

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 9 January, 2018 11:36 AM
To: 'admin-d@lkkauto.com'
Subject: OI : YP1946J / TP : SLG2788T/LKK / DOA : 08/12/2017 (DSMCV1702903)
Attachments: YP1946J - SAS.pdf; SLG2788T - SAS.pdf; SLG2788T - ESTIMATE.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CYCLE & CARRIAGE AUTOMOTIVE PTE LTD**,

ADDRESS : 209 PANDAN GARDENS
SINGAPORE 609339

PERSON TO CONTACT : EDWIN @ 6568 4501

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



CERTIFICATE OF INSURANCE

MITSUBISHI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Tan Hock Boon
Period of Insurance : 27 Sep 2017 To 26 Sep 2018
Engine No. : 4A92CL7288
Chassis No. : JMYSRCY1AGU005925

Vehicle No. : SLG2713T
Policy No. : 2100402555-01
Endorsement No. :
Issued Date : 04 Sep 2017

ABOUT THE COVER

Make/Model : MITSUBISHI LANCER EX 1.6L
Engine Capacity/Tonnage : 1,590.00 CC
Driver Restriction : NA
Sum Insured* : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's behalf (subject to the conditions of this Policy)
 This Policy will indemnify the Policyholder for his liability arising from any 3rd party death or bodily injury claim.
 You have to pay the additional sum of \$1,000 as "No Fault and Drunk-Related Death" (No Fault and Drunk-Related Death) - sum insured for 1st and 2nd class of claimant who has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and business purposes and for the purpose of the vehicle's use as a private motor vehicle. This policy does not cover the vehicle when used for hire or reward, speed-testing, the carriage of goods other than samples or specimens with any kind of container, or for any other purpose not intended by the manufacturer.

Loss of Use : 150000 + 100000

* Limitations mentioned in Schedule 2 of the Motor Vehicle Policy Form and Conditions of Insurance. The sum insured of the Road Transport Act (RTA) 1961 is not to be included under these headings.

EXCESS

Section 1

Fire : \$0, Own Damage : \$200, Theft : \$0, Road Cover : \$0

Section 2

Property Damage : \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Tan Hock Boon : \$200, Own Damage

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Customer Service Centres: For all claims, contact us at 0500 000 000 or 0500 000 000.
 2. Cycle & Carriage Customer Service Centres: For all claims, contact us at 0500 000 000 or 0500 000 000.
 3. Cycle & Carriage Repair & Paint Centres: For all claims, contact us at 0500 000 000 or 0500 000 000.
- For other Approved Reporting Centres: AIG Approved Reporting Centres, please contact us at 0500 000 000 or 0500 000 000. Approved Reporting Centres are listed on the AIG website: www.aig.com.sg or AIG SG Mobile App. Search, search and download AIG SG App on Google Play or App Store.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OBS BANK LTD

I/We hereby certify that the policy is issued on the basis of the information provided by the policyholder. The policyholder is responsible for the accuracy of the information provided. The policy is issued on the basis of the information provided by the policyholder. The policy is issued on the basis of the information provided by the policyholder.

0500720791

CYCLE & CARRIAGE - SINGAPORE

239 ALEXANDRA ROAD

SINGAPORE 159530

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S2579756F**
Name: **LO HOI YU**

Birth Date: **05 Dec 1965**
Issue Date: **27 Jun 2003**

000604328E

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 3 Motor Cars and Motor Tractors the weight of which includes does not exceed 3,500 kilograms	29 Jul 2005

FOR C&C USE ONLY

NP 428A

License No: S2579756F



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS TAN HOCK BOON	Cust No/Name	/MS TAN HOCK BOON
BLK 73 TELOK BLANGAH HEIGHTS	Reg No/Reg Date	SLG2788T / 27/09/201
#03-309	Date In/Mileage	/ 0
SINGAPORE 100073	Chassis No	JMYSRCY1AGU005925
Contact No Mobile: 96973593	Engine No	4A92CL7288
	Make/Model	MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim	W03 WHITE SOLID / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	08/12/2017/ 17:21	QUE	261 / Edwin Caina	18127			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1100 1650.00
RENEW & RE-ALIGN RR DAMAGED PORTION:								
RENEW BOOTLID								
REPAIR RR END PNL & RR BUMPER								240 1260.00
E PNT98000								✓ 150.00
RESPRAY RR BUMPER , RR END PNL & BOOTLID								
E PNT88000								100. 200.00
REMOVE & REFIT BOOTLID COMPONENT								
E PNT88000								30 50.00
REMOVE & REFIT SPARETYRE BOARD,TRIM,CARPET TO FACILITATE REPAIR								✓ 200.00
A 54900099								
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								40. 120.00
USING HI-SCAN PRO TEST								80. 100.00
M SUNDRY								20. 30.00
APPLY ANTI CORROSION ON AFFECTED AREAS								40. 40.00
E PNT88000								67 724.00
REMOVE & REFIT REVERSE SENSOR								88 88.00
M SUNDRY								88 88.00
Sundries								174 174.00
M SUNDRY								70 70.00
SUPPLY C&C BADGE								49 49.00
M PANEL,TRUNK LID					1.00	724.00	00.00	54 54.00
M HINGE,TRUNK LID,LH					1.00	88.00	00.00	40 40.00
M HINGE,TRUNK LID,RH					1.00	88.00	00.00	
M WEATHERSTRIP,TRUNK LID					1.00	174.00	00.00	
M LATCH,TRUNK LID					1.00	70.00	00.00	
M MARK,THREE-DIA					1.00	49.00	00.00	
M MARK,LANCER					1.00	54.00	00.00	
M MARK,EX					1.00	40.00	00.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tanjun 97493749.

SURVEYOR SIGNATURE: Tanjun

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME:

SURVEYOR SIGNATURE:

Confirm & accepted by

DATE: 9/1/18

REMARKS:

Ready before paint
sur @ 11k auto.com
4 days.

7% GST on

Nett

5087.00

5,087.00

356.09

Total Payable

5,443.09

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

VEHICLE NO : SLG 2788 T
MODEL : MIT LANCER EX 1.6A
WIP : 18127

Material	:	\$	<u>867.00</u>
Labour	:	\$	<u>2,600.00</u>
Sub-Total	:	\$	<u>3,467.00</u>
	:	\$	<u>3,467.00</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>3,467.00</u>
GST 7%	:	\$	<u>242.69</u>
Grand Total	:	\$	<u>3,709.69</u>
Finalise By/Date	:	<u>LOI / 17/05/18</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 11 WORKING DAYS + 4 Days (2) Weekends
+ 0 Days () Public Holiday
TOTAL DAYS REPAIR TOOK = 15

☒ TP claim SHD4270U

☐ Claim GIA / LTA fee -

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others -

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ms TAN HOCK BOON	Cust No/Name	/Ms TAN HOCK BOON
BLK 73 TELOK BLANGAH HEIGHTS	Reg No/Reg Date	SLG2788T / 27/09/2016
#03-309	Date In/Mileage	09/01/2018/ 30980
SINGAPORE 100073	Chassis/Package	JMYSRCYIAGU005925 /DC17R
Contact No Mobile: 96973593	Engine No	4A92CL7288
09/01/	Make/Model	MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim	W03 WHITE SOLID / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	17/05/2018/ 12:53	TLE	260 / AiTing	18127			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR DAMAGED PARTS, REPLACE BOOT LID, REPAIR REAR BUMPER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1100.00
E PNT98000 RESPRAY ON REAR BUMPER, BOOT LID, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 840.00
E PNT88000 REMOVE & REINSTALL BOOT LID COMPONENTS, TRIMS AND ALL OTHER ATTACHMENTS TO FACILITATE REPAIR								✓ 150.00
E PNT88000 REMOVE & REINSTALL SPARE TIRE BOARD, TRIMS, CARPET TO FACILITATE REPAIR								✓ 100.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 200.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								✓ 40.00
E PNT88000 REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR								✓ 80.00
M SUNDRY SUNDRIES								✓ 20.00
M SUNDRY SUPPLY C&C BADGE								✓ 40.00
X	PANEL, TRUNK LID				1.00	✓ 724.00	00.00	724.00
X	MARK, THREE-DIA				1.00	✓ 49.00	00.00	49.00
X	MARK, EX				1.00	✓ 40.00	00.00	40.00
X	MARK, LANCER				1.00	✓ 54.00	00.00	54.00
Z TEXT TP CLAIM ERGO YP1946J DOA : 08.12.17 SURVEYOR TAUFIKH LKK 09.01.18 "Guarantee your warranty, maintain with Cycle & Carriage."								
Parts					867.00	Nett		3,467.00
Labour					2,500.00	7% GST on 3467.00		242.69
Standard Menu					0.00			
Specialist Job					0.00	Total Payable		3,709.69
Diagnostics Job					0.00			
Sundry/Others					100.00			
Total(w/o GST)					3,467.00			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EG18000535/T1vbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 22-05-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 1946J	Veh. Inspected	SLG 2788T
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCV1702903	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	09/01/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI LANCER EX	c.c	1590
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JMYSRCY1AGU005925	Colour	WHITE
Odometer	30980	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/12/2017	Inspection Date	09/01/2018
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 2788T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	PANEL, TRUNK LID (SN)	BENT	724.00	724.00
1	HINGE, TRUNK LID, LH (SN)	TO REPAIR SEE LABOUR	88.00	-
1	HINGE, TRUNK LID, RH (SN)	TO REPAIR SEE LABOUR	88.00	-
1	WEATHERSTRIP, TRUNK LID (SN)	NOT NECESSARY	174.00	-
1	LATCH, TRUNK LID (SN)	NOT NECESSARY	70.00	-
1	MARK, THREE-DIA (SN)	NECESSARY	49.00	49.00
1	MARK, LANCER (SN)	NECESSARY	54.00	54.00
1	MARK, EX (SN)	NECESSARY	40.00	40.00
1	SUNDRIES (SN)	NECESSARY	30.00	20.00
1	C&C BADGE (SN)	NECESSARY	40.00	40.00
			1,357.00	927.00
LABOUR				
	RENEW & RE-ALIGN RR DAMAGED PORTION; RENEW BOOTLID. REPAIR RR END PNL & RR BUMPER. INCLUSIVE OF THE REPAIR OF HINGE, TRUNK LID, LH AND HINGE, TRUNK LID, RH.		1,650.00	1,100.00
	RESPRAY RR BUMPER, RR END PNL & BOOTLID.		1,260.00	840.00
	REMOVE & REFIT BOOTLID COMPONENT.		150.00	150.00
	REMOVE & REFIT SPARETYRE BOARD, TRIM, CARPET TO FACILITATE REPAIR.		200.00	100.00
	CHECK WIRING & ELECTRICAL SYSTEM.		50.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	APPLY ANTI CORROSION ON AFFECTED AREAS.		120.00	40.00
	REMOVE & REFIT REVERSE SENSOR.		100.00	80.00
	-		-	-
	-		-	-
	-		-	-
			3,730.00	2,540.00
GRAND TOTAL			5,087.00	3,467.00

Report Ref No. CS/EGI18000535/T1vbn2



RECOMMENDED COST OF REPAIRS			3,467.00
-----------------------------	--	--	----------

Report Ref No. CS/EGI18000535/T1vbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.