



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS TAN HOCK BOON	Cust No/Name	/MS TAN HOCK BOON
BLK 73 TELOK BLANGAH HEIGHTS	Reg No/Reg Date	SLG2788T / 27/09/201
#03-309	Date In/Mileage	/ 0
SINGAPORE 100073	Chassis No	JMYSRCY1AGU005925
Contact No Mobile: 96973593	Engine No	4A92CL7288
	Make/Model	MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim	W03 WHITE SOLID / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	08/12/2017/ 17:21	QUE	261 / Edwin Caina	18127		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1650.00
RENEW & RE-ALIGN RR DAMAGED PORTION:							
RENEW BOOTLID							
REPAIR RR END PNL & RR BUMPER							
E PNT98000							1260.00
RESPRAY RR BUMPER , RR END PNL & BOOTLID							
E PNT88000							150.00
REMOVE & REFIT BOOTLID COMPONENT							
E PNT88000							200.00
REMOVE & REFIT SPARETYRE BOARD,TRIM,CARPET TO FACILITATE REPAIR							
A 54900099							50.00
CHECK WIRING & ELECTRICAL SYSTEM							
A 10028901							200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							120.00
APPLY ANTI CORROSION ON AFFECTED AREAS							
E PNT88000							100.00
REMOVE & REFIT REVERSE SENSOR							
M SUNDRY							30.00
Sundries							
M SUNDRY							40.00
SUPPLY C&C BADGE							
M	PANEL,TRUNK LID			1.00	724.00	00.00	724.00
M	HINGE,TRUNK LID,LH			1.00	88.00	00.00	88.00
M	HINGE,TRUNK LID,RH			1.00	88.00	00.00	88.00
M	WEATHERSTRIP,TRUNK LID			1.00	174.00	00.00	174.00
M	LATCH,TRUNK LID			1.00	70.00	00.00	70.00
M	MARK,THREE-DIA			1.00	49.00	00.00	49.00
M	MARK,LANCER			1.00	54.00	00.00	54.00
M	MARK,EX			1.00	40.00	00.00	40.00

Confirm & accepted by

7% GST on **Nett** **5,087.00**
356.09

Total Payable **5,443.09**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.