

ASS. REC. BY:

REF:

CS/mc18000544/Titb22

Special Instruction:

SURVEYOR

Taufik

ASSIGNMENT (Office)

McLennan

From (Person):

Jasmine Lok

of

msgh

Date/Time: 09/01/2018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLK 7660Z

Insured:

SJE J354L

at Workshop m/s

Performanca

Tel:

6319 0774

of

303 Alexandra Rd

Policy No:

8802359108mp

Claim No:

545025

Sum Insured:

Excess:

Make of Veh:

D.O.A. 07/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

16.01.2018 @ after 10am

H.O.D. Endorsement:

Date/Time:

09/01/2018

304pm

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate Chua

SLK 7660Z - X

SJE J354L - X

Part by Part \$5594.60 Red: 1353.40 (19%)

Tan

MSIG

ASSIGNMENT

Date 16/01/2018

SLK 7660Z

20/7 Jan.

Estimated Cost

CC / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No SLK 7660Z
at Workshop No Performance
303 Alexandra Road

Insured

Policy No

Claims No

Sum Insured Excess

Client's Record After 10 am

Make of Veh

chua

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Ball or Marker value

DAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs days Repair Yes or No

Est. Sum % 3 Val Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date Person Contacted

Vehicle IN / OUT

Type Motor / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover
Truck / Trailer

Make BMW 216D

1496

Colour Bronze

So Reading 15449

Eng No

C No

W03 A2E S2 0405 B45781

Gen Cond Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Mod Nil / SRIM / STD A/Rim or

Tyre Size

205/55 R17

BS / DUN / EXNOVA / GY / RS / LIZA / MIC / HTSU / PIR / SUMI

TOYO / YOKO or

Front

R Bal

6

Rear

R Bal

6

L Bal

6

L Bal

6

D.O.A.

D.O.

4/1/18/10/10

Survey held at

pml

Des of Damages Frt / Rear / D/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

RECEIVED 13 SEP 2018

Signature

13/9/2018

One Time Fee Reason



Prel. Report



Final Report

BLA Typist

Date Time Fee Reason

Days Of Repair

3

Resurvey No. of Trip

Survey Fee

200

Transporter

3480

Price

10

210

Add Fee



Site Insp



Int Insp



Test Insp



Acc Insp

Receipt Number

559460




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18000544/T1tb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 09-01-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJE 2354L	Veh. Inspected	SLK 7660Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	09/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/01/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	08 Jan 2018		09 Jan 2018 18:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ALLAN LAI MUN LOONG (ALLAN LI WENLONG), ID: S7309003B, Tel: +6596658170, Email: NOEMAIL									
Main Claimant: KOH LIANG HUAY, ID: S1747347F									
Vehicle Reg. No.: SLK7660Z		Date of Loss: 07/01/2018 21:00 - :59							
Claim Type: TP / 545025		Policy/Cover Note No.: B80235910SMP (Comprehensive) Coverage: 25/11/2017 - 24/11/2018							
Vehicle Reg. No. (Insured): SJU2354L		Policy No. (Claimant):							
		Excess:							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/01/2018]									
Driver/Custodian (Insured): ALLAN LAI MUN LOONG (ALLAN LI WENLONG) (44 / Male), NRIC: S7309003B, Tel: +6596658170									
Adj. Asg. Remarks: ON WP									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 12 September 2018 7:08 PM
To: PBSP; Taufikh (LKKAUTO)
Subject: RE: FINAL REPORT / SLK7660Z

Dear Caroline,

Confirm total labour & parts : \$5,594.60

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 10 September 2018 6:29 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: Re: FINAL REPORT / SLK7660Z

attachments

From: PBSP
Sent: Monday, 10 September 2018 6:28:06 PM
To: taufikh@lkkauto.com; Denise Tay
Subject: FINAL REPORT / SLK7660Z

Dear Taufikh and Denise

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour :2,465.00
Total Parts :3,129.60
Total Labour & Parts :5,594.60

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/01/2018 16:07
Date Of Accident	07/01/2018 23:45
Exact Location Of Accident	BLK 22 DOVER CRESCENT CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK7660Z
Insured/Policyholder	
Name Of Registered Owner	KOH LIANG HUAY
NRIC No	S1747347F
Email Address	EKOH2003@YAHOO.CO.UK
Mobile Phone No	(LOCAL) +65-88353743
Alternative Phone No	OFFICE-97465323

Vehicle Particulars

Manufacturer	BMW
Model	216 GRAND TOURER
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	C0067293
Cover Note Number	

Driver

Name of Driver	MICHAEL SEET
NRIC No	S2510747J
Date Of Birth	04/10/1961
Occupation	INDOOR
Date Of Driving Pass	13/07/1983
Driving Experience	34 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97465323
Fax Number	
Contact Number	
Email Address	MSEET2002@YAHOO.CO.UK

Address	BLK 22 DOVER CRESCENT #02-352
Postcode	130022
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU2354L
Vehicle Make/Model/Colour	BMW 320
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ALAN LAI
NRIC/Passport Number	S7309003B
Contact Number	96658170
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

 11.50am
8-1-2017

Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

8/1/2018
@ 1506hr

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At about _____ at night my car was hit while it was parked in the parking lot in front of Elk 22 Dover Crescent, S130022. I have a copy of the video footage.

The driver was trying to do a 3-point u-turn. While reversing, his ~~toe~~ right rear bumper hit my front left bumper. His vehicle number is 5542354L.


I was not present at that time. He left a note for me to contact him. In the morning around 8:20am, I discovered the note and took pictures of the damage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature 8-1-2018
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.:

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559N GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

08 JAN 2018

Estimate No. : b1 45416
Date Estimated : 08/01/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Koh Liang Huay
299 Bedok South Avenue 3 Bedok Court
#05-04

Singapore 469298

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7660Z	5B45781	26/01/2017	216d G TOURER	0

DESCRIPTION

Replace front bumper and remove attachment etc include knock on accident dent

850 1,275.00

Spraypainting front bumper

934 1,038.00

To replace left headlight including program and conduct tests for proper function.

451 531.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

Sundries.

? 80.00

Total Labour 1: 3,101.00

DESCRIPTION

FRT BUMPER LH INSERT
FRT BUMPER RH INSERT
LH VERTICAL STRUT
FRT IMPACT ABSORBER
FRT LH BOTTOM DEFORMATION ELEMENT
FRT BUMPER BOTTOM CARRIER
FRT LH SIDE PANEL TOP MOUNTING
FRT RH SIDE PANEL TOP MOUNTING
LH ROD
LH SUPPORT FOG LAMP (GESCHLOSSEN)
FRT BUMPER PANEL PRIMED (PMA)
GRILLE SIDE OPEN LH (LUXURY LINE+PD)
FRT BUMPER TOP CARRIER
PLAQUE 82MM
LH HEADLIGHT LED TECHNOLOGY

QTY	PRIC	VALUE
1	9.35	? 9.35
1	9.45	? 9.45
1	47.00	? 47.00
1	46.60	? 46.60
1	82.25	? 82.25
1	140.10	? 140.10
1	8.60	? 8.60
1	8.65	? 8.65
1	19.50	? 19.50
1	49.70	? 49.70
1	821.50	del 821.50
1	95.85	auto 95.85
1	359.90	7 359.90
1	67.80	nei 67.80
1	2,085.75	art 2,085.75

Total Parts : 3,852.00



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45416
Date Estimated : 08/01/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7660Z	5B45781	26/01/2017	216d G TOURER	0

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before and after repairing
- To display damaged parts for resurvey
- Parts prices on a "no prejudice" basis
- Third party claims on a "no prejudice" basis
- No illegal practices
- Supplemental claims to be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No.	Claim No.
Date & Time 16/1/18 1010	Excess \$6
Surveyor's Name Taufik	Sign [Signature]
Surveyor's Tel 97495574	Authorized Yes / No
Authorized Date - WP	Time
RESURVEY PARTS PHOTO BY SURVEYOR Y/N / No P.M. Yes / No	
Surveyor's E-mail Taufik@lkkauto.com	
No. of Working Days Recommend 3 days	

[Signature]
19/1/18

07 1107

Labour 1	:	3,101.00
Parts	:	3,852.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	486.71
Grand Total	:	7,439.71

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45416
Date Estimated : 08/01/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Koh Liang Huay
299 Bedok South Avenue 3 Bedok Court
#05-04

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 469298

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE		
SLK7660Z	5B45781	26/01/2017	216d G TOURER	0		
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments include knocking out dents caused by the accident			850.00		850.00	
To spray paint front bumper			934.00		934.00	
To replace LH LED technology headlight include programming and conducting tests for proper function			451.00		451.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.			150.00		150.00	
Sundries.			80.00		80.00	
DESCRIPTION			UNIT PRICE	QTY	DISC. %	NETT
# LH FINISHER (LUXURY LINE) *			58.70	1.00		58.70
FRT BUMPER PANEL PRIMED (PMA)			821.50	1.00		821.50
GRILLE SIDE OPEN LH (LUXURY LINE+PD)			95.85	1.00		95.85
PLAQUE 82MM			67.80	1.00		67.80
LH HEADLIGHT LED TECHNOLOGY			2,085.75	1.00		2,085.75

SUPPLEMENTARY ITEMS

Total Labour :	2,465.00
Total Parts :	3,129.60
Total Labour & Parts :	5,594.60
Deduction for Excess :	
Total Repair Costs less Excess:	5,594.60
GST @7%:	391.62
Grand Total :	5,986.22

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45416
Date Estimated : 08/01/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Koh Liang Huay
299 Bedok South Avenue 3 Bedok Court
#05-04

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 469298

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLK7660Z	5B45781	26/01/2017	216d G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# LH FINISHER (LUXURY LINE) *	58.70	1.00		58.70

Total Labour :	
Total Parts :	58.70
Total Labour & Parts :	58.70

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jan 2018		09 Jan 2018 18:58 Edit Adj Rpt	S\$5,594.60 Edit Estimates	S\$5,594.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ALLAN LAI MUN LOONG(ALLAN LI WENLONG) , ID: S7309003B, Tel: +6596658170, Email: NOEMAIL									
Main Claimant: KOH LIANG HUAY , ID: S1747347F									
Vehicle Reg. No.: SLK7660Z		Date of Loss: 07/01/2018 21:00 - :59 [11 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 545025		Policy/Cover Note No.: B80235910SMP (Comprehensive) Coverage: 25/11/2017 - 24/11/2018							
Vehicle Reg. No. (Insured): SJU2354L		Policy No. (Claimant):							
		Excess:							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 10/01/2018]									
Driver/Custodian (Insured): ALLAN LAI MUN LOONG(ALLAN LI WENLONG) (44 / Male), NRIC: S7309003B, Tel: +6596658170									
Adj Asg. Remarks: ON WP									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK7660Z (545025)
[SJU2354L]
TP
KOH LIANG HUAY
Jan 7 2018 9:00PM
[ALLAN LAI MUN LOONG(ALLAN LI WENLONG)]
Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	09/01/18 18:20	Accident Statement <small>From: SC - Reg. No: SJU2354L, Claimant: ALLAN LAI MUN LOONG(ALLAN LI WENLONG)</small>	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
2	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
3	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
4	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
5	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
6	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
7	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
8	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
9	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
10	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
11	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
12	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
13	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
14	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
15	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
16	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
17	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
18	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
19	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
20	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
21	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
22	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
23	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
24	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
25	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
26	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
27	13/09/18 11:29	General View	Load JPG	<input checked="" type="checkbox"/>	
28	13/09/18 11:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	
29	13/09/18 11:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	
30	13/09/18 11:29	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	09/01/18 18:20	E-FILE REPORT (SLK7660Z)	Load PDF		

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
		MSIG Insurance (Singapore) Pte. Ltd. (HQ)			
		From: SC - Reg. No: SJU2354L, Claimant: ALLAN LAI MUN LOONG (ALLAN LI WENLONG)			
2	09/01/18 18:21	TP EST BILL & ACCDT REPORT		Load PDF	
3	09/01/18 18:25	EMAIL TP OUR LIST OF SJE & THEY NOMINATED LKK TO BE SJE		Load PDF	
No	Relabel/Reorder			Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)			
1	14/09/18 12:09	Supplementary		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000544/TITBE2

Date: 14/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B80235910SMP

Claimant Vehicle No : SLK7660Z

Insured Vehicle No : SJU2354L

Date of Loss: 07/01/2018

Nature of Claim: TP

Claim No: 545025

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK7660Z

Make & Model: BMW 216D, 1.5 D Gran Tourer (F46) (A)

Engine No: 39449805B37C15A

Reg. Date: 26/01/2017 (Man. Year: 2016)

Chassis No: WBA2E320405B45781

Colour: Bronze

Odometer: 15449 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17

Rear Tyre Size: 205/55 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,990.70	3,209.60	781.10	19.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,021.00	2,385.00	636.00	21.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,011.70	5,594.60	1,417.10	20.21
+ GST 7.00/7.00% (S\$)	490.82	391.62	99.20	20.21
Nett Amount (S\$)	7,502.52	5,986.22	1,516.30	20.21

INSPECTION

Date of Assignment: 09/01/2018

Date Inspected: 16/01/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2018)
Parts:	M1-MPV	BMW 216D 1.5 D Gran Tourer (F46) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK7660Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*FRT BUMPER LH INSERT	Not Necessary	9.35 FS	*- FS
3	1		*FRT BUMPER RH INSERT	Not Necessary	9.45 FS	*- FS
4	1		*LH VERTICAL STRUT	Not Necessary	47.00 FS	*- FS
5	1		*FRT IMPACT ABSORBER	Not Necessary	46.60 FS	*- FS
6	1		*FRT LH BOTTOM DEFORMATION ELEMENT	Not Necessary	82.25 FS	*- FS
7	1		*FRT BUMPER BOTTOM CARRIER	Not Necessary	140.10 FS	*- FS
8	1		*FRT LH SIDE PANEL TOP MOUNTING	Not Necessary	8.60 FS	*- FS
9	1		*FRT RH SIDE PANEL TOP MOULDING	Not Necessary	8.65 FS	*- FS
10	1		*LH ROD	Not Necessary	19.50 FS	*- FS
11	1		*LH SUPPORT FOG LAMP (GESCHLOSSEN)	Not Necessary	49.70 FS	*- FS
12	1		*FRT BUMPER PANEL PRIMED (PMA)	Deformed	821.50 FS	*821.50 FS
13	1		*GRILLE SIDE OPEN LH (LUXURY LINE+PD)	Cut	95.85 FS	*95.85 FS
14	1		*FRT BUMPER TOP CARRIER	Not Necessary	359.90 FS	*- FS
15	1		*PLAQUE 82MM	Necessary	67.80 FS	*67.80 FS
16	1		*LH HEADLIGHT LED TECHNOLOGY	Cut	2,085.75 FS	*2,085.75 FS
17	1		*LH FINISHER (LUXURY LINE)	Deformed	58.70 FS	*58.70 FS
Total Parts (S\$)					3,990.70	3,209.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE FRONT BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	1,275.00	850.00
2	SPRAY PAINTING FRONT BUMPER	New	1,038.00	934.00
3	TO REPLACE LEFT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	451.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (S\$)			3,021.00	2,385.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >