

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SGJ9747J (AIG)

Date : 05-01-2018

Accident Date : 02-01-2018

Our Ref : SLR2830X / CHAN

STEVEN TAN
C/O ALAN'S UNITED AUTO PTE LTD
BLK 7 SIN MING IND. EST. SECTOR C
#01-76
SINGAPORE 575642

Not Noted
1-13-1
Runny B4 paint
2 days

ESTIMATE COST OF REPAIR FOR HONDA CIVIC SLR2830X

1 PC	FRONT BUMPER FASCIA	<i>Noted</i>	\$579.90 ✓
1 PC	FRONT O/S BUMPER SIDE RETAINER	<i>in</i>	\$13.60 X
1 PC	FRONT O/S BUMPER FOGLAMP COVER	<i>in</i>	\$38.50 X
			\$631.10
		LESS 20%	\$126.22
			<u>\$504.88</u>

\$504.88

TO PUTTY AND SPRAY FRONT BUMPER AND FRONT O/S FENDER \$500.00 *2201*

TO REMOVE FRONT DAMAGED PARTS, PANEL BEATING FRONT O/S FENDER
,ALIGN,ADJUST,RENEW REPLACE PARTS AND REFIX \$450.00 *2001*
\$1,454.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Stamp:

Singapore Dollars One Thousand Four Hundred Fifty Four And Cents Eighty Eight Only