

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 242C***Not Noted***AAD1801-052***Resumy B4 part*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHD 242C**

VF1ABL15AUC282330

RENAULT

LATITUDE

3.1.2018

**AXA****PART****LIST**

|   |   |                             |
|---|---|-----------------------------|
| 1 | 1 | BUMPER COVER REAR           |
| 2 | 1 | BUMPER LOWER REAR           |
| 3 | 1 | BUMPER BRACKET CTR REAR     |
| 4 | 1 | BUMEPR BRACKET SIDE RH REAR |
| 5 | 1 | BUMEPR RETAINER RH REAR     |
| 6 | 1 | BUMPER REFLECTOR RH         |
| 7 | 1 | BUMPER BEAM REAR            |
| 8 | 1 | BUMPER BEAM BRACKET RH REAR |

|    |                        |   |
|----|------------------------|---|
| \$ | <i>Bumper</i> 1,108.46 | ✓ |
| \$ | <i>car</i> 768.84      | ✓ |
| \$ | <i>SL</i> 113.47       | X |
| \$ | <i>SL</i> 135.97       | X |
| \$ | <i>SL</i> 44.99        | X |
| \$ | <i>SL</i> 43.61        | X |
| \$ | <i>RL</i> 777.52       | ✓ |
| \$ | <i>RL</i> 225.95       | X |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>3,218.81</b> |
| <b>10%</b>   | <b>\$</b> | <b>321.88</b>   |
|              | <b>\$</b> | <b>2,896.93</b> |

**Specical Nett**

|   |      |                                |
|---|------|--------------------------------|
| 1 | 1SET | PARKING AID                    |
| 2 | 1SET | REAR BUMPER CLIP               |
| 3 | 1SET | BUMPER BRACKET CTR CLIP        |
| 4 | 1SET | BUMEPR BRACKET SIDE CLIP RH RR |
| 5 | 1SET | BUMEPR RETAINER RH CLIP RR     |
| 6 | 1SET | BUMPER LOWER REAR RIVET        |
| 7 | 1SET | BUMPER LOWER REAR CLIP         |

|    |                  |   |
|----|------------------|---|
| \$ | <i>SL</i> 700.00 | X |
| \$ | <i>RL</i> 66.00  | ✓ |
| \$ | <i>RL</i> 33.00  | ✓ |
| \$ | <i>RL</i> 10.00  | X |
| \$ | <i>RL</i> 20.00  | X |
| \$ | <i>RL</i> 22.00  | X |
| \$ | <i>RL</i> 66.00  | ✓ |

|              |           |               |
|--------------|-----------|---------------|
| <b>TOTAL</b> | <b>\$</b> | <b>917.00</b> |
|--------------|-----------|---------------|

|                    |           |                 |
|--------------------|-----------|-----------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>3,813.93</b> |
|--------------------|-----------|-----------------|

**Trans-cab Auto Services Pte Ltd****AAD1801-052**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 242C****LABOUR**

|                                                                                                                                 |    |          |      |
|---------------------------------------------------------------------------------------------------------------------------------|----|----------|------|
| Putty And Spray Painting Of The Affected Portion.                                                                               | \$ | 3,000.00 | 2200 |
| Panel Beating, Knocking And Straightening The<br>Necessary Portion, Remove And Renewal Of Parts,<br>Adjust And Realign The Same | \$ | 2,800.00 | 2000 |
| To Rust-Proofing Of The Affected Areas.                                                                                         | \$ | 170.00   | nn X |
| To reinstall rear bumper parking sensor.                                                                                        | \$ | 170.00   | 600  |
| To transfer of rear end panel fittings, attachment<br>and perform water seepage test.                                           | \$ | 170.00   | nn X |
| To check steering geometry and computer wheel<br>alignment                                                                      | \$ | 220.00   | nn X |

**TOTAL \$ 6,530.00****Over All Total \$ 10,343.93****(PARTS BY PARTS)****Repair Days****10 Days****2 days**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: