

# CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM17D07299C01

Assessment Number: KKHC0208

Version: CHINATAI/2

Date Calculated: 10/01/2018 07:34

Full Report - V1

Registration: SCR8873P

Printed: 10/01/2018 15:35

|                         |   |                      |       |    |             |
|-------------------------|---|----------------------|-------|----|-------------|
| 1000                    | 1 | ENG OIL FILTER HSING | Renew | 0% | 95.00*      |
| 1000                    | 1 | 'O' RING-BIG         | Renew | 0% | 15.00*      |
| 1000                    | 1 | 'O' RING -SMALL      | Renew | 0% | 12.00*      |
| f: OEM Parts            |   |                      |       |    |             |
| g: Original             |   |                      |       |    |             |
| h: Secondhand           |   |                      |       |    |             |
| p: Parallel             |   |                      |       |    |             |
| x: Exchange             |   |                      |       |    |             |
| Sub Total               |   |                      |       |    | \$33,394.56 |
| Mark Up From Cost (5 %) |   |                      |       |    | \$1,669.73  |
| Sundry Parts (Fixed)    |   |                      |       |    | \$100.00    |
| Total Parts             |   |                      |       |    | \$35,164.29 |

## NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

| Extras       | Description                      | Betterment | Price      |
|--------------|----------------------------------|------------|------------|
|              | FRT NUMBER PLATE SPECIALIST      | 0%         | \$40.00    |
|              | AUDATEX FEES SPECIALIST          |            | \$42.00    |
|              | AIR CON GAS SPECIALIST           | 0%         | \$50.00    |
|              | ANTI FREEZE SPECIALIST           |            | \$20.00    |
|              | BRAKE OIL @2LX\$10 SPECIALIST    | 0%         | \$20.00    |
|              | ENGINE OIL @4.5LX\$20 SPECIALIST |            | \$90.00    |
|              | WHEEL ALIGNMENT SPECIALIST       | 0%         | \$80.00    |
|              | FRT TYRE LH SPECIALIST           |            | \$220.00   |
|              | FRT TYRE RH SPECIALIST           | 0%         | \$220.00   |
|              | REAR TYRE RH SPECIALIST          |            | \$220.00   |
|              | FRT RIM LH SPECIALIST            | 0%         | \$520.00   |
|              | FRT RIM RH SPECIALIST            |            | \$520.00   |
|              | REAR RIM LH SPECIALIST           | 0%         | \$520.00   |
|              | REAR RIM RH SPECIALIST           |            | \$520.00   |
|              | FRT WS SEALANT SPECIALIST        | 0%         | \$40.00    |
|              | FRT WS DAMP SEAL SPECIALIST      |            | \$20.00    |
|              | ERP BRACKET SPECIALIST           | 0%         | \$26.00    |
|              | PRIVATE HIRE SPECIALIST          |            | \$25.00    |
|              | STICKER                          |            |            |
|              | FRT WS SOLAR FILM SPECIALIST     | 0%         | \$220.00   |
|              | BATTERY SPECIALIST               |            | \$180.00   |
|              | OIL SUMP SEALANT SPECIALIST      | 0%         | \$40.00    |
| Total Extras |                                  |            | \$3,633.00 |

## Final Calculation

|                                |             |
|--------------------------------|-------------|
| Total Parts                    | \$35,164.29 |
| Labour                         |             |
| Total Panel/Mechanical         | \$2,405.80  |
| Total Paintwork                | \$1,196.00  |
| Total Visual Alignment work    | \$55.20     |
| Total Labour                   | \$3,657.00  |
| Additional Costs               |             |
| Corr Prot Materials External   | \$0.00      |
| Corr Prot Materials Internal   | \$0.00      |
| Cost of Specialist             | \$3,633.00  |
| Total of Additional Costs      | \$3,633.00  |
| Total Paint/Material Costs     | \$617.60    |
| Repair Costs Excludes GST      | \$43,071.89 |
| Deductions                     |             |
| Deduction for Excess ( Fixed ) | -\$1,000.00 |
| Total Deductions               | -\$1,000.00 |

**CHINA TAIPING INSURANCE (S) PTE LTD**

**Claim Reference: SNM17D07299C01**

**Assessment Number: KKHC0208**

**Version: CHINATAI/2**

**Date Calculated: 10/01/2018 07:34**

**Full Report -V1**

**Registration: SCR8873P**

**Printed: 10/01/2018 15:35**

**Grand Total Excludes GST (After Deduction)**

**\$42,071.89**

**GST @ 7 %**

**\$2,945.03**

**Grand Total Includes GST (After Deduction)**

**\$45,016.92**

**Assessment Notes**



Auto  
Consultants  
Pte Ltd

## STATEMENT

### PARTICULARS

Name : CHONG EE MING CHRISTOPHER  
 NRIC / Passport No. : S8741068D  
 Address : BLK 319 SHUNFU ROAD #08-10 S(570319)  
BLK 445 SIN MING AVE #04-457  
 Telephone : (R) 62578788 (O)   
 (HP) 91830887  
 Sex / Age : M / 30  
 Occupation / Name of Company : UBER DRIVER / SELF EMPLOYED (EMING VEHICLES)  
 Nationality : S'POREAN

Recorded By : MUHD NAZIL Date : 16/01/18 Time: 1100  
 Place Recorded: NAVENA SQUARE  
 Language Spoken: ENGLISH Interpreted By: N/A

### FACTS OF CASE:

I am the owner and driver of the vehicle no. 3CR1F73P involved in the accident on 28/12/17 at 8300 hours. I am a Ube driver. I had picked up a passenger from 311 Tanglin Katong Rd and sent to YBD Upper Stranmillis Crescent. I reached the destination before midnight. I felt sleepy. So I slept in the car at the pick-up / drop off point for about 3-4 hours. By the time I woke up, it was about 0200 hours. I left the passenger's address and proceeded home. I was driving along Bugis Road towards Bumilok Green, heading back to Shunfu Road. I don't recall how was the traffic, but the weather was clear and the road surface was dry. I was travelling around market 40 to 60 kmph. I don't remember what speed I was travelling at. I don't remember what happened. But I think I fell asleep. When I woke up, I remember going over green fences and finally coming to a stop where I hit a tree. The airbag did not deploy. I was in a daze for a moment. I got myself out of the car. I felt pain but I don't remember where I checked the car for the damages. A resident (male) heard the crash and came to my aid. He was insistent

Signed:

Recorded by:

MUHD NAZIL

S8741068D

LEE BTO / INQUIRY



Lee Sheng. Auto.

Case 2 KKH1 Built prob.

Anglia admin

Lee. car came in 2pm. last day  
dash. hit car at dot time. 29/12 car  
but out.



Auto  
Consultants  
Pro Ltd

Mr Wong  
workshop

### STATEMENT

on calling an ambulance I don't remember what he said. there were other drivers who came to the accident scene. the ambulance came shortly. the Traffic Police officers on bikes came later. I was examined by the paramedics. They advised me to go to the hospital but I did not want to go as I did not want to pay for the ambulance. furthermore I was not injured. I declined medical assistance. the attending Traffic Police officer told me to stop picking up vehicular debris from the road and call for a tow truck and advised me to make a police report. So I sat down by the side of the road and called my mother. My mother came shortly after. then I searched for a tow truck company on the Internet and called the 1st company I saw. the tow truck arrived in 30 minutes. the TP was still there when the tow truck arrived. the officer gave me a piece of paper with ~~an~~ investigating officer Mr. Ma's name and a case number on it.

The car was towed to Progressive Auto. I emailed Chiu Tai Ping ~~the~~ and they called me. they said Progressive is not an authorized YTI workshop. So I called my dad's friend and he arranged for the car to be towed to K. Kim Hin Auto. I made a police report at Bishan NPC on 28/12/17 at 1232 hours. The insurance report was made at SMRT Woodlands on 28/12/17 at 1853 hours.

I got a call from K. Kim Hin Auto asking me where the car came from. I told them it was Lee Sheng Auto as the car was brought there from Progressive Auto. I went down there the car on 30/12/17 at 1200 hours at Kim Hin Auto.

I wish to state that I did not consume any alcohol or any medication that cause drowsiness or impair my ability to drive at the date and time of accident.

I hereby confirm that the above statement is correct and true at the time it was written.

Signed: CL  
S8.74/068D

Recorded by: KL MUTHU RAJAN  
LEE AUTO CONSULTANT

**K.KIM HIN AUTO PTE LTD**  
**160 Sin Ming Drive**  
**#02-20 Sin Ming AutoCity**  
**Singapore 575722**

**Claim Reference:**  
**Assessment Number: KKHC0208**  
**Version: K.KIMHIN/2**  
**Date Calculated: 18/03/2018 03:45**

**Full Report - V1**  
**Registration: SCR8873P**  
**Printed: 18/03/2018 11:51**

---

**Summary Information**

**Claim**

|                       |                                 |                            |            |
|-----------------------|---------------------------------|----------------------------|------------|
| Location:             | Singapore (SG)                  | Currency:                  | SGD        |
| Printed by:           | SANDRA KHONG                    | Date of Incident:          | 28/11/2017 |
| Authorisation Status: | Interim                         | Able to Authorise Repairs: | TBA        |
| Work Provider:        | China Taiping Insurance (S) Pte | Repairs Authorised:        | TBA        |
| Claim Reference:      |                                 | Estimated Repair Time:     |            |
| Policy Number:        | DMHCSN1748561700                | Quote Due Date:            |            |
| Other Reference:      |                                 | Actual Repair Days:        |            |
| Third Party:          |                                 | Parts Ordered Date:        |            |
| Insured Amount:       |                                 | Hire Car Start:            |            |
| Under Warranty:       |                                 | Hire Car End:              |            |
| Warranty Expired:     |                                 | Vehicle Collected:         |            |

**Vehicle Details**

**Vehicle**

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | TOYOTA            |
| Model:              | Camry             |
| Sub Model:          | BASE MODEL        |
| Model Sheet Number: | YCA 01            |
| Registration:       | SCR8873P          |
| Registration Month: |                   |
| Registration Year:  |                   |
| VIN Number:         | MR053AK5004007612 |
| Odometer:           | Not Known         |
| Colour:             |                   |
| Engine Number:      | 2ARU131457        |
| Fuel Level:         | %                 |

**Model Specs**

|                      |                    |
|----------------------|--------------------|
| FROM 03/2009         | XENON HEADLAMPS    |
| FOG LAMPS            | HEADLAMP LEVELLING |
| FRONT PARKING SYSTEM | 2.4 LTR 123KW      |
| CHINA VERSION        | TWO COAT METALLIC  |
| PREPARE OFF VEHICLE  |                    |

---

**Vehicle Condition**

**Vehicle Status**



|                         |                               |            |
|-------------------------|-------------------------------|------------|
| Pre-Accident Condition: | Severity of Impact:           |            |
| Steering:               | Vehicle Status on Inspection: |            |
| Brakes Pedal Travel:    | Date of Inspection:           | 05/01/2018 |
| Place of Inspection:    |                               |            |
| Pre-Accident Damage:    |                               |            |
| Tyres Condition:        | Tread Depth RHF:              |            |
| Tread Depth LHF:        | Tread Depth RHR:              |            |
| Tread Depth LHR:        | Direction of Impact:          |            |
| Damage Areas:           |                               |            |



# K.KIM HIN AUTO PTE LTD

Claim Reference:  
 Assessment Number: KKHC0208  
 Version: K.KIMHIN/2  
 Date Calculated: 18/03/2018 03:45

Full Report - V1  
 Registration: SCR8873P  
 Printed: 18/03/2018 11:51



## Addresses

## Cost Summary

|                           |             |
|---------------------------|-------------|
| Total Labour              | \$4,020.40  |
| Total Paint/Material      | \$593.77    |
| Total Parts               | \$33,346.05 |
| Total of Additional Costs | \$2,893.00  |
| Repair Cost Exc GST:      | \$40,853.22 |
| Overall Discount (20%):   | -\$8,170.64 |
| Excess:                   | TBA         |
| After Deduction -         |             |
| Grand Total Exc GST:      | \$32,682.58 |
| 7 % GST:                  | \$2,287.78  |
| Grand Total Inc GST:      | \$34,970.36 |

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR  
 Price/Dent = \$46.00/HR

| Repair / Guide Number | Repair Details                                                                                | WU   | Cost Price (\$) |
|-----------------------|-----------------------------------------------------------------------------------------------|------|-----------------|
| 043233C               | ADD: ADJUST FRONT TOE                                                                         | 1.0  | 4.60            |
| 043233                | ALIGN VEHICLE CPL                                                                             | 12.0 | 55.20           |
| M030ZAX               | R + R L/F AXLE HALF (ADD/WORK)                                                                | 11.0 | 50.60           |
| B140                  | RENEW FRONT PANEL                                                                             | 22.0 | 101.20          |
| B150)                 | RENEW COMPLETE R/F WHEELHOUSE                                                                 | 32.0 | 147.20          |
| NO NUMBER             | RENEW LEFT FRONT SIDE MEMBER CLOSING                                                          | 15.0 | 69.00           |
| NO NUMBER             | ADD/WORK FOR PARKING AID SENSOR DRILLING                                                      | 3.0  | 13.80           |
| NO NUMBER             | R + R FRONT PARKING AID SENSOR/S                                                              | 1.0  | 4.60            |
| NO NUMBER             | R + R L/F CENTRE PARKING AID SENSOR                                                           | 1.0  | 4.60            |
| NO NUMBER             | R + R R/F CENTRE PARKING AID SENSOR                                                           | 1.0  | 4.60            |
| B110                  | RENEW L/FRT WING (FRT BUMPER AND L/HEADLAMP ASSY REMOVED)                                     | 5.0  | 23.00           |
| B110                  | RENEW R/FRT WING (FRT BUMPER AND R/HEADLAMP ASSY REMOVED)                                     | 5.0  | 23.00           |
| B100                  | R + R LEFT SILL RAIL                                                                          | 3.0  | 13.80           |
| B100                  | R + R RIGHT SILL RAIL                                                                         | 3.0  | 13.80           |
| B020                  | RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS | 15.0 | 69.00           |
| B040                  | RENEW BOTH HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS                              | 7.0  | 32.20           |
| B070                  | RENEW BONNET                                                                                  | 6.0  | 27.60           |

# K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHC0208

Version: K.KIMHIN/2

Date Calculated: 18/03/2018 03:45

Full Report - V1

Registration: SCR8873P

Printed: 18/03/2018 11:51

|           |                                                                                        |      |        |
|-----------|----------------------------------------------------------------------------------------|------|--------|
| 530121)   | R + R BONNET OPENER CABLE                                                              | 2.0  | 9.20   |
| NO NUMBER | RENEW BATTERY TRAY                                                                     | 5.0  | 23.00  |
| B085)     | R + R WIRE LINKAGE                                                                     | 1.0  | 4.60   |
| G010      | R + R WINDSCREEN                                                                       | 33.0 | 151.80 |
|           | INCLUDES: A-PILLAR TRIM,<br>SUN VISOR, REAR VIEW MIRROR AND<br>REQUIRED ATTACHED PARTS |      |        |
| 743261    | R + R LEFT FRONT DOOR MOULDING                                                         | 2.0  | 9.20   |
| 743261    | R + R RIGHT FRONT DOOR MOULDING                                                        | 2.0  | 9.20   |
| 743011    | R + R L/LOWER A-PILLAR TRIM                                                            | 2.0  | 9.20   |
| 743011    | R + R R/LOWER A-PILLAR TRIM                                                            | 2.0  | 9.20   |
| 752051    | R + R R/DOOR MIRROR                                                                    | 3.0  | 13.80  |
| B420      | RENEW REAR BUMPER                                                                      | 6.0  | 27.60  |
|           | INCLUDES: BUMPER AND ALL<br>REQUIRED ATTACHED PARTS R + R                              |      |        |
| 743061)   | R + R REAR PARCEL SHELF TRIM                                                           | 1.0  | 4.60   |
| M260      | R + R FUEL TANK                                                                        | 9.0  | 41.40  |
| M230)     | R + R INSTRUMENT PANEL                                                                 | 7.0  | 32.20  |
| 550351)   | RENEW INSTRUMENT PANEL (REMOVED)                                                       | 3.0  | 13.80  |
| 743641    | R + R CENTRE CONSOLE INSERT                                                            | 3.0  | 13.80  |
| M010)     | RENEW CONDENSER (REMOVED)                                                              | 1.0  | 4.60   |
| NO NUMBER | R + R AIR CONDITIONING HOSE                                                            | 4.0  | 18.40  |
| NO NUMBER | R + R AIR CONDITIONING PIPE                                                            | 4.0  | 18.40  |
| NO NUMBER | R + R AIR CONDITIONING PIPE                                                            | 5.0  | 23.00  |
| NO NUMBER | R + R AIR CONDITIONING HOSE                                                            | 4.0  | 18.40  |
| B450)     | R + R SEAT CUSHION                                                                     | 1.0  | 4.60   |
| B450)     | R + R LEFT REAR SEAT BACK REST                                                         | 2.0  | 9.20   |
| B450)     | R + R RIGHT REAR SEAT BACK REST                                                        | 2.0  | 9.20   |
| NO NUMBER | R + R L/R SEAT SIDE PAD                                                                | 1.0  | 4.60   |
| NO NUMBER | R + R R/R SEAT SIDE PAD                                                                | 1.0  | 4.60   |
| NO NUMBER | R + R L/ENGINE COMPARTMENT FUSE BOX                                                    | 7.0  | 32.20  |
| M010      | R + R RADIATOR AND CONDENSER<br>(FRONT BUMPER REMOVED)                                 | 16.0 | 73.60  |
|           | INCLUDES: BLEED COOLING SYSTEM                                                         |      |        |
| M010)     | RENEW RADIATOR                                                                         | 3.0  | 13.80  |
| 160111)   | R + R LOWER RADIATOR HOSE                                                              | 2.0  | 9.20   |
| 160101)   | R + R UPPER RADIATOR HOSE                                                              | 2.0  | 9.20   |
| 170521)   | R + R EXHAUST MANIFOLD                                                                 | 2.0  | 9.20   |
| 151011    | R + R OIL STRAINER                                                                     | 5.0  | 23.00  |
| 112011)   | R + R OIL PAN                                                                          | 10.0 | 46.00  |
| NO NUMBER | DETACH + REFIT EXHAUST SYSTEM                                                          | 3.0  | 13.80  |
| 170251    | R + R EXHAUST SYSTEM ATTACHED PARTS                                                    | 3.0  | 13.80  |
| 170171)   | R + R FRONT EXHAUST PIPE                                                               | 3.0  | 13.80  |
| 170181)   | R + R CENTRE SILENCER                                                                  | 2.0  | 9.20   |
| M240      | R + R REAR SILENCER                                                                    | 2.0  | 9.20   |
| 473011A)  | R + R FRONT BRAKE DISC/S                                                               | 2.0  | 9.20   |
| 896051)   | R + R ABS BRAKE SYSTEM                                                                 | 1.0  | 4.60   |
|           | DOES NOT INCLUDE: BLEED BRAKE SYSTEM                                                   |      |        |
| 896081)   | R + R R/F ABS SENSOR                                                                   | 1.0  | 4.60   |
| 896081)   | R + R R/F ABS SENSOR                                                                   | 1.0  | 4.60   |
| 431151)   | R + R LEFT FRONT SPRING/SHOCK ABSORBER                                                 | 1.0  | 4.60   |
| 431151)   | R + R RIGHT FRONT SPRING/SHOCK ABSORBER                                                | 1.0  | 4.60   |



# K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHC0208

Version: K.KIMHIN/2

Date Calculated: 18/03/2018 03:45

Full Report - V1

Registration: SCR8873P

Printed: 18/03/2018 11:51

|           |                                                                                |       |        |
|-----------|--------------------------------------------------------------------------------|-------|--------|
| NO NUMBER | R + R FRONT AXLE CARRIER                                                       | 18.0  | 82.80  |
| NO NUMBER | RENEW FRONT AXLE SUPPORT<br>(REMOVED)                                          | 6.0   | 27.60  |
|           | INCLUDES: CONVERT STEERING AND ALL<br>RUBBER MOUNTS, RENEW IF NECESSARY        |       |        |
| 434601)   | R + R R/F AXLE SHAFT CPL                                                       | 1.0   | 4.60   |
| 434211)   | RENEW LEFT FRONT STEERING KNUCKLE<br>DOES NOT INCLUDE: VEHICLE ALIGNMENT       | 4.0   | 18.40  |
| 434211)   | RENEW RIGHT FRONT STEERING KNUCKLE<br>DOES NOT INCLUDE: VEHICLE ALIGNMENT      | 4.0   | 18.40  |
| 434021A)  | R + R FRONT WHEEL HUB (COMPOSITE WORK)                                         | 1.0   | 4.60   |
| 004466)   | VENT R/F BRAKE SYSTEM                                                          | 2.0   | 9.20   |
| 004466A)  | BLEED BRAKE SYSTEM                                                             | 1.0   | 4.60   |
| 420018)   | R + R LEFT REAR WHEEL                                                          | 1.0   | 4.60   |
| 420018)   | R + R RIGHT REAR WHEEL                                                         | 1.0   | 4.60   |
| 420091)   | R + R LEFT REAR TYRE/WHEEL                                                     | 3.0   | 13.80  |
| 420091)   | R + R RIGHT REAR TYRE/WHEEL                                                    | 3.0   | 13.80  |
| 473061A)  | R + R REAR BRAKE DISC/S                                                        | 2.0   | 9.20   |
| 422041A)  | RENEW REAR WHEEL HUBS                                                          | 1.0   | 4.60   |
| 482201A)  | R + R REAR SUSPENSION STRUT                                                    | 2.0   | 9.20   |
| 482201)   | RENEW LEFT REAR SHOCK ABSORBER                                                 | 1.0   | 4.60   |
| 482201)   | RENEW RIGHT REAR SHOCK ABSORBER                                                | 1.0   | 4.60   |
| 482041A)  | DETACH AND REFIT REAR CONTROL ARM                                              | 5.0   | 23.00  |
| 482041)   | R + R L/R CONTROL ARM REAR<br>DOES NOT INCLUDE: MEASURE REAR VEHICLE           | 1.0   | 4.60   |
| 482041)   | R + R R/R CONTROL ARM REAR<br>DOES NOT INCLUDE: MEASURE REAR VEHICLE           | 1.0   | 4.60   |
| 482021)   | R + R REAR LEFT FRONT CONTROL ARM<br>DOES NOT INCLUDE: REAR VEHICLE ALIGNMENT  | 1.0   | 4.60   |
| 482021)   | R + R REAR RIGHT FRONT CONTROL ARM<br>DOES NOT INCLUDE: REAR VEHICLE ALIGNMENT | 1.0   | 4.60   |
| 482091)   | R + R LEFT REAR TENSION STRUT                                                  | 2.0   | 9.20   |
| 482091)   | R + R RIGHT REAR TENSION STRUT                                                 | 2.0   | 9.20   |
| NO NUMBER | R + R L/R STEERING KNUCKLE                                                     | 6.0   | 27.60  |
| NO NUMBER | R + R R/R STEERING KNUCKLE                                                     | 6.0   | 27.60  |
| 004466)   | VENT L/R BRAKE SYSTEM                                                          | 3.0   | 13.80  |
| 004466)   | VENT R/R BRAKE SYSTEM                                                          | 3.0   | 13.80  |
| 0245      | PANEL WORK FRONT                                                               | 30.0* | 138.00 |
| 9715      | REMOVE AND REFIT ENGINE WITH GEARBOX                                           | 40.0* | 184.00 |
| 9889      | HANDHELD MEAS SYS ALIGN BODY SHELL                                             | 20.0* | 92.00  |
| 1117      | REPAIR L/F WHEELHOUSE CPL                                                      | 30.0* | 138.00 |
| 1211      | REPAIR L/INN SIDE MEMBER                                                       | 35.0* | 161.00 |
| 1482      | REPAIR RIGHT FRONT DOOR                                                        | 30.0* | 138.00 |
| 9081      | CHECK REAR AXLE SUBFRAME                                                       | 15.0* | 69.00  |

## LABOUR COST

|                                      |         |            |
|--------------------------------------|---------|------------|
| Total Work Units                     | 599.0   |            |
| Panel / Mechanical Labour            | 58.6HRS | \$2,695.60 |
| Visual Alignment Labour              | 1.3HRS  | \$59.80    |
| Corrosion Protection External Labour | 0.0HRS  | 0.00       |
| Corrosion Protection Internal Labour | 0.0HRS  | 0.00       |
| Sub Total                            | 59.9HRS | \$2,755.40 |
| Paint Labour                         | 27.5HRS | \$1,265.00 |



# K.KIM HIN AUTO PTE LTD

Claim Reference:  
Assessment Number: KKHC0208  
Version: K.KIMHIN/2  
Date Calculated: 18/03/2018 03:45

Full Report - V1  
Registration: SCR8873P  
Printed: 18/03/2018 11:51

**Total Labour** 87.4HRS \$4,020.40

**PAINT WORK** Time Basis 10 WU = 1 HR. Price = \$46.00/HR  
**Guide Number Description** WU Cost Price (\$)

|                              |                                           |         |            |
|------------------------------|-------------------------------------------|---------|------------|
|                              | - TWO COAT METALLIC                       |         |            |
|                              | - PREPARE OFF VEHICLE                     |         |            |
| 340                          | BUMPER SUPPORT SURFACE PAINT              | 4.0     |            |
| 988                          | LOCK CARRIER STRUT SURFACE PAINT          | 4.0     |            |
| 1009                         | FRONT PANEL SURFACE PAINT                 | 7.0     |            |
| 1118                         | R/F WHEELHOUSE CPL SURFACE PAINT          | 6.0     |            |
| 1212                         | R/INN SIDE MEMBER SURFACE PAINT           | 5.0     |            |
| 1781                         | L/R DOOR NEW PART PAINTING                | 14.0    |            |
| 1782                         | R/R DOOR NEW PART PAINTING                | 14.0    |            |
| 9551                         | L/R WHEEL NEW PART PAINTING               | 7.0     |            |
| 9552                         | R/R WHEEL NEW PART PAINTING               | 7.0     |            |
| 283                          | FRONT BUMPER NEW PART PAINT K1R           | 13.0    |            |
| 1746                         | R/DOOR MIRROR HSG NEW PART PAINT K1R      | 3.0     |            |
| 2185                         | L/SILL MOULDING NEW PART PAINT K1R        | 7.0     |            |
| 2186                         | R/SILL MOULDING NEW PART PAINT K1R        | 7.0     |            |
| 2583                         | REAR BUMPER NEW PART PAINT K1R            | 14.0    |            |
| 471                          | BONNET REPAIR PAINTING >50%               | 41.0    |            |
| 741                          | L/F WING REPAIR PAINTING >50%             | 16.0    |            |
| 742                          | R/F WING REPAIR PAINTING >50%             | 16.0    |            |
| 1482                         | RIGHT FRONT DOOR REPAIR PAINTING >50%     | 25.0    |            |
| 1117                         | L/F WHEELHOUSE CPL SURFACE PAINT          | 6.0     |            |
| 1211                         | L/INN SIDE MEMBER SURFACE PAINT           | 5.0     |            |
| 1481                         | LEFT FRONT DOOR SURFACE PAINT             | 8.0     |            |
| 3481                         | L/R WING SURFACE PAINT                    | 8.0     |            |
| 3482                         | R/R WING SURFACE PAINT                    | 8.0     |            |
| <b>LABOUR COST - PAINT</b>   |                                           |         |            |
|                              | <b>TIME(PAINT)</b>                        | 245.0   |            |
|                              | Preparation Main Work Plastic             | 5.0     |            |
|                              | Preparation Main Work Metal               | 25.0    |            |
|                              | Preparation Work Multi Layer Paint        | 0.0     |            |
|                              | <b>Total Work Units (10WU/HR)</b>         | 275.0   |            |
|                              | <b>Total Paintwork Labour</b>             | 27.5HRS | \$1,265.00 |
| <b>MATERIAL COST - PAINT</b> |                                           |         |            |
|                              | <b>Cost Price</b>                         |         |            |
|                              | New Part Painting                         |         | \$86.68    |
|                              | New Part Painting - Plastic K1R           |         | \$197.29   |
|                              | Material-Constant Main Work Metal         |         | \$28.60    |
|                              | Surface-/Blend Paint                      |         | \$138.69   |
|                              | Repair Painting                           |         | \$133.51   |
|                              | Material-Const Main Work Plastic          |         | \$9.00     |
|                              | <b>Total Excluding Pearlescent Uplift</b> |         | \$593.77   |
|                              | Pearlescent Uplift @ 0.0%                 |         | \$0.00     |
|                              | <b>Total Paint Material Cost</b>          |         | \$593.77   |

## PARTS

|           |     |                    |             |          | Price Valid: 01/06/2015 |            |
|-----------|-----|--------------------|-------------|----------|-------------------------|------------|
| Guide No. | Qty | Description        | Part Number | Supplier | Bet.                    | Price (\$) |
| 257       | 1   | FRONT NUMBER PLATE | KNPL3       |          | 0%                      | 18.00U     |
| 260       | 1   | FRT NO PLATE BRKT  | 52114 06100 |          | 0%                      | 50.00*     |

# K.KIM HIN AUTO PTE LTD

Claim Reference:  
Assessment Number: KKHC0208  
Version: K.KIMHIN/2  
Date Calculated: 18/03/2018 03:45

Full Report - V1  
Registration: SCR8873P  
Printed: 18/03/2018 11:51

|      |   |                      |               |    |           |
|------|---|----------------------|---------------|----|-----------|
| 283  | 1 | FRONT BUMPER         | 52119 06951   | 0% | 220.00*   |
| 297  | 1 | L/FOG LAMP COVER     | 52040 06110   | 0% | 80.00*    |
| 298  | 1 | R/FOG LAMP COVER     | 52030 06110   | 0% | 80.00*    |
| 301  | 1 | L/F OUTER SENSOR     | 89341 33180B0 | 0% | 165.00*   |
| 302  | 1 | R/F OUTER SENSOR     | 89341 33180B0 | 0% | 165.00*   |
| 303  | 1 | L/PARK AID SENS CVR  | 89348 33080A0 | 0% | 18.00*    |
| 304  | 1 | R/PARK AID SENS CVR  | 89348 33080A0 | 0% | 18.00*    |
| 317  | 1 | L/F UPP BUMPER BRKT  | 52536 06110   | 0% | 45.00*    |
| 318  | 1 | R/F UPP BUMPER BRKT  | 52535 06120   | 0% | 45.00*    |
| 340  | 1 | BUMPER SUPPORT       | 52021 06080   | 0% | 150.00*   |
| 344  | 1 | FRT BUMPER ABSORBER  | 52611 06180   | 0% | 65.00*    |
| 410  | 1 | GRILLE               | 53101 06270   | 0% | 170.00*   |
| 412  | 1 | CTR BUMPER GRILLE    | 53112 06160   | 0% | 80.00*    |
| 471  | 1 | BONNET               | 53301 06140   | 0% | 360.00*   |
| 475  | 1 | L/BONNET HINGE       | 53420 33180   | 0% | 40.00*    |
| 476  | 1 | R/BONNET HINGE       | 53410 33180   | 0% | 40.00*    |
| 481  | 1 | BONNET INSULATION    | 53341 06210   | 0% | 95.00*    |
| 493  | 1 | LOWER BONNET LOCK    | 53510 06160   | 0% | 55.00*    |
| 497  | 1 | L/BONNET DAMPER      | 53450 06060   | 0% | 120.00*   |
| 498  | 1 | R/BONNET DAMPER      | 53440 06070   | 0% | 120.00*   |
| 500  | 1 | CONTROL CABLE        | 53630 06140   | 0% | 60.00*    |
| 527  | 1 | BONNET FRONT SEAL    | 53381 06090   | 0% | 45.00*    |
| 561  | 1 | LEFT HEADLAMP ASSY   | 81150 06630   | 0% | 1,300.00* |
| 562  | 1 | RIGHT HEADLAMP ASSY  | 81110 06630   | 0% | 1,300.00* |
| 637  | 1 | L/F FOG LAMP CPL     | 81220 06052   | 0% | 110.00*   |
| 638  | 1 | R/F FOG LAMP CPL     | 81210 06052   | 0% | 110.00*   |
| 741  | 1 | L/F WING             | 53802 06170   | 0% | 185.00*   |
| 742  | 1 | R/F WING             | 53801 06160   | 0% | 185.00*   |
| 767  | 1 | L/WING MOULDING      | 53826 06060   | 0% | 45.00*    |
| 768  | 1 | R/WING MOULDING      | 53825 06060   | 0% | 45.00*    |
| 841  | 1 | L/WHEELHOUSE SHELL   | 53876 06100   | 0% | 65.00*    |
| 842  | 1 | R/WHEELHOUSE SHELL   | 53875 06100   | 0% | 65.00*    |
| 988  | 1 | LOCK CARRIER STRUT   | 53208 06070   | 0% | 45.00*    |
| 1009 | 1 | FRONT PANEL          | 53201 06160   | 0% | 220.00*   |
| 1118 | 1 | R/F WHEELHOUSE CPL   | 53701 06150   | 0% | 195.00*   |
| 1169 | 1 | L/RADIATOR AIR GUIDE | 53294 06110   | 0% | 55.00*    |
| 1170 | 1 | R/RADIATOR AIR GUIDE | 53293 06120   | 0% | 55.00*    |
| 1203 | 1 | L/F BUMPER REINF     | 57118 06080   | 0% | 65.00*    |
| 1212 | 1 | R/INN SIDE MEMBER    | 57027 06051   | 0% | 590.00*   |
| 1392 | 1 | AIR GUIDE TRIM       | 55708 06130   | 0% | 145.00*   |
| 1401 | 1 | WINDSCREEN           | 56101 06431   | 0% | 420.00*   |
| 1411 | 1 | WINDSCREEN BOND KIT  | PZ49I 00C1131 | 0% | 38.18U    |
| 1415 | 2 | CLIP FASTENING       | 56115 30120   | 0% | 4.76U     |
| 1416 | 2 | CLIP FASTENING       | 56116 22050   | 0% | 3.96U     |
| 1436 | 1 | WASHER CONTAINER     | 85315 06190   | 0% | 95.00*    |
| 1453 | 1 | L/F WIPER ARM        | 85221 06100   | 0% | 95.00*    |
| 1454 | 1 | R/F WIPER ARM        | 85211 06100   | 0% | 95.00*    |
| 1457 | 1 | L/F WIPER BLADE      | 85222 33250   | 0% | 60.00*    |
| 1458 | 1 | R/F WIPER BLADE      | 85212 53081   | 0% | 60.00*    |
| 1738 | 1 | R/DOOR MIRROR        | 87910 06322A0 | 0% | 420.00*   |
| 2185 | 1 | L/SILL MOULDING      | 75852 06903   | 0% | 195.00*   |
| 2186 | 1 | R/SILL MOULDING      | 75851 06903   | 0% | 195.00*   |



# K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHC0208

Version: K.KIMHIN/2

Date Calculated: 18/03/2018 03:45

Full Report - V1

Registration: SCR8873P

Printed: 18/03/2018 11:51

|      |   |                      |               |    |           |
|------|---|----------------------|---------------|----|-----------|
| 2583 | 1 | REAR BUMPER          | 52159 06923   | 0% | 260.00*   |
| 3011 | 1 | BADGE "VVT-I" L      | 75443 06260   | 0% | 18.00*    |
| 3012 | 1 | BADGE "VVT-I" R      | 75443 06540   | 0% | 18.00*    |
| 4331 | 1 | INSTRUMENT PNL TRIM  | 55401 06161C0 | 0% | 600.00*   |
| 4455 | 1 | COMPRESSOR           | 88310 06280   | 0% | 580.00*   |
| 4465 | 1 | CONDENSER            | 88460 06220   | 0% | 375.00*   |
| 4481 | 1 | COMPR/CONDENSER TUBE | 88711 06340   | 0% | 165.00*   |
| 4482 | 1 | COND/EVAPORATOR PIPE | 88710 06271   | 0% | 195.00*   |
| 4483 | 1 | COMPR/EVAP TUBE      | 88712 06180   | 0% | 185.00*   |
| 4485 | 1 | FRT PIPE COMPR/COND  | 88715 06080   | 0% | 115.00*   |
| 7011 | 1 | FRT AXLE CARRIER     | 51100 06100   | 0% | 980.00*   |
| 7017 | 1 | L/F SUSPN BUFFER     | 52213 06130   | 0% | 80.00*    |
| 7018 | 1 | R/F SUSPN BUFFER     | 52213 06130   | 0% | 80.00*    |
| 7025 | 1 | L/R BUFFER           | 52216 06110   | 0% | 80.00*    |
| 7026 | 1 | R/R BUFFER           | 52216 06110   | 0% | 80.00*    |
| 7027 | 1 | L/F CONTROL ARM BUSH | 52211 06130   | 0% | 80.00*    |
| 7028 | 1 | R/F CONTROL ARM BUSH | 52211 06130   | 0% | 80.00*    |
| 7029 | 1 | L/R CONTROL ARM BUSH | 52217 06090   | 0% | 80.00*    |
| 7030 | 1 | R/R CONTROL ARM BUSH | 52215 06110   | 0% | 80.00*    |
| 7053 | 1 | L/LWR AXLE STEERING  | 48069 06140   | 0% | 145.00*   |
| 7054 | 1 | R/LWR AXLE STEERING  | 48068 06140   | 0% | 145.00*   |
| 7065 | 1 | L/CARRIER JOINT      | 43340 09130   | 0% | 75.00*    |
| 7066 | 1 | R/CARRIER JOINT      | 43330 09710   | 0% | 75.00*    |
| 7069 | 1 | L/SEAT W/OUT SPRING  | 48471 41010   | 0% | 35.00*    |
| 7070 | 1 | R/SEAT W/OUT SPRING  | 48471 41010   | 0% | 35.00*    |
| 7077 | 1 | L/F STRUT            | 48520 09K90   | 0% | 215.00*   |
| 7078 | 1 | R/F STRUT            | 48510 09S30   | 0% | 215.00*   |
| 7081 | 1 | L/F STEERING KNUCKLE | 43212 06230   | 0% | 185.00*   |
| 7082 | 1 | R/F STEERING KNUCKLE | 43211 06230   | 0% | 185.00*   |
| 7091 | 1 | L/UPP SUPP MOUNTING  | 48609 06170   | 0% | 80.00*    |
| 7092 | 1 | R/UPP SUPP MOUNTING  | 48609 06170   | 0% | 80.00*    |
| 7101 | 1 | L/F DAMPER BUFFER    | 48331 33032   | 0% | 25.00*    |
| 7102 | 1 | R/F DAMPER BUFFER    | 48331 33032   | 0% | 25.00*    |
| 7117 | 1 | L/F WHEEL BEARING    | 90363 C0002   | 0% | 75.00*    |
| 7118 | 1 | R/F WHEEL BEARING    | 90363 C0002   | 0% | 75.00*    |
| 7131 | 1 | L/F WHEEL HUB        | 43502 06110   | 0% | 175.00*   |
| 7132 | 1 | R/F WHEEL HUB        | 43502 06110   | 0% | 175.00*   |
| 7241 | 1 | ABS BRAKE UNIT       | 44050 06090   | 0% | 4,100.00* |
| 7300 | 1 | POWER STEERING CPL   | 44250 06321   | 0% | 590.00*   |
| 7761 | 1 | RADIATOR             | 16400 0H291   | 0% | 400.00*   |
| 7767 | 1 | RADIATOR SHROUD      | 16711 0H150   | 0% | 125.00*   |
| 7769 | 1 | L/UPP RADIATOR BRKT  | 16523 0H040   | 0% | 18.00*    |
| 7770 | 1 | R/UPP RADIATOR BRKT  | 16523 0H040   | 0% | 18.00*    |
| 7771 | 1 | L/LWR RADIATOR BRKT  | 16535 0H040   | 0% | 18.00*    |
| 7772 | 1 | R/LWR RADIATOR BRKT  | 16535 0H040   | 0% | 18.00*    |
| 7773 | 1 | LWR RADIATOR HOSE    | 16572 0H140   | 0% | 40.00*    |
| 7776 | 1 | UPPER RADIATOR HOSE  | 16571 0H160   | 0% | 35.00*    |
| 7787 | 1 | EXPANSION TANK       | 16470 0H090   | 0% | 105.00*   |
| 7789 | 1 | L/FAN MOTOR          | 16363 02120   | 0% | 180.00*   |
| 7790 | 1 | R/FAN MOTOR          | 16363 0H170   | 0% | 180.00*   |
| 7793 | 1 | L/BLOWER FAN         | 16361 0H190   | 0% | 80.00*    |
| 7794 | 1 | R/BLOWER FAN         | 16361 0H200   | 0% | 80.00*    |



# K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHC0208

Version: K.KIMHIN/2

Date Calculated: 18/03/2018 03:45

Full Report - V1

Registration: SCR8873P

Printed: 18/03/2018 11:51

|      |   |                      |             |    |           |
|------|---|----------------------|-------------|----|-----------|
| 8041 | 1 | OIL FILTER           | 90915 YZZJ2 | 0% | 18.00*    |
| 8067 | 1 | SUMP                 | 12101 0H080 | 0% | 115.00*   |
| 8375 | 1 | AIR INTAKE HOSE      | 17750 0H090 | 0% | 70.00*    |
| 8391 | 1 | AIR FILTER ASSY      | 17700 0H131 | 0% | 280.00*   |
| 8626 | 1 | FRONT ENGINE STRUT   | 12309 0H090 | 0% | 145.00*   |
| 8677 | 1 | RR CTR ENGINE MNTG   | 12372 0H110 | 0% | 135.00*   |
| 8678 | 1 | UPPER ENGINE BRACKET | 12362 0V020 | 0% | 145.00*   |
| 8679 | 1 | FRT CTR SILENTBLOCK  | 12361 0H110 | 0% | 145.00*   |
| 8781 | 1 | L/ENGINE COVER       | 51442 06120 | 0% | 75.00*    |
| 8782 | 1 | R/ENGINE COVER       | 51441 06130 | 0% | 75.00*    |
| 8797 | 1 | FRONT HEAT SHIELD    | 25586 28090 | 0% | 130.00*   |
| 8801 | 1 | EXHAUST MANIFOLD     | 25051 28330 | 0% | 2,650.00* |
| 8805 | 1 | EXHAUST INSULATION   | 17167 28060 | 0% | 265.00*   |
| 8811 | 1 | FRONT LAMBDA PROBE   | 89467 33080 | 0% | 165.00*   |
| 8815 | 1 | FRONT EXHAUST PIPE   | 17410 0H240 | 0% | 195.00*   |
| 8823 | 1 | EXHAUST PIPE         | 17420 0H210 | 0% | 220.00*   |
| 9113 | 1 | L/R STRG KNUCKLE     | 42305 06180 | 0% | 220.00*   |
| 9114 | 1 | R/R STRG KNUCKLE     | 42304 06200 | 0% | 220.00*   |
| 9181 | 1 | L/R WHEEL HUB CPL    | 42460 06040 | 0% | 300.00*   |
| 9182 | 1 | R/R WHEEL HUB CPL    | 42450 06060 | 0% | 300.00*   |
| 9201 | 1 | L/R SPRING LEG       | 48540 09750 | 0% | 185.00*   |
| 9202 | 1 | R/R SPRING LEG       | 48530 09L90 | 0% | 185.00*   |
| 9213 | 1 | L/BUMPER BOOT        | 48760 06160 | 0% | 130.00*   |
| 9214 | 1 | R/BUMPER BOOT        | 48750 06160 | 0% | 130.00*   |
| 9247 | 1 | L/R DAMPER           | 48341 32053 | 0% | 25.00*    |
| 9248 | 1 | R/R DAMPER           | 48341 32053 | 0% | 25.00*    |
| 9325 | 1 | L/R TOWING STRUT     | 48780 06060 | 0% | 145.00*   |
| 9326 | 1 | REAR TOWING STRUT    | 48780 06060 | 0% | 145.00*   |
| 9385 | 1 | L/R TRAILING ARM FRT | 48710 06050 | 0% | 155.00*   |
| 9386 | 1 | R/R TRAILING ARM FRT | 48710 06050 | 0% | 155.00*   |
| 9391 | 1 | L/R TRAILING ARM RR  | 48740 06070 | 0% | 125.00*   |
| 9392 | 1 | R/R TRAILING ARM RR  | 48730 06070 | 0% | 125.00*   |
| 9631 | 1 | BATTERY HOLDER       | 74431 06050 | 0% | 45.00*    |
| 9645 | 1 | L/HORN               | 86510 06101 | 0% | 60.00*    |
| 9646 | 1 | R/HORN               | 86520 06091 | 0% | 60.00*    |
| 9660 | 1 | FUSE BOX             | 82740 33020 | 0% | 220.00*   |
| 9662 | 1 | LOWER FUSE BOX COVER | 82663 33070 | 0% | 120.00*   |
| 1000 | 1 | FRT TOW CVR          | Renew       | 0% | 12.00*    |
| 1000 | 1 | FRT PARKING SEN WIRE | Renew       | 0% | 1,350.00* |
| 1000 | 1 | BONNET CHROME        | Renew       | 0% | 75.00*    |
| 1000 | 1 | BONNET STOPPER LH    | Renew       | 0% | 12.00*    |
| 1000 | 1 | BONNET STOPPER RH    | Renew       | 0% | 12.00*    |
| 1000 | 1 | FRT SUP TOP STOP LH  | Renew       | 0% | 15.00*    |
| 1000 | 1 | FRT SUP TOP STOP RH  | Renew       | 0% | 15.00*    |
| 1000 | 1 | FRT SUPP TOP GARNISH | Renew       | 0% | 110.00*   |
| 1000 | 1 | OUTSIDE TEMP SENSOR  | Renew       | 0% | 85.00*    |
| 1000 | 1 | WING SHIELD BRKT LH  | Renew       | 0% | 6.50*     |
| 1000 | 1 | WING SHIELD BRKT RH  | Renew       | 0% | 6.50*     |
| 1000 | 1 | FRT WING INN BRKT LH | Renew       | 0% | 50.00*    |
| 1000 | 1 | FRT WING INN BRKT RH | Renew       | 0% | 50.00*    |
| 1000 | 1 | BATTERY TOP BRKT     | Renew       | 0% | 30.00*    |
| 1000 | 1 | WIPER SIDE GAR LH    | Renew       | 0% | 30.00*    |



# K.KIM HIN AUTO PTE LTD

Claim Reference:  
Assessment Number: KKHC0208  
Version: K.KIMHIN/2  
Date Calculated: 18/03/2018 03:45

Full Report - V1  
Registration: SCR8873P  
Printed: 18/03/2018 11:51

|      |   |                      |       |    |         |
|------|---|----------------------|-------|----|---------|
| 1000 | 1 | WIPER SIDE GAR RH    | Renew | 0% | 30.00*  |
| 1000 | 1 | RR FLOOR UNDERCOVER  | Renew | 0% | 90.00*  |
| 1000 | 1 | SKIRT CHROME MLD LH  | Renew | 0% | 95.00*  |
| 1000 | 1 | SKIRT CHROME MLD RH  | Renew | 0% | 95.00*  |
| 1000 | 1 | FLOOR PNL LWR GAR LH | Renew | 0% | 235.00* |
| 1000 | 1 | FLOOR PNL LWR GAR RH | Renew | 0% | 235.00* |
| 1000 | 1 | ENG UNDERCOVER LH    | Renew | 0% | 95.00*  |
| 1000 | 1 | ENG UNDERCOVER RH    | Renew | 0% | 95.00*  |
| 1000 | 1 | 'O' RING-BIG         | Renew | 0% | 15.00*  |
| 1000 | 1 | 'O' RING -SMALL      | Renew | 0% | 12.00*  |

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

|                         |  |                    |
|-------------------------|--|--------------------|
| Sub Total               |  | \$31,662.90        |
| Mark Up From Cost (5 %) |  | \$1,583.15         |
| Sundry Parts (Fixed)    |  | \$100.00           |
| <b>Total Parts</b>      |  | <b>\$33,346.05</b> |

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

| Description                      | Betterment | Price             |
|----------------------------------|------------|-------------------|
| FRT NUMBER PLATE SPECIALIST      | 0%         | \$40.00           |
| AUDATEX FEES SPECIALIST          |            | \$42.00           |
| AIR CON GAS SPECIALIST           | 0%         | \$50.00           |
| ANTI FREEZE SPECIALIST           |            | \$20.00           |
| BRAKE OIL @2LX\$10 SPECIALIST    | 0%         | \$20.00           |
| ENGINE OIL @4.5LX\$20 SPECIALIST |            | \$90.00           |
| WHEEL ALIGNMENT SPECIALIST       | 0%         | \$80.00           |
| FRT TYRE LH SPECIALIST           |            | \$220.00          |
| FRT TYRE RH SPECIALIST           | 0%         | \$220.00          |
| REAR TYRE RH SPECIALIST          |            | \$220.00          |
| FRT RIM LH SPECIALIST            | 0%         | \$520.00          |
| FRT RIM RH SPECIALIST            |            | \$520.00          |
| REAR RIM RH SPECIALIST           | 0%         | \$520.00          |
| FRT WS SEALANT SPECIALIST        |            | \$40.00           |
| FRT WS DAMP SEAL SPECIALIST      | 0%         | \$20.00           |
| ERP BRACKET SPECIALIST           |            | \$26.00           |
| PRIVATE HIRE SPECIALIST          | 0%         | \$25.00           |
| STICKER                          |            |                   |
| BATTERY SPECIALIST               |            | \$180.00          |
| OIL SUMP SEALANT SPECIALIST      | 0%         | \$40.00           |
| <b>Total Extras</b>              |            | <b>\$2,893.00</b> |

## Final Calculation

|                                  |            |                    |
|----------------------------------|------------|--------------------|
| <b>Total Parts</b>               |            | <b>\$33,346.05</b> |
| <b>Labour</b>                    |            |                    |
| Total Panel/Mechanical           | \$2,695.60 |                    |
| Total Paintwork                  | \$1,265.00 |                    |
| Total Visual Alignment work      | \$59.80    |                    |
| <b>Total Labour</b>              |            | <b>\$4,020.40</b>  |
| <b>Additional Costs</b>          |            |                    |
| Corr Prot Materials External     | \$0.00     |                    |
| Corr Prot Materials Internal     | \$0.00     |                    |
| Cost of Specialist               | \$2,893.00 |                    |
| <b>Total of Additional Costs</b> |            | <b>\$2,893.00</b>  |

**K.KIM HIN AUTO PTE LTD**

**Claim Reference:**  
**Assessment Number: KKHC0208**  
**Version: K.KIMHIN/2**  
**Date Calculated: 18/03/2018 03:45**

**Full Report - V1**  
**Registration: SCR8873P**  
**Printed: 18/03/2018 11:51**

|                                                   |                    |
|---------------------------------------------------|--------------------|
| <b>Total Paint/Material Costs</b>                 | <b>\$593.77</b>    |
| <b>Repair Costs Excludes GST</b>                  | <b>\$40,853.22</b> |
| <b>Deductions</b>                                 |                    |
| Deduction (20.00 %) Before GST                    | -\$8,170.64        |
| Deduction for Excess                              | TBA                |
| <b>Total Deductions</b>                           | <b>-\$8,170.64</b> |
| <b>Grand Total Excludes GST (After Deduction)</b> | <b>\$32,682.58</b> |
| GST @ 7 %                                         | \$2,287.78         |
| <b>Grand Total Includes GST (After Deduction)</b> | <b>\$34,970.36</b> |

**Assessment Notes**



CO. REG. NO: 199402370D

GST NO: M2-0123250-3



AUTO PTE LTD

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

### PARTICULARS OF CLAIM

|                               |                                                      |                       |                   |
|-------------------------------|------------------------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                                      | Ref. No:              |                   |
| Policy No:                    | DMHCSN1748561700                                     | Date of Loss:         | 28/12/2017        |
| Vehicle Reg. No.:             | SCR8873P                                             | Driveable?            |                   |
| Driver Age/Info:              | 30 / MALE                                            | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                                   | Third Party Involved? | YES               |
| Insured/Claimant:             | EMING VEHICLES                                       | Contact No:           | +6591830887       |
| Driver:                       | CHONG EE MING CHRISTOPHER                            |                       |                   |
| Make/Model:                   | TOYOTA CAMRY, 2.5 (A)                                | Vehicle Reg. Date:    | 06/05/2014        |
| Vehicle Colour:               | SILVER                                               |                       |                   |
| Engine No:                    | 2ARU131457                                           | Chassis No:           | MR053AK5004007612 |
| Odometer:                     | 0 KM                                                 |                       |                   |
| Paint Type:                   |                                                      |                       |                   |
| Total Loss?                   | NO                                                   |                       |                   |
| Est. Duration of Repair (day) | 21                                                   |                       |                   |
| Description of Accident/Loss  | PLEASE REFER TO SKETCH PLAN.                         |                       |                   |
| Remarks:                      | VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY. THANK YOU. |                       |                   |
| Present Location:             | K KIM HIN AUTO PTE LTD (HQ)                          |                       |                   |

| COST OF CLAIMS            | Amount           |
|---------------------------|------------------|
| Parts                     | 50,357.29        |
| Miscellaneous Items       | 0.00             |
| Labour                    | 4,610.40         |
| Paintwork Labour          | 0.00             |
| Towing                    | 0.00             |
| <b>Gross Total (\$\$)</b> | <b>54,967.69</b> |
| <b>+ GST 7.00% (\$\$)</b> | <b>3,847.74</b>  |
| <b>Nett Amount (\$\$)</b> | <b>58,815.43</b> |

This claim is handled by: WONG SHU MAN

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jan 2018)

Parts: 143 TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: K Kim Hin Auto Pte Ltd/SCR8873P/08/01/2018 11:48

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars           | %Disc | %Depr | Amount                                   |
|-----|-----|----------|-----------------------|-------|-------|------------------------------------------|
| 1   | 1   | NA       | *ABS BRAKE UNIT       | 0.00  | 0.00  | *4,100.00 F <sub>UNT</sub> ✓             |
| 2   | 1   | NA       | *AIR FILTER ASSY      | 0.00  | 0.00  | *280.00 F <sub>DIS</sub> ✓               |
| 3   | 1   | NA       | *AIR GUIDE TRIM       | 0.00  | 0.00  | *145.00 F <sub>UNT</sub> ✓               |
| 4   | 1   | NA       | *AIR INTAKE HOSE      | 0.00  | 0.00  | *70.00 F <sub>DIS</sub> ✓                |
| 5   | 1   | NA       | *BADGE "VVT-I" L      | 0.00  | 0.00  | *18.00 F <sub>REC</sub> ✓                |
| 6   | 1   | NA       | *BADGE "VVT-I" R      | 0.00  | 0.00  | *18.00 F <sub>REC</sub> ✓                |
| 7   | 1   | NA       | *BATTERY              | 0.00  | 0.00  | *F <sub>X</sub> ✓                        |
| 8   | 1   | NA       | *BATTERY HOLDER       | 0.00  | 0.00  | *45.00 F <sub>BT</sub> ✓                 |
| 9   | 1   | NA       | *BATTERY TOP BRKT     | 0.00  | 0.00  | *30.00 F <sub>BT</sub> ✓                 |
| 10  | 1   | NA       | *BONNET               | 0.00  | 0.00  | *360.00 F <sub>BT</sub> ✓                |
| 11  | 1   | NA       | *BONNET CHROME        | 0.00  | 0.00  | *75.00 F <sub>DD</sub> ✓                 |
| 12  | 1   | NA       | *BONNET FRONT SEAL    | 0.00  | 0.00  | *45.00 F <sub>REC</sub> ✓                |
| 13  | 1   | NA       | *BONNET INSULATION    | 0.00  | 0.00  | *95.00 F <sub>DIS</sub> ✓                |
| 14  | 1   | NA       | *BONNET STOPPER LH    | 0.00  | 0.00  | *12.00 F <sub>REC</sub> ✓                |
| 15  | 1   | NA       | *BONNET STOPPER RH    | 0.00  | 0.00  | *12.00 F <sub>REC</sub> ✓                |
| 16  | 1   | NA       | *BUMPER SUPPORT       | 0.00  | 0.00  | *150.00 F <sub>BT</sub> ✓                |
| 17  | 1   | NA       | *CLIP FASTENING       | 0.00  | 0.00  | *4.66 F <sub>REC</sub> ✓                 |
| 18  | 1   | NA       | *CLIP FASTENING       | 0.00  | 0.00  | *3.96 F <sub>REC</sub> ✓                 |
| 19  | 1   | NA       | *COMPR/CONDENSER TUBE | 0.00  | 0.00  | *165.00 F <sub>BT</sub> ✓                |
| 20  | 1   | NA       | *COMPR/EVAP TUBE      | 0.00  | 0.00  | *185.00 F <sub>BT</sub> ✓                |
| 21  | 1   | NA       | *COMPRESSOR           | 0.00  | 0.00  | *580.00 F <sub>BT</sub> ✓                |
| 22  | 1   | NA       | *COND/EVAPORATOR PIPE | 0.00  | 0.00  | *195.00 F <sub>BT</sub> ✓                |
| 23  | 1   | NA       | *CONDENSER            | 0.00  | 0.00  | *375.00 F <sub>BT</sub> ✓                |
| 24  | 1   | NA       | *CONTROL CABLE        | 0.00  | 0.00  | *60.00 F <sub>CLIP</sub> ✓               |
| 25  | 1   | NA       | *CRANKSHAFT PULLEY    | 0.00  | 0.00  | *215.00 F <sub>X<sub>SHC</sub></sub> ✓   |
| 26  | 1   | NA       | *CTR BUMPER GRILLE    | 0.00  | 0.00  | *80.00 F <sub>DIS</sub> ✓                |
| 27  | 1   | NA       | *DRIVE BELT TENSIONER | 0.00  | 0.00  | *155.00 F <sub>UNT</sub> ✓               |
| 28  | 1   | NA       | *ELECTRIC FUEL PUMP   | 0.00  | 0.00  | *195.00 F <sub>X<sub>SHC</sub></sub> ✓   |
| 29  | 1   | NA       | *ENG OIL FILTER HSING | 0.00  | 0.00  | *95.00 F <sub>X<sub>SHC</sub></sub> ✓    |
| 30  | 1   | NA       | *ENG UNDERCOVER LH    | 0.00  | 0.00  | *95.00 F <sub>DIS</sub> ✓                |
| 31  | 1   | NA       | *ENG UNDERCOVER RH    | 0.00  | 0.00  | *95.00 F <sub>DIS</sub> ✓                |
| 32  | 1   | NA       | *ENGINE CONTROL UNIT  | 0.00  | 0.00  | *7,100.00 F <sub>X<sub>SHC</sub></sub> ✓ |
| 33  | 1   | NA       | *EXHAUST INSULATION   | 0.00  | 0.00  | *265.00 F <sub>BT</sub> ✓                |
| 34  | 1   | NA       | *EXHAUST MANIFOLD     | 0.00  | 0.00  | *2,650.00 F <sub>DD</sub> ✓              |
| 35  | 1   | NA       | *EXHAUST PIPE         | 0.00  | 0.00  | *220.00 F <sub>DD</sub> ✓                |
| 36  | 1   | NA       | *EXPANSION TANK       | 0.00  | 0.00  | *105.00 F <sub>DIS</sub> ✓               |
| 37  | 1   | NA       | *FLOOR PNL LWR GAR LH | 0.00  | 0.00  | *235.00 F <sub>DIS</sub> ✓               |
| 38  | 1   | NA       | *FLOOR PNL LWR GAR RH | 0.00  | 0.00  | *235.00 F <sub>DIS</sub> ✓               |
| 39  | 1   | NA       | *FRONT BUMPER         | 0.00  | 0.00  | *220.00 F <sub>BT</sub> ✓                |
| 40  | 1   | NA       | *FRONT ENGINE STRUT   | 0.00  | 0.00  | *145.00 F <sub>BT</sub> ✓                |
| 41  | 1   | NA       | *FRONT ENGINE SUPPORT | 0.00  | 0.00  | *135.00 F <sub>X<sub>SHC</sub></sub> ✓   |
| 42  | 1   | NA       | *FRONT EXHAUST PIPE   | 0.00  | 0.00  | *195.00 F <sub>DD</sub> ✓                |
| 43  | 1   | NA       | *FRONT HEAT SHIELD    | 0.00  | 0.00  | *130.00 F <sub>BT</sub> ✓                |
| 44  | 1   | NA       | *FRONT LAMBDA PROBE   | 0.00  | 0.00  | *165.00 F <sub>DD</sub> ✓                |
| 45  | 1   | NA       | *FRONT NUMBER PLATE   | 0.00  | 0.00  | *18.00 F <sub>DIS</sub> ✓                |

K Kim Hin Auto Pte Ltd/SCR8873P/08/01/2018 11:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS



| No. | Qty | Part No. | Particulars           | %Disc | %Depr | Amount          |
|-----|-----|----------|-----------------------|-------|-------|-----------------|
| 46  | 1   | NA       | *FRONT PANEL          | 0.00  | 0.00  | *220.00 FBT     |
| 47  | 1   | NA       | *FRONT STABILISER     | 0.00  | 0.00  | *195.00 F XAN   |
| 48  | 1   | NA       | *FRT AXLE CARRIER     | 0.00  | 0.00  | *980.00 FBT     |
| 49  | 1   | NA       | *FRT BUMPER ABSORBER  | 0.00  | 0.00  | *65.00 F MIS    |
| 50  | 1   | NA       | *FRT CTR SILENTBLOCK  | 0.00  | 0.00  | *145.00 F Tn    |
| 51  | 1   | NA       | *FRT NO PLATE BRKT    | 0.00  | 0.00  | *50.00 F MIS    |
| 52  | 1   | NA       | *FRT PARKING SEN WIRE | 0.00  | 0.00  | *1,350.00 F DIS |
| 53  | 1   | NA       | *FRT PIPE COMPR/COND  | 0.00  | 0.00  | *115.00 F BT    |
| 54  | 1   | NA       | *FRT SUP TOP STOP LH  | 0.00  | 0.00  | *15.00 F MIS    |
| 55  | 1   | NA       | *FRT SUP TOP STOP RH  | 0.00  | 0.00  | *15.00 F MIS    |
| 56  | 1   | NA       | *FRT SUPP TOP GARNISH | 0.00  | 0.00  | *110.00 F DIS   |
| 57  | 1   | NA       | *FRT TOW CVR          | 0.00  | 0.00  | *12.00 F MIS    |
| 58  | 1   | NA       | *FRT WING INN BRKT LH | 0.00  | 0.00  | *50.00 F DIS    |
| 59  | 1   | NA       | *FRT WING INN BRKT RH | 0.00  | 0.00  | *50.00 F DIS    |
| 60  | 1   | NA       | *FUEL TANK            | 0.00  | 0.00  | *800.00 F XAN   |
| 61  | 1   | NA       | *FUSE BOX             | 0.00  | 0.00  | *220.00 F DIS   |
| 62  | 1   | NA       | *GRILLE               | 0.00  | 0.00  | *170.00 F MIS   |
| 63  | 1   | NA       | *INSTRUMENT PNL TRIM  | 0.00  | 0.00  | *600.00 F CRA   |
| 64  | 1   | NA       | *L/BLOWER FAN         | 0.00  | 0.00  | *80.00 F DIS    |
| 65  | 1   | NA       | *L/BONNET DAMPER      | 0.00  | 0.00  | *120.00 F BT    |
| 66  | 1   | NA       | *L/BONNET HINGE       | 0.00  | 0.00  | *40.00 F BT     |
| 67  | 1   | NA       | *L/BUMPER BOOT        | 0.00  | 0.00  | *130.00 F XAN   |
| 68  | 1   | NA       | *L/CARRIER JOINT      | 0.00  | 0.00  | *75.00 FBT      |
| 69  | 1   | NA       | *L/DRIVE SHAFT CPL    | 0.00  | 0.00  | *480.00 F XAN   |
| 70  | 1   | NA       | *L/ENGINE COVER       | 0.00  | 0.00  | *75.00 F DIS    |
| 71  | 1   | NA       | *L/F AXLE CARRIER     | 0.00  | 0.00  | *75.00 F XAN    |
| 72  | 1   | NA       | *L/F BUMPER REINF     | 0.00  | 0.00  | *65.00 F BT     |
| 73  | 1   | NA       | *L/F CONTROL ARM BUSH | 0.00  | 0.00  | *80.00 F Tn     |
| 74  | 1   | NA       | *L/F DAMPER BUFFER    | 0.00  | 0.00  | *25.00 F Tn     |
| 75  | 1   | NA       | *L/F FOG LAMP CPL     | 0.00  | 0.00  | *110.00 F MIS   |
| 76  | 1   | NA       | *L/F OUTER SENSOR     | 0.00  | 0.00  | *165.00 F MIS   |
| 77  | 1   | NA       | *L/F STABI ROD        | 0.00  | 0.00  | *75.00 F XAN    |
| 78  | 1   | NA       | *L/F STABILISER BUSH  | 0.00  | 0.00  | *30.00 F XAN    |
| 79  | 1   | NA       | *L/F STEERING KNUCKLE | 0.00  | 0.00  | *185.00 F BT    |
| 80  | 1   | NA       | *L/F STRUT            | 0.00  | 0.00  | *215.00 F BT    |
| 81  | 1   | NA       | *L/F SUSPN BUFFER     | 0.00  | 0.00  | *80.00 F BT     |
| 82  | 1   | NA       | *L/F UPP BUMPER BRKT  | 0.00  | 0.00  | *45.00 F DIS    |
| 83  | 1   | NA       | *L/F WHEEL BEARING    | 0.00  | 0.00  | *75.00 F DO     |
| 84  | 1   | NA       | *L/F WHEEL HUB        | 0.00  | 0.00  | *175.00 F DO    |
| 85  | 1   | NA       | *L/F WHEELHOUSE CPL   | 0.00  | 0.00  | *195.00 F KR    |
| 86  | 1   | NA       | *L/F WING             | 0.00  | 0.00  | *185.00 F BT    |
| 87  | 1   | NA       | *L/F WIPER ARM        | 0.00  | 0.00  | *95.00 FBT      |
| 88  | 1   | NA       | *L/F WIPER BLADE      | 0.00  | 0.00  | *60.00 F OUT    |
| 89  | 1   | NA       | *L/FAN MOTOR          | 0.00  | 0.00  | *180.00 FBT     |
| 90  | 1   | NA       | *L/FOG LAMP COVER     | 0.00  | 0.00  | *80.00 F MIS    |
| 91  | 1   | NA       | *L/HORN               | 0.00  | 0.00  | *60.00 F BT     |
| 92  | 1   | NA       | *L/LWR AXLE STEERING  | 0.00  | 0.00  | *145.00 FBT     |
| 93  | 1   | NA       | *L/LWR RADIATOR BRKT  | 0.00  | 0.00  | *18.00 F BT     |
| 94  | 1   | NA       | *L/PARK AID SENS CVR  | 0.00  | 0.00  | *18.00 F MIS    |
| 95  | 1   | NA       | *L/R BUFFER           | 0.00  | 0.00  | *80.00 F BT     |
| 96  | 1   | NA       | *L/R CONTROL ARM BUSH | 0.00  | 0.00  | *80.00 F Tn     |
| 97  | 1   | NA       | *L/R DAMPER           | 0.00  | 0.00  | *25.00 F XAN    |
| 98  | 1   | NA       | *L/R EXHAUST RUBBER   | 0.00  | 0.00  | *35.00 F XAN    |
| 99  | 1   | NA       | *L/R FRONT AXLE BRKT  | 0.00  | 0.00  | *75.00 F XAN    |
| 100 | 1   | NA       | *L/R SPRING LEG       | 0.00  | 0.00  | *185.00 F XAN   |
| 101 | 1   | NA       | *L/R STABI ROD        | 0.00  | 0.00  | *80.00 F Tn     |
| 102 | 1   | NA       | *L/R STRG KNUCKLE     | 0.00  | 0.00  | *220.00 F DO    |
| 103 | 1   | NA       | *L/R TOWING STRUT     | 0.00  | 0.00  | *145.00 F MIS   |
| 104 | 1   | NA       | *L/R TRAILING ARM FRT | 0.00  | 0.00  | *155.00 F BT    |

| No. | Qty | Part No. | Particulars           | %Disc | %Depr | Amount                 |
|-----|-----|----------|-----------------------|-------|-------|------------------------|
| 105 | 1   | NA       | *L/R TRAILING ARM RR  | 0.00  | 0.00  | *125.00 F <i>can</i>   |
| 106 | 1   | NA       | *L/R TYRE             | 0.00  | 0.00  | *143.00 F <i>can</i>   |
| 107 | 1   | NA       | *L/R WHEEL            | 0.00  | 0.00  | *110.38 F <i>can</i>   |
| 108 | 1   | NA       | *L/R WHEEL HUB CPL    | 0.00  | 0.00  | *300.00 F <i>can</i>   |
| 109 | 1   | NA       | *L/RADIATOR AIR GUIDE | 0.00  | 0.00  | *55.00 F <i>can</i>    |
| 110 | 1   | NA       | *L/SEAT W/OUT SPRING  | 0.00  | 0.00  | *35.00 F <i>BT</i>     |
| 111 | 1   | NA       | *L/SILL MOULDING      | 0.00  | 0.00  | *195.00 F <i>BR</i>    |
| 112 | 1   | NA       | *L/UPP RADIATOR BRKT  | 0.00  | 0.00  | *18.00 F <i>BT</i>     |
| 113 | 1   | NA       | *L/UPP SUPP MOUNTING  | 0.00  | 0.00  | *80.00 F <i>BT</i>     |
| 114 | 1   | NA       | *L/WHEELHOUSE SHELL   | 0.00  | 0.00  | *65.00 F <i>MIS</i>    |
| 115 | 1   | NA       | *L/WING COVER PANEL   | 0.00  | 0.00  | *45.00 F <i>XGUC</i>   |
| 116 | 1   | NA       | *L/WING MOULDING      | 0.00  | 0.00  | *45.00 F <i>MIS</i>    |
| 117 | 1   | NA       | *LEFT HEADLAMP ASSY   | 0.00  | 0.00  | *1,300.00 F <i>CAN</i> |
| 118 | 1   | NA       | *LOCK CARRIER STRUT   | 0.00  | 0.00  | *45.00 F <i>BT</i>     |
| 119 | 1   | NA       | *LOWER BONNET LOCK    | 0.00  | 0.00  | *55.00 F <i>BT</i>     |
| 120 | 1   | NA       | *LOWER ENGINE SUPPORT | 0.00  | 0.00  | *135.00 F <i>can</i>   |
| 121 | 1   | NA       | *LOWER FUSE BOX COVER | 0.00  | 0.00  | *120.00 F <i>DIS</i>   |
| 122 | 1   | NA       | *LWR RADIATOR HOSE    | 0.00  | 0.00  | *40.00 F <i>DIS</i>    |
| 123 | 1   | NA       | **O' RING -SMALL      | 0.00  | 0.00  | *12.00 F <i>new</i>    |
| 124 | 1   | NA       | **O' RING-BIG         | 0.00  | 0.00  | *15.00 F <i>new</i>    |
| 125 | 1   | NA       | *OIL FILTER           | 0.00  | 0.00  | *18.00 F <i>can</i>    |
| 126 | 1   | NA       | *OIL STRAINER         | 0.00  | 0.00  | *75.00 F <i>XGUC</i>   |
| 127 | 1   | NA       | *OUTSIDE TEMP SENSOR  | 0.00  | 0.00  | *85.00 F <i>MIS</i>    |
| 128 | 1   | NA       | *POWER STEERING CPL   | 0.00  | 0.00  | *590.00 F <i>can</i>   |
| 129 | 1   | NA       | *R/BLOWER FAN         | 0.00  | 0.00  | *80.00 F <i>DIS</i>    |
| 130 | 1   | NA       | *R/BONNET DAMPER      | 0.00  | 0.00  | *120.00 F <i>BT</i>    |
| 131 | 1   | NA       | *R/BONNET HINGE       | 0.00  | 0.00  | *40.00 F <i>BT</i>     |
| 132 | 1   | NA       | *R/BUMPER BOOT        | 0.00  | 0.00  | *130.00 F <i>can</i>   |
| 133 | 1   | NA       | *R/CARRIER JOINT      | 0.00  | 0.00  | *75.00 F <i>BT</i>     |
| 134 | 1   | NA       | *R/DOOR MIRROR        | 0.00  | 0.00  | *420.00 F <i>LRA</i>   |
| 135 | 1   | NA       | *R/DRIVE SHAFT CPL    | 0.00  | 0.00  | *540.00 F <i>can</i>   |
| 136 | 1   | NA       | *R/ENGINE COVER       | 0.00  | 0.00  | *75.00 F <i>DIS</i>    |
| 137 | 1   | NA       | *R/F AXLE CARRIER     | 0.00  | 0.00  | *75.00 F <i>can</i>    |
| 138 | 1   | NA       | *R/F CONTROL ARM BUSH | 0.00  | 0.00  | *80.00 F <i>TO</i>     |
| 139 | 1   | NA       | *R/F DAMPER BUFFER    | 0.00  | 0.00  | *25.00 F <i>TO</i>     |
| 140 | 1   | NA       | *R/F FOG LAMP CPL     | 0.00  | 0.00  | *110.00 F <i>MIS</i>   |
| 141 | 1   | NA       | *R/F OUTER SENSOR     | 0.00  | 0.00  | *165.00 F <i>MIS</i>   |
| 142 | 1   | NA       | *R/F STABI ROD        | 0.00  | 0.00  | *75.00 F <i>can</i>    |
| 143 | 1   | NA       | *R/F STABILISER BUSH  | 0.00  | 0.00  | *30.00 F <i>can</i>    |
| 144 | 1   | NA       | *R/F STEERING KNUCKLE | 0.00  | 0.00  | *185.00 F <i>BT</i>    |
| 145 | 1   | NA       | *R/F STRUT            | 0.00  | 0.00  | *215.00 F <i>BT</i>    |
| 146 | 1   | NA       | *R/F SUSPN BUFFER     | 0.00  | 0.00  | *80.00 F <i>BT</i>     |
| 147 | 1   | NA       | *R/F UPP BUMPER BRKT  | 0.00  | 0.00  | *45.00 F <i>DIS</i>    |
| 148 | 1   | NA       | *R/F WHEEL BEARING    | 0.00  | 0.00  | *75.00 F <i>DIS</i>    |
| 149 | 1   | NA       | *R/F WHEEL HUB        | 0.00  | 0.00  | *175.00 F <i>DIS</i>   |
| 150 | 1   | NA       | *R/F WHEELHOUSE CPL   | 0.00  | 0.00  | *195.00 F <i>BT</i>    |
| 151 | 1   | NA       | *R/F WING             | 0.00  | 0.00  | *185.00 F <i>BT</i>    |
| 152 | 1   | NA       | *R/F WIPER ARM        | 0.00  | 0.00  | *95.00 F <i>CAN</i>    |
| 153 | 1   | NA       | *R/F WIPER BLADE      | 0.00  | 0.00  | *60.00 F <i>MIS</i>    |
| 154 | 1   | NA       | *R/FAN MOTOR          | 0.00  | 0.00  | *180.00 F <i>BT</i>    |
| 155 | 1   | NA       | *R/FOG LAMP COVER     | 0.00  | 0.00  | *80.00 F <i>MIS</i>    |
| 156 | 1   | NA       | *R/HORN               | 0.00  | 0.00  | *60.00 F <i>BT</i>     |
| 157 | 1   | NA       | *R/INN SIDE MEMBER    | 0.00  | 0.00  | *590.00 F <i>BT</i>    |
| 158 | 1   | NA       | *R/LWR AXLE STEERING  | 0.00  | 0.00  | *145.00 F <i>BT</i>    |
| 159 | 1   | NA       | *R/LWR RADIATOR BRKT  | 0.00  | 0.00  | *18.00 F <i>BT</i>     |
| 160 | 1   | NA       | *R/PARK AID SENS CVR  | 0.00  | 0.00  | *18.00 F <i>MIS</i>    |
| 161 | 1   | NA       | *R/R BUFFER           | 0.00  | 0.00  | *80.00 F <i>BT</i>     |
| 162 | 1   | NA       | *R/R CONTROL ARM BUSH | 0.00  | 0.00  | *80.00 F <i>TO</i>     |
| 163 | 1   | NA       | *R/R DAMPER           | 0.00  | 0.00  | *25.00 F <i>XGUC</i>   |

K Kim Hin Auto Pte Ltd/SCR8873P/08/01/2018 11:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS



| No. | Qty | Part No. | Particulars                       | %Disc | %Depr | Amount          |
|-----|-----|----------|-----------------------------------|-------|-------|-----------------|
| 164 | 1   | NA       | *R/R EXHAUST RUBBER               | 0.00  | 0.00  | *35.00 F XAN    |
| 165 | 1   | NA       | *R/R FRONT AXLE BRKT              | 0.00  | 0.00  | *75.00 F XAN    |
| 166 | 1   | NA       | *R/R SPRING LEG                   | 0.00  | 0.00  | *185.00 F XAN   |
| 167 | 1   | NA       | *R/R STABI ROD                    | 0.00  | 0.00  | *80.00 F XAN    |
| 168 | 1   | NA       | *R/R STRG KNUCKLE                 | 0.00  | 0.00  | *220.00 F DD    |
| 169 | 1   | NA       | *R/R TRAILING ARM FRT             | 0.00  | 0.00  | *155.00 F BT    |
| 170 | 1   | NA       | *R/R TRAILING ARM RR              | 0.00  | 0.00  | *125.00 F XAN   |
| 171 | 1   | NA       | *R/R TYRE                         | 0.00  | 0.00  | *143.00 F XAN   |
| 172 | 1   | NA       | *R/R WHEEL                        | 0.00  | 0.00  | *110.38 F XAN   |
| 173 | 1   | NA       | *R/R WHEEL HUB CPL                | 0.00  | 0.00  | *300.00 F DD    |
| 174 | 1   | NA       | *R/RADIATOR AIR GUIDE             | 0.00  | 0.00  | *55.00 F DD     |
| 175 | 1   | NA       | *R/SEAT W/OUT SPRING              | 0.00  | 0.00  | *35.00 F BT     |
| 176 | 1   | NA       | *R/SILL MOULDING                  | 0.00  | 0.00  | *195.00 F BR    |
| 177 | 1   | NA       | *R/UPP RADIATOR BRKT              | 0.00  | 0.00  | *18.00 F BT     |
| 178 | 1   | NA       | *R/UPP SUPP MOUNTING              | 0.00  | 0.00  | *80.00 F BT     |
| 179 | 1   | NA       | *R/WHEELHOUSE SHELL               | 0.00  | 0.00  | *65.00 F XAN    |
| 180 | 1   | NA       | *R/WING COVER PANEL               | 0.00  | 0.00  | *45.00 F XAN    |
| 181 | 1   | NA       | *R/WING MOULDING                  | 0.00  | 0.00  | *45.00 F XAN    |
| 182 | 1   | NA       | *RADIATOR                         | 0.00  | 0.00  | *400.00 F BT    |
| 183 | 1   | NA       | *RADIATOR SHROUD                  | 0.00  | 0.00  | *125.00 F DIS   |
| 184 | 1   | NA       | *REAR BUMPER                      | 0.00  | 0.00  | de *260.00 F    |
| 185 | 1   | NA       | *REAR EXHAUST RUBBER              | 0.00  | 0.00  | *35.00 F XAN    |
| 186 | 1   | NA       | *REAR HEAT SHIELD                 | 0.00  | 0.00  | *80.00 F XAN    |
| 187 | 1   | NA       | *REAR SILENCER                    | 0.00  | 0.00  | *230.00 F DD    |
| 188 | 1   | NA       | *REAR TOWING STRUT                | 0.00  | 0.00  | *145.00 F XAN   |
| 189 | 1   | NA       | *RIGHT FRONT DOOR                 | 0.00  | 0.00  | *F XAN          |
| 190 | 1   | NA       | *RIGHT HEADLAMP ASSY              | 0.00  | 0.00  | *1,300.00 F CFA |
| 191 | 1   | NA       | *RR CTR ENGINE MNTG               | 0.00  | 0.00  | *135.00 F TH    |
| 192 | 1   | NA       | *RR FLOOR UNDERCOVER              | 0.00  | 0.00  | *90.00 F PS     |
| 193 | 1   | NA       | *SKIRT CHROME MLD LH              | 0.00  | 0.00  | *95.00 F CHT    |
| 194 | 1   | NA       | *SKIRT CHROME MLD RH              | 0.00  | 0.00  | *95.00 F CHT    |
| 195 | 1   | NA       | *SPECIALIST AIR CON GAS           | 0     | 0.00  | *50.00 FS REC   |
| 196 | 1   | NA       | *SPECIALIST ANTI FREEZE           | 0     | 0.00  | *20.00 FS REC   |
| 197 | 1   | NA       | *SPECIALIST AUDATEX FEES          | 0     | 0.00  | *42.00 FS       |
| 198 | 1   | NA       | *SPECIALIST BATTERY               | 0     | 0.00  | *180.00 FS XAN  |
| 199 | 1   | NA       | *SPECIALIST BRAKE OIL @2LX\$10    | 0     | 0.00  | *20.00 FS XAN   |
| 200 | 1   | NA       | *SPECIALIST ENGINE OIL @4.5LX\$20 | 0     | 0.00  | *90.00 FS REC   |
| 201 | 1   | NA       | *SPECIALIST ERP BRACKET           | 0     | 0.00  | *26.00 FS REC   |
| 202 | 1   | NA       | *SPECIALIST FRT NUMBER PLATE      | 0     | 0.00  | REC *40.00 F    |
| 203 | 1   | NA       | *SPECIALIST FRT RIM LH            | 0     | 0.00  | *520.00 FS XAN  |
| 204 | 1   | NA       | *SPECIALIST FRT RIM RH            | 0     | 0.00  | *520.00 FS CHT  |
| 205 | 1   | NA       | *SPECIALIST FRT TYRE LH           | 0     | 0.00  | *220.00 FS CHT  |
| 206 | 1   | NA       | *SPECIALIST FRT TYRE RH           | 0     | 0.00  | *220.00 FS CHT  |
| 207 | 1   | NA       | *SPECIALIST FRT WS DAMP SEAL      | 0     | 0.00  | *20.00 FS REC   |
| 208 | 1   | NA       | *SPECIALIST FRT WS SEALANT        | 0     | 0.00  | *40.00 FS REC   |
| 209 | 1   | NA       | *SPECIALIST FRT WS SOLAR FILM     | 0     | 0.00  | *220.00 FS XAN  |
| 210 | 1   | NA       | *SPECIALIST OIL SUMP SEALANT      | 0     | 0.00  | *40.00 FS REC   |
| 211 | 1   | NA       | *SPECIALIST PRIVATE HIRE STICKER  | 0     | 0.00  | *25.00 FS REC   |
| 212 | 1   | NA       | *SPECIALIST REAR RIM LH           | 0     | 0.00  | *520.00 FS XAN  |
| 213 | 1   | NA       | *SPECIALIST REAR RIM RH           | 0     | 0.00  | *520.00 FS XAN  |
| 214 | 1   | NA       | *SPECIALIST REAR TYRE LH          | 0     | 0.00  | *220.00 FS XAN  |
| 215 | 1   | NA       | *SPECIALIST REAR TYRE RH          | 0     | 0.00  | *220.00 FS CHT  |
| 216 | 1   | NA       | *SPECIALIST WHEEL ALIGNMENT       | 0     | 0.00  | REC *80.00 FS   |
| 217 | 1   | NA       | *SUMP                             | 0.00  | 0.00  | *115.00 F dr    |
| 218 | 1   | NA       | *SUNDRY PARTS                     | 0     | 0.00  | *100.00 FS REC  |
| 219 | 1   | NA       | *UPPER ENGINE BRACKET             | 0.00  | 0.00  | *145.00 F TH    |
| 220 | 1   | NA       | *UPPER FUSE BOX COVER             | 0.00  | 0.00  | *75.00 F XAN    |
| 221 | 1   | NA       | *UPPER RADIATOR HOSE              | 0.00  | 0.00  | *35.00 F BT     |
| 222 | 1   | NA       | *V-BELT                           | 0.00  | 0.00  | *120.00 F XAN   |

K Kim Hin Auto Pte Ltd/SCR8873P/08/01/2018 11:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

| No.                               | Qty | Part No. | Particulars          | %Disc | %Depr | Amount              |
|-----------------------------------|-----|----------|----------------------|-------|-------|---------------------|
| 223                               | 1   | NA       | *WASHER CONTAINER    | 0.00  | 0.00  | *95.00 F <i>MS</i>  |
| 224                               | 1   | NA       | *WATER PUMP PULLEY   | 0.00  | 0.00  | *125.00 F <i>MS</i> |
| 225                               | 1   | NA       | *WINDSCREEN          | 0.00  | 0.00  | *420.00 F <i>MS</i> |
| 226                               | 1   | NA       | *WINDSCREEN BOND KIT | 0.00  | 0.00  | *38.18 F <i>MS</i>  |
| 227                               | 1   | NA       | *WING SHIELD BRKT LH | 0.00  | 0.00  | *6.50 F <i>MS</i>   |
| 228                               | 1   | NA       | *WING SHIELD BRKT RH | 0.00  | 0.00  | *6.50 F <i>MS</i>   |
| 229                               | 1   | NA       | *WIPER LINKAGE CPL   | 0.00  | 0.00  | *215.00 F <i>MS</i> |
| 230                               | 1   | NA       | *WIPER SIDE GAR LH   | 0.00  | 0.00  | *30.00 F <i>MS</i>  |
| 231                               | 1   | NA       | *WIPER SIDE GAR RH   | 0.00  | 0.00  | *30.00 F <i>MS</i>  |
| Sub Total (S\$)                   |     |          |                      |       |       | 48,147.56           |
| + Margin on L,N Items 5.00% (S\$) |     |          |                      |       |       | 2,209.73            |
| Total Parts (S\$)                 |     |          |                      |       |       | 50,357.29           |

F=Franchise part, S=SpclNett.

K Kim Hin Auto Pte Ltd/SCR8873P/08/01/2018 11:48. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS



## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                      | Particulars                   | Lab.Type | Amount   |
|-------------------------|-------------------------------|----------|----------|
| <u>Labour Items</u>     |                               |          |          |
| 1                       | Total Paint Labour            | New      | 1,196.00 |
| 2                       | Total Paint Materials         | New      | 617.60   |
| 3                       | Total Panel/Mechanical Labour | New      | 2,796.80 |
| Gross Labour Cost (S\$) |                               |          | 4,610.40 |

K Kim Hin Auto Pte Ltd/SCR8873P/08/01/2018 11:48, Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore

408933

Claim Reference: SNM17D07299C01  
Assessment Number: KKHC0208  
Version: LKKAUTOC/2  
Date Calculated: 12/10/2018 03:07

Full Report - V1  
Registration: SCR8873P  
Printed: 12/10/2018 10:08

## Summary Information

### Claim

|                       |                                |                            |            |
|-----------------------|--------------------------------|----------------------------|------------|
| Location:             | Singapore (SG)                 | Currency:                  | SGD        |
| Printed by:           | LKK AUTO                       | Date of Incident:          | 28/11/2017 |
| Authorisation Status: | Interim                        | Able to Authorise Repairs: | TBA        |
| Work Provider:        | China Taiping Insurance (S) Pt | Repairs Authorised:        | TBA        |
| Claim Reference:      | SNM17D07299C01                 | Estimated Repair Time:     |            |
| Policy Number:        | DMHCSN1748561700               | Quote Due Date:            |            |
| Other Reference:      |                                | Actual Repair Days:        |            |
| Third Party:          |                                | Parts Ordered Date:        |            |
| Insured Amount:       |                                | Hire Car Start:            |            |
| Under Warranty:       |                                | Hire Car End:              |            |
| Warranty Expired:     |                                | Vehicle Collected:         |            |

### Vehicle Details

#### Vehicle

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | TOYOTA            |
| Model:              | Camry             |
| Sub Model:          | BASE MODEL        |
| Model Sheet Number: | YCA 01            |
| Registration:       | SCR8873P          |
| Registration Month: |                   |
| Registration Year:  |                   |
| VIN Number:         | MR053AK5004007612 |
| Odometer:           | Not Known         |
| Colour:             |                   |
| Engine Number:      | 2ARU131457        |
| Fuel Level:         | %                 |

#### Model Specs



|                      |                    |
|----------------------|--------------------|
| FROM 03/2009         | XENON HEADLAMPS    |
| FOG LAMPS            | HEADLAMP LEVELLING |
| FRONT PARKING SYSTEM | 2.4 LTR 123KW      |
| CHINA VERSION        | TWO COAT METALLIC  |
| PREPARE OFF VEHICLE  |                    |

## Vehicle Condition

### Vehicle Status

|                         |                               |            |
|-------------------------|-------------------------------|------------|
| Pre-Accident Condition: | Severity of Impact:           |            |
| Steering:               | Vehicle Status on Inspection: |            |
| Brakes Pedal Travel:    | Date of Inspection:           | 05/01/2018 |
| Place of Inspection:    |                               |            |
| Pre-Accident Damage:    |                               |            |
| Tyres Condition:        |                               |            |
| Tread Depth LHF:        | Tread Depth RHF:              |            |
| Tread Depth LHR:        | Tread Depth RHR:              |            |
| Damage Areas:           | Direction of Impact:          |            |





## Addresses

## Cost Summary

|                           |             |
|---------------------------|-------------|
| Total Labour              | \$3,542.00  |
| Total Paint/Material      | \$617.60    |
| Total Parts               | \$31,820.40 |
| Total of Additional Costs | \$1,673.00  |
| Repair Cost Exc GST:      | \$37,653.00 |
| Overall Discount (0.0%):  | - \$0.00    |
| Excess:                   | -\$1,000.00 |
| After Deduction -         |             |
| Grand Total Exc GST:      | \$36,653.00 |
| 7 % GST:                  | \$2,565.71  |
| Grand Total Inc GST:      | \$39,218.71 |

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR  
Price/Dent = \$46.00/HR

| Repair / Guide Number | Repair Details                                                                                | WU   | Cost Price (\$) |
|-----------------------|-----------------------------------------------------------------------------------------------|------|-----------------|
| 043233                | ALIGN VEHICLE CPL                                                                             | 12.0 | 55.20           |
| M030ZAX               | R + R L/F AXLE HALF (ADD/WORK)                                                                | 11.0 | 50.60           |
| B140                  | RENEW FRONT PANEL                                                                             | 22.0 | 101.20          |
| B150)                 | RENEW COMPLETE R/F WHEELHOUSE                                                                 | 32.0 | 147.20          |
| NO NUMBER             | RENEW LEFT FRONT SIDE MEMBER CLOSING                                                          | 15.0 | 69.00           |
| NO NUMBER             | ADD/WORK FOR PARKING AID SENSOR DRILLING                                                      | 3.0  | 13.80           |
| NO NUMBER             | R + R FRONT PARKING AID SENSOR/S                                                              | 1.0  | 4.60            |
| NO NUMBER             | R + R L/F CENTRE PARKING AID SENSOR                                                           | 1.0  | 4.60            |
| NO NUMBER             | R + R R/F CENTRE PARKING AID SENSOR                                                           | 1.0  | 4.60            |
| B110                  | RENEW L/FRT WING (FRT BUMPER AND L/HEADLAMP ASSY REMOVED)                                     | 5.0  | 23.00           |
| B110                  | RENEW R/FRT WING (FRT BUMPER AND R/HEADLAMP ASSY REMOVED)                                     | 5.0  | 23.00           |
| B100                  | R + R LEFT SILL RAIL                                                                          | 3.0  | 13.80           |
| B100                  | R + R RIGHT SILL RAIL                                                                         | 3.0  | 13.80           |
| B020                  | RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS | 15.0 | 69.00           |
| B040                  | RENEW BOTH HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS                              | 7.0  | 32.20           |
| B070                  | RENEW BONNET                                                                                  | 6.0  | 27.60           |
| 530121)               | R + R BONNET OPENER CABLE                                                                     | 2.0  | 9.20            |

|           |                                                                                        |      |        |
|-----------|----------------------------------------------------------------------------------------|------|--------|
| NO NUMBER | RENEW BATTERY TRAY                                                                     | 5.0  | 23.00  |
| G010      | R + R WINDSCREEN                                                                       | 33.0 | 151.80 |
|           | INCLUDES: A-PILLAR TRIM,<br>SUN VISOR, REAR VIEW MIRROR AND<br>REQUIRED ATTACHED PARTS |      |        |
| 743261    | R + R LEFT FRONT DOOR MOULDING                                                         | 2.0  | 9.20   |
| 743261    | R + R RIGHT FRONT DOOR MOULDING                                                        | 2.0  | 9.20   |
| 743011    | R + R L/LOWER A-PILLAR TRIM                                                            | 2.0  | 9.20   |
| 743011    | R + R R/LOWER A-PILLAR TRIM                                                            | 2.0  | 9.20   |
| 752051    | R + R R/DOOR MIRROR                                                                    | 3.0  | 13.80  |
| B420      | RENEW REAR BUMPER                                                                      | 6.0  | 27.60  |
|           | INCLUDES: BUMPER AND ALL<br>REQUIRED ATTACHED PARTS R + R                              |      |        |
| M230)     | R + R INSTRUMENT PANEL                                                                 | 7.0  | 32.20  |
| 50351)    | RENEW INSTRUMENT PANEL (REMOVED)                                                       | 3.0  | 13.80  |
| 743641    | R + R CENTRE CONSOLE INSERT                                                            | 3.0  | 13.80  |
| M010)     | RENEW CONDENSER (REMOVED)                                                              | 1.0  | 4.60   |
| NO NUMBER | R + R AIR CONDITIONING HOSE                                                            | 4.0  | 18.40  |
| NO NUMBER | R + R AIR CONDITIONING PIPE                                                            | 4.0  | 18.40  |
| NO NUMBER | R + R AIR CONDITIONING PIPE                                                            | 5.0  | 23.00  |
| NO NUMBER | R + R AIR CONDITIONING HOSE                                                            | 4.0  | 18.40  |
| NO NUMBER | R + R L/ENGINE COMPARTMENT FUSE BOX                                                    | 7.0  | 32.20  |
| M010      | R + R RADIATOR AND CONDENSER<br>(FRONT BUMPER REMOVED)                                 | 16.0 | 73.60  |
|           | INCLUDES: BLEED COOLING SYSTEM                                                         |      |        |
| M010)     | RENEW RADIATOR                                                                         | 3.0  | 13.80  |
| 160111)   | R + R LOWER RADIATOR HOSE                                                              | 2.0  | 9.20   |
| 160101)   | R + R UPPER RADIATOR HOSE                                                              | 2.0  | 9.20   |
| 170521)   | R + R EXHAUST MANIFOLD                                                                 | 2.0  | 9.20   |
| 151011    | R + R OIL STRAINER                                                                     | 5.0  | 23.00  |
| 112011)   | R + R OIL PAN                                                                          | 10.0 | 46.00  |
| NO NUMBER | DETACH + REFIT EXHAUST SYSTEM                                                          | 3.0  | 13.80  |
| 170251    | R + R EXHAUST SYSTEM ATTACHED PARTS                                                    | 3.0  | 13.80  |
| 170171)   | R + R FRONT EXHAUST PIPE                                                               | 3.0  | 13.80  |
| 170181)   | R + R CENTRE SILENCER                                                                  | 2.0  | 9.20   |
| M240      | R + R REAR SILENCER                                                                    | 3.0  | 13.80  |
| 473011A)  | R + R FRONT BRAKE DISC/S                                                               | 2.0  | 9.20   |
| 896051)   | R + R ABS BRAKE SYSTEM                                                                 | 1.0  | 4.60   |
|           | DOES NOT INCLUDE: BLEED BRAKE SYSTEM                                                   |      |        |
| 896081)   | R + R R/F ABS SENSOR                                                                   | 1.0  | 4.60   |
| 896081)   | R + R R/F ABS SENSOR                                                                   | 1.0  | 4.60   |
| 431151)   | R + R LEFT FRONT SPRING/SHOCK ABSORBER                                                 | 1.0  | 4.60   |
| 431151)   | R + R RIGHT FRONT SPRING/SHOCK ABSORBER                                                | 1.0  | 4.60   |
| NO NUMBER | R + R FRONT AXLE CARRIER                                                               | 18.0 | 82.80  |
| NO NUMBER | RENEW FRONT AXLE SUPPORT<br>(REMOVED)                                                  | 6.0  | 27.60  |
|           | INCLUDES: CONVERT STEERING AND ALL<br>RUBBER MOUNTS, RENEW IF NECESSARY                |      |        |
| 434211)   | RENEW LEFT FRONT STEERING KNUCKLE<br>DOES NOT INCLUDE: VEHICLE ALIGNMENT               | 4.0  | 18.40  |
| 434211)   | RENEW RIGHT FRONT STEERING KNUCKLE<br>DOES NOT INCLUDE: VEHICLE ALIGNMENT              | 4.0  | 18.40  |



|           |                                          |       |        |
|-----------|------------------------------------------|-------|--------|
| 434021A)  | R + R FRONT WHEEL HUB (COMPOSITE WORK)   | 1.0   | 4.60   |
| 004466)   | VENT R/F BRAKE SYSTEM                    | 2.0   | 9.20   |
| 004466A)  | BLEED BRAKE SYSTEM                       | 1.0   | 4.60   |
| 420018)   | R + R LEFT REAR WHEEL                    | 1.0   | 4.60   |
| 420018)   | R + R RIGHT REAR WHEEL                   | 1.0   | 4.60   |
| 473061A)  | R + R REAR BRAKE DISC/S                  | 2.0   | 9.20   |
| 422041A)  | RENEW REAR WHEEL HUBS                    | 1.0   | 4.60   |
| 482041A)  | DETACH AND REFIT REAR CONTROL ARM        | 5.0   | 23.00  |
| 482041)   | R + R L/R CONTROL ARM REAR               | 1.0   | 4.60   |
|           | DOES NOT INCLUDE: MEASURE REAR VEHICLE   |       |        |
| 482041)   | R + R R/R CONTROL ARM REAR               | 1.0   | 4.60   |
|           | DOES NOT INCLUDE: MEASURE REAR VEHICLE   |       |        |
| 482021)   | R + R REAR LEFT FRONT CONTROL ARM        | 1.0   | 4.60   |
|           | DOES NOT INCLUDE: REAR VEHICLE ALIGNMENT |       |        |
| 482021)   | R + R REAR RIGHT FRONT CONTROL ARM       | 1.0   | 4.60   |
|           | DOES NOT INCLUDE: REAR VEHICLE ALIGNMENT |       |        |
| 482091)   | R + R LEFT REAR TENSION STRUT            | 2.0   | 9.20   |
| 482091)   | R + R RIGHT REAR TENSION STRUT           | 2.0   | 9.20   |
| NO NUMBER | R + R L/R STEERING KNUCKLE               | 6.0   | 27.60  |
| NO NUMBER | R + R R/R STEERING KNUCKLE               | 6.0   | 27.60  |
| 004466)   | VENT L/R BRAKE SYSTEM                    | 3.0   | 13.80  |
| 004466)   | VENT R/R BRAKE SYSTEM                    | 3.0   | 13.80  |
| 0245      | PANEL WORK FRONT                         | 30.0* | 138.00 |
| 9715      | REMOVE AND REFIT ENGINE WITH GEARBOX     | 40.0* | 184.00 |
| 9889      | HANDHELD MEAS SYS ALIGN BODY SHELL       | 20.0* | 92.00  |
| 1211      | REPAIR L/INN SIDE MEMBER                 | 35.0* | 161.00 |
| 9081      | CHECK REAR AXLE SUBFRAME                 | 15.0* | 69.00  |

#### LABOUR COST

|                                      |         |            |
|--------------------------------------|---------|------------|
| Total Work Units                     | 510.0   |            |
| Panel / Mechanical Labour            | 49.8HRS | \$2,290.80 |
| Visual Alignment Labour              | 1.2HRS  | \$55.20    |
| Corrosion Protection External Labour | 0.0HRS  | 0.00       |
| Corrosion Protection Internal Labour | 0.0HRS  | 0.00       |
| Sub Total                            | 51.0HRS | \$2,346.00 |
| Paint Labour                         | 26.0HRS | \$1,196.00 |
| Total Labour                         | 77.0HRS | \$3,542.00 |

| PAINT WORK   |                                    | Time Basis 10 WU = 1 HR. Price = \$46.00/HR |                 |
|--------------|------------------------------------|---------------------------------------------|-----------------|
| Guide Number | Description                        | WU                                          | Cost Price (\$) |
|              | - TWO COAT METALLIC                |                                             |                 |
|              | - PREPARE OFF VEHICLE              |                                             |                 |
| 340          | BUMPER SUPPORT SURFACE PAINT       | 4.0                                         |                 |
| 988          | LOCK CARRIER STRUT SURFACE PAINT   | 4.0                                         |                 |
| 1009         | FRONT PANEL SURFACE PAINT          | 7.0                                         |                 |
| 1117         | L/F WHEELHOUSE CPL SURFACE PAINT   | 6.0                                         |                 |
| 1118         | R/F WHEELHOUSE CPL SURFACE PAINT   | 6.0                                         |                 |
| 1212         | R/INN SIDE MEMBER SURFACE PAINT    | 5.0                                         |                 |
| 1481         | LEFT FRONT DOOR NEW PART PAINTING  | 16.0                                        |                 |
| 1482         | RIGHT FRONT DOOR NEW PART PAINTING | 16.0                                        |                 |
| 1781         | L/R DOOR NEW PART PAINTING         | 14.0                                        |                 |
| 1782         | R/R DOOR NEW PART PAINTING         | 14.0                                        |                 |