

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45417
Date Estimated : 08/01/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Chu Leong Tho
52 Jago Close

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 428451

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SDQ8880L	G885344	28/04/2017	530iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper R/L right front fender and attachment include knocking cause by accident	1700.00		1,700.00	
To spray paint front bumper and front RH fender	1730.00		1,730.00	
To replace front RH rim include balancing (1x)	94.00		94.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00	
* To replace front RH tyre Michelin Primacy 3 245/40/19	517.50		517.50	(A)
Sundries.	80.00		80.00	

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
ALLOY RIM FERRICGREY 8JX19 SPK 663	1,367.30	1.00		1,367.30
FRT BUMPER PANEL PRIMED (PMA/PDC)	1,258.85	1.00		1,258.85

SUPPLEMENTARY ITEMS

Total Labour :	4,722.50
Total Parts :	2,626.15
Total Labour & Parts :	7,348.65
Deduction for Excess :	
Total Repair Costs less Excess:	7,348.65
GST @7%:	514.41
Grand Total :	7,863.06