

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

# **SMRT Accident Vehicle Repair Estimates**

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6071P

Ref. No : TAX/01/18/2031

Reg. Date : 01/11/2017

Vehicle Type : TAXI

Make : TOYOTA PRIUS

Model : PRIUS4

Name of Driver : LIM SOO KHOON

Type of Accident : SIDE SWIPE

Date / Time of Accident : 07/01/2018 10:56:00 AM

Accident Reported Date / Time: 08/01/2018 12:00:00 AM

Surveyor is Required? : Yes

Survey by :

Vehicle is Towed Back? : No

Towed Back Date/Time


Replacement Vehicle issued? : No

Accident Repair Job Card No : 000024093967

Special Instruction to ARC, if any:

SLJ6076Y - FWD

Prepared Date : 08/01/2018 10:04:12 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKB3FU503573344 Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates** 

Quotation from ARC Adjusted by Surveyor, if applicable

Total Labout Charges : 1,183.00 0.00

Total Spray Painting Charges : 1,494.00 0.00

Total Material Charges : 3,274.42 3,274.42

Other Charges : 700.00 0.00

TOTAL : 6,651.42 0.00

Lum Sum Total : 0.00 0.00

No. of Repair Days : 7.00 0.00

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 08/01/2018 11:55:12 AM 01/01/1900 12:00:00 AM

7

Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/01/2018 11:20:49 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : 0.00 Prepared Date : 1/8/2018 11:55:14 AM

#### **Section D - Details of Repair Estimates**

#### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,183.00	0.00
Total Labour	1,183.00	0.00

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	0.00
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00
TO RESPRAY REAR DOOR LH	378.00	0.00
TO RESPRAY REAR FENDER LH	378.00	0.00
RESPRAY WHEEL CAP	180.00	0.00
Total Spray Painting & Panel Beating	1,494.00	0.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO TRANSFER DOOR MECHANISM	240.00	0.00
TO REMOVE / REFIT SEAT	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	700.00	0.00

### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
67002471 62			PANEL SUB-ASSY, FRONT DOOR LH	1	1,249.60	25.00	937.20	Replace	Replace	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No
75860479 00			MOULDING ASSY, BODY ROCKER PANEL , LH	1	576.00	25.00	432.00	Replace	Replace	No
67004472 10			PANEL SUB-ASSY, REAR DOOR , LH	1	1,243.90	25.00	932.92	Replace	Replace	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace	No
61602471 60			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace	No
65638470 60			LINER, REAR FENDER , LH	1	135.80	25.00	101.85	Replace	Replace	No
42602471 80			CAP SUB-ASSY, WHEEL	1	175.80	25.00	131.85	Replace	Replace	No
TOTAL MATERIALS							3,274.43	3,274.42		
	TOTAL MATERIALS(Discounted)					3,274.42 3,274.42				

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									