

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0034/2018/JT
Date	:	9-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Chua Chet Shiu
Address	:	404 Dunearn Road #04-06 Singapore 289609
Telephone	:	HP +65 9673 7637
Type of Claim	:	Third party Claims
Policy No.	:	PNVP2017-00008031
Vehicle No	:	SLH 3872 X
Model Code	:	Audi A3 Sedan 1.4 TFSI (A)
Model / Year	:	Oct-16
Engine No	:	CZC 567401
Chassis No	:	WAUZZZ8V7G1107369
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	7-Jan-18
Place of Accident	:	Road before Adam Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLH 3872 X.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function.	S/N \$	280.00	✓
2	To remove and transfer rear lids convenience lock system and wire harness for tail lights.	S/N \$	280.00	✓
3	To remove and install reverse camera assy.	S/N TBC		✓
4	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	480.00	?
5	To dismantle rear bumper and rear lid. Cut out and weld rear outer, inner rear cross panel and connecting plates. Re-align rear lock carrier Renew rear bumper and rear lid. Re-organize rear crash management components. Reinstall all parts removed.	\$	3,600.00	1500.
6	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatment.	\$	2,200.00	1650
7	To carry out diagnostic checks.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 7,032.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 3872 X.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Distorted.</i>	\$ 1,619.00	✓
2	REAR BUMPER SPOILER <i>Deformed</i>	\$ 206.00	✓
3	REAR BUMPER GUIDE - LHS/RHS <i>New</i>	\$ 28.00	X
4	REAR BUMPER LOCKING MECHANISM <i>New</i>	2 \$ 50.00	X
5	REAR BUMPER LIGHT REFLECTOR - LHS/RHS <i>New</i>	\$ 52.00	X
6	REAR REINFORCEMENT BEAM ?	\$ 501.00	?
7	REAR BUMPER BRACKET ?	\$ 22.00	?
8	REAR BUMPER INNER GUIDE - LHS/RHS <i>New</i>	\$ 114.00	X
9	REAR PARKING AID SENSOR ?	\$ 421.00	?
10	REAR LID <i>Buckled</i>	\$ 2,310.00	✓
11	REAR LID WEATHERSTRIP <i>New</i>	\$ 176.00	X
12	REAR LID STRIKER <i>New</i>	\$ 44.00	X
13	REAR LID LOCK ?	\$ 170.00	?
14	REAR LID PUSH BUTTON <i>New</i>	\$ 159.00	X
15	PACKING ADHESIVE <i>New</i>	\$ 15.00	✓
16	OUTER LED TAIL LIGHT - LHS/RHS <i>New</i>	\$ 1,892.00	X
17	OUTER LED TAIL LIGHT TRIM - LHS/RHS ?	\$ 52.00	?
18	INNER LED TAIL LIGHT - LHS/RHS <i>New</i>	\$ 1,132.00	X
SUB- TOTAL SPARE PARTS		\$ 8,963.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 3872 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
19	INNER LED TAIL LIGHT TRIM - LHS/RHS <i>new</i>	\$	52.00 <i>R</i>
20	AUDI EMBLEM <i>?</i>	\$	108.00 ✓
21	"A3" EMBLEM <i>new</i>	\$	83.00 ✓
22	"TFSI" EMBLEM	\$	83.00 ✓
23	REAR CROSS PANEL <i>?</i>	\$	317.00 <i>?</i>
24	CROSS PANEL REINFORCEMENT PANEL <i>?</i>	\$	645.00 <i>?</i>
25	INNER CROSS PANEL TRIM <i>?</i>	\$	135.00 <i>?</i>
26	REAR NUMBER PLATE <i>new</i>	S/N \$	25.00 <i>X</i>
27	ACRYLIC SEALER <i>?</i>	S/N \$	180.00 <i>?</i>
28	CAVITY WAX <i>?</i>	S/N \$	140.00 <i>?</i>
29	STONE CHIP <i>?</i>	S/N \$	140.00 <i>?</i>
30	SUNDRIES <i>?</i>	\$	500.00 <i>?</i>
GRAND TOTAL SPARE PARTS		:	\$ 11,371.00
TOTAL LABOUR CHARGES		:	\$ 7,032.00
GRAND TOTAL		:	\$ 18,403.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 09/04/18
Authorised Date :
Excess Cost :
Liability :
Remarks : xte Authorised, 06 Pays

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant