

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

169942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 3491
Date Estimated : 03/01/2018
Prepared By : Wong Guo Xiang

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Low Koon Hoong
11 Springside Walk

Singapore 786612

- ACCOUNT - 2000

CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SL85195X	VF3LPHNYWGS255627	27/09/2017	3081.2 Allurel7	0

DESCRIPTION	VALUE
SUNDRIES	30 150.00
REPLACE/REPAIR REAR RHS DOOR, REAR RHS FENDER	1200 2,400.00
RESpray REAR RHS DOOR, REAR RHS FENDER	1200 1,800.00
WIRING CONNECTION & CHECK (NETT)	✓ 150.00
TRANSFER REAR RHS DOOR MECHANISM (NETT)	X 300.00
TUFF KOTE @ \$60 PER PANEL (NETT)	X 120.00
SEALANT FOR BODY PANEL @ \$90 PER PANEL	X 90.00
WHEEL ALIGNMENT (NETT)	X 600.00
TO CONDUCT ECU COMPUTER DIAGNOSTIC CHECK INCLUDING CLEAR FAULT CODE (NETT)	✓ 600.00

Total Labour 1: 6,210.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
9802165580	REAR DOOR RH ASS	1	790.00	10.00	Rx 711.00
9809036080	RHR DR INNER SEALING PANEL	1	54.00	10.00	X 48.60
9677904380	RHR DR LWR WEATHERSTRIP AV	1	67.00	10.00	X 60.30
9677917780	RHR DR LWR ENTRY SEAL AR	1	47.00	10.00	X 42.30
9677919480	RHR DR DECORATIVE STRIP AV	1	61.00	10.00	X 54.90
1610017580	FT/RR BODY SEALING ADHESIVES SET	1	22.00	10.00	X 19.80
1612686580	MKT DOOR FIXINGS CLIP-SET	1	223.00	10.00	X 200.70
1610095980	REAR WING RH	1	1,350.00	10.00	Rx 1,215.00

Total Parts : 2,352.60

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 3491
Date Estimated : 03/01/2018
Prepared By : Wong Guo Xiang

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SL85195X	VF3LPHNYWGS255627	27/09/2017	3081.2 Allure17	0

Tan Jiah 97495749
10/1/18 @ 12pm.
- WP
Resurvey after repair
4 days.
See @ lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Service Officer

Contact

Labour 1	:	6,210.00
Parts	:	2,352.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	599.38
Grand Total	:	9,161.98

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.