

# COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC3340M

MAKE : HYUNDAI

MODEL : SONATA

Date : 09.01.2018

| Qty                            | Parts Description / Labour                | Type | Unit Price | Amount      |               |
|--------------------------------|-------------------------------------------|------|------------|-------------|---------------|
| 1                              | Rear Bumper <i>cut</i>                    |      |            | \$ 578.40   | <i>L</i>      |
| 10                             | Rear Bumper clips <i>HL</i>               |      | \$2.20     | \$ 22.00    | <i>L</i>      |
| 1                              | Rear Fender – RH <i>Replaced</i>          |      |            | \$ 1,935.90 | <i>L</i>      |
| 1                              | Wheel cover – RH <i>2pc</i>               |      |            | \$ 145.00   | <i>X</i>      |
| 1                              | Tail lamp – RH <i>crack</i>               |      |            | \$ 344.00   | <i>L</i>      |
| SUB TOTAL                      |                                           |      |            | \$ 3,025.30 |               |
| LESS 20%                       |                                           |      |            | 605.06      |               |
| DISCOUNTED TOTAL               |                                           |      |            | \$ 2,420.24 |               |
| 1                              | Sealant <i>HL</i>                         |      |            | \$ 46.00    | <i>L</i>      |
| 1                              | Booking APP – Rear fender right <i>HL</i> |      |            | \$ 80.00    | Nett <i>L</i> |
|                                |                                           |      |            | \$ 0.00     |               |
| Labour Charge                  |                                           |      |            |             |               |
| Panel Beating                  |                                           |      |            | \$ 600.00   | <i>450/-</i>  |
| Spray Painting Charge          |                                           |      |            | \$ 600.00   | <i>400/-</i>  |
| Wiring Charge                  |                                           |      |            | \$ 80.00    | <i>20/-</i>   |
| Tuff Kote                      |                                           |      |            | \$ 100.00   | <i>40/-</i>   |
| Remove/refix reverse sensor    |                                           |      |            | \$ 120.00   | <i>40/-</i>   |
| Remove/refix rear windscreen   |                                           |      |            | \$ 150.00   | <i>80/-</i>   |
| 09/01/2018 @ 1530 TOTAL LABOUR |                                           |      |            | \$ 1,650.00 |               |
| <i>HLA Andrew</i>              |                                           |      |            |             |               |
| <i>1530M</i>                   |                                           |      |            |             |               |
| <i>3 days</i> ESTIMATE TOTAL   |                                           |      |            | \$ 4,070.24 |               |
| <i>2KE Ando</i>                |                                           |      |            |             |               |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.