



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2008 ASTON MARTIN DBS 6.0L MT ABS XXXXXX (SDS2020G)

Date of Loss

4 January 2018

Time of Loss

10.45

Loss Description

SDS2020G (INSD) HIT LEFT REAR OF SBS8156H (TP)

Comment

Workshop Details

Total Rebate Amount

200288

Nett Loss Amount

\$117,712.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

21/06/2018



Days of work completion *

162



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SDS2020G

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

04/09/2009



Mileage

46806

Age of Vehicle

8

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2008

ASSESSMENT INFO...

2008

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

TAN TIANG HWEE DONALD

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... ASTON MARTIN DBS 6.0L MT ABS

ASSESSMENT INFO... ASTON MARTIN

CATEGORY Model

POLICY INFORMAT... XXXXXX

ASSESSMENT INFO... DBS 6.0L MT ABS D/AB HID 2WD 2DR

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... SCFAA05D39GE00639

CATEGORY Date of Birth

FNOL INFORMATI... 3 January 1960

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 58

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... SCFAA05D39GE00639

CATEGORY Engine No

POLICY INFORMAT... AM08/23708

ASSESSMENT INFO... AM08/23708

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 5935

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 318000

FNOL INFORMATI... 22

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF... ▼

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy 

CATEGORY Address

FNOL INFORMATI... 49 OEI TIONG HAM PARK, 267054,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Married

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S1400423H

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

10/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

20000

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

245/35R20

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

295/30R20

Front left side

PIRELLI6mm

Front right side

PIRELLI6mm

Rear left side

PIRELLI6mm

Rear right side

PIRELLI6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts															
Add Approve Deny															
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART)
☐		1	1			HOOD ASSY			Cracked	26495				26495	Revie
☐		2	1			CVR ASY RAD SUPT LWR			Serviceable	0	0	0	0	0	Deny
☐		3	1			CVR ASY FRT BMPR			Cracked	6444.9				6444.9	Revie
☐		4	1			MESH LWR FRT GRILL			Deformed	596.7				596.7	Revie
☐		5	5			EXT FENDER CLIP (5)			Necessary	14.76				73.8	Revie
☐		6	20			RIVET DOME HEAD PACK			Necessary	1.17				23.4	Revie
☐		7	1			FRONT SPLITTER - RH			Cracked	6718.5				6718.5	Revie
☐		8	1			FRONT SPLITTER - LH			Cracked	6718.5				6718.5	Revie
☐		9	1			ROW BUMPRBEAM ASY F			Bent	1991.7				1991.7	Revie
☐		10	1			RAD GRILLE & SUPPT			Cracked	4581				4581	Revie
☐		11	1			PANEL-GRILLE OPENING			Cracked	516.69				516.69	Revie
☐		12	1			BADGE ASSY AML			Necessary	374.58				374.58	Revie

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART)
☐		13	1			LATCH ASY HOOD SECON			Serviceable	0	0	0	0	0	Deny
☐		14	1			SECONDARY LATCH STKR			Bent	40.05				40.05	Revie
☐		15	1			AUTOMOTIVE EXTERIOR - FRT BUMPER			Cracked	18934.38				18934.38	Revie
☐		16	1			HEADLAMP ASY RH RHD			Serviceable	0	0	0	0	0	Deny
☐		17	1			AMBIENT AIR SENSOR			Serviceable	0	0	0	0	0	Deny
☐		18	1			DUCT - AIR INTAKE RH			Serviceable	0	0	0	0	0	Deny
☐		19	2			PARKING AID SENSOR			Damaged	116.01				232.02	Revie
☐		20	2			PARKING SENSOR DECOU			Necessary	31.14				62.28	Revie
☐		21	1			BODY PANEL SEALANT X			Necessary	738.18				738.18	Revie
☐		22	1			ADHESIVE SEALER FL2			Necessary	322.47				322.47	Revie
☐		23	1			SCREW/WASHER M6X18C			Necessary	1.53				1.53	Revie
☐		24	10			C WASHER 20 X 6.4			Necessary	1.08				10.8	Revie
☐		25	1			EXT FENDER CLIP (5)			Necessary	14.76				14.76	Revie
☐		26	2			BUFFER ASSY HOODBUMP			Necessary	2.07				4.14	Revie

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PAR)
		27	20			RET GRILLE BUMPER PA			Necessary	0.54				10.8	Revis
		28	1			BRKT MTG BONNET LOCK			Bent	1304.19				1304.19	Revis
		29	2			SCREW M4 SELF TAP			Necessary	0.63				1.26	Revis
		30	1			BONNET LATCH			Bent	64.26				64.26	Revis
		31	100			CLIP-FIRTREE PK 100			Necessary	0.45				45	Revis
		32	10			CLIP-BUMPER GRL (10)			Necessary	1.17				11.7	Revis
		33	2			M6 NUT-FLEXAX (5)			Necessary	7.74				15.48	Revis
		34	20			NUT-M4 HEX FLG (20)			Necessary	0.54				10.8	Revis
		35	1			SCREW			Necessary	0.99				0.99	Revis
		36	10			SCREW/WSHR M6X20 (10)			Necessary	1.17				11.7	Revis
		37	19			SCREW / WASHER M6X18 C			Necessary	1.53				29.07	Revis
		38	20			CLIP SPG M6 PK OF 10			Necessary	1.89				37.8	Revis
		39	2			FENDER DAMPER PAD			Necessary	20.07				40.14	Revis
		40	1			GRL ASSY RAD CTR			Damaged	2621.25				2621.25	Revis
		41	1			BUMP FRT LWR TAPE CT			Necessary	120.96				120.96	Revis

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART)
		42	1			FULL UNDERTRAY FRONT			Deformed	2621.25				2621.25	Revie
		43	10			WSHR 25MM x 6.4MM-10			Necessary	1.08				10.8	Revie
		44	2			PARKING SENSOR DECOU			Necessary	31.14				62.28	Revie
		45	1			LATCH ASY HOOD SECON			Bent	385.29				385.29	Revie

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
		1		TO REPLACE FRONT BONNET, RH FRONT FENDER, FRONT BUMPER BEAM	5600	0	0	Reviewing	
		2		TO PUTTY, SPRAY FRONT BUMPER RH FRONT FENDER, ETC	3300	0	0	Reviewing	
		3		TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	1000	0	0	Reviewing	

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 7 DAYS	Reviewing			
		2	NUMBER PLATE AND INCL HOLDER	Reviewing	60	CRACKED	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$72,260.40			Claim Amount	\$72,260.40			

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$9,900.00	\$9,900.00
Miscellaneous	\$60.00	\$60.00
Excess	-\$20,000.00	-\$20,000.00
Spare Parts	\$82,300.40	\$82,300.40

Submit for Review