

ASG REC. BY:

REF:

C9 / ASG18000585 / Giber

Special Instruction:

SUNATOR

(112)

ASSIGNMENT (Office)

Smart claim

From (Person):

Yvonne Ang

of

ASM

Date/Time:

10-01-2018 10:51am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCX 366H

Insured:

at Workshop m/s

Kah Motor

Tel:

of

15 Ubi Rd 4 floor to Alan's United

Policy No:

Claim No:

S8MD06UV

Sum Insured:

Excess:

\$ 800.00

Make of Veh:

(Client's Record)

D.O.A.

08-01-2018

CA / REV / REP. / REV 24 HRS

Date/Time:

10-01-2018 1:45pm

Person Contacted:

Mr. Lim

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SCX 366H - X

10/1/18 @ 9.53am

revert to Yvonne Ang via Smart Claims.

19/1/18

Submit Uneconomical Total Loss Report.

27/1/18 @ 6.28pm

Yvonne Ang informed C/A as the investigation clear.

19/1/18 @ 6.25pm

Yvonne Ang informed that the vehicle was to Alan's United.

23/1/18 @ 11.54am

2nd revert to Yvonne Ang via Smart Claims. (Alan's United)

23/1/18 @ 11.51am

informed Remy C/A not more than US \$20000 LS EX: \$500.

Surveyor

Xbcl

REF: AXA

ASSIGNMENT

OPC

From: _____ Date: _____
 Estimated Cost: _____
☒ OB / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Kah Motor
 of _____
 Insured: Kenny
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: \$800
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$777 60500
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 20 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SCX 366H Yr Regn: 19 Jun 2015
 Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Jazz c.c. 1498
 Colour: silver Insured / Std / NI / NA
 Sp. Reading: 25389 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHMGK 5850 FX 203A
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/55R16
 R: 11
 BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 11-01-18
 Survey held at W/S 10:30
 Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ UIC / ☒ Rooftop or
and
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
11/1	'opc' <u>\$22k</u> Inform him (81006303) Max repair limit \$20k If over \$20k then total loss. He will check and set back. Total loss due to beyond beyond repair.

RECEIVED 7 JUL 2018

09/07/18 @ 11:30am confirmed with Kenny U.S. \$20k
 Date/Time, File Pass to? ☐ : Prel. Report (Ref \$9175.80, \$1175.80) Days Of Repair: 23/12/18
☒ : Final Report Resurvey No. of Trip: 4 Survey Fee: 300
 Date/Time, File Return to? 11/07/18 Add Fee: ☐ : Site Insp (\$) \$ + RS \$
☐ : Interview (\$) Photos
☐ : Tech. Invs (\$) Others
☐ : Weekend (\$)
 Report Format: Smart Claims
 Lump Sum / J.B.I: (\$ 20,000)
 TOTAL 300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18000585/Gqb

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 10-01-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SCX 366H
Policy No.	Coverage (\$)	0.00
Claim No. S8M006UU	Excess (\$)	800.00
Assign From SMART CLAIM (YVONNE ANG)	Assign Date	10/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 08/01/2018	Inspection Date 10/01/2018
Survey held at KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No: CS/ASM/8000585/G96
 Policy Type: OD/TP/TP RES/TL/EVA

SCX 366H

Case Handler

Typist

Admin (Catherine): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA/REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Gino Diany): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Catherine 17/1/18
 Case Handler Date

◀ Service Request Details

Claim

S8M006UU

Reference

None 

Loss Date

January 8, 2018

Request Date

January 10, 2018

Due Date

January 17, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Incident Only

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

[Decline Work](#)[Accept Work](#)

Vehicle Information

Incident Vehicle Registration #

SCX366H

Make

HONDA

Service Address

51 Ubi Avenue 1 #01-25 Paya Ubi, , 408933

Primary Contact/Insured

PEK SIM YET

49 JALAN HAJI SALAM, 468834, Singapore, Singapore

92369627

openv1ew04@yahoo.com

Claim Handler

Default Owner

Additional Instructions

PENDING INVESTIGATION, EXCESS \$300 + \$500 \$800

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Shiau Chan (LKKAuto)

From: alan khong chin wah <alanauto@gmail.com>
Sent: Monday, 7 May 2018 11:32 AM
To: Shiau Chan (LKKAuto)
Subject: Re: ATTACHED SCX366H AFTER REPAIR PHOTO ,FINAL AMOUNT FOR FINALIZE (AXA OWN DAMAGED CLAIM) ***LKK REF:CS/ASM18000585/Gqb

Dear Shiau Chan

Ok confirmed at \$20,000.00 at 24 repair days thank you .

Regards
Kenny
Alan's United Auto Pte Ltd
64538686

On Mon, May 7, 2018 at 10:56 AM, Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Alan,

Offer Lump Sum \$20,000.00 before excess \$800.00 and 24 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)
Sent: Monday, 16 April 2018 10:27 AM
To: alan khong chin wah <alanauto@gmail.com>
Cc: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>
Subject: RE: ATTACHED SCX366H AFTER REPAIR PHOTO ,FINAL AMOUNT FOR FINALIZE (AXA OWN DAMAGED CLAIM) ***LKK REF:CS/ASM18000585/Gqb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 23 January 2018 11:56 AM
To: kennychan@alanutd.com
Cc: SUR
Subject: RE: ESTIMATE MARKING OF VEHICLE SCX 366H

Dear Kenny,

As instructed by our client, please proceed to repair the insured vehicle **SCX 366H** at repair cost not more than **\$20,000.00 on Lump Sum basis (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: kennychan@alanutd.com [mailto:kennychan@alanutd.com]
Sent: Monday, 22 January 2018 5:14 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: ESTIMATE MARKING OF VEHICLE SCX 366H

Dear Shiau Chan

Had received your marking estimate ,here by enclosed Lump Sum letter signed by owner and we will agreed max. of \$20,000.00 for Lump Sum repair to the vehicle SCX366H , kindly reply to confirm authorize repair thank you .

Regards

Kenny

Alan's United Auto Pte Ltd

64538686

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Monday, January 22, 2018 4:39 PM
To: kennychan@alanutd.com
Cc: SUR <sur@lkkauto.com>
Subject: ESTIMATE MARKING OF VEHICLE SCX 366H

Dear Kenny,

As spoken with you.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M006UU

Date: 22nd January 2018

Our Ref: CS/ASM18000585/Gqb

The Motor Claims Department
AXA Insurance Singapore Pte Ltd

Attn: Yvonne Ang

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SCX 366H


We thank you for the instruction on 10/01/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/01/2018 (10.30am) at the premises 15 UBI ROAD 4, repair at M/s ALAN'S UNITED and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 29,125.80</u>
Revised Estimate Amount	: <u>S\$ 21,506.28</u>
"Check" Items Amount	: <u>S\$ 5,587.76</u>
Total	: <u>S\$ 27,094.04</u>
Market Value	: <u>S\$ 60,500.00</u>
LTA Reimbursement Value	: <u>S\$ 40,327.00</u>
Nett Value	: <u>S\$ 20,173.00</u>

Description of Damage:

The vehicle sustained damages at the front portion, n/s body & undercarriage.
The chassis frame affected due to collision.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Repairer agreed repair cost not more than Lump Sum \$20,000.00.

Estimated normal period for repairs: 24 working days.

We have NOT authorised the repairs.

Yours faithfully

Guo Qiang
Automobile Assessor



SERVICE REQUESTS

MESSAGES

CLAIMS



SCX366H - INVESTIGATION CLEAR

Type

Question

Message

Please proceed to authorize repair if within economical limit

[Reply](#)

Shiau Chan (LKKAuto)

From: kennychan@alanutd.com
Sent: Monday, 22 January 2018 5:14 PM
To: Shiau Chan (LKKAuto)
Subject: RE: ESTIMATE MARKING OF VEHICLE SCX 366H
Attachments: SKM_284e18012217270.pdf

Dear Shiau Chan

Had received your marking estimate ,here by enclosed Lump Sum letter signed by owner and we will agreed max. of \$20,000.00 for Lump Sum repair to the vehicle SCX366H , kindly reply to confirm authorize repair thank you .

Regards
Kenny
Alan's United Auto Pte Ltd
64538686

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Monday, January 22, 2018 4:39 PM
To: kennychan@alanutd.com
Cc: SUR <sur@lkkauto.com>
Subject: ESTIMATE MARKING OF VEHICLE SCX 366H

Dear Kenny,

As spoken with you.

Please refer to the attachment.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



redefining / insurance

AXA INSURANCE SINGAPORE PTE LTD
☎ 1800-880 4888 (Within Singapore)
(65) 6880 4888 (International)
☎ (65) 6338 2522
🌐 www.axa.com.sg

Letter of Authorisation for Lump Sum Repair

1. I, [Name] [NRIC] YET PEK SIM, the owner of vehicle [no.] SCX366 H ("Vehicle") do hereby authorize the [Workshop/Insurer] to repair the Vehicle on a lump sum basis instead of part by part.
2. The [Workshop/Insurer] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorisation for lump sum repair for the Vehicle.
3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out the repair and I note that the [Workshop/Insurer] will not be furnishing a detailed breakdown of parts or price for such lump sum repair.
4. I am aware that AXA Insurance Singapore Pte Ltd ("AXA Insurance") does not encourage lump sum repair as AXA Insurance strongly recommends repairs for vehicles on a part by part basis for transparency reasons. I confirm that I will hold AXA Insurance harmless from any claims arising from the lump sum repair of the Vehicle which I have authorised.

Signed and acknowledged by:

Y-P. Sim

Signature of policyholder

Date:

Kenny



Name and signature of workshop personnel including workshop stamp

Date:



RE: MV RANGE \$ 60K - \$64K

Type

🔔 Question

Message

Dear Yvonne, refer to the above valuation, according to our surveyor that the vehicle is constructive total loss. - Shiau Chan

Reply



MV RANGE \$ 60K - \$64K

Type

🔗 Question

Message

Please take note the MV range above. Thanks

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S8M006UU

Date: 12th January 2018

Our Ref: CS/ASM18000585/Gqb

The Motor Claims Department
AXA Insurance Singapore Pte L td

Attn: Yvonne Ang

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SCX 366H .


We thank you for the instruction on 10/01/2018 .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/01/2018 (10.30am) at the premises of M/s KAH MOTOR and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 41,991.69</u> .
Revised Estimate Amount	: <u>S\$ 36,305.32</u> .
"Check" Items Amount	: <u>S\$ 3,396.37</u> .
Total	: <u>S\$ 39,701.69</u> .
Market Value	: <u>S\$ 60,500.00</u> .
LTA Reimbursement Value	: <u>S\$ 40,327.00</u> .
Nett Value	: <u>S\$ 20,173.00</u> .

Description of Damage:

The vehicle sustained damages at the front portion, n/s body & undercarriage.
The chassis frame affected due to collision.



Comments/ Present Status:

Damages consistent.

Repair cost not economical.

Estimated normal period for repairs: 24 working days.

We have NOT authorised the repairs.

Yours faithfully

Guo Qiang
Automobile Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3716I
Vehicle Details	
Vehicle No.:	SCX366H
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	L15B31000587
Chassis No.:	JHMGK5850FX203193
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$15,189.00
Original Registration Date:	19 Jun 2015
First Registration Date:	19 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$5,189.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jun 2025
PARF Rebate Amount:	\$3,891.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$36,436.00
Total Rebate Amount:	\$40,327.00

The information contained herein is correct as at 11 Jan 2018

▶ Honda Jazz Used Vehicle List (9 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Honda Jazz 1.5A RS	\$72,800	\$9,990 /yr	23-Jan-2015	1,498 cc	49,520 km	Dickson Automobile	Available

5 Years Agent Warranty, Just Serviced At Kah Motor, 1 Owner! Extremely Good Condition As Good As New! Fuel Efficiently Up To 17.8KM/L! Low Maintenance, Low Fuel Consumption! Buy It From Us With A Peace...

Office No. - 68447667

Eric Lee - 91827304 | Jonathan Quah - 91901666 | Ricky Eng - 91853390

Honda Jazz 1.5A	\$74,800	\$9,710 /yr	18-Jun-2015	1,498 cc	15,628 km	CarTrade SG	Available
-----------------	----------	-------------	-------------	----------	-----------	-------------	-----------

Viewing Strictly By Appointment Only. Bought Brand New For S\$412000. Five (5) Years Warranty With All Times Service And Maintained By Agent. Low Mileage, Clocked At 12457km, Hardly Used.

Office No. - -

Bobby Boh - 86663300

Honda Jazz 1.5A RS	\$77,800	\$9,550 /yr	02-Sep-2015	1,498 cc	33,740 km		Available
--------------------	----------	-------------	-------------	----------	-----------	--	-----------

100% Genuine Mileage, Super Low Mileage Only At 33740km, Owner Seldom Drive, Almost Like Brand New, Value For Money, Buy With Peace Of Mind, Agent Services, Still Under Agent Warranty With Free Serv...

Office No. - -

Chew - 86113718

Honda Jazz 1.5A RS	\$83,700	\$10,240 /yr	17-Sep-2015	1,498 cc	13,500 km		Available
--------------------	----------	--------------	-------------	----------	-----------	--	-----------

RS Model With Low Mileage! Two More Free Servicing To Inherit From Agent Kah Motor, Immaculate Condition, Call To Arrange Viewing.

Office No. - -

Mr Lim - 88183199

Honda Jazz 1.5A RS	\$84,888	\$10,280 /yr	08-Oct-2015	1,498 cc	6,000 km	Munich Alpina Pte Ltd	Available
--------------------	----------	--------------	-------------	----------	----------	-----------------------	-----------

Beautiful Red Beast, Owner's Second Car, Selling Due To An Upgrade. Still Under Warranty By KAH Motor, Full Serviced Records, Lowest Mileage, Accident Free, Like New Interior Due To Low Usage, Trade I...

Office No. - -

Joseph - 82021811 | Damien - 97825861

Honda Jazz 1.5A RS	\$76,900	\$9,100 /yr	26-Nov-2015	1,498 cc	33,630 km	Swee Watt Motor Trading	Available
--------------------	----------	-------------	-------------	----------	-----------	-------------------------	-----------

[We Assure 100% Genuine Mileage], Super Low Mileage Only At 33630km, Owner Seldom Drive, Almost Like Brand New, Value For Money, Buy With Peace Of Mind, Agent Services, Still Under Agent Warranty Till...

Office No. - 63441932

Mr Ivan - 97570832 | Kelvin - 96350832 | Ms Ivy - 97370832 | Mr Ang - 96320832

Honda Jazz 1.5A RS	\$78,800	\$9,280 /yr	14-Dec-2015	1,498 cc	32,800 km	Car House Enterprise (S) Pte Ltd	Available
--------------------	----------	-------------	-------------	----------	-----------	----------------------------------	-----------

Kah Motor Agent Warranty Till 2020. Well Maintained And Service Regularly! All Time Favourite Economical Jap Hatchback! Hassle Free Unit! Buy With A Piece Of Mind! Flexible Loan Packages With Loan Int...

Office No. - 64433902

Amanda - 97561414 | Ken Khoh - 81011311

Honda Jazz 1.5A RS	\$77,800	\$9,160 /yr	15-Dec-2015	1,498 cc	43,000 km	Autocar Pte Ltd	Available
--------------------	----------	-------------	-------------	----------	-----------	-----------------	-----------

Beautiful Sporty Red Original Paintwork. 1 Owner, Low Mileage Done. Very Well Maintained And Serviced With Agent. Still Under Warranty By Kah Motor. Clean And Neat Interior. Most Popular Honda HatchBa...

Office No. - -

Keith - 97427882 | Rachel - 93883243 | Haz - 87504181

Honda Jazz 1.5A RS	\$79,500	\$9,320 /yr	30-Dec-2015	1,498 cc	31,733 km	Henly Enterprises Co	Available
--------------------	----------	-------------	-------------	----------	-----------	----------------------	-----------

Single Owner, New Condition, Low Mileage, Trade In Acceptable, Call Mobile.

Office No. - 67476011

Edwin - 92331607 | Alan Seah - 96622171

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/01/2018 19:15
Date Of Accident	08/01/2018 01:20
Exact Location Of Accident	JUNCTION OF SIMEI AVENUE & UPPER CHANGI ROAD EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCX366H
Insured/Policyholder	
Name Of Registered Owner	YET PEK SIM
NRIC No	S1763716I
Email Address	OPENV1EW04@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97502249
Alternative Phone No	OFFICE-92369627
Vehicle Particulars	
Manufacturer	HONDA
Model	JAZZ-1.5 VTIR CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA205530
Cover Note Number	
Driver	
Name of Driver	GABRIEL, CHONG JUN WEI
NRIC No	S9512628F
Date Of Birth	14/04/1995
Occupation	INDOOR
Date Of Driving Pass	03/02/2015
Driving Experience	2 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92369627
Fax Number	
Contact Number	OFFICE-97502249
EEmail Address	GABRIELCHONG7@GMAIL.COM

Address	49 JALAN HAJI SALAM
Postcode	468834
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT - OWN DAMAGE CLAIM

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ4860B
Vehicle Make/Model/Colour	MERCEDES/ E250 / BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	AMAR KUKULJAC
NRIC/Passport Number	S8272383H
Contact Number	91094093
Address	APT BLK 86 TELOK BLANGAH HEIGHTS #02-377
Postcode	100086
Insurance Company Name	EQ INSURANCE COMPANY LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	2

DETAILS OF INJURED PERSON 1

Name	GABRIEL CHONG JUN WEI
Approximate Age	22

Injuries Sustain

LEFT ABDOMUN

Injured person in which vehicle?

SCX366H

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

49 JALAN HAJI SALAM

Postcode

468834

Vehicle No

SCX366H

SKETCH PLAN

Annex D

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Please continue to Annex E

Sketch Plan Pg. 2

Vehicle No SCX 366 H

Annex E

Describe Circumstances of the Accident

On 8th January 2018 around 1:20pm, I was driving my Honda Jazz car plate SCX 366 H along Simi Ave towards Xilin Ave. I reached the traffic junction with Upper Chang Road East and intended to turn right towards Upper Chang Road East. The traffic light was green in my favour and I didn't see any oncoming traffic so I decided to turn right towards Upper Chang Road East. As I was about to complete my turn, a vehicle (Mercedes Benz 2250 SLK4860B) from my left hit my car's front left bonnet. Upon impact, my car was pushed to the right and turned 90 degrees. I was in a confused state after the impact and stayed in the car. I was from the other car got out from their car and they were not injured. A while later, traffic police arrived shortly and I followed his instructions. Upon inspection of the impact, my damage is on my left bonnet and the other car's damage is in his right bonnet. We took photos of the accident, exchanged particulars and called for tow trucks to move the vehicles. I sustained bruises on my left knuckle, right knee, lower left abdomen and a strain on my left arm. When I reached home, I had nausea feelings twice and I felt a sharp pain in my left abdomen when I move my body in certain angles and at certain times when I breathe.

Declaration

We declare the foregoing particulars are true in every respect.

M. P. Ch
Policyholder's Signature / Date & Time

Solih 08/01/2018 @ 1:50 hrs
Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel



redefining / insurance

AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore)

(65) 6880 4888 (International)

(65) 6880 4740

customer.care@axa.com.sg

www.axa.com.sg

YET PEK SIM
49 JALAN HAJI SALAM
SINGAPORE 468834

New business

date

23/05/2017

your servicing distributor

DESDA TRADING / 03110

your servicing distributor contact

62511162

Policy Schedule

Your SmartDrive Comprehensive Flexi

Your policy snapshot

Policyholder name	YET PEK SIM	Policy number	VA1 / GA205530
Cover	Comprehensive	FIN / NRIC	S1763716I
Period of Insurance	from 19/06/2017 to 18/06/2018 (both dates inclusive)		

Premium breakdown

Gross Premium after 50% NCD	SGD 989.47
Total Discounts	- SGD 264.83
7% GST	SGD 50.73
Final Premium	SGD 775.36

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Flexi Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Loss or Damage
- Legal Liability
- Workshop of Your Choice
- Medical and dental expenses up to \$1,000 per person for you, your named drivers and your immediate family members
- Reimbursement of 110% of your car's market value in the event of total loss due to flood (without Basic Own Damage Excess)

Add-on Benefits

- Personal accident benefit of up to \$ 50,000.00 for you and your named drivers
- No Claim Discount Protector

Vehicle details

Make & Model of Vehicle	HONDA JAZZ 1.5	Year of manufacture	2015
Vehicle registration number	SCX366H	Type of Use	Private use
Body type	HATCHB	Engine capacity (c.c.)	1498
Seating capacity (excl driver)	4	Engine number	L15B31000587
Off-Peak car	Yes	Chassis number	JHMGK5850FX203193

Insured's Estimated Market Value

Limitation to use

Finance Loan Company

Market Value at the time of Loss (including accessories and spare parts)

As per Certificate of Insurance

Nil

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 300.00
Windscreen Excess	SGD 100.00

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9512628F



Name

GABRIEL CHONG JUN WEI

张俊伟

Race

CHINESE

Date of birth

14-04-1995

Sex

M

Country of birth

SINGAPORE

S9512628F

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence No. S9512628F

Name

GABRIEL CHONG JUN WEI



Birth Date: 14 Apr 1995

Issue Date: 03 Feb 2015



062293817J

SG
50



46Q1838



NAME No. S9512628F

Date of issue

09-07-2010

Address

49 JALAN HAJI SALAM
SINGAPORE 468834

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 03 Feb 2015



Licence No: S9512628F

NP 420A

YET PEK SIM
49 JALAN HAJI SALAM
SINGAPORE, 468834
SINGAPORE

KF012
OCBC BANKING CORPORATION LIMITED
65 CHULIA STREET
OCBC CENTRE
SINGAPORE, 049513
SINGAPORE

Regn. No.: SCX366H
Sales Exec: 1103

Customer No *****37161
Registration Date: 19. June 2015

Vehicle JAZZ 1.5VTIR CVT 15YM (EURO
Model GK585FLX-NH700M
Color : NH700M ALABASTER SILVER M

Engine : L15B31000587
Chassis : JHMGK5850FX203193

OPT-JAZZ-RIKOOLP63-PROMO ←
REAR 4PCS ACTIVE SENSORS
JAZZ 15 FLOOR MAT CVT

JAZZ 15 STEP ILLUMINATION

REGISTRATION NO RETENTION
DVR,BLACKVUE 1 CHANNEL

100.00



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Vehicle - in
Kindly Help to arrange
Surveyor to survey this
vehicle thanks

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SCX366H
Chassis No : JHMGK5850FX203193
Model : JAZZ 1.5VTIR CVT 15YM (EURO 4)
Owner's Name : YET PEK SIM
Ins Policy No. : VA1/GA205530
Date of Accident : 8/1/2018

Document No. : SQT18000091 Page 1
Date : 8. Jan 2018
Customer No. : WA006
Svc Advisor : LIM CHOU SIONG
Engine No : L15B31000587
Date | Time : 8. Jan 2018 10:44:17 AM
Surveyor Name :
Survey Date :

Authorisation Date :
hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts before painting
Parts are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount Incl GST
BO-NUM-COMP-OPC-L	NUMBER PLATE WITH CASING-OPC-L / BT	1	45.00		45.00	3.15	48.15
60100-T5A-000ZZ	HOOD COMP / BUC	1	527.00	35	342.55	23.98	366.53
80050-SP0-000	LABELAIR CONDITIONER CAUTION / MC.	1	1.80	35	1.17	0.08	1.25
60120-TAR-000ZZ	HINGE COMP.R.HOOD = 4 BT	1	24.90	35	16.18	1.13	17.31
60170-TAR-000ZZ	HINGE COMPL.HOOD = 4 BT	1	24.90	35	16.18	1.13	17.31
74141-T5B-000	INSULATORHOOD / IN.	1	86.00	35	55.90	3.91	59.81
74147-T5A-000	GARNISH ASSYHOOD - cut	1	40.10	35	26.06	1.82	27.88
74198-T5A-000	GARNISH ASSYL.HOOD ?	1	14.10	35	9.16	0.64	9.80
74200-T5A-000	COWL TOP ASSYFR. - CAA	1	173.20	35	112.58	7.88	120.46
74192-T5A-000	RUBBERL.HOOD SEAL ?	1	4.10	35	2.66	0.19	2.85
60211-T5R-A00ZZ	PANELR.FR.FENDER = 4 BUC.	1	390.80	35	254.02	17.78	271.80
60261-T5R-A00ZZ	PANELL.FR.FENDER = 4 BUC.	1	390.80	35	254.02	17.78	271.80
60640-T5A-300ZZ	BRACKET,COMP R.FR.FENDER ?	1	43.00	35	27.95	1.96	29.91
60690-T5A-300ZZ	BRACKET COMP,L.FR.FENDER - BT	1	40.90	35	26.58	1.86	28.44
74150-T5A-000	FENDER ASSYL.FR INNER / DIS.	1	76.80	35	49.92	3.49	53.41
74155-T5A-J00	ENCLOSURE,L.FR.FENDER - ee	1	9999.99	35	6499.99	455.00	6954.99
74111-T5A-000	COVERENGINE UNDER - ee.	1	86.00	35	55.90	3.91	59.81
74165-T5A-010	GUARDL.FR.SPLASH - ee.	1	22.70	35	14.75	1.03	15.78
91501-TR0-003	CLIPINNER FENDER - MC.	10	2.30	35	14.95	1.05	16.00
60400-T5B-310ZZ	BULKHEAD COMPFR. - BUC.	1	374.30	35	243.29	17.03	260.32
08CLA-P9911LK8	COOLANTANTI-FREEZE / MC.	3	23.20	35	45.24	3.17	48.41



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
 Registration No : SCX366H
 Chassis No : JHMGK5850FX203193
 Model : JAZZ 1.5VTIR CVT 15YM (EURO 4)
 Owner's Name : YET PEK SIM
 Ins Policy No. : VA1/GA205530
 Date of Accident : 8/1/2018

Document No. : SQT18000091 Page 2
 Date : 8. Jan 2018
 Customer No. : WA006
 Svc Advisor : LIM CHOU SIONG
 Engine No : L15B31000587
 Date | Time : 8. Jan 2018 10:44:17 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
04684-T5A-300ZZ	EXTENSION SETL.FR. / RT	1	92.50	35	60.12	4.21	64.33
60710-T5A-300ZZ	MEMBER COMPL.FR.WHEELHOUSE / Bue.	1	70.00	35	45.50	3.19	48.69
60750-T5A-315ZZ	HOUSING COMPL.FR.DAMPER / Bue.	1	225.90	35	146.83	10.28	157.11
60912-T5A-300ZZ	PLATEL.FR.BACK ?	1	105.50	35	68.57	4.80	73.37
60944-T5A-300ZZ	PLATEL.SIDE FRAME ?	1	30.20	35	19.63	1.37	21.00
60945-T5A-300ZZ	GUSSETL.FR.SIDE - RT.	1	45.20	35	29.38	2.06	31.44
60910-T5A-J01ZZ	FRAME COMPL.FR. ?	1	448.60	35	291.59	20.41	312.00
04641-TAS-300ZZ	PANEL SETL.SIDE SILL / Bue.	1	232.30	35	150.99	10.57	161.56
71850-T5B-003ZB	GARNISH ASSYL.SIDE SILL / Bue.	1	363.60	35	236.34	16.54	252.88
67550-TAR-306ZZ	PANEL COMPL.RR.DOOR / Bue.	1	676.10	35	439.46	30.76	470.22
67865-T5A-003	TAPEL.RR.DOOR SASH / Bue.	1	15.40	35	10.01	0.70	10.71
73371-T5A-003	GLASSL.FR.CORNER / SM	1	208.60	35	135.59	9.49	145.08
73336-T5A-003	RUBBER.L.WINDSHIELD DAMPER /	1	36.10	35	23.46	1.64	25.10
73525-SYY-000	RUBBERRR.QTR.W/SHIELD /	1	9.50	35	6.17	0.43	6.60
91513-T5A-003	CLIPFR.CORN.WINDSHIELD /	3	3.60	35	7.02	0.49	7.51
73111-TAR-J02	GLASS SET.FR.WINDSHIELD / CRA	1	1384.50	35	899.92	62.99	962.91
73129-T5A-000	SEALFR.INSTRUMENT /	1	4.70	35	3.05	0.21	3.26
73150-T5A-J01	MOLDINGFR.WINDSHIELD UPPER /	1	16.20	35	10.53	0.74	11.27
73151-T5A-003	MOLDINGFR.WINDSHIELD LOWER /	1	39.80	35	25.87	1.81	27.68
73225-TM8-000	RUBBER.AWINDSHIELD DAM /	2	3.60	35	4.68	0.33	5.01
91568-SWA-A01	CLIPFR.WINDSHIELD UPPER /	2	4.40	35	5.72	0.40	6.12
BO-WS-SEALANT	WINDSCREEN SEALANT (N) /	2	60.00		120.00	8.40	128.40
71105-T5A-000	COVERFR.GRILLE / Bue.	1	11.80	35	7.67	0.54	8.21
71120-TAS-003	GRILLE ASSYFR. / CRA	1	288.90	35	187.78	13.14	200.92
91505-TM8-003	CLIPBUMPER / Bue.	20	2.00	35	26.00	1.82	27.82
04711-T5A-000ZZ	FACEFR.BUMPER / M.S.	1	494.70	35	321.55	22.51	344.06
71102-T5A-000	LOWER GRILLEFR.BUMPER / Bue.	1	27.50	35	17.87	1.25	19.12
71103-T5A-N00	GARNISHR.FR.BUMPER ?	1	23.30	35	15.14	1.06	16.20
71108-T5A-N00	GARNISHL.FR.BUMPER / M.S.	1	23.30	35	15.14	1.06	16.20
71110-T5A-000	SPOILERFR.BUMPER LIP / Bue.	1	56.30	35	36.59	2.56	39.15

Printed on 9/1/2018 7:19:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SCX366H

Chassis No : JHMGK5850FX203193

Model : JAZZ 1.5VTIR CVT 15YM (EURO 4)

Owner's Name : YET PEK SIM

Ins Policy No. : VA1/GA205530

Date of Accident : 8/1/2018

Document No. : SQT18000091 Page 3

Date : 8. Jan 2018

Customer No. : WA006

Svc Advisor : LIM CHOU SIONG

Engine No : L15B31000587

Date | Time : 8. Jan 2018 10:44:17 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
71130-T5A-000ZZ	BEAM COMPFR.BUMPER / BT	1	219.40	35	142.61	9.98	152.59
71140-T5A-000	BRACKETR.HEADLIGHT / ee	1	23.60	35	15.34	1.07	16.41
71190-T5A-000	BRACKETL.HEADLIGHT / Dis.	1	21.90	35	14.23	1.00	15.23
71145-T5A-000	BASEFR.LICENCE PLATE / BT	1	50.90	35	33.08	2.32	35.40
71193-T5A-000	SPACERR.FR.BUMPER / } mcl	1	10.40	35	6.76	0.47	7.23
71198-T5A-000	SPACERL.FR.BUMPER / }	1	10.40	35	6.76	0.47	7.23
71107-T5A-000	DUCTL.FR.BUMPER SIDE / ee	1	10.80	35	7.02	0.49	7.51
71106-T5A-000	DUCTR.FR.BUMPER SIDE / ?	1	12.90	35	8.38	0.59	8.97
80525-T2F-A01	SENSOR ASSYAMBIENT / ?	1	42.60	35	27.69	1.94	29.63
91555-SL0-A01	CLIPCOUPLER / mcl	1	2.60	35	1.69	0.12	1.81
80311-T5A-003	HOSE COMPSUCTION / ?	1	121.50	35	78.97	5.53	84.50
80315-T5B-003	HOSE COMPDISCHARGE / ?	1	141.90	35	92.23	6.46	98.69
80341-T5A-003	PIPE COMPRECEIVER / ?	1	109.70	35	71.30	4.99	76.29
50850-T9A-003	RUBBER ASSYTRANSMISSION MTG / ?	1	108.20	35	70.33	4.92	75.25
50690-T5A-003	BRACKETTORQUE ROD CVT / ?	1	34.80	35	22.62	1.58	24.20
80100-T5B-003	CONDENSER ASSY / Cut	1	704.40	35	457.86	32.05	489.91
19010-5R1-901	RADIATOR COMP / ?	1	1187.40	35	771.81	54.03	825.84
19015-5R1-003	SHROUD COMP / ?	1	89.30	35	58.04	4.06	62.10
38615-5R1-003	SHROUD COMP / ?	1	44.90	35	29.18	2.04	31.22
31521-T5A-000	BOXBATTERY / } Cut	1	5.70	35	3.70	0.26	3.96
31531-T5A-003	COVERBATTERY / }	1	7.70	35	5.00	0.35	5.35
33100-T5A-J21	HEADLIGHT ASSY.R. / ?	1	1118.60	35	727.09	50.90	777.99
33150-T5A-J21	HEADLIGHT ASSYL / Dis.	1	1118.60	35	727.09	50.90	777.99
33900-TY0-003	LIGHT ASSY FR.FOG / NAH / n.s.	1	261.90	35	170.23	11.92	182.15
33650-T5A-003	LIGHT ASSY L.FR.POSITION / Dis.	1	180.60	35	117.39	8.22	125.61
BB-42B20L	BATTERY - MAINTENANCE FREE / ?	1	114.00		114.00	7.98	121.98
51216-T5A-J11	KNUCKLEL.FR. / BT	1	107.40	35	69.81	4.89	74.70
44300-T5A-951	BEARING ASSYFR.HUB / mcl	1	49.50	35	32.17	2.25	34.42
51360-T5A-J11	ARM ASSYL.FR.LOWER / BT	1	151.80	35	98.67	6.91	105.58
51325-T5A-003	LINK COMPL.FR.STABILIZER / BT.	1	43.10	35	28.01	1.96	29.97

Printed on 9/1/2018 7:19:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
 Registration No : SCX366H
 Chassis No : JHMGK5850FX203193
 Model : JAZZ 1.5VTIR CVT 15YM (EURO 4)
 Owner's Name : YET PEK SIM
 Ins Policy No. : VA1/GA205530
 Date of Accident : 8/1/2018

Document No. : SQT18000091 Page 4
 Date : 8. Jan 2018
 Customer No. : WA006
 Svc Advisor : LIM CHOU SIONG
 Engine No : L15B31000587
 Date | Time : 8. Jan 2018 10:44:17 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
57455-T5A-013	SENSOR ASSYL.FR. ?	1	158.60	35	103.09	7.22	110.31
51621-T5A-J14	DAMPER UNITL.FR. - BT	1	292.60	35	190.19	13.31	203.50
45256-T5B-000	GRARDL.FR.BRAKE SPLASH ?	1	6.30	35	4.09	0.29	4.38
44306-T5B-000	DRIVESHAFT ASSYL. - BT } - photo.	1	961.60	35	625.04	43.75	668.79
50200-T5A-J03	SUB FRAME COMP - BT	1	740.00	35	481.00	33.67	514.67
53400-TAR-T01	BOX ASSYSTEEERING GEAR ?	1	1148.70	35	746.65	52.27	798.92
53410-T5B-003	END COMPRACK - 40T	1	88.70	35	57.65	4.04	61.69
53560-T5A-003	END COMPTIE ROD	1	71.80	35	46.67	3.27	49.94
01465-T5A-010	HOSE SETFR.BRAKE ?	1	55.70	35	36.20	2.53	38.73
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J - Act.	1	819.60	35	532.74	37.29	570.03
77810-T5A-N81ZA	MODULE ASSYDRIVER	1	1640.30	35	1066.19	74.63	1140.82
77820-T5A-J80	MODULE ASSYPASSENGER	1	2236.80	35	1453.92	101.77	1555.69
77100-T5A-J10ZA	PANEL COMPINSTRUMENT	1	718.50	35	467.02	32.69	499.71
81450-TAR-U01ZD	TONGUE ASSYR.FR.SEATBELT	1	445.90	35	289.83	20.29	310.12
81850-TAR-U01ZC	TONGUE ASSYL.FR.SEATBELT	1	445.90	35	289.83	20.29	310.12
77930-T5A-J01	SENSOR ASSYFR.CRASH - DM	2	61.50	35	79.95	5.60	85.55
77960-T5A-J41	SRS UNITREWRITABLE - Act	1	806.70	35	524.35	36.70	561.05
D-185/55R16SP2030	DUNLOP TYRE - Act	1	206.00		206.00	14.42	220.42
Sum Item					22691.69	1,688.41	24,280.10

BO-NUM-SEAL	SEAL NUMBER PLATE - BT	1	80.00		80.00	5.60	85.60
BO-TOW-SW	TOWING SERVICE (AFTER OFFICE HOUR, WINCH OUT)	1	130.00		130.00	9.10	139.10
BO-R-COOL-FRQ	SUPPLY & INSTALL SOLAR FILM ON FRONT QTR GLASS.	1	160.00		160.00	11.20	171.20
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
BO-R-COOL-FWS	SUPPLY & INSTALL SOLAR FILM ON FRONT WINDSCREEN.	1	280.00		280.00	19.60	299.60
Sum Ext. Service					830.00	58.10	888.10

BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	80.00		80.00	5.60	85.60

Printed on 9/1/2018 7:19:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
 Registration No : SCX366H
 Chassis No : JHMGK5850FX203193
 Model : JAZZ 1.5VTIR CVT 15YM (EURO 4)
 Owner's Name : YET PEK SIM
 Ins Policy No. : VA1/GA205530
 Date of Accident : 8/1/2018

Document No. : SQT18000091 Page 5
 Date : 8. Jan 2018
 Customer No. : WA006
 Svc Advisor : LIM CHOU SIONG
 Engine No : L15B31000587
 Date | Time : 8. Jan 2018 10:44:17 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	/	100.00	7.00	107.00
BG41R	REPLACE FR. L QTR GLASS (N)	1	180.00	/	180.00	12.60	192.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	180.00	/	180.00	12.60	192.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	1	230.00	/	230.00	16.10	246.10
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	180	250.00	17.50	267.50
BG01R	REPLACE FR. WINDSCREEN (N)	1	280.00	/	280.00	19.60	299.60
BOMISC1	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	1	280.00	/	280.00	19.60	299.60
BMI02D	REMOVE & INSTALL CARPET, FR L SEATS, RR L SEAT.	1	320.00	/	320.00	22.40	342.40
BKDR21R	REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST	1	350.00	/	350.00	24.50	374.50
BMS00R	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU &	1	450.00	/	450.00	31.50	481.50
BMU01R	REMOVE & REPLACE FR SUBFRAME & STEERING RACK, ASSY.	1	650.00	/	650.00	45.50	695.50
BMU11R	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS (N)	1	650.00	/	650.00	45.50	695.50
BME00D	REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS	1	1000.00	(900) S	1000.00	70.00	1070.00
BMI00R	REMOVE & RENEW DASHBOARD EVAPORATOR UNIT	1	1000.00	/	1000.00	70.00	1070.00
BKOT00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	1	1200.00	photo /	1200.00	84.00	1284.00
BKBH11B	CUT OFF & RENEW BULKHEAD FR L HOUSING COMP., FR L	1	6500.00	5400	6500.00	455.00	6955.00
BP06R	SPRAY PAINTING ON FR BUMPER, BONNET, FR L SPRAY,	1	4500.00	3500	4500.00	315.00	4815.00
BOJSE	BODY JOINT SEALANT.	3	80.00	/	240.00	16.80	256.80
Sum Labor					18470.00	1,292.90	19,762.90

Survey By : Gye Qianf - 82880282
 Date & Time : 11/01/2018
 Excess : \$800
 Status : Not Authorized
 Signature : 23 - 24 Days.

Total Amount 41,991.69 2,939.41 44,931.10
 Total (Inclusive of GST) 44,931.10

before paint photos.

Printed on 9/1/2018 7:19:18 PM

This is a computer generated invoice. No signature is required.
 Part prices are subjected to change without notice.
 The above estimated cost of repair do not include any unforeseen damages.
 GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	: AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.:	: SQT18000091	Page	6
Registration No	: SCX366H	Date	: 8. Jan 2018		
Chassis No	: JHMGK5850FX203193	Customer No.	: WA006		
Model	: JAZZ 1.5VTIR CVT 15YM (EURO 4)	Svc Advisor	: LIM CHOU SIONG		
Owner's Name	: YET PEK SIM	Engine No	: L15B31000587		
Ins Policy No.	: VA1/GA205530	Date Time	: 8. Jan 2018 10:44:17 AM		
Date of Accident	: 8/1/2018	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount Incl GST
------	-------------	-----	------------	--------	--------	---------	-----------------

C S Lim

81006303 (401)

Engine Room Harness wire ?

Resonator chamber - CPA

Headlight adjuster⁴¹ - BT

Printed on 9/1/2018 7:19:18 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05715

Your Reference : GA205530/1
Accident Date : 08-Jan-2018

Date : 19-Jan-2018

Our Ref : 218016 / UHAN

PAGE : 1

AXA INSURANCE SINGAPORE PRIVATE LIMITED
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

Gua Bup.
20/1/18.

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5VTIR CVTABS SCX366H

1 pc	Passenger air bag / <i>Act</i>	1,640.30 /
1 pc	Steering air bag / <i>Act</i>	2,236.80 /
1 pc	Steering air bag coil spring / <i>Act</i>	268.90 /
1 pc	Steering air bag sensor / <i>Act</i>	223.80 /
1 pc	Front n/s chassis a/bag sensor / <i>Act</i>	223.80 /
1 pc	Air bag control unit / <i>Act</i>	806.70 /
2 pcs	Front safety belt / <i>Act</i>	891.80 /
1 pc	Gear level centre console / <i>CCA</i>	205.50X /
1 pc	Front instrument panel / <i>CCA</i>	718.50 /
1 pc	N/s dashboard lower cover / <i>CCA</i>	122.40X /
1 pc	Front windscreen glass / <i>CCA</i>	1,469.20 /
1 pc	Front w/s glass moulding / <i>CCA</i>	145.00 /
1 pc	Front wiper garnish / <i>CCA</i>	173.20 /
1 pc	Bonnet / <i>CCA</i>	527.00 /
1 pc	Bonnet insulator / <i>CCA</i>	86.00 /
1 pc	O/s bonnet garnish / <i>CCA</i>	40.10 /
1 pc	Bonnet inner lock / <i>CCA</i>	87.70 /
2 pcs	Bonnet hinge / <i>BT</i>	49.80 /
2 pcs	Front fender / <i>CCA</i>	813.20 /
1 pc	Front n/s fender side support / <i>BT</i>	85.20 /
1 pc	Front n/s fender inner garnish / <i>BT</i>	36.30 /
1 pc	Frt n/s fender inner panel-in / <i>CCA</i>	92.50 /
1 pc	Frt n/s fender inner panel-out / <i>CCA</i>	70.00 /
1 pc	Frt n/s inner panel support(in) / <i>CCA</i>	30.20 /
1 pc	Frt n/s inner panel support(out) / <i>CCA</i>	45.20 /
1 pc	Front n/s chassis member / <i>BT</i>	466.70 /
1 pc	N/s chassis member outer panel / <i>BT</i>	105.50 /
1 pc	Front n/s fender inner shield / <i>CCA</i>	76.80 /

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : GA205530/1

Page : 2

1 pc	Engine under cover complete	ee	180.60	/
1 pc	Front n/s quarter glass	SM	208.60	/
1 pc	Frt n/s quarter glass moulding	mc	55.50	/
1 pc	Front n/s side skirt	ee	363.60	/
1 pc	N/s rocker panel	Buc	232.30	/
1 pc	Front n/s door	X Part Repair	860.40	X
2 pcs	Front n/s door hinge	X	76.00	X
1 pc	Front n/s door frame tape	X	25.40	X
1 pc	Rear n/s door	Buc	703.40	/
1 pc	Rear n/s door tape	mc	15.40	/
1 pc	Rear n/s door glass regulator	X - or.	151.80	? ✓
2 pcs	Headlamp	CH-Dis	2,237.20	118.6 x 2
1 pc	N/s headlamp bracket	X - BT	23.60	? ✓
1 pc	N/s headlamp adjuster sensor	X - DM	279.60	? ✓
1 pc	Front support panel	BT	376.30	? ✓
1 pc	Radiator -auto	X	1,187.40	? ✓
1 pc	Radiator fan cowling	X	89.30	? } X
1 pc	Radiator fan motor	X	119.90	? } X
1 pc	Radiator fan blade	X	45.50	? } X
1 pc	Radiator top hose	X	26.80	? } X
1 pc	Radiator lower hose	X	16.80	? } X
1 pc	Air con condenser	Cut	704.40	/
1 pc	Air con condenser fan cowling	X	44.90	? } X
1 pc	Air con condenser fan motor	X	286.10	? } X
1 pc	Air con condenser fan blade	X	49.20	? } X
1 pc	Air con suction hose	X	121.50	? ✓
1 pc	Air con discharge hose	X - BT	141.90	? ✓
1 pc	Air con liquid pipe	X - NN	109.70	? X
1 pc	Front bumper fascia	Dis	494.70	/
1 pc	Front bumper lower lip	ee	56.30	/
1 pc	Front n/s bumper side retainer	Dis	10.40	/
1 pc	Front bumper reinforcement	BT	219.40	/
1 pc	Front bumper lower grille	ee	27.50	/
1 pc	Frt bumper no.plate garnish	ee	50.90	/
1 pc	Front bumper n/s side guide	X - ee	10.80	? ✓
1 pc	Front bumper n/s foglamp	X	261.90	/
1 pc	Front bumper n/s day lamp	X - Dis.	180.60	/

Con't Page 3 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : GA205530/1

Page : 3

1 pc	Front bumper n/s foglamp cover	mis	23.30	/
1 pc	Radiator grille assy	CRA	288.90	/
6 pcs	Radiator grille clip	ABC @ S\$ 3.20	19.20	/
1 pc	Radiator grille top cover	RE	11.80	/
1 pc	Lh engine mounting	TN	108.20	?/✓
1 pc	Lh engine mounting bracket	BT	34.80	?/✓
1 pc	Rh engine mounting	TN	124.00	?/✓
1 pc	Gear box mounting & Rear mounting	BT	108.20	?/✓
1 pc	Front n/s shock absorber		292.60	/
1 pc	Front n/s lower arm		151.80	/
1 pc	Front n/s knuckle arm		187.40	/
1 pc	Front n/s knuckle bearing hup	BT	138.30	/
1 pc	Front n/s wheel bearing		79.50	/
1 pc	Front stabiliza bar		169.90	/
1 pc	Front n/s stabiliza bar link		43.10	/
1 pc	Front n/s drive shaft		961.60	/
1 pc	Steering rack n pinon	BT	1,148.70	?/✓
1 pc	Front engine cross member	BT	740.00	/
1 pc	wire harness1	NN	653.90	?/X
1 pc	Front n/s sport rim	Cut	819.60	/
			27,888.50	19989.1
Less 20% :			5,577.70	15991.28
				22,310.80
1 pc	Front w/s glass sealant		60.00	sn
1 pc	ERP ID bracket		25.00	sn
1 pc	Front n/s quarter glass sealant		30.00	sn
1 pc	Radiator coolant		30.00	sn
2 pcs	Auto gear box oil	@ S\$ 20.00	40.00	sn
1 pc	Front weekend plate with box		50.00	sn
1 pc	Front n/s tyre	Cut	150	300.00 sn
				285
To towing			60.00	/
To rewire damaged parts and refocus headlamp beam.			250.00	80

Con't Page 4 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : GA205530/1

Page : 4

To remove & renew front windscreen glass and conduct water leak test.	150.00	200
To remove roof lining, front and rear seats, trim board and carpet	120.00	80
To remove air con condenser, pipes and drier, vacuum and to recharge gas.	120.00	100
To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.	200.00	/
To remove and lift up engine assy.	400.00	350
To dismantle and lower front undercarriage	250.00	/
To check and adjust wheel alignment	80.00	60
To check chassis alignment — take photos.	300.00	250 X
To putty and spray replaced parts	1,800.00	1500
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	2,200.00	2000
To remove front weekend no. plate, reseal and send for inspection	100.00	/
To remove, renew front seat belt, Steering air bag, passenger air bag, air bag sensor, air bag control unit, air bag sensor wire, diagnostic & reset air bag system	250.00	/
Total :		SS29,125.80

Singapore Dollars Twenty Nine Thousand One Hundred and Twenty Five and Cents Eighty Only

Guo Qiang (kk)
82880282

21506.28
2%: 17200
Max repair limit \$20K

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : GA205530/1

Date : 26-01-2018

Accident Date : 08-01-2018

Our Ref : 218016 /CHAN

AXA INSURANCE SINGAPORE PRIVATE LIMITED

8 SHENTON WAY

27-01 AXA TOWER

SINGAPORE 068811

SUPPLEMENTARY ITEM PRICE FOR HONDA JAZZ 1.5VTIR CVTABS SOX366H

1 PC	N/S LOWER RESONATOR BOX	/ WA	\$87.70
1 PC	N/S STABILIZA BAR BRACKET	/ BT.	\$9.50
1 PC	N/S STABILIZA BAR BRACKET BUSH	/	\$11.60
			\$108.80
		LESS 20%	\$21.76
			<u>\$87.04</u>

Gu. Q. 4
29/1/18 .

Singapore Dollars Eighty Seven And Cents Four Only

Shiau Chan (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Monday, 26 February 2018 8:58 AM
To: Guo Qiang (LKKAUTO); Shiau Chan (LKKAUTO)
Cc: alan khong chin wah; SUR
Subject: RE: ATTACHED SCX366H AFTER REPAIR PHOTO ,FINAL AMOUNT FOR FINALIZE (AXA OWN DAMAGED CLAIM) ***LKK REF:CS/ASM18000585/Gqb

Dear Guo Qiang / Shiau Chan,

For your information and necessary action please.

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: alan khong chin wah [mailto:alanauto@gmail.com]
Sent: Friday, 23 February 2018 3:03 PM
To: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Subject: Re: ATTACHED SCX366H AFTER REPAIR PHOTO ,FINAL AMOUNT FOR FINALIZE (AXA OWN DAMAGED CLAIM) ***LKK REF:CS/ASM18000585/Gqb

Dear Shu Pei

May I know when can I have the finalize ,thank you .

Regards

Kenny

Alan's United Auto pte Ltd

64538686

On Thu, Feb 22, 2018 at 12:56 PM, Shu Pei (LKKAUTO) <shupeil@lkkauto.com> wrote:

Dear Kenny,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Guo Qiang / Shiau Chan,

For your information and necessary action please.

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: alan khong chin wah [mailto:alanauto@gmail.com]

Sent: Thursday, 22 February 2018 10:53 AM

To: Admin A <admin-a@lkkauto.com>

Subject: ATTACHED SCX366H AFTER REPAIR PHOTO ,FINAL AMOUNT FOR FINALIZE (AXA OWN DAMAGED CLAIM)

Dear Guo Qiang

Attached the above vehicle after repair photo , final amount for your finalize , total L/SUM \$20800.00 please confirm thank you .

Regards

Kenny

Alan's United Auto Pte Ltd

64538686

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : GA205530/1
Accident Date : 08-Jan-2018

No. : 05715

Date : 19-Jan-2018

Our Ref : 218016 / CHAN

PAGE : 1

AXA INSURANCE SINGAPORE PRIVATE LIMITED
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

Guo Rui.
20/1/18.

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5VTIR CVTABS SCX366H

1 pc	Passenger air bag	/ <i>Act</i>	1,640.30 /
1 pc	Steering air bag	/ <i>Act</i>	2,236.80 /
1 pc	Steering air bag coil spring	/	268.90 /
1 pc	Steering air bag sensor	/ <i>Act</i>	223.80 /
1 pc	Front n/s chassis a/bag sensor	/	223.80 /
1 pc	Air bag control unit	/ <i>Act</i>	806.70 /
2 pcs	Front safety belt	/ <i>Act</i> @ S\$445.90	891.80 /
1 pc	Gear level centre console	Act <i>CCA</i>	205.50 X /
1 pc	Front instrument panel	<i>CCA</i>	718.50 /
1 pc	N/s dashboard lower cover	X <i>NRV</i>	122.40 X
1 pc	Front windscreen glass	<i>CCA</i>	1,469.20 /
1 pc	Front w/s glass moulding	NRV	145.00 /
1 pc	Front wiper garnish	<i>CCA</i>	173.20 /
1 pc	Bonnet	<i>me</i>	527.00 /
1 pc	Bonnet insulator	<i>TV</i>	86.00 /
1 pc	O/s bonnet garnish	<i>CCA</i>	40.10 /
1 pc	Bonnet inner lock	<i>BT</i>	87.70 /
2 pcs	Bonnet hinge	<i>BT</i> @ S\$ 24.90	49.80 /
2 pcs	Front fender	<i>me</i> @ S\$406.60	813.20 /
1 pc	Front n/s fender side support	<i>BT</i>	85.20 /
1 pc	Front n/s fender inner garnish	<i>BT</i> <i>BR</i>	36.30 /
1 pc	Frt n/s fender inner panel-in	<i>50.5</i>	92.50 /
1 pc	Frt n/s fender inner panel-out	<i>50.5</i>	70.00 /
1 pc	Frt n/s inner panel support(in	<i>50.5</i>	30.20 /
1 pc	Frt n/s inner panel support(O)	<i>BT</i>	45.20 /
1 pc	Front n/s chassis member	<i>BT</i>	466.70 /
1 pc	N/s chassis member outer panel	<i>BT</i>	105.50 /
1 pc	Front n/s fender inner shield	<i>CC</i>	76.80 /

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05715

Your Reference : GA205530/1
Accident Date : 08-Jan-2018

Date : 19-Jan-2018

Our Ref : 218016 / CHAN

PAGE : 1

AXA INSURANCE SINGAPORE PRIVATE LIMITED
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5VTIR CVTABS SCX366H

1 pc	Passenger air bag	/ Act	1,640.30 /
1 pc	Steering air bag	/	2,236.80 /
1 pc	Steering air bag coil spring	/	268.90 /
1 pc	Steering air bag sensor	/ Act	223.80 /
1 pc	Front n/s chassis a/bag sensor	/	223.80 /
1 pc	Air bag control unit	/ Act	806.70 /
2 pcs	Front safety belt	/ @ S\$445.90	891.80 /
1 pc	Gear level centre console	X NV	205.50 X
1 pc	Front instrument panel	/ CFA	718.50 /
1 pc	N/s dashboard lower cover	X NV	122.40 X
1 pc	Front windscreen glass	/ CFA	1,469.20 /
1 pc	Front w/s glass moulding	/ NV	145.00 /
1 pc	Front wiper garnish	/ CFA	173.20 /
1 pc	Bonnet	/ BNC	527.00 /
1 pc	Bonnet insulator	/ TV	86.00 /
1 pc	O/s bonnet garnish	/ Cut	40.10 /
1 pc	Bonnet inner lock	/ BT	87.70 /
2 pcs	Bonnet hinge	/ BT @ S\$ 24.90	49.80 /
2 pcs	Front fender	/ BNC @ S\$406.60	813.20 /
1 pc	Front n/s fender side support	/ BT	85.20 /
1 pc	Front n/s fender inner garnish	/ ?	36.30 /
1 pc	Frt n/s fender inner panel-in	/ 40.5	92.50 /
1 pc	Frt n/s fender inner panel-out	/	70.00 /
1 pc	Frt n/s inner panel support(in)	/ 40.5	30.20 /
1 pc	Frt n/s inner panel support(0)	/	45.20 /
1 pc	Front n/s chassis member	/ ?	466.70 ?
1 pc	N/s chassis member outer panel	/ ?	105.50 ?
1 pc	Front n/s fender inner shield	/ BNC	76.80 /

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : 64205530/1

Page : 2

1 pc	Engine under cover complete	ee	180.60	/
1 pc	Front n/s quarter glass	SM	208.60	/
1 pc	Frt n/s quarter glass moulding	mc	55.50	/
1 pc	Front n/s side skirt	ee	363.60	/
1 pc	N/s rocker panel	mc	232.30	/
1 pc	Front n/s door	X mc repair	860.40	X
2 pcs	Front n/s door hinge	X	76.00	X
1 pc	Front n/s door frame tape	X June S\$ 38.00	25.40	X
1 pc	Rear n/s door	mc	703.40	/
1 pc	Rear n/s door tape	mc	15.40	/
1 pc	Rear n/s door glass regulator	X - or	151.80	? ✓
2 pcs	Headlamp	mc / dis		
1 pc	N/s headlamp bracket	X - BT	2,237.20	1118.6 X 2
1 pc	N/s headlamp adjuster sensor	X - dm	23.60	? ✓
1 pc	Front support panel	X - BT	279.60	? ✓
1 pc	Radiator - auto	X	376.30	/
1 pc	Radiator fan cowling	X	1,187.40	? ✓
1 pc	Radiator fan motor	X	89.30	? X
1 pc	Radiator fan blade	X	119.90	? X
1 pc	Radiator top hose	X	45.50	? X
1 pc	Radiator lower hose	X	26.80	? X
1 pc	Air con condenser	cut	16.80	? X
1 pc	Air con condenser fan cowling	X	704.40	/
1 pc	Air con condenser fan motor	X	44.90	? X
1 pc	Air con condenser fan blade	X	286.10	? X
1 pc	Air con suction hose	X	49.20	? X
1 pc	Air con discharge hose	X - BT	121.50	? X
1 pc	Air con liquid pipe	X	141.90	? ✓
1 pc	Front bumper fascia	dis	109.70	? X
1 pc	Front bumper lower lip	ee	494.70	/
1 pc	Front n/s bumper side retainer	dis	56.30	/
1 pc	Front bumper reinforcement	BT	10.40	/
1 pc	Front bumper lower grille	ee	219.40	/
1 pc	Frt bumper no. plate garnish	mc	27.50	/
1 pc	Front bumper n/s side guide	X - ee	50.90	/
1 pc	Front bumper n/s foglamp	X	10.80	? ✓
1 pc	Front bumper n/s day lamp	dis	261.90	/
			180.60	/

Con't Page 3 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : GA205530/1

Page : 3

1 pc	Front bumper n/s foglamp cover / <i>mis</i>	23.30 /	
1 pc	Radiator grille assy / <i>CPA</i>	288.90 /	
6 pcs	Radiator grille clip / <i>MC</i>	19.20 /	
1 pc	Radiator grille top cover / <i>RL</i>	11.80 /	
1 pc	Lh engine mounting / <i>?</i>	108.20 /	✓
1 pc	Lh engine mounting bracket / <i>?</i>	34.80 /	✓
1 pc	Rh engine mounting / <i>?</i>	124.00 /	✓
1 pc	Gear box mounting / <i>8 Rear mounting</i>	108.20 /	✓
1 pc	Front n/s shock absorber	292.60 /	
1 pc	Front n/s lower arm	151.80 /	
1 pc	Front n/s knuckle arm	187.40 /	
1 pc	Front n/s knuckle bearing hub	138.30 /	
1 pc	Front n/s wheel bearing	79.50 /	
1 pc	Front stabiliza bar	169.90 /	
1 pc	Front n/s stabiliza bar link	43.10 /	
1 pc	Front n/s drive shaft	961.60 /	
1 pc	Steering rack n pinon / <i>BT</i>	1,148.70 /	✓
1 pc	Front engine cross member	740.00 /	
1 pc	wire harness / <i>8</i>	653.90 /	×
1 pc	Front n/s sport rim	819.60 /	
		27,888.50	19989.1
	Less 20% :	5,577.70	15991.28
			22,410.80
1 pc	Front w/s glass sealant		60.00 sn
1 pc	ERP IU bracket		25.00 sn
1 pc	Front n/s quarter glass sealant		30.00 sn
1 pc	Radiator coolant		30.00 sn
2 pcs	Auto gear box oil		40.00 sn
1 pc	Front weekend plate with box		50.00 sn
1 pc	Front n/s tyre		150 300.00 sn
			285
	To towing		60.00 /
	To rewire damaged parts and refocus headlamp beam.		250.00 80

Con't Page 4

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : GA205530/1

Page : 4

To remove & renew front windscreen glass and conduct water leak test.	150.00 20
To remove roof lining, front and rear seats, trim board and carpet	120.00 80
To remove air con condenser, pipes and drier, vacuum and to recharge gas	120.00 100
To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.	200.00 /
To remove and lift up engine assy.	400.00 350
To dismantle and lower front undercarriage	250.00 /
To check and adjust wheel alignment	80.00 60
To check chassis alignment — take photos.	300.00 250 R
To putty and spray replaced parts	1,800.00 1500
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	2,200.00 2000
To remove front weekend no. plate, reseal and send for inspection	100.00 /
To remove, renew front seat belt, Steering air bag, passenger air bag, air bag sensor, air bag control unit, air bag sensor wire, diagnostic & reset air bag system	5130 250.00 /
Total :	S\$29,125.80

Singapore Dollars Twenty Nine Thousand One Hundred and Twenty Five and Cents Eighty Only

Kuo Xiang (Lkk) P20192.56

80880282

S.P 87.04

SN 385.00

L 5380

76044.60

52080.92

20835.65

21506.28

21%: 17200

Max repair limit 720K

L/sum

20,800.00

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

TAX INVOICE

No. : 225156

Date : 07.05.2018

PAGE : 1

Your Reference : GA205530/1
Accident Date : 08-Jan-2018

Our Ref : 218016 / CHAN

AXA INSURANCE SINGAPORE PRIVATE LIMITED
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

FINAL REPAIR COST FOR HONDA JAZZ 1.5VTIR CVTABS SCX366H
=====

To supply spare parts

To towing

To rewire damaged parts and refocus
headlamp beam.

To remove & renew front windscreen
glass and conduct water leak test.

To remove roof lining, front and
rear seats, trim board and carpet

To remove air con condenser, pipes
and drier, vacuum and to recharge
gas

To remove and renew front
instrument panel assy, to rewiring
and transfer instrument fittings.

To remove and lift up engine assy.

To dismantle and lower front
undercarriage

Con't Page 2

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : GA205530/1

Page : 2

To check and adjust wheel alignment

To check chassis alignment

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

To remove front weekend no. plate,
reseal and send for inspection

To remove, renew front seat belt,
Steering air bag, passenger air bag,
air bag sensor, air bag control unit
, air bag sensor wire, diagnostic &
reset air bag system

	20,000.00
Less Excess	800.00

	19,200.00
Add 7% GST :	1,344.00

Total :	S\$20,544.00
	=====

Singapore Dollars Twenty Thousand Five Hundred
and Forty Four Only

AXA INSURANCE PTE LTD
MOTO CLAIMS DEPARTMENT
8 SHENTON WAY #24-01
AXA TOWER
SINGAPORE 068811.

DATE: 10-2-2018

SATISFACTION & DISCHARGE VOUCHER

I / WE HEREBY DECLARE THAT THE REPAIRS TO MY / OUR HONDA JAZZ
VEHICLE NO. SCX 366H HAVE BEEN COMPLETED TO MY / OUR

SATISFACTION AND I / WE AGREED THAT THE PAYMENT OF AMOUNT SIN DLRS:

TWENTY THOUSAND FIVE HUNDRED FORTY FOUR ONLY -

PAID TO M/S ALAN'S UNITED AUTO PTE LTD., OF BLK 7 SIN MING INDUSTRIAL
ESTATE, #01-76, SINGAPORE 575642., FOR SUCH REPAIRS ARE IN FULL DISCHARGE
OF OUR CLAIM UNDER POLICY NO. 6A205530/1 IN RESPECT OF
THE DAMAGES CAUSED IN THE ACCIDENT WHICH OCCURRED ON 08-01-2018

SS 20,544.00

7-Pch
SIGNATURE OF INSURED