

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

TAX INVOICE

No. : 225156

Date : 07.05.2018

PAGE : 1

Your Reference : GA205530/1
Accident Date : 08-Jan-2018

Our Ref : 218016 / CHAN

AXA INSURANCE SINGAPORE PRIVATE LIMITED
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

FINAL REPAIR COST FOR HONDA JAZZ 1.5VTIR CVTABS SCX366H
=====

To supply spare parts

To towing

To rewire damaged parts and refocus
headlamp beam.

To remove & renew front windscreen
glass and conduct water leak test.

To remove roof lining, front and
rear seats, trim board and carpet

To remove air con condenser, pipes
and drier, vacuum and to recharge
gas

To remove and renew front
instrument panel assy, to rewiring
and transfer instrument fittings.

To remove and lift up engine assy.

To dismantle and lower front
undercarriage

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : GA205530/1

Page : 2

To check and adjust wheel alignment

To check chassis alignment

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

To remove front weekend no. plate,
reseal and send for inspection

To remove, renew front seat belt,
Steering air bag, passenger air bag,
air bag sensor, air bag control unit
, air bag sensor wire, diagnostic &
reset air bag system

	20,000.00
Less Excess	800.00

	19,200.00
Add 7% GST :	1,344.00

Total :	S\$20,544.00
	=====

Singapore Dollars Twenty Thousand Five Hundred
and Forty Four Only