



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR	SMRT	VEH TYPE :	VAN	UNIT	D/IST
VEH NO :	GBC 7544 L		REPAIR TYPE:		ACCIDENT
VEH MAKE/MODEL	MERCEDES BENZ VITO		ODOMETER:		44116

Reference No.
7544/SPF/4W/18/01/08

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Bonnet	\$510.00	1	17%	596.70	596.70
1.2	LH bonnet hinge	\$65.00	1	17%	76.05	76.05
1.3	RH bonnet hinge	\$65.00	1	17%	76.05	76.05
1.4	Front bumper	\$350.00	1	17%	409.50	409.50
1.5	Front bumper retainer LH & RH	\$35.00	2	17%	40.95	81.90
1.6	Front bumper support	\$645.00	1	17%	754.65	754.65
1.7	Front bumper centre garnish	\$420.00	1	17%	491.40	491.40
1.8	Radiator grill	\$85.00	1	17%	99.45	99.45
1.9	Front support panel	\$500.00	1	17%	585.00	585.00
1.10	LH head lamp	\$600.00	1	17%	702.00	702.00
1.11	LH fender	\$545.00	1	17%	637.65	637.65
1.12	LH fender signal	\$25.00	1	17%	29.25	29.25
1.13	LH fender panel	\$375.00	1	17%	438.75	438.75
1.14	LH door shell	\$1,000.00	1	17%	1170.00	1170.00
1.15	LH door protector	\$120.00	1	17%	140.40	140.40
1.16	LH door upper hinge	\$115.00	1	17%	134.55	134.55
1.17	LH door lower hinge	\$115.00	1	17%	134.55	134.55
1.18	LH quarter glass moulding	\$45.00	1	17%	52.65	52.65
1.19	Air con pipe	\$180.00	2	17%	210.60	421.20
1.20	ECU control unit box	\$290.00	1	17%	339.30	339.30
1.21	Front tyre	\$145.00	2	17%	169.65	339.30
1.22	LH rim	\$400.00	1	17%	468.00	468.00
1.23	LH wheel cap	\$185.00	1	17%	216.45	216.45
1.24	LH shock absorber	\$475.00	1	17%	555.75	555.75
1.25	LH lower arm	\$860.00	1	17%	1006.20	1006.20
1.26	LH knuckle arm and bearing	\$1,545.00	1	17%	1807.65	1807.65
1.27	Stabilizer bar	\$285.00	1	17%	333.45	333.45
1.28	Stabilizer bar link	\$80.00	1	17%	93.60	93.60
1.29	Steering rack	\$4,290.00	1	17%	5019.30	5019.30
1.30	Tie rod end	\$130.00	1	17%	152.10	152.10
1.31	Steering air bag	\$2,000.00	1	17%	2340.00	2340.00
1.32	Steering air bag clock spring	\$245.00	1	17%	286.65	286.65
1.33	Passenger air bag	\$2,000.00	1	17%	2340.00	2340.00
1.34	Dash board	\$1,400.00	1	17%	1638.00	1638.00
1.35	Passenger safety belt	\$550.00	1	17%	643.50	643.50
1.36	Driver safety belt	\$550.00	1	17%	643.50	643.50
2	Additional Services					
2.1	NA			0%	0.00	0.00
Remarks:					Parts Total:	\$ 25,254.45

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Front Bonnet	59.00	12	826.00
	Remove and replace bonnet			
	Remove and replace both bonnet hinge			
	Putty and spray paint bonnet (3 colour)			
1.2	Front Bumper	59.00	10	708.00
	Remove and replace front bumper			
	Remove and replace both front bumper retainer			
	Remove and replace front bumper support			
	Replace front bumper centre garnish			
	Putty and spray paint front bumper			
1.3	Remove and replace radiator grill	59.00	0.5	59.00
1.4	Remove and replace LH head lamp	59.00	1	59.00
1.5	Front Fender	59.00	8	472.00
	Remove and replace LH fender			
	Remove and replace LH fender signal			
	Remove and replace LH panel			
	Putty and spray paint LH fender and panel (2 colour)			
1.6	Front Door LH	59.00	26	1770.00
	Remove and replace LH door shell			
	Remove and transfer LH door existing door accessory to new door			
	Panel beat and align LH door pillar			
	Remove and replace LH door upper and lower hinge			
	Replace LH door protector			
	Putty and spray paint LH door			

LKK Auto Consultants Force notify
The Repaired of the following
• To survey before after spray painting
• To display damaged parts during survey
• Parts prices are subject to local market
• Third party survey is on a "Without Prejudice" basis
• No legal modification is allowed
• Supplemental claim(s) must be reviewed and
• subject to final approval from Insurance Company
Acknowledged by Repaired
Signature:
Date:

1.7	Panel beat L/H door rocker panel	59.00	1	590.00
	Putty and spray paint L/H door rocker panel			
1.8	Front Quarter Glass LH	59.00	2	118.00
	Remove and re-install quarter glass			
	Replace quarter glass moulding			
1.9	Vehicle Air Con	59.00	3	236.00
	Remove and replace air con pipe			
	Top up air con gas			
1.10	ECU	59.00	14	826.00
	Remove and replace ECU control unit box			
	Labour for wiring			
	Computerise reprogramming			
1.11	Under carriage	59.00	15	885.00
	Remove and replace front both tyre			
	Replace L/H tyre rim cap			
	Remove and replace L/H shock absorber			
	Remove and replace L/H upper arm			
	Remove and replace L/H knuckle arm and bearing			
	Remove and replace stabilizer bar			
	Remove and replace stabilizer bar link			
1.12	Steering Assy	59.00	6	354.00
	Remove and replace steering rack			
	Remove and replace tie rod end			
1.13	Air Bags	59.00	10	590.00
	Remove and replace steering air bag			
	Remove and replace steering clock spring			
	Remove and replace passenger air bag			
	Computerise reprogramming			
1.15	Remove and replace dash board	59.00	12	708.00
1.16	Safety Belt Assy	59.00	1	118.00
	Remove and replace passenger safety belt			
	Remove and replace driver safety belt			
1.18	Labour for wheel alignment	38.00	3	114.00
1.19	Diagnose & reset all wiring	38.00	3	114.00
		SUB-TOTAL	147	8547.00
2	Additional Services			
2.1	Towing Service From Station to Workshop (SOR 8)	138.60	1	138.60
2.2	Return Service From Workshop to Station (SOR 7)	44.10	1	44.10
		SUB-TOTAL	2	182.70
		Labour Total:		\$ 8,729.70
		GRAND TOTAL :		\$ 33,984.15
		Total sum billed under SOR only :		\$ 182.70
		Total sum billed under CVR only :		\$ 33,801.45
Contractor shall complete the entire repair within <u>60</u> working days upon quotation approved date. (Include parts awaiting time)				

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	KONG SEW KUI	Name:		Name:	
Date:	11.9.2017	Date:		Date:	
Sign:		Sign:		Sign:	

Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made

Resurvey check items

15/11/18 @ 3pm

Taufik

97495749

12/1/18 @ 1630