REF: NS/TNC180	00 591/Stbez
	IGNMENT
From: Date: Estimated Cost:	Veh No: SHC 4740k. Yr Regn: 22/1/16  Type: M.Car / M.Cycle / Bus / Van / Lorry / Caxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No:	Make: Toyota Prins. c.c 1799
at Workshop m/s	Colour Marcon A/C: Insured / Std / NI / NA
of	Sp.Reading /60776 T/Radio: Insured / Std / NI / NA
Insured: 67 4729 G	Eng/No:
Policy No. 5038126247-08 160917-150918	C/No: JTDKN 364805766860
Claims No. WT/09770N - 002	Gen. Cond: Good / Pair / Poor / Burnt
Sum Insured: Excess;	Steering: Ingreder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: loorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Mil / S/Rim / STD A/Rim or
	Tyre Size: F: 195/65 Kls
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /
repair at the time of inspection.	TOYOIYOKO or Sallou
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs:days Res.: Yes or No	D.O.A. 8/1/18.
Lum Sum: % 3 Val.: Yes or No	Survey held at SmRT:
CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	Des. of Damages : Frt / Rear / Q/S// N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time I Action / Instruction	
SICHTHER - NO TOUR 12325	18/1 10/10/10 TAX/01/18/2041
<u> </u>	lue.
Part by Part \$3336.64 (P.	ed: 6823.76.67%)
ate/Time, File Pass to? : Preli. Report	Days Of Repair: 5
Doll Typist. : Final Report	Resurvey No. of Trip: Survey Fee: 160
Date/Time, File Return to?	Transportation:
Add Fee	: Site Insp (\$ ) _s+RSSI : Interview (\$ ) Photos 35
Report Format:	: Tech. Invs (\$ ) Others
ump Sum / 181: (\$ 3336.64 )	:Weekend (\$ )
- San Vanis April 1900	TOTAL 195



TEL: 6841 0055 FAX: 6841 6315





	ANCE CO-OPERATIVE LTD		NS/INC1800059	
73 BRAS BASAH ROA #05-01 NTUC TRADE 189556	D UNION HOUSESINGAPORE	Date:	10-01-2018	
		Code:	INC4	
	Policy Particulars	:- THIR	D PARTY CLAIM	
Insured Veh.	GT 4929G	Veh. Ir	nspected	SHC 4740K
Policy No.	5038126247-08	Cover	age (\$)	0.00
Claim No.		Exces	s (\$)	0.00
Assign From	•	Assig	n Date	09/01/2018
	∵ Vehicle Partl	culars 8	Condition	A TOTAL CONTRACTOR OF THE CONT
Make & Model		c.c		0
Engine No.	HIDDEN	Year c	of Reg.	
Chassis No.		Colou	r	
Odometer	-	Steeri	ng	
Brakes		Modifi	cation	,
General			.,	•
	Condit	ons of	Tyrés	
	Size	Make		Balance
R/H Front Tyre				mm
L/H Front Tyre				mm
R/H Rear Tyre				mm
L/H Rear Tyre		<u> </u>	· ·	mm
	Descript	on of D	amages, , ,	
	ara⊭ <b>n</b> ara 4 <b>0 mer</b> Genera	linform	ation	
Accident Date	08/01/2018		ction Date	09/01/2018
Survey held at	SMRT AUTOMOTIVE SERVICE	<del></del>		
	60 WOODLANDS INDUSTRIAL	PARK E	4 SINGAPORE 757	705
	R			
A)THE INSPECTION	ON WAS CONDUCTED ON A"WI"	THOUT P	REJUDICE" BASIS	L

Policy Search Page 1 of 1

<b>eBao</b> Tech	:		Miller of the second						Gene	eralClaim
Hello, NAC_PAYA_UBI_80	0601					<b>)</b>	Change La	nguage	• Change Passwo	rd Log Out
My Desktop	Polic	y Query								,
Notice of Loss	Policy No	o.				Date of Acci	dent	08/0	1/2018 14:41	
	Vehicle M	No.(For Motor)	GT4929G	<del></del>						
						STREET				
	Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	-	038126247-08	AV-IMPACT TECHNOLOGIES	52984082X	GCV	Third Party, Fire & Theft	GT4929G	GT4929G	16/09/2017	15/09/2018
						Continue «				

Intended PARF Rebate Details

PARF Eligibility Expiry Date:

PARF Eligibility:

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type: Company 5369K Owner ID: Vehicle Details SHC4740K Vehicle No.: Vehicle to be Exported: No 10 Jan 2018 Intended De-registration Date: Vehicle Make: TOYOTA Vehicle Model: PRIUS TAXI (SMRT) **Primary Colour:** Maroon Manufacturing Year: 2015 Engine No.: 2ZR6558518 JTDKN36U805766860 Chassis No.: 100.0 kW (134 bhp) **Maximum Power Output:** \$29,508.00 Open Market Value: 22 Jan 2016 **Original Registration Date:** First Registration Date: 22 Jan 2016 **Transfer Count:** \$5,000.00 Actual ARF Paid:

Yes

21 Jan 2024

PARF Rebate Amount:

\$3,750.00

**Intended COE Rebate Details** 

**COE Expiry Date:** 

21 Jan 2024

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$45,307.00

COE Rebate Amount:

\$34,147.00

**Total Rebate Amount:** 

\$37,897.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Jan 2018

**OK** 

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No	Date of Accident
•				יייכפוויי ברוויכיר	מוני כו שככומנוור
7	M1/09/5403-002	SMRT TAXI PTE LTD	SHB 5086P	FBK 4667T	7106/61/26
,	100 0001100/ 101			1001 101	7107/77/77
7	M1/09//299-002	SMRT TAXI PTE LTD	SHB 1927	L 39259 JRS	11/01/2010
				30 CO 21 C	11/01/2010
3	M1/0972718-002	COMFORT TRANSPORTATION	SHA 4630E	FRF 1449H	5/12/2017
,	100 01 10100/ 101			110117 701	0/ 12/ 201/
4	MII/09/6/46-002	SMRT TAXI PTE LTD	SHF 200M	SHR 86765	5/1/2019
١				2000	0707/7/6
ς	MT/0977011-002	SMRT TAXI PTE LTD	SHC 4740K	59797	8/1/2018

#### SINGAPORE ACCIDENT STATEMENT

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT	
Date Of Report	08/01/2018 13:11	
Date Of Accident	08/01/2018 10:30	
Exact Location Of Accident	TECK WHYE LANE	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	

Vehicle Registration Number

SHC4740K

Insured/Policyholder

Name Of Registered Owner

SMRT TAXIS PTE LTD

Co Reg No

198905369K

**Email Address** 

NOEMAIL

Mobile Phone No

Alternative Phone No

OFFICE-80000000

Vehicle Particulars

Manufacturer

TOYOTA

Model

PRIUS TAXI-1.8 (A)

Exact Purpose for which vehicle was being used at

HIRE AND REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

Type Of Coverage

TAXI

**Insurance Company** 

Name of Insurance Company

FIRST CAPITAL INSURANCE LTD THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

YES

Policy Number

Cover Note Number

Driver

Name of Driver

NG WEI TECK COLLIN

D-17087562MFSH

NRIC No. S7046116A Date Of Birth 30/12/1970 Occupation OUTDOOR Date Of Driving Pass 19/08/2011

**Driving Experience** 

6 YEARS AND 4 MONTHS

Gender

MALE

Mobile Number

Fax Number

Contact Number EMail Address

NOEMAIL

Address 536 JELAPANG ROAD

19-20

Postcode 670536

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - HIRER

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - MAJOR/MINOR RD

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?
Was any other material or property damaged?

YES

I have been approached by unknown person(s)

. . \_

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: UNKNOWN

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### **Circumstances of Accident**

I WAS TRAVELLING STRAIGHT ALONG TECK WHYE LANE WITH A PASSENGER ON BOARD WHEN THE VEHICLE GT4929G SUDDENLY DASHED OUT OF THE CAR PARK EXIT AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?

YE\$

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE TOO LARGE

Was there any audio recorded?

NO

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

GT4929G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

**GOODS VEHICLE** 

Name of Driver

GOH KIM CHUAN

NRIC/Passport Number

S1146405Z

Contact Number

Address

Address Postcode

Insurance Company Name

'Nature Of Damage No. Of Passenger (Including Driver)

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could invoive disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

ii)-for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name:

ph 8(1) 2-18

NRIC/FIN No.:

# SKETCH PLAN TECK WHYE LANE みぐた <u>,</u> A TECK CHUA CHU KANG LENG HUP MAN CHEE & COMBINED CHEA TEMPLE TEMPLE DESCRIBE CIRCUMSTANCES OF THE ACCIDENT DECLARATIONS I/We declare the foresbing particulars are true in every respect. do 8/1/24 Policyholder's Signature Driver's Signature Reporting Centre Personnel's Signature Date & Time: (If driver is not the policyholder) Name: Date & Time: NRIC/FIN No.:



(5-1-18/co:42 15-1-18/14:42

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

## **SMRT Accident Vehicle Repair Estimates**

G 1-1 0/1

				7-1-18/14:4	2
Section A - To be complete	ted by claims Advis	or/Duty officer at A	ccident Reporting C	entre	
Reg. No	: SHC4740K	<b>∠\\</b>			
Ref. No	: TAX/01/18/20	41			
Reg. Date	: 22/01/2016				
Vehicle Type	: TAXI				
Make /	TOYOTA PRI	us			
Model	PRIUS				
Name of Driver	: NG WEI TECI	K COLLIN	•	/4 k	
Type of Accident	: HEAD TO SID	DE	American American	* <b>5</b>	
Date / Time of Accident	: 08/01/2018 10	):30:00 AM			
Accident Reported Date / Ti	me: 08/01/20\18 12	2:00:00 AM	; ;		
Surveyor is Required?	: Yes		01		
Survey by	: Sebasti	an .			1
Vehicle is Towed Back?	: No		Account		
Towed Back Date/Time	:	ł	Washington State	a Al Arge	Ì
Replacement Vehicle issued	1? : No	1	Osmai	6555 8888	ŀ
Accident Repair Job Card No	o : 000024093979			24/102	
Special Instruction to ARC, if	any:				1
3T4929G NTUL P	ρ				
Prepared Date	: 08/01/2018 0	02:01:39 PM			- 1
			<u> </u>		
					<del></del>
				*	
Recording Camera		Vohicia te Wega	09/01	raining recense great-draw	
Radio Antenna	— <u>— — — — — — — — — — — — — — — — — — </u>				
1 <sup>st</sup> witness	[]		Time In: 17-00 Prin	(et) H (et)	
Ond to	ate	Wega Job No:_	01 0070		
2 willess Da	ate	11-11-1	18/1/18	$\mathcal{A}$	
		Vahicle sont to SMT			
وراه ا	F		Time in: 1000 Date	vor:	
E (1)2	973	. Received by (Si	METI:	/,	
KM 1/57	747	Committee with Manie II Part of Manie III			
	•				
	00/	2/1/18	13, 80PG	2 C1	
		31,1,0,	3. 40/	. 77	

Section B - To be Completed by Service Advisor, Accident Repair Centre

· Chassis No :

Mileage

0

Work Shop :

Repair Completed Date / Time:

Summary of Repair Estimates

**Quotation from ARC** 

Adjusted by Surveyor, if applicable

**Total Labout Charges** 

1,183.00

600.00

**Total Spray Painting Charges** 

1,692.00

900.00

**Total Material Charges** 

3,556.70

1,606.64

Other Charges ...

TOTAL

1,185.00 7,616.70 230.00 3,336.64

**Lum Sum Total** 

0.00

0.00

No. of Repair Days

7.00

5.00

Prepared / Adjusted By

SEBASTIAN (LKK)

Arc / Surveyor Sing Off Date

: 08/01/2018 06:51:47 PM

09/01/2018 02:42:02 PM

repared / Adjusted Date

Remarks

repared Date :

08/01/2018 06:49:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

**Quotation No** 

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

### Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scopé	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,183.00	600.00
Total Labour	1,183.00	600.00

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00 1 /	200.00 /
TO RESPRAY ROCKER PANEL MOULDING	180.00	100.00 /
TO RESPRAY REAR DOOR RH	378.00	200.00
TO RESPRAY REAR FENDER RH	378.00 {/	200.00 /
TO REPSRAY REAR BUMPER	378.00	200.00
Fotal Spray Painting & Panel Beating	1,692.00	900.00

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

lob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00
O APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40.00
O TRANSFER DOOR MECHANISM	240,00	120.00 /
O PROVIDE LABOUR & MATERIAL FOR SOLAR ILM (NET)	125.00	0.00
O REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00
O REMOVE AND REFIT WIRE HARDESS	120.00	40.00
O REMOVE / REFIT SEAT	120.00	0.00
O TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
O REPLACE SUNDRY PARTS	100.00	0.00
O WASH AND VACUUM	60.00	0.00
otal Other Costs	1,185.00	230,00

Part	Portion	Stock No	Part Name	Qty	List Price	Discount	Final Price	ARC	Surveyor	Photos
Number					(\$)	(%)	(\$)	Recommen	Approved	
67001- 47070		6505528	DOOR FRT/RH	V	1 894.40	25.00	670.80	Replace	Replace	No V
			STICKER DECAL SMRT (DOOR)	1	1 60.00	0.00	60.00	Replace	Replace	No V
39030- 47070			DOOR LOCK FRT/RH	X	1 575.80	25.00	431.85	Replace	Check	No X
39210- 74030			DOOR OUTER HANDLE FRT/RH	12,	1 370.80	100.00	0.00	Replace	Repair	NoR
89217- 74010 ————			COVER, FRONT DOOR OUTSIDE HANDLE	1	1 14.10	25.00	10.57	Replace	Replace	No V
39005- ₽7170			CYLINDER SET, LOCK	X	1 236.10	10.00	212.49	Replace	Check	No X
39205- 17050			DOOR INNER HANDLE FRT/RH	X	84.70	25.00	0.00	Replace	Not given	No X
35710- 17120F			DOOR REGULATOR MOTOR FRONT RH	X	947.80	10.00	853.02	Replace	Check	No X
i9801- i2070			DOOR REGULATOR SUB-ASSY, FRT/REAR RH	X	1 224.80	25.00	168.60	Replace	Check	No X
7900			MOULDING BODY, RH	R	673.60	100.00	0.00	Replace	Repair	No R
7003- 7080		6505486	DOOR RR/RH	V	954.50	25.00	715.87	Replace	Replace	No /
8770- 2031			HINGE LOWER RHR, DOOR	X1	52.00	25.00	39.00	Replace	Check	No X
8750- 0121			HINGE UPPER RHR, DOOR	Z	81.70	25.00	61.28	Replace	Check	No X
8630- 7031			CHECK ASSY, RR DOOR,	乂1	150.30	25.00	112.73	Replace	Check	No X
1604- 7090			FENDER RR/RH	R	766.80	100.00	0.00	Replace	Repair	No R
- 1	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No /
			STICKER DECAL 6555 8888	U	21.60	0.00	21.60	Replace	Replace	No V
2710- 7130			QUARTER GLASS RR/RH	Хο	846.50	25.00	0.00	Replace	Not given	No X
	COMMO N		SEALANT W/SCREEN	∞	37.00	0.00	0.00	Replace	Not given	No X
5637- 7021		6505480	FENDER LINER RR/RH	L°	141.30	25.00	0.00	Replace	Not given	No X
?159- '905		6505548	BUMPER REAR	12	458.60	100.00	0.00	Replace	Repair	No R
2575- 2020			BUMPER SIDE RETAINER RR/RH	$\propto^1$	94.80	25.00	71.10	Replace	Check	No X
		1	PIXEL STICKER		60.00 (1207	0.00	120.00	Replace I	Replace	No 1
·		T	OTAL MATERIALS				L	3,556.71	1,606.64	<u> </u>
		TOTAL	MATERIALS(Discoun	ted)				3,556.70	1 606 64	

Ided Spare Parts / Material Usage After Surveyor Signed off

Part umber	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	TOTAL SUPPLEMENTARY MATERIALS								





60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

## **SMRT Accident Vehicle Repair Estimates**

NTW

6,17

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHC4740K

-- ----

Ref. No

TAX/01/18/2041

Reg. Date

22/01/2016

Vehicle Type

TAXI

Make

TOYOTA PRIUS

Model

PRIUS

Name of Driver

: NG WEI TECK COLLIN

Type of Accident

HEAD TO SIDE

Date / Time of Accident

08/01/2018 10:30:00 AM

Accident Reported Date / Time :

08/01/2018 12:00:00 AM

Surveyor is Required?

: Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Νo

Accident Repair Job Card No :

o: 000024093979

Special Instruction to ARC, if any :

GT4929G

Prepared Date

08/01/2018 02:01:39 PM

Sebartian. 9/1/18.

- Part by part repair.

- Question Mark Item Photo

- Photo Before Paint

Sebestianyeany & / kkanto.com.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- \* Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

/01/18/2041

Page:

Control of the Completed by Service Advisor, Accident Repair Centre

Chassis No :

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

**Total Spray Painting Charges** 

**Quotation from ARC** 

Adjusted by Surveyor, if applicable

**Total Labout Charges** 

1,183.00

1,692.00

0.00 0.00

**Total Material Charges** 

6,100.40

6,100.40

Other Charges

1,185.00

0.00

**TOTAL** 

10,160.40

0.00

**Lum Sum Total** No. of Repair Days

0.00 7.00

0.00

Prepared / Adjusted By

5 days.

0.00

Arc / Surveyor Sing Off Date

: 08/01/2018 06:51:47 PM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date :

08/01/2018 06:49:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date:

### Section D - Details of Repair Estimates

# Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,183.00	0.00 6-0
Total Labour	1,183.00	0.00

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00100
TO RESPRAY REAR DOOR RH	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200.
Fotal Spray Painting & Panel Beating	1,692.00	0.00

### <sup>2</sup>art 3 - Other Costs - Accident and Accident Repair Related Expenses

lob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
O APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
O TRANSFER DOOR MECHANISM	240.00	0.00 120
O PROVIDE LABOUR & MATERIAL FOR SOLAR ILM (NET)	125.00	0.00 ×
O REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 ×
O REMOVE AND REFIT WIRE HARDESS	120.00	0.00 40
O REMOVE / REFIT SEAT	120.00	0.00 ×
O TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 ×
O REPLACE SUNDRY PARTS	100.00	0.00 ×
O WASH AND VACUUM	60.00	0.00 ×
otal Other Costs	1,185.00	0.00

AX/01/18/2041 Page:

### Part 4 - Spare Parts / Material Usage

			· · · · · · · · · · · · · · · · · · ·							
,Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
37001- 47070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace \( \square 0.1	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace √ M	No C
39030- 17070			DOOR LOCK FRT/RH	1	575.80	25.00	431.85	Replace	Replace ?	No
39210- 74030			DOOR OUTER HANDLE FRT/RH	1	370.80	25.00	278.10	Replace	Replace	No R
39217- 74010			COVER, FRONT DOOR OUTSIDE HANDLE	1	14.10	25.00	10.57	Replace	Replace √ w	No S
39005- 17170			CYLINDER SET, LOCK	1	236.10	10.00	212.49	Replace	Replace ?	No
39205- 17050			DOOR INNER HANDLE FRT/RH	1	84.70	25.00	63.52	Replace	Replace <b>×</b>	No
35710- 17120F			DOOR REGULATOR MOTOR FRONT RH	1	947.80	10.00	853.02	Replace	Replace つ	No
39801- 32070			DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1	224.80	25.00	168.60	Replace	Replace	No
′5851- ∤7900			MOULDING BODY, RH	1	673.60	25.00	505.20	Replace	Replace L	No
7003- 7080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace $\sqrt{1}$	No )T
i8770- i2031			HINGE LOWER RHR, DOOR	1	52.00	25.00	39.00	Replace	Replace ?	No
i8750- :0121			HINGE UPPER RHR, DOOR	1	81.70	25.00	61.27	Replace	Replace 7	No
8630- 7031			CHECK ASSY, RR DOOR,	1	150.30	25.00	112.72	Replace	Replace 7	No
1604- 7090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace R	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No c
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No IEC
2710- 7130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace 😾	No
	COMMO N		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace ×	No
5637- 7021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.97	Replace	Replace ×	No
2159- 7905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace R	No
2575- 7020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace >	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace/NR	No
_		T	OTAL MATERIALS					6,100.44	•	
		TOTAL	MATERIALS(Discoun	ted)				6,100.40	6,100.40	

### dded Spare Parts / Material Usage After Surveyor Signed off


Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
·	TC	OTAL SUPPLEMENTARY MA	TERIA	LS					



### **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSUR	RANCE CO-OPERATIVE LTD	Ref:	NS/INC1800059	91/Stbe2
73 BRAS BASAH ROA #05-01 NTUC TRADE 189556	D UNION HOUSESINGAPORE	Date:	30-01-2018 INC4	
1.	Policy Particulars	:- TḤIR	D PARTY CLAIM	
Insured Veh.	GT 4929G	Veh. I	nspected	SHC 4740K
Policy No.	5038126247-08	Cover	age (\$)	0.00
Claim No.	MT/0977011-002	Exces	s (\$)	0.00
Assign From		Assig	n Date	09/01/2018
2.	Vehicle Parti	culars 8	Condition	
Make & Model	TOYOTA PRIUS	c.c		1798
Engine No.	HIDDEN	Year o	of Reg.	2016
Chassis No.	JTDKN36U805766860	Colou	r	MAROON
Odometer	160976	Steeri	ng	IN ORDER
Brakes	IN ORDER	Modifi	ication	NIL
General	FAIR			
3.	Conditi	опѕ об	Tyres	
	Size	Make		Balance
R/H Front Tyre	195/65 R15	FALKE	N	6 mm
L/H Front Tyre	195/65 R15	FALKE	N	6 mm
R/H Rear Tyre	195/65 R15	FALKE	N	6 mm
⊔H Rear Tyre	195/65 R15	FALKE	N	6 mm
<b>4.</b>	Description	on of D	amages.	
THE VEHICLE SUS DAMAGES SEE D	STAINED DAMAGES AT THE O/S ETAILS.	S BODY.		
5		l Inform	ation	
Accident Date	08/01/2018	inspec	ction Date	09/01/2018
Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	TD	
	60 WOODLANDS INDUSTRIAL	PARK E		
5a.	R	emarks	的数少数24元4 从2003 第754 - 200	
	ON WAS CONDUCTED ON A'WIT CE TO YOUR INSTRUCTIONS, W		REJUDICE" BASIS	•
<b>56.</b>	Estimate	Days o	Repair	
ESTIMATED NOR	MAL PERIOD FOR REPAIR:		5 Working Days	



### **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4740K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR FRT / RH (DISC 25%)	DENTED	894.40	670.80
1	COVER, FRONT DOOR OUTSIDE HANDLE (DISC 25%)	MISSING	14.10	10.57
1	DOOR RR/RH (DISC 25%)	DENTED	954.50	715.87
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	DOOR LOCK FRT/RH	NOT NECESSARY	575.80	-
1	CYLINDER SET, LOCK	NOT NECESSARY	236.10	-
1	DOOR INNER HANDLE FRT / RH	NOT NECESSARY	84.70	-
1	DOOR REGULATOR MOTOR FRONT RH	NOT NECESSARY	947.80	-
1	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	NOT NECESSARY	224.80	-
1	HINGE LOWER RHR, DOOR	NOT NECESSARY	52.00	-
1	HINGE UPPER RHR, DOOR	NOT NECESSARY	81.70	-
1	CHECK ASSY, RR DOOR	NOT NECESSARY	150.30	-
1	QUARTER GLASS RR/RH	NOT NECESSARY	846.50	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-1
1	FENDER LINER RR/RH	NOT NECESSARY	141.30	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	DOOR OUTER HANDLE FRT / RH	TO REPAIR	370.80	-
1	MOULDING BODY, RH	TO REPAIR	673.60	-
1	FENDER RR/RH	TO REPAIR	766.80	-
1	BUMPER REAR	TO REPAIR	458.60	-
			7,815.00	1,606.64
	LABOUR		,	-
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		2,108.00	790.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,792.00	940.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-

Report Ref No. NS/INC18000591/Stbe2



#### **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By . Workshop (\$).	Our Adjusted. (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			4,060.00	1,730.00
	GRAND TOTAL		11,875.00	3,336.64

|--|

Report Ref No. NS/INC18000591/Stbe2

YEANG WAI KEEN

Automotive Assessor

M.

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser