






# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18000593/Stb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 10-01-2018	
Code: INC4				
<b>1. Policy Particulars - THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 8676S	Veh. Inspected	SHF 200M	
Policy No.	5095103893	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	09/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	05/01/2018	Inspection Date	09/01/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident

Vehicle No.(For Motor)

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5095103893	PREMIER TAXIS PTE. LTD.	200304975H	GFT	Third Party	SHB8676S	SHB8676S	20/10/2017	

Continue

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0975403-002	SMRT TAXI PTE LTD	SHB 5086P	FBK 4667T	27/12/2017
2	MT/0977299-002	SMRT TAXI PTE LTD	SHB 192Z	SHC 6576E	11/01/2018
3	MT/0972718-002	COMFORT TRANSPORTATION	SHA 4630E	FBE 1449H	6/12/2017
4	MT/0976746-002	SMRT TAXI PTE LTD	SHF 200M	SHB 8676S	5/1/2018
5	MT/0977011-002	SMRT TAXI PTE LTD	SHC 4740K	GT 4929G	8/1/2018

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	08/01/2018 11:47
Date Of Accident	05/01/2018 17:40
Exact Location Of Accident	PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF200M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

#### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

#### Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

#### Driver

Name of Driver	TAN KAH HOCK
NRIC No	S0141291D
Date Of Birth	07/04/1950
Occupation	OUTDOOR
Date Of Driving Pass	04/06/1969
Driving Experience	48 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	115 ANG MO KIO AVENUE 4 06-399
Postcode	560115
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING ALONG PIE AT THE RIGHT MOST LANE WITH THREE PASSENGERS ON BOARD WHEN THE FRONT VEHICLE SKF8005Y CAME TO A STOP DUE TO TRAFFIC CONGESTED AHEAD. I APPLIED BRAKE AND ABLE TO STOP IN TIME. HOWEVER, THE SILVERCAB SHB8676S FROM BEHIND FAILED TO STOP AND COLLIDED ONTO THE REAR PORTION OF MY TAXI. DUE TO THE IMPACT, MY TAXI WAS PUSHED FORWARD AND RESULTED TO HIT ONTO THE REAR PORTION OF SKF8005Y.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB8676S
Vehicle Make/Model/Colour	SILVERCAB
Details Of Properties	

Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKF8005Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN CHAI LYE
NRIC/Passport Number	S1830796J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



### Sketch Plan Pg. 2

### SKETCH PLAN

↑      ↑      ↑      ↑

□      □      □      □

C      A      B

C - SKF 80057

A - SHF 200M

B - SHB 86765

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

### Vehicle Details

Vehicle No.:	SHF200M
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8254058
Chassis No.:	JTDKB3FU503576339
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	14 Dec 2017
First Registration Date:	14 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Dec 2025

**PARF Rebate Amount:** **\$3,750.00**

**Intended COE Rebate Details**

**COE Expiry Date:** **13 Dec 2025**

**COE Category:** **A - Car up to 1600cc & 97kW (130bhp)**

**COE Period(Years):** **8**

**PQP Paid:** **\$34,159.00**

**COE Rebate Amount:** **\$33,837.00**

**Total Rebate Amount:** **\$37,587.00**

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Jan 2018

**OK**

13-1-18 / 10:45

13-1-18 / 14:45

9-1-18 / 14:45

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF200M  
 Ref. No : TAX/01/18/2037  
 Reg. Date : 14/12/2017  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS4  
 Name of Driver : TAN KAH HOCK  
 Type of Accident : CHAIN COLLISION  
 Date / Time of Accident : 05/01/2018 05:40:00 PM  
 Accident Reported Date / Time : 08/01/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : Sebastian  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024093982  
 Special Instruction to ARC, if any :

DROVE IN / SHB8676S (SILVERCAB) - NTUC  
 BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)  
 & Email : sebastianeang @lkkauto.com HP:90036121

Prepared Date : 08/01/2018 12:19:16 PM



QC 12/1/18 18.36 Reject P+ Bumper upper NO clip  
 13/1/18 10.26 Pass

Recording Camera

Radio Antenna

1st witness

2nd witness

☐ ☒  
☐ ☒  
 Date 9-1-18  
 Date

Vehicle to Wega Date In: 09/01 Towing:  
 Time In: 1700 Driver: TAT  
 Wega Job No: 01/0021  
 Vehicle sent to SMRT Date In: 12-1-18 Towing:  
 Time In: 14-00 Driver:  
 Received by (SMRT):

E 1/2 F  
 KM 78/8

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU503576339


Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	400.00
Total Spray Painting Charges	: 1,296.00	500.00
Total Material Charges	: 2,677.14	1,615.07
Other Charges	: 360.00	30.00
<b>TOTAL</b>	<b>: 5,178.14</b>	<b>2,545.07</b>
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	4.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 08/01/2018 02:40:55 PM	09/01/2018 02:45:29 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/01/2018 02:37:15 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1201-0406

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 15/1.

Prepared Date :

1615.07 /  
400 /  
+ 530 /  
-----  
2545.07 /

Sebastian  
22/1/18

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00 ✓	200.00
TO REPAIR REAR PORTION	507.00 ✓	200.00
<b>Total Labour</b>	<b>845.00</b>	<b>400.00</b> ✓

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00 ✓	200.00 ✓
TO REPSRAY REAR BUMPER	378.00 ✓	200.00 ✓
TO RESPRAY BUMPER BEAM	180.00 ✗	0.00
TO RESPRAY FILLER RR BUMPER RH	180.00 ✗	0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00 ✓	100.00 ✓
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,296.00</b>	<b>500.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>360.00</b>	<b>30.00</b>

1853.90

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5211947962			COVER, FR BUMPER	1	495.50	100.00	0.00	Replace	Repair	No <i>NR</i>
5310147080			GRILLE SUB-ASSY	1	335.60	25.00	251.70	Replace	Check	No <i>X</i>
5211447190			BRACKET, FR BUMPER	1	99.80	25.00	74.85	Replace	Check	No <i>X</i>
			NUMBER PLATE	0	35.00	0.00	0.00	Replace	Not given	No <i>X</i>
			NUMBER PLATE FRAME	0	25.00	0.00	0.00	Replace	Not given	No <i>X</i>
7531047060			EMBLEM ASSY FRONT	1	87.10	25.00	65.32	Replace	Replace	No <i>✓</i>
5261147140			ABSORBER, FR BUMPER	1	70.30	25.00	52.73	Replace	Check	No <i>X</i>
5202147110			REINFORCEMENT FRONT UPPER	1	691.10	25.00	518.33	Replace	Check	No <i>X</i>
5215947913			COVER, RR BUMPER ASSY	1	423.90	100.00	0.00	Replace	Repair	No <i>NR</i>
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Check	No <i>X</i>
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No <i>✓</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>✓</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>✓</i>
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No <i>✓</i>
5246147010			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Check	No <i>X</i>
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.53	Replace	Check	No <i>X</i>
5259147050			SEAL, RR BUMPER, RH	1	85.20	25.00	63.90	Replace	Check	No <i>X</i>
5256547900			FILLER, RR BUMPER, RH	0	119.90	25.00	0.00	Replace	Not given	No <i>X</i>
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No <i>✓</i>
8158147010			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	10.00	438.12	Replace	Replace	No <i>✓</i>
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	100.00	0.00	Replace	Repair	No <i>NR</i>
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No <i>✓</i>
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No <i>✓</i>
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No <i>✓</i>
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No <i>✓</i>
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>✓</i>
TOTAL MATERIALS							2,677.17	1,615.07		
TOTAL MATERIALS(Discounted)							2,677.14	1,615.07		


# SMRT Accident Vehicle Repair Estimates

G1A

NTUC

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF200M  
Ref. No : TAX/01/18/2037  
Reg. Date : 14/12/2017  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS4  
Name of Driver : TAN KAH HOCK  
Type of Accident : CHAIN COLLISION  
Date / Time of Accident : 05/01/2018 05:40:00 PM  
Accident Reported Date / Time : 08/01/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by :  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No :  
Special Instruction to ARC, if any :  
DROVE IN / SHB8676S (SILVERCAB) - NTUC  
Prepared Date : 08/01/2018 12:19:16 PM



Sebastian.  
9/1/18.

- Part by part repair.
- Question mark Item Photo
- Photo Before Paint

90036121

sebastianyang@lkkauto.com.

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : Mileage : 0  
Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	845.00	0.00
Total Spray Painting Charges :	1,296.00	0.00
Total Material Charges :	4,184.99	4,184.99
Other Charges :	360.00	0.00
<b>TOTAL :</b>	<b>6,685.99</b>	<b>0.00</b>
<b>Lum Sum Total :</b>	<b>0.00</b>	<b>0.00</b>
No. of Repair Days :	6.00	<del>0.00</del>
Prepared / Adjusted By :		4 days
Arc / Surveyor Sign Off Date :	08/01/2018 02:40:55 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/01/2018 02:37:15 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00	0.00 J 400
TO REPAIR REAR PORTION	507.00	0.00 J
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00 ?	0.00
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 X
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
Total Spray Painting & Panel Beating	1,296.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	360.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
2119479 02			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace R	No
3101470 00			GRILLE SUB-ASSY	1	335.60	25.00	251.70	Replace	Replace ?	No
2114471 00			BRACKET, FR BUMPER	1	99.80	25.00	74.85	Replace	Replace ?	No
			NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace X	No
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace X	No
5310470 00			EMBLEM ASSY FRONT	1	87.10	25.00	65.32	Replace	Replace / NEC	No
2611471 00			ABSORBER, FR BUMPER	1	70.30	25.00	52.72	Replace	Replace ?	No
2021471 00			REINFORCEMENT FRONT UPPER	1	691.10	25.00	518.32	Replace	Replace ?	No
2159479 03			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace R	No
2169470 00			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace <del>Deform</del> ?	No ?
2453470 00			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace ✓	No Deform
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace / NEC	No
2023470 00			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace ?	No
2461470 00			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace ?	No
2575470 00			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace ?	No
2591470 00			SEAL, RR BUMPER , RH	1	85.20	25.00	63.90	Replace	Replace ?	No
2565479 00			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace X	No
2161160 00			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace / NEC	No
1581470 00			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	10.00	438.12	Replace	Replace ✓ SCR.	No
6801471 0A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace X R	No
5403480 00			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace / NEC	No
5441470 00			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓ NEC	No
5442471 00			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓ NEC	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
TOTAL MATERIALS								4,185.05	4,184.99	
TOTAL MATERIALS(Discounted)							4,184.99	4,184.99		

Added Spare Parts / material Usage After Surveyor Signed on

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									


**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Thatcham *escribe*

Reg. No: 52983356E GST Reg. No. 20-0405911-H

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18000593/Stbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 30-01-2018	
			Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 8676S	Veh. Inspected	SHF 200M	
Policy No.	5095103893	Coverage (\$)	0.00	
Claim No.	MT/0976746-002	Excess (\$)	0.00	
Assign From		Assign Date	09/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU503576339	Colour	MAROON	
Odometer	7819	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS				
<b>5. General Information</b>				
Accident Date	05/01/2018	Inspection Date	09/01/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 200M**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	EMBLEM ASSY FRONT (DISC 25%)	NECESSARY	87.10	65.32
1	GUARD, RR BUMPER, LOWER (DISC 25%)	DEFORMED	558.30	418.72
1	REAR BUMPER REINFORCEMENT (DISC 25%)	DENTED	318.80	239.10
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.72
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	LENS & BODY ASSY, RR BUMPER, RH (DISC 10%)	SCRATCHED	486.80	438.12
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	GRILLE SUB-ASSY	NOT NECESSARY	335.60	-
1	BRACKET, FR BUMPER	NOT NECESSARY	99.80	-
1	NUMBER PLATE	NOT NECESSARY	35.00	-
1	NUMBER PLATE FRAME	NOT NECESSARY	25.00	-
1	ABSORBER, FR BUMPER	NOT NECESSARY	70.30	-
1	REINFORCEMENT FRONT UPPER	NOT NECESSARY	691.10	-
1	COVER, GUARD RR BUMPER LOWER	NOT NECESSARY	14.80	-
3	PAD, RR BUMPER, CTR @\$2.20	NOT NECESSARY	6.60	-
1	RETAINER, RR BUMPER, RH	NOT NECESSARY	112.70	-
1	SEAL, RR BUMPER, RH	NOT NECESSARY	85.20	-
1	FILLER, RR BUMPER, RH	NOT NECESSARY	119.90	-
1	COVER, FR BUMPER	TO REPAIR	495.50	-
1	COVER, RR BUMPER ASSY	TO REPAIR	423.90	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	TO REPAIR	891.20	-
			<b>5,352.90</b>	<b>1,615.07</b>

Report Ref No. NS/INC18000593/Stbe2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,045.00	430.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,296.00	500.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,501.00	930.00
	<b>GRAND TOTAL</b>		<b>7,853.90</b>	<b>2,545.07</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>2,545.07</b>

Report Ref No. NS/INC18000593/Stbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.