

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Not Allowed
dlk
2/5 \$
32g
15/1/18
The ph. After repair

DATE : 9/1/2018

M/S INDIAN INT'L INS LTD

Dear Sir

ESTIMATE REPAIR COST FOR SKP 9138M

S/N	QTY	DESCRIPTION		\$
1	1 PC	BOOTLID <i>20/300</i>		957.40 ✓
2	1 PC	BOOTLID BADGE <i>nu</i>		74.40 =
3	1 PC	BOOTLID MAZDA EMBLEM <i>nu</i>		53.40 =
4	1 PC	BOOTLID RUBBER		129.30 ?
5	1 PC	BOOTLID SKYACTIN EMBLEM <i>nu</i>		63.60 -
6	2 PCS	BOOTLID REFFLECTOR <i>11</i>		888.60 x
7	2 PCS	TAILLAMP <i>17</i>		1,830.00 x
8	1 PC	REAR BUMPER <i>20/200</i>		1,074.80 ✓
9	1 SET	REAR BUMPER CLIPS <i>nu</i>		40.00 ✓
10	1 PC	REAR BUMPER SPONGE <i>NS</i>		79.20 x
11	1 PC	REAR BUMPER REINFORCEMENT		537.30 ?
12	1 PC	REAR BUMPER REFLECTOR <i>17</i>		102.00 x
13	2 PCS	REAR BUMPER TOW HOOK COVER <i>17</i>		32.40 x
14	1 PC	REAR NUMBER PLATE LAMP <i>11</i>		142.20 x
15	1 PC	REAR END PANEL		505.10 ?
16	1 PC	REAR END PANEL GARNISH		85.10 ?
				\$ 6,594.80
LESS 20%				\$ (1,318.96)
				\$ 5,275.84

17	1 SET	SPECIAL NETT <i>nu</i>	\$	280.00 x
18	2 PCS	BOOT CAMERA <i>should</i>	\$	250.00 2005.~
19		PARKING SENSOR	\$	1,100.00 800
20		To spray paint.	\$	1,100.00 520
21		labour charge to renew damage parts	\$	80.00 50
22		To remove and refit rear electrical wiring.renew sensor	\$	80.00 30
23		To apply undercoating.	\$	80.00 60
23		To remove and refit garnishes, carpets , etc	\$	8,245.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1
Signed by Repairer

Signature:

Date: