


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB817E
Ref. No : TAX/01/18/2030
Reg. Date : 10/10/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : GOH CHEE KEON LOURENS
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 06/01/2018 05:15:00 AM
Accident Reported Date / Time : 08/01/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 06/01/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093966
Special Instruction to ARC,if any :
TOWED \$40 / SHA5383L (COMFORT) III
Prepared Date : 08/01/2018 09:16:48 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU903572309

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	845.00	0.00
Total Spray Painting Charges :	1,494.00	0.00
Total Material Charges :	2,769.95	2,769.95
Other Charges :	780.00	0.00
TOTAL :	5,888.95	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	5.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	08/01/2018 10:42:28 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/01/2018 10:42:28 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	845.00	0.00
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR LH	378.00	0.00
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00
TO RESPRAY REAR FENDER LH	378.00	0.00
RESPRAY WHEEL CAP	180.00	0.00
TO REPSRAY REAR BUMPER	378.00	0.00
Total Spray Painting & Panel Beating	1,494.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO REMOVE AND REFIT TYRE	120.00	0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
TO TRANSFER DOOR MECHANISM	120.00	0.00
Total Other Costs	780.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
6700447210			PANEL SUB-ASSY, REAR DOOR , LH	1	1,243.90	25.00	932.92	Replace	Replace	No
7586047900			MOULDING ASSY, BODY ROCKER PANEL , LH	1	576.00	25.00	432.00	Replace	Replace	No
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace	No
4260247180			CAP SUB-ASSY, WHEEL	1	175.80	25.00	131.85	Replace	Replace	No
			TYRE	1	126.74	0.00	126.74	Replace	Replace	No
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No
5256647900			FILLER, RR BUMPER , LH	1	119.90	25.00	89.92	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
TOTAL MATERIALS							2,769.97	2,769.95		
TOTAL MATERIALS(Discounted)							2,769.95	2,769.95		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									