

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9260P

DATE 9/1/2018 9:53

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover <i>Cnt</i>			\$ 562.30	✓
	Front Bumper Sponge <i>NH</i>			\$ 142.20	x
	Front Bumper Reinforcement <i>NH</i>			\$ 526.10	x
	Front Bumper Grille (LH) <i>Cnt</i>			\$ 40.30	✓
	Front Bumper Bracket Top (LH) <i>SC</i>			\$ 22.40	x
	Front Bumper Retainer Mounting <i>SC</i>			\$ 9.20	x
	Headlamp Support Panel Assy <i>NH</i>			\$ 1,067.50	x
	Headlamp (LH) <i>Scrapped</i>			\$ 1,388.00	✓
	Front Fender (LH) <i>Scrapped</i>			\$ 619.00	✓
	Front Fender Shield (LH) <i>SC</i>			\$ 169.80	x
	Front Fender Retainer <i>SC</i>			\$ 9.20	x
	SUB TOTAL			\$ 4,556.00	
	LESS 20%			\$ 911.20	
	DISCOUNTED TOTAL			\$ 3,644.80	
	Front Fender Advertisement Logo (LH) <i>NH</i>			\$ 100.00	Nett ✓
				\$ 100.00	
	Labour Charge				
	Panel Beating			\$ 560.00	400/-
	Spray Painting Charge			\$ 400.00	360/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	20/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00	NH
	TOTAL LABOUR			\$ 1,210.00	
	ESTIMATE TOTAL			\$ 4,954.80	
	09/01/2018 @ 1500m Hua Andrew L/Sun 2 days. 2 KIC Andu				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					